CITY OF ROME



PHASE I ENVIRONMENTAL SITE ASSESSMENT

FORMER ROME-TURNEY RADIATOR COMPANY – 109 CANAL STREET
ROME, ONEIDA COUNTY, NEW YORK 13440

Prepared for:
CITY OF ROME
198 N. Washington St.
Rome, NY 13440

Bergmann Project No. 10118.00

Issuance Date: August 24, 2015

TABLE OF CONTENTS

SECTION		PAGE
1.0	INTRODUCTION	1
1.01	Purpose	1
1.02	Intended Use	1
1.03	Objectives	1
1.04	Limiting Conditions and Deviations	1
2.0	SITE DESCRIPTION	2
2.01	Location and Description	2
2.02	Site Vicinity and Characteristics	2
2.03	Current Uses of the Property	2
2.04	Description of Current Structures, Roads and Improvements	2
2.05	Past Uses of the Property	5
2.06	Current and Past Uses of Adjoining Properties	5
3.0	ENVIRONMENTAL RECORDS REVIEW	6
3.01	Standard Environmental Record Sources, Federal, State and County	6
3.02	Environmental Listings for the Subject Property	6
3.03	Identified Off-Site Environmental Listings	7
3.04	Unmapped Listed Sites	18
3.05	Additional Records Sources and Interviews	18
4.0	SUBJECT PROPERTY PHYSICAL SETTING REVIEW	25
4.01	Historical Use Information	25
4.02	Topographic Map Review	25
4.03	Historic Sanborn® Map Review	25
4.04	Historic Aerial Photograph Review	28
4.05	City Directory Image Review	29

TABLE OF CONTENTS (Continued)

SECTION **PAGE**

4.06 Wetland Review 29
4.07 Flood Hazard Boundary Review 29
4.08 Soil Survey Review, Local Groundwater and Subsurface Characterization 29
5.0 INFORMATION GATHERED DURING THE SITE RECONNAISSANCE VISIT 30
5.01 On-Site Buildings and Structures 30
5.02 Hazardous Substances in Connection with Identified Uses 30
5.03 Underground Storage Tanks and Aboveground Storage Tanks 30
5.04 Indications of Polychlorinated Biphenyls (PCBs) 30
5.05 Indications of Solid Waste Disposal 30
5.06 Other Conditions or Concerns 30
6.0 BUSINESS ENVIRONMENTAL RISK CONSIDERATIONS 31
6.01 Environmental Regulatory Compliance 31
6.02 Asbestos Containing Materials 31
6.03 Lead Based Paint 31
6.04 On-Site Radon 31
6.05 Vapor Encroachment 32
6.06 Indoor Air Quality 32
6.07 Lead in Drinking Water 32
6.08 High Voltage Power Lines 32
6.09 Cultural, Historic and Archeological Resources 32
6.10 Wetlands and Surface Waters 32
6.11 Threatened, Endangered and Other Protected Species 32
6.12 Wildlife Sanctuaries and Other Natural Resource Preserves 32
6.13 Biological Agents 32
6.14 Mold 33

TABLE OF CONTENTS (Continued)

SECTION **PAGE**

6.15 Potential Impacts/Implications of Environmental Issues for Site Development and Construction 33

7.0 PHASE I ESA FINDINGS AND OPINION 33

7.01 Findings 33

7.02 Opinion 34

7.03 Recommendations 34

7.04 Statement of Reliance 34

7.05 Significant Data Gaps 35

8.0 SIGNATURES 35

9.0 QUALIFICATIONS 35

TABLES

Table 1: Reviewed Environmental Database Records 7

Table 2: Identified Off-Site Environmental Listings 8

Table 3: City Directory Listings for the Subject Property 29

FIGURES

Figure 1: Property Location Map

Figure 2: Site Boundary Map

PHOTOGRAPHS

Photographs from the August 4, 2015 site reconnaissance visit.

APPENDICES

Appendix A: Site Forms

Appendix B: EDR Database Report

Appendix C: FOIL Requests/FOIL Responses

Appendix D: Topographic Maps

Appendix E: Historic Sanborn® Map Report

Appendix F: Historic Aerial Photographs

Appendix G: City Directory Image Report

Appendix H: NYSDEC Environmental Resource Map

Appendix I: FEMA Flood Insurance Rate Map

1.0 INTRODUCTION

1.01 *Purpose*

The purpose of this Phase I Environmental Site Assessment (Phase I ESA) report is to document the investigative activities conducted to identify Recognized Environmental Conditions (RECs) at the subject property identified as the Former Rome-Turney Radiator Company, 109 Canal Street in the City of Rome, Oneida County, New York 13440 (the subject property). This Phase I ESA was conducted as part of an evaluation for the sale of the building at the subject property. The general location of the subject property is shown on Figure 1 - Property Location Map.

This Phase I ESA was conducted in accordance with ASTM Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process E-1527-13, published November 2013, and was conducted in accordance with the U.S. Environmental Protection Agency (EPA) All Appropriate Inquiry (AAI).

1.02 *Intended Use*

This Phase I ESA was conducted by Bergmann Associates (Bergmann) for use by the City of Rome and their financial institution(s) as part of the sale of the building at the subject property. Bergmann acknowledges that this report may be conveyed to and relied upon by the City of Rome, its successors, assigns or financial investors.

1.03 *Objectives*

The primary objective of this Phase I ESA is to identify and document RECs at the subject property, in accordance with the ASTM standard. The scope of this Phase I ESA consisted of:

- Review of readily available public records, historic aerial photographs, city directories, and maps.
- Site reconnaissance of the subject property.
- Interviews with property owner-representatives, government agencies and review of existing environmental reports and documents.
- Completion of this Phase I ESA report.

1.04 *Limiting Conditions and Deviations*

As part of the Phase I ESA, Bergmann personnel conducted a site reconnaissance and walk-over of the subject property on Tuesday, August 4, 2015. Bergmann's site observation form and interview form are available in Appendix A –Site Forms. An environmental interview was conducted with Mr. Dennis Gillen, representative of the City of Rome.

Limiting Conditions

Portions of the ground surface in the courtyard and building contents could not be viewed, as noted below.

Vegetative and Debris Cover

During the site reconnaissance, portions of the exterior courtyard were covered in vegetation and debris. Bergmann's inability to view the ground surface in its entirety is considered a limiting condition to this Phase I ESA.

Building Collapse

During the site reconnaissance, building debris from a roof collapse was located in the southwest corner of the building footprint. Bergmann's inability to view the building contents in their entirety is considered a limiting condition to this Phase I ESA.

Limited View of Floor Surface

During the site reconnaissance, piles of building materials, paperwork, clothing and other miscellaneous materials prevented the observation of floor surfaces in the rear maintenance area and rooms in the central and eastern portions of the building. Bergmann's inability to view the interior floor surface in its entirety is considered a limiting condition to this Phase I ESA.

Relationship of the Purchase Price to the Value of the Property

Bergmann was not provided with the purchase price of the subject property or with information relative to the value of the property, assuming the property is not contaminated. Tax information obtained from www.LandMaxData.com on August 5, 2015 lists the Assessor Full Market Value of the subject property as approximately $111,000. This Phase I ESA assumes that the user/prospective property owner will consider the relationship of the purchase price relative to the fair market value of the property and consider whether or not the difference in purchase price and fair market value is due to the presence of releases or threatened releases of hazardous substances.

2.0 SITE DESCRIPTION

2.01 *Location and Description*

The subject property for this Phase I ESA consists of one vacant former industrial building with associated paved driveway and courtyard. The general location of the subject property is shown on Figure 1 – Property Location Map. The subject property is an irregular-shaped lot measuring approximately 1.5 acres and defined as tax parcel number 242.066-0001-001.0000000. The subject property is bounded to the north by railroad tracks, to the south by a vacant parcel of land, to the east by Erie Boulevard, across which is a hotel and to the west by Canal Street, across which are residential buildings.

A map showing the subject property boundary is included as Figure 2 – Site Boundary Map.

2.02 *Site Vicinity and Characteristics*

The subject property is situated in a mixed use area in the City of Rome, New York. Photographs of the subject property are provided in the Photographs Section of this report.

2.03 *Current Uses of the Property*

The subject property consists of one vacant former manufacturing building with a driveway, courtyard and a small yard along the east side of the building.

2.04 *Description of Current Structures, Roads and Improvements*

Structures

At the time of the August 4, 2015 site visit, the subject property contained one vacant former manufacturing and warehouse building.

The building was divided into multiple areas described below and referenced on Figure 3 – Building Plan.

Receiving & Shipping Area

The receiving & shipping area contained an overhead five-ton Robbins & Myers hoist spanning the ceiling, a large pile of debris including paper, cardboard, plastic, oil cans, rolled vinyl sheeting, wood pallets, metal, cloth and miscellaneous garbage, overturned furniture, welding supplies and an overturned box of small electrical components. The floor in this area was stained in places.

Warehouse

The warehouse section of the building was partially collapsed during the site reconnaissance and according to neighborhood residents, the collapse occurred approximately three years ago. The debris in this area of the warehouse included roofing material, wood, concrete block, metal, electrical wiring, lighting fixtures, clothing, stuffed animals, boxes, papers and other miscellaneous debris. A six-inch metal pipe with suspected asbestos containing material (ACM) coating was located in the southernmost corner of this area. The remainder of the warehouse contained papers, small cans of varnish, an empty cardboard drum formerly containing welding electrodes rods and fluxes, a can of enamel and a cardboard box of miscellaneous paper and cardboard material. In the northernmost corner of the warehouse, staining was visible and piping remnants indicated a former process area, the floor in this area was stained. A four-inch metal pipe and cloth wiring in the wall of this corner appeared suspect for ACM. Windows were visible along the south and east walls, the glazing and caulking on the windows appeared suspect for ACM.

Eastern Production Shop

Two production shops were located in the central portion of the building. The eastern production shop in the central portion of the building contained a trench which ran across the length of the eastern wall and led to a 2' x 6' pit in the southeast corner. Another pit was observed in this area, measuring 4'x10' which contained bricks. A 2" pipe was attached to the wall and ran across the length of the eastern wall, above the trench. The floor in this area was stained and cracked in areas. A white 55-gallon drum labeled as Hetron® 922 Resin was located in the southeast corner, adjacent to a concrete stage. The floor in this corner was stained. Floor spalling was observed along the western wall of this area. In the northern section of the production shop was an area with metal tiling measuring 9 x 15 tiles. A fire door was located just north of this tiling. The eastern production shop also contained glazed windows with caulking.

Western Production Shop

The western production shop contained miscellaneous paper and ceiling, wall and skylight insulation debris from the destruction of partition walls by vandals, a 3' x 9' floor trench and two 8" floor drains. The floor in this area was stained in places and mold growth was visible on floor and wall surfaces and on debris throughout the area. A garage door along the western wall appeared damaged by vandals. A small piece of transite board was located to the west of a partition wall. Transite is suspected to contain ACM. Additional transite board was not observed within the building. Skylights in this portion of the building were broken and the glass was strewn across the floor surface. A block walled room was located in the northwest corner of the western production shop. This area contained general debris; however, the room is labeled as a hazardous materials storage room on a site plan provided in the Site Investigation Report discussed in Section 3.05 of this report.

Shop Foreman Office/Locker Rooms

The shop foreman office area in the northeast portion of the building contained a small kitchenette and divided office spaces. Wood and building material debris was scattered throughout this area, some of which was covered in moss and mold, and fluorescent light bulbs and ballasts were broken on the ground surface in the office area. A locker room was located east of the foreman office area. Building debris was scattered on the floor throughout this area, ceiling tiles in this area were missing, and exposed piping and wiring was visible above metal tile framing.

Production Area

The production area in the northeast corner of the subject property building contained a metal shelving unit and a loveseat. The wood ceiling in this area was in poor condition and was weathered, stained and pitted and the paint on the walls in the area was peeling away from the concrete block walls which were also weathered and pitted. A two-foot by four-foot pit and a six-foot by three-foot steel-lined pit were located in the northern portion of the production area and were filled with water.

Machine Room

The machine room in the northern portion of the subject property contained a large debris pile containing cardboard, paper, plastic and rolls of vinyl sheeting or flooring. A 55-gallon drum of UN 1866 Resin Solution which appeared empty was located in the western portion of the room, next to a sofa. A debris pile was located west of the sofa which contained four 5-gallon carboys of cooking grease, a tire, cardboard and cloth. An elevator shaft with fire doors was located along the southern wall, and a floor pit which was covered by a wood board was located in front of the elevator shaft. The machine room also contained glazed windows with caulking.

Office

An office was located in the northwest corner of the subject property. The office contained cardboard boxes of paperwork, abandoned furniture, three 15-gallon carboys of unknown contents and miscellaneous debris. A four-foot by six-foot floor pit was located in the central portion of the office area. The northern portion of the office contained six glazed windows. The southern portion of the office contained personal items from the previous owner, including photographs, paintings, textbooks, magazines, television sets, clothing, sports equipment and other household items.

Second Floor – Above Office

The second floor office area was filled with debris, including paperwork, clothing, office supplies, books, furniture, boxes, packing materials, insulation, ceiling tiles, fluorescent light bulbs and ballasts, metal framing, a 5-gallon pail of Astro-Draw 2001-A drawing oil, a black plastic 55-gallon drum of unknown contents and household and office items. Vermiculite was noted in the office area on the floor and in the ceiling. Vermiculite is typically positive for ACM. Several holes were observed in the outer walls of the second floor office area.

Second Floor – Plan Room

The second floor plan room contained wood molds and tables and paper plans. An elevator shaft with fire doors was located off the south wall of this room.

Second Floor – Above Eastern Production Room

The room above the eastern production room on the second floor contained household debris including a crib, clothing, laundry baskets, papers, chair cushions and toys. This area formerly contained a flat belt system, and remnants of the system were visible on the ceiling and support beams. A fiberglass vat measuring approximately 3’ x 11’ was overturned in the center of the room. The room also contained glazed windows with caulking.

Third Floor – Above Plan Room

Above the plan room was a third floor area containing general household debris and glazed windows with caulking. A pile of spent aerosol cans was located near the stairs on the eastern side of the room. A roof access door and an elevator shaft with fire doors were located on the south side of the room.

Due to the age of the construction and items observed during the site reconnaissance, ACM is suspected within the building at the subject property. Suspect ACM within items at the subject property is considered a business environmental risk (BER).

Due to the age of the construction and items observed during the site reconnaissance, lead based paint (LBP) is suspected for painted surfaces within the building at the subject property. LBP on surfaces at the subject property is considered a BER.

The material threat of release of petroleum and/or other hazardous materials associated with historic industrial and manufacturing operations to the subsurface at the subject property is considered a REC.

The material threat of release of petroleum and/or other hazardous materials stored at the subject property to the subsurface at the subject property is considered a REC.

Photographs were collected during the site visit and are included in the Photographs Section of this report.

Parking and Access Roads

At the time of the August 4, 2015 site visit, access to the subject property was provided by Canal Street. Two driveways were located along the western edge of the subject property, leading to a courtyard area.

Grass or Undeveloped Areas

At the time of the August 4, 2015 site visit, the subject property included a small grassy area on the eastern side of the building.

2.05 *Past Uses of the Property*

The subject property formerly operated as the Rome-Turney Radiator Company – a manufacturer of radiators from 1905 until the early 1990s when the company went out of business. From 1992 through 1995, the property was operated by Lynch Realty, The Music Factory (an internet search indicated that this was an asphalt company), Rome-Turney Radiator Co. and Serway Brothers Inc. – Plastic Laminating Division (an internet search indicated that this was a cabinet making company). From 1999 through 2003, the property was operated by The Music Factory and the Rome-Turney Radiator Company. In 2008, the property was operated by Elegrace Casket, Inc. (an internet search indicated that this was a casket making company), Rofin LLC (an internet search indicated that this was a global supplier of industrial coolers who purchased all assets of Rome-Turney Radiator Company) and the Rome-Turney Radiator Company. In 2013, the property was operated by The Music Factory.

The material threat of release of petroleum and/or other hazardous materials associated with historic industrial and manufacturing operations to the subsurface at the subject property is considered a REC.

2.06 *Current and Past Uses of Adjoining Properties*

North of the Subject Property

At the time of the site visit, a railroad, a pump house and a drug store bordered the subject property to the north.

East of the Subject Property

At the time of the site visit, Erie Boulevard bordered the subject property to the east, beyond which was a hotel.

South of the Subject Property

At the time of the site visit, a vacant lot and residential buildings bordered the subject property to the south.

West of the Subject Property

At the time of the site visit, an industrial property bordered the subject property to the west.

3.0 ENVIRONMENTAL RECORDS REVIEW

3.01 *Standard Environmental Record Sources, Federal, State and County*

Regulatory database searches were conducted for the subject property as part of the scope of this Phase I ESA. The regulatory database search was conducted for Bergmann by Environmental Data Resources Inc. (EDR), a nationally recognized database search service.

The regulatory databases searched include the following:

- EDR report dated July 28, 2015.
- Review of the USEPA web-based Envirofacts Database August 2014.
- Review of the NYSDEC web-based Environmental Databases August 2014.

The database searches were conducted at or beyond the radii established by the Federal All Appropriate Inquiry (AAI) Rule and/or ASTM E 1527-13, which ever was greater, for the subject property. The EDR database reviewed by Bergmann for this Phase I ESA is included in Appendix B - EDR Database Search Report.

A summary of the major environmental databases searched by EDR is provided in Table 1 located below. The dates of the environmental databases were the most recent releases as of the July 28, 2015 EDR environmental database review. These reviews were supplemented with a search using the Federal USEPA Envirofacts web-based databases, the NYSDEC web-based PBS/CBS/MOSF registries and the NYSDEC Spills Event web-based database and the findings are summarized below.

3.02 *Environmental Listings for the Subject Property*

The subject property was listed on the following databases searched by EDR and reviewed by Bergmann:

- The subject property is listed on the New York State Department of Environmental Conservation (NYSDEC) Leaking Tanks (LTANKS) database as Rome-Turney Radiator under Program Number 8802056. On June 6, 1988, two 5,000 gallon underground storage tanks (USTs) containing #2 fuel oil at the subject property failed a tightness test. Free floating product was observed on groundwater near the tanks. The tanks were removed on July 21, 1988 and a monitoring well was installed. On April 11, 1989, contaminated soil was removed from the subject property. Soil disposal records were received by the NYSDEC representative on August 31, 1990. An investigation at the subject property was never completed. The spill remains open.
- The subject property is listed on the United States Environmental Protection Agency (US EPA) FINDS database as Elegrace Casket Company Inc under Registry ID 110019481880 as an environmental reporting facility.
- The subject property is listed on the Petroleum Bulk Storage (PBS) database under number 6-389331. The subject property formerly contained two 5,000 gallon USTs containing #2 fuel oil which were removed prior to 1991.

The potential presence of remaining soil and groundwater contamination at the subject property from a historic spill which was not closed is considered a REC.

The material threat of release of petroleum and/or other hazardous materials associated with historic industrial and manufacturing operations to the subsurface at the subject property is considered a REC.

The environmental database review did not locate other listings in the regulatory database searches conducted for the subject property as part of the scope of this Phase I ESA. A review of un-mapped/orphan sites did not indicate an un-mapped listing of the subject property. The subject property was not identified as a Federal or State NPL or Inactive Hazardous Waste Disposal Site, active landfill or solid waste disposal site. The subject property was not identified as located on a Native American Indian reservation or on tribal administered lands.

Table 1
Reviewed Environmental Database Records

Source Reviewed	Agency[1]	ASTM Minimum Search Distance	Recent Date of Record Update[2]
Federal NPL List	US EPA	1.25 miles	03/26/2015
Federal Proposed NPL	US EPA	1.25 miles	03/26/2015
Federal De-listed NPL List	US EPA	1.25 miles	03/26/2015
Federal CERCLIS List	US EPA	0.75 miles	10/25/2013
Federal CERCLIS-NFRAP List	US EPA	0.75 miles	10/25/2013
Federal RCRA CORRACTS List	US EPA	1.25 miles	03/10/2015
Federal RCRA TSDF List	US EPA	0.75 miles	03/10/2015
Federal RCRA Generators List	US EPA	0.5 miles	03/10/2015
Federal ERNS List	US EPA	0.25 miles	03/30/2015
CERCLA Lien	US EPA	0.25 miles	02/18/2014
State/Tribal List of Inactive Hazardous Waste Sites	NYSDEC	0.5 miles	06/26/2015
State/Tribal List of Solid Waste Facilities	NYSDEC	0.75 miles	06/24/2015
State/Tribal Registry of Petroleum & Chemical Bulk Storage Facilities	NYSDEC	0.5 miles	06/24/2015
State/Tribal LTANKS Registry	NYSDEC	0.75 miles	05/18/2015
State Spills Inventory	NYSDEC	0.75 miles	05/18/2015
State/Tribal VCP Sites	NYSDEC	0.75 miles	06/26/2015
State/Tribal Brownfield Sites	NYSDEC	0.75 miles	06/26/2015

1. US EPA – United States Environmental Protection Agency
   NYSDEC – New York State Department of Environmental Conservation
2 Record updates are based on the database records reported in the Environmental Database Search conducted on July 28, 2015. The referenced dates are the most recent government releases as of the July 2015 database review.

3.03 *Identified Off-Site Environmental Listings*

The environmental database identified off-site listings that are not located on the subject property but which lie within 1 mile of the subject property which may present recognized environmental concerns to the subject property. The properties identified in the table below are within 1 mile of the subject property. The properties in bold are portions of the subject property or adjoining properties.

Table 2
Identified Off-Site Environmental Listings

Site	Address	Database	Location & Report Information Summary
Behind Walgreens/ New Walgreens Construction	*201 South James Street Rome, NY*	*NY SPILLS*	*0-⅛-mile NNW – Adjoining the subject property* *NY SPILLS: 1206069 and 1206074 (duplicate spill)* *On 9/19/2012, a blown line on a garbage truck spilled two gallons of hydraulic oil at the site. The spill was closed on 9/19/2012 meeting NYSDEC Cleanup Standards.* *NY SPILLS: 0702658* *On 6/4/2007, a UST was discovered while excavation occurred at the site. The spill corresponds to Spill Number 0600485 at 102-104 Front Street, Rome, NY.*
		BCP	*BCP: 356404* *This BCP Application was for remediation of the property to allow for development of a new Walgreens Drug Store. The BCP application was denied in 2006 because the current owner was already addressing the site in the NYSDEC Spill Program.*
A Plus Facility #60003 Sunoco #0363-2254	*131 South James Street Rome, NY*	*LTANKS*	*0-⅛-mile N – Adjoining the subject property* *LTANKS: 0200885* *On 4/23/2002, a tank at the site failed a tightness test. The spill was closed on 5/28/2002 meeting NYSDEC Cleanup Standards.* *LTANKS: 8702667* *On 7/2/1987, a tank failed a tightness test at the site. The tank was repaired and passed a second test. The spill was closed on 3/20/1990 meeting NYSDEC Standards.*
		UST *HIST UST*	*UST/HIST UST: 6-065633* *The site formerly contained three 12,000 gallon USTs, one 6,000 gallon UST and three 4,000 gallon USTs containing gasoline are listed as closed-removed.*
		NY SPILLS	*NY SPILLS: 8402303* *On 11/27/1984, contamination was discovered at the site. A remediation occurred at the site over the course of approximately 25 years. The spill was closed on 7/10/2008 not meeting NYSDEC Standards.*
Vacant Warehouse	*102-104 Front Street Rome, NY*	*NY SPILLS*	*0-⅛-mile NNW – Adjoining the subject property* *NY SPILLS: 0600485* *On 4/12/2006, contaminated soil was encountered during an excavation. An investigation revealed multiple buried USTs and contaminated soils. The spill was closed on 8/1/2007 not meeting NYSDEC Cleanup Standards.*
		UST	*UST: 6-601127* *The facility formerly contained one 1,000 gallon UST containing #2 fuel oil and one 2,000 gallon UST containing diesel, one 275 gallon UST containing #2 fuel oil and two 550 gallon USTs containing #2 fuel oil which are listed as closed-removed.*
AM/PM Mini Mart	*South James & Erie Boulevard Rome, NY*	*LTANKS*	*0-⅛-mile N – Adjoining the subject property* *LTANKS: 8500741* *On 5/24/1985, a tank failed a tightness test at the site. The spill was closed on 5/28/1985 meeting NYSDEC Cleanup Standards.*
		NY SPILLS	*NY SPILLS: 8500642* *On 5/22/1985, a dry chemical fire occurred at the on-site gasoline station. The spill was closed on 5/22/1985 meeting NYSDEC Cleanup Standards.*

Site	Address	Database	Location & Report Information Summary
JA Car Wash	***229 South James Street Rome, NY***	***RCRA NonGen/NLR***	***0-⅛-mile WNW – Adjoining the subject property RCRA NonGen/NLR: NYD987032406 The facility is a handler of hazardous waste. Wastes include benzene and ignitable waste. No violations are listed.***
		FINDS	***FINDS: 110004503635***
		NY ERP	***ERP: 59168 Residual petroleum contamination remains at this site from a former spill that was closed not meeting NYSDEC Cleanup Standards.***
		LTANKS	***LTANKS: 9109197 On 11/27/1991, a tank failed a tightness test at the site. Contaminated soil and groundwater was discovered at the site, and a remedial action was initiated. The spill was closed on 10/22/2004 not meeting NYSDEC Cleanup Standards.***
		UST HIST UST	***UST/HIST-UST: 6-140848 The facility formerly contained three 4,000 gallon USTs containing gasoline and four 2,000 gallon USTs containing gasoline are listed as closed-removed.***
Bouton Physical Therapy	221 South James Street Rome, NY	LTANKS	0-⅛-mile WNW LTANKS: 0409032 On 11/16/2004, a tank and contaminated soil was discovered during an excavation at the site. Contaminated soil was removed and disposed. The spill was closed on 6/15/2006 meeting NYSDEC Cleanup Standards.
Travel Inn	145 East Whitesboro Street Rome, NY	LTANKS	0-⅛-mile ESE LTANKS: 0508864 On 10/25/2005, contaminated soil was discovered during a tank removal. Contaminated soil was removed from the site, except for in inaccessible areas. The spill was closed on 11/30/2005 not meeting NYSDEC Cleanup Standards.
Revere Printing, Inc.	100 Bouck Street Rome, NY	RCRA-CESQG MANIFEST	0-⅛-mile SE RCRA-CESQG/MANIFEST ID: NYD987017233 The facility is a CESQG, a generator and transporter of ignitable hazardous waste. The facility was formerly a SQG. No violations are listed.
		UST HIST UST	UST/HIST UST: 6-600750 The facility formerly contained one 6,000 gallon UST containing kerosene, one 2,000 gallon UST containing fuel oil and one 500 gallon UST containing an unknown material which are listed as closed-removed.
		NY SPILLS	NY SPILLS: 9804875 On 7/20/1998, an unknown amount of #2 fuel oil was spilled at the facility. The tank was scheduled to be removed and contaminated soil was scheduled to be stockpiled. The spill was closed on 11/6/1998 not meeting NYSDEC Cleanup Standards.
		FINDS	FINDS: 110004495804
Rome Electronics, Inc.	216 Erie Boulevard Rome, NY	UST HIST UST	0-⅛-mile SE UST/HIST UST: 6-600595 The facility formerly contained one 3,000 gallon UST containing #2 fuel oil. The tank is listed as closed-removed.

Site	Address	Database	Location & Report Information Summary
U Haul	244 Erie Boulevard East Rome, NY	UST HIST UST NY SPILLS	0-⅛-mile SE UST/HIST UST: 6-022985 The facility contains one 1,000 gallon UST containing #2 fuel oil which is listed as in-service. The facility formerly contained two 6,000 gallon USTs containing gasoline which are listed as closed-removed. NY SPILLS: 9210138 On 11/24/1992, contaminated soil was discovered surrounding removed USTs. Contaminated soil and old tanks were removed from the site. The spill was closed on 12/18/2006 meeting NYSDEC Cleanup Standards.
Rome Agway Coop Inc.	300 West Street Rome, NY	UST HIST UST AST HIST AST	0-⅛-mile W UST/HIST UST: 6-129526 The facility formerly contained one 1,000 gallon UST containing diesel. The tank is listed as closed prior to micro conversion, 3/1991. AST/HIST AST: 6-129526 The facility formerly contained one 275-gallon AST containing #2 fuel oil. The tank is listed as closed prior to micro conversion, 3/1991.
Norstar Bank Upstate New York	Rome Trust Office Rome, NY	UST HIST UST	0-⅛-mile NNW UST/HIST UST: 6-600067 The facility formerly contained one 1,000 gallon UST containing #2 fuel oil. The tank is listed as closed-in place.
Rome Fire Department	200 South James Park Rome, NY	NY SPILLS	0-⅛-mile NW NY SPILLS: 8904741 On 8/12/1989, a fuel tank ruptured on a passenger vehicle and spilled one gallon of gasoline into a nearby sewer. The spill was closed on 8/12/1989 meeting NYSDEC Cleanup Standards.
Valvoline Quick Change	176 Black Rover Boulevard Rome, NY	NY SPILLS	0-⅛-mile ENE NY SPILLS: 9012064 On 2/19/1991, 50 gallons of non-polychlorinated biphenyl (PCB) oil leaked out of the on-site building and entered the sewer. The spill was closed on 12/12/1995 meeting NYSDEC Cleanup Standards.
Meth Lab Disposal Site	Railroad Street and Bouck Street Rome, NY	NY SPILLS	0-⅛-mile E NY SPILLS: 1205822 On 9/11/2012, a meth lab was found in a field near the intersection of Railroad and Bouck Streets. The spill was closed on 11/14/2012 meeting NYSDEC Cleanup Standards.
Kemp Truck Repair	Canal Street Rome, NY	NY SPILLS	0-⅛-mile SSE NY SPILLS: 9900354 On 4/9/1999, a former employee of Kemp Oil stated that he was aware of the company allowing the dumping of petroleum products from the tank trucks inside the garage and then deliberately pumping it outside. He stated that the ground behind the garage is all black. A garden hose was observed pumping from a sump at the site to the rear yard. The property owner is now deceased and the property is owned by other parties. The spill was closed on 6/8/2005 not meeting NYSDEC Cleanup Standards.
Arco Petroleum Products	South James and Erie Rome, NY	RCRA Non-Gen/NLR MANIFEST	0-⅛-mile NNE RCRA Non-Gen/NLR/MANIFEST: NYD982716458 The facility is a handler and transporter of ignitable hazardous waste. The facility was formerly a SQG. No violations are listed.
R&S Steel, LLC	412 Canal Street Rome, NY	RCRA-SQG MANIFEST	⅛-¼-mile SSE RCRA-SQG/MANIFEST ID: NYR000110981 The facility is a small quantity generator (SQG), a generator and transporter of hazardous waste. Wastes include ignitable waste and spent non-halogenated solvents. The facility was formerly a conditionally exempt small quantity generator (CESQG). No violations are listed for the facility.

Site	Address	Database	Location & Report Information Summary
Kemp Oil Site	250 Erie Street Rome, NY	NY LTANKS	⅛-¼ -mile WSW NY LTANKS No. 9907653 On 9/24/1999, a UST at the site leaked gasoline to the subsurface. The spill was closed on 9/24/1999 not meeting NYSDEC Cleanup Standards.
		UST	UST: 6-131172 The facility formerly contained two 1,000 gallon USTs containing unlisted materials which are listed as closed-removed.
		AST	AST: 6-131172 The facility formerly contained one 20,000 gallon AST, three 15,000 gallon ASTs, two 500 gallon ASTs and two 300 gallon ASTs containing an unlisted material which are listed as closed-removed.
		NY SPILLS	NY SPILLS: 9907630 On 9/23/1999, seven tanks were removed from the site, one overturned and spilled an unknown amount of petroleum at the site. Free product was observed coming from the west wall of the excavation. The NYSDEC sent a letter requiring a site assessment. The spill remains open. NY SPILLS: 9410572 On 11/8/1994, one gallon of gasoline spilled onto a wood surface at the site. The spill was closed on 6/4/1996 meeting NYSDEC Cleanup Standards.
NIMO, Rome	Kingsley Avenue Rome, NY	NY HSWDS	⅛-¼-mile ESE EPA ID: NYD980664221 The facility is listed as a Coal Gasification Plant.
		EDR MGP	The facility is a former Manufactured Gas Plant (MGP). Groundwater at the site is contaminated by MGP wastes.
		SHWS	SHWS: 56266 The facility is a hazardous waste site, classified as a significant threat to the public health or environment – action required.
		NY SPILLS	NY SPILLS: 0304087 On 7/18/2003, contaminated soil and groundwater were discovered during an excavation at the site. Soil and groundwater were removed from the site. The spill was closed on 11/5/2003 not meeting NYSDEC Cleanup Standards. NY SPILLS: 9807928 On 9/28/1998, 7 gallons of hydraulic oil was spilled at the site. The spill was cleaned up and closed on 9/29/1998 meeting NYSDEC Cleanup Standards.
Rome Fire Department	168 Black River Boulevard Rome, NY	LTANKS	⅛-¼-mile NNE LTANKS: 9400388 On 4/8/1994, 120 gallons of gasoline spilled at the site. The tank and contaminated soil were removed from the site. The spill was closed on 4/12/1994 meeting NYSDEC Cleanup Standards. LTANKS: 8702034 On 6/10/1987, a tank failed a tightness test at the site. The tank could not be removed due to nearby utilities. The tank was closed in place and the spill was closed on 4/29/1991 meeting NYSDEC Cleanup Standards. LTANKS: 9309113 On 10/20/1993, contaminated soil was discovered during a tank removal. Two 3,000 gallon tanks were moved and holes were observed in the bottom of both tanks. The spill was closed on 6/15/1994 meeting NYSDEC Cleanup Standards.

Site	Address	Database	Location & Report Information Summary
Rome Bulk Material	Liberty Plaza Rome, NY	SWF/LF	⅛-¼-mile NW SWF/LF: The facility is an inactive transfer station.
Agway	312 South James Street Rome, NY	LTANKS	⅛-¼-mile WSW LTANKS: 8605923 On 12/17/1986, tanks were excavated from the site and holes were observed in the bottom of the tanks. A sheen was observed on water in the excavation. Contaminated soil was removed from the site and disposed. The spill was closed on 12/11/1989 meeting NYSDEC Cleanup Standards.
		UST HIST UST	UST/HIST UST: 6-600881 The facility formerly contained one 500 gallon UST containing used oil and one 3,000 gallon UST containing leaded gasoline which are listed as closed-removed.
		NY SPILLS	NY SPILLS: 9104791 On 8/2/1991, a black stain was observed on the floor surface of the building. The spill was closed on 8/2/1991 meeting NYSDEC Cleanup Standards.
		RCRA NonGen/NLR MANIFEST	RCRA NonGen/NLR/MANIFEST: NYD099892150 The facility is a handler and transporter of hazardous waste. The facility was formerly a SQG. No violations are listed.
		FINDS	FINDS: 110009469315
Transfiguration Church	111 Ridge Road Rome, NY	LTANKS	⅛-¼-mile WSW LTANKS: 8601754 On 6/13/1986, an unknown amount of #2 fuel oil was spilled at the site. The spill was closed on 6/21/1986 meeting NYSDEC Cleanup Standards.
		UST	UST: 6-021873 The facility formerly contained one 8,000 gallon UST containing #2 fuel oil which is listed as closed prior to micro conversion 3/1991. The facility formerly contained two 1,000 gallon USTs containing #2 fuel oil which are listed as converted to non-regulated use.
Rome Animal Control Unit	112 West Liberty Street Rome, NY	LTANKS	⅛-¼-mile NNE LTANKS: 0507336 On 9/19/2005, a tank at the site was overfilled. The spill was cleaned up and closed on 9/19/2005 meeting NYSDEC Cleanup Standards.
Tamburino Facility	230 Ridge Street Rome, NY	UST HIST UST	⅛-¼-mile W UST/HIST UST: 6-600380 The facility formerly contained one 550 gallon UST containing waste oil/used oil which is listed as closed-in place, one 1,000 gallon UST, one 2,000 gallon UST and one 3,000 gallon UST containing gasoline which area listed as closed-removed.
Rome Iron Group, Ltd.	412 Canal Street Rome, NY	UST	⅛-¼-mile SSE UST: 6-432814 The facility formerly contained one 1,000 gallon UST containing gasoline, one 1,000 gallon UST containing diesel and one 1,000 gallon UST containing #2 fuel oil which are listed as closed-removed. The facility also formerly contained one 2,000 gallon UST containing gasoline which is listed as closed-in place.
		RCRA NonGen/NLR MANIFEST	RCRA NonGen/NLR/MANIFEST: NYD987029121 The facility is a handler and transporter of hazardous waste. Wastes include spent nonhalogenated solvents and ignitable wastes. The facility was formerly a SQG. The facility has two listed violations.
		FINDS	FINDS: 110004501502

Site	Address	Database	Location & Report Information Summary
Proline Automotive	416 Canal Street Rome, NY	EDR Historical Auto Stations	⅛-¼-mile SSE The facility is listed as a historical auto repair station in 2002.
Dutch's Body Shop	319 West Street Rome, NY	EDR Historical Auto Stations	⅛-¼-mile W The facility is listed as a historical auto repair station in 2008.
Proline Automotive	428 Canal Street Rome, NY	EDR Historical Auto Stations	⅛-¼-mile SSE The facility is listed as a historical auto repair station from 2003 through 2010.
Nolan & Adolfi Hayes	Liberty Street Rome City Hall Rome, NY	LTANKS	⅛-¼ -mile N LTANKS: 8600647 On 4/28/1986, 25 gallons of #2 fuel oil was spilled at the site. Contaminated soil was removed and storm drains and catch basins were cleaned. The spill was closed on 6/21/1986 meeting NYSDEC Cleanup Standards.
NYSDOT Bridge	Whitesboro Street Rome, NY	UST HIST UST	⅛-¼-mile SSE UST/HIST UST: 6-600652 The facility formerly contained two 1,000 gallon USTs containing gasoline and one 1,000 gallon UST containing kerosene which are listed as closed-removed.
Plaza Restaurant	229 East Dominick Street Rome, NY	NY LTANKS	⅛-¼ -mile E NY LTANKS No. 9605346 On 7/25/1996, a leaking UST was discovered during a street repair. The spill was closed on 8/28/1996 meeting NYSDEC Cleanup Standards.
Sears Oil, Inc.	7064 Lado Drive Rome, NY	NY LTANKS NY SPILLS RCRA-CESQG NY MANIFEST FINDS	⅛-¼ -mile E NY LTANKS No. 9002211 On 5/25/1990, a tank was overfilled at the site and one gallon of #2 fuel oil was spilled. Absorbent pads were used, and the spill was closed on 5/25/1990 meeting NYSDEC Cleanup Standards. NY SPILLS No. 8904665 On 8/10/1989, a gas pump at the site leaked an unknown amount of diesel at the site. The spill was closed on 8/22/1990 meeting NYSDEC Cleanup Standards. EPA ID: NYD981182579 The facility is a handler and transporter of hazardous waste. No violations are listed for the facility. Materials listed are non-listed ignitable wastes. FINDS ID: 110004402290
Rome City Hall	198 North Washington Street Rome, NY	UST	⅛-¼-mile NNW UST: 6-433535 The facility formerly contained one 6,000 gallon UST containing #2 fuel oil. The tank is listed as closed-removed. The facility formerly contained a second 6,000 gallon UST containing #2 fuel oil. This tank is listed as closed prior to micro conversion, 3/1991.
Former General Cable Facility	Mill Street/Harbor Way Rome, NY	CERCLIS NY SPILLS US BROWNFIELDS	¼-½-mile ESE EPA ID: NY0001119403 National Priorities List (NPL) No Further Remedial Action Planned (NFRAP) listing: site does not qualify for the NPL based on a preliminary assessment. NY SPILLS No. 9704748 On 7/2/1997, unauthorized scavenging of building equipment from the building caused a spill of approximately four ounces of mercury in the building. The spill was closed on 11/9/2000 meeting NYSDEC Cleanup Standards. NY SPILLS No. 1303334 On 6/27/2013, a four-inch fuel oil supply line was encountered during excavation. Approximately 1,300 tons of contaminated soil was sent off site for disposal. The spill was closed on 11/25/2013 meeting NYSDEC Cleanup Standards. US BROWNFIELDS: The site underwent a Phase I ESA through the US EPA Brownfield program.



Site	Address	Database	Location & Report Information Summary
Rome City Hall	Liberty Street Rome, NY	LTANKS	¼-½-mile N LTANKS: 8702026 On 6/10/1987, a tank failed a tightness test at the site. The tank was excavated and retested. Soil surrounding the tank was removed and disposed. The spill was closed on 9/29/1987 meeting NYSDEC Cleanup Standards.
Verizon New York, Inc.	137 North Washington Street Rome, NY	LTANKS TANKS	¼-½-mile N LTANKS: 8702204 On 6/17/1987, a 6,000 gallon tank failed a tightness test. The tank and surrounding soil was removed from the site. The spill was closed on 2/23/1990 meeting NYSDEC Cleanup Standards. TANKS: 6-414565 The facility is listed as an active PBS site. The registration of the site expires on 6/30/2017. No further information is available.
City of Rome Police Department	301 North James Street Rome, NY	LTANKS	¼-½-mile NNE LTANKS: 9410599 On 11/8/1994, a 5,000 gallon tank was removed from the site. Contaminated soil was encountered and numerous holes were observed in the bottom of the tank. The spill was closed on 9/11/1997 meeting NYSDEC Cleanup Standards. LTANKS: 9905328 On 8/3/1999, a 550 gallon tank was removed from the site and contaminated soil was discovered. The spill was closed on 10/21/1999 not meeting NYSDEC Cleanup Standards. LTANKS: 8705018 On 9/15/1987, a 10,000 gallon UST at the site failed a tightness test. The tank was emptied and filled in place, as utilities and building elements prevented excavation. The spill was closed on 2/15/1991 meeting NYSDEC Cleanup Standards.
Sears Realty Co., Inc.	201 North George Street Rome, NY	LTANKS	¼-½-mile NNW LTANKS: 8700903 On 5/1/1987, three 3,000 gallon USTs were excavated at the site. Holes were observed in one of the tanks. The tanks and associated contaminated soil was removed from the site and the gas station was closed. The spill was closed on 11/30/1988 meeting NYSDEC Cleanup Standards.
Gurley & Fleet	301 Black River Road Rome, NY	LTANKS	¼-½-mile NE LTANKS: 8907530 On 10/27/1989, contaminated soil was discovered surrounding an abandoned tank. Contaminated soil was removed from the site and the spill was closed on 4/1/1994 meeting NYSDEC Cleanup Standards.
Ganeszoort Elementary School	Liberty Street Rome, NY	LTANKS	¼-½-mile NNW LTANKS: 8800715 On 4/22/1988, a 10,000 gallon UST failed a tightness test. The spill was closed on 11/14/1988 meeting NYSDEC Cleanup Standards.
Walsh Residence	108 West Embargo Street Rome, NY	LTANKS	¼-½-mile NNE LTANKS: 9708408 On 10/17/1997, 50 gallons of #2 fuel oil spilled from a tank at the site due to an overfill. The spill was cleaned up and closed on 2/28/2005 meeting NYSDEC Cleanup Standards.
Kekis Mobil Service	400 West Dominick Street Rome, NY	LTANKS	¼-½-mile NW LTANKS: 8706960 On 11/12/1987, four 4,000 gallon USTs were removed from the site and contaminated soil was removed from the site. The spill was closed on 2/6/1989 meeting NYSDEC Cleanup Standards.
NIMO, Rome Jay and Madison MGP	106 South Madison Street Rome, NY	EDR MGP	¼-½-mile NW EDR MGP: The site was formerly a manufactured gas plant.

Site	Address	Database	Location & Report Information Summary
City of Rome DPW	132 Race Street Rome, NY	RCRA-CESQG NY MANIFEST	¼-½-mile SE EPA ID: NYD986931152 The facility is a conditionally exempt small quantity generator (CESQG), a handler and transporter of hazardous waste. The facility has two recorded violations. Wastes include halogenated solvents and ignitable hazardous materials.
		FINDS	FINDS ID: 110004456268
		NY SWF/LF	NY SWF/LF: The facility is listed as an inactive construction and demolition (C&D) processing facility.
		NY HIST UST NY AST	NY HIST UST/NY UST/NY AST ID: 6-433500 The facility formerly contained two USTs which are listed as closed-removed. The facility is an active AST site with one 275 gallon AST containing waste oil, one 550 gallon ASTs containing waste oil/used oil, one 550 gallon AST containing diesel, four 550 gallon ASTs containing lube oil and one 1,000 gallon AST containing diesel.
		NY SPILLS	NY SPILLS No. 0606854 On 9/14/2006, one gallon of hydraulic oil was spilled into the Mohawk River from the DPW facility. The spill was cleaned with speedy-dry and closed on 9/18/2006 not meeting NYSDEC Cleanup Standards. NY SPILLS No. 0705403 On 8/10/2007, one gallon of hydraulic oil was spilled into the Mohawk River from the DPR facility. The spill was cleaned up with speedy-dry and absorbent pads and closed on 8/13/2007 meeting NYSDEC Cleanup Standards. NY SPILLS No. 0608921 On 11/3/2006, approximately 2 quarts of transmission fluid spilled at the site. The spill was cleaned with absorbent pads and the spill was closed on 11/22/2006 meeting NYSDEC Cleanup Standards. NY SPILLS No. 9700481 On 4/10/1997, a 55 gallon drum used to catch oil overfills had a leak. Approximately ½ a 55 gallon drum of soil was contaminated and removed from the site. The spill was closed on 6/18/1997 meeting NYSDEC Cleanup Standards. NY SPILLS No. 8604572 On 10/17/1986 a delivery truck spilled an unknown amount of petroleum. The spill was closed on 10/17/1986 meeting NYSDEC Cleanup Standards.
		NY LTANKS	NY LTANKS No. 8807798 On 12/24/1988, a tank was overfilled at the site. Absorbent pads were used to clean the spill. The spill was closed on 12/27/1988 meeting NYSDEC Cleanup Standards. NY LTANKS No. 8805218Fkel On 9/16/1988, a tank was overfilled at the site. Absorbent pads were used to clean the spill. The spill was closed on 9/20/1988 meeting NYSDEC Cleanup Standards. NY LTANKS No. 8702144 On 6/15/1987, a tank failed a tightness test. The spill was closed on 6/19/1997 not meeting NYSDEC Cleanup Standards.
DeCarlis Residence	118 West South Street Rome, NY	LTANKS	¼-½-mile SW LTANKS: 8709652 On 2/16/1988, a 275 gallon tank spilled in a basement and entered the sewer main. The spill was cleaned up and closed on 2/16/1988 meeting NYSDEC Cleanup Standards.
Garcia Residence	735 South James Street Rome, NY	LTANKS	¼-½-mile SW LTANKS: 0303378 On 6/30/2003, petroleum spilled at the site. The spill was closed on 9/25/2003 meeting NYSDEC Cleanup Standards.

Site	Address	Database	Location & Report Information Summary
Former Rome Cable Site, Building Complex #1	421 Ridge Street Rome, NY	NY ERP	¼-½-mile WNW NY ERP: 58361, HW Code: E633053 The site consists of the Former Rome Cable Corporation, Building Complex No. 1 (Operable Unit No. 1) and Complex 3 (Operable Unit No. 2), which is approximately 10.2 acres in size. Prior uses that have led to site contamination include the use of chlorinated solvents used to clean machines and wire, petroleum used to heat the on-site furnaces and as lubricants, and asbestos containing material used as pipe insulation. Several small petroleum spills have been documented. The site has an "A" classification: assigned to a non-registry site in any remedial program where work is underway and not yet complete.
		NY SPILLS	NY SPILLS: 0300089 On 3/31/2003, a recirculating water system flooded the basement of the building. No spill occurred and the spill number was closed on 4/2/2003 meeting NYSDEC Cleanup Standards.
Lynn H. Scott, Inc.	300 West Court Street Rome, NY	LTANKS	¼-½-mile N LTANKS: 9011756 On 2/8/1991, a 10,000 gallon tank was removed from the site and holes were observed in the bottom of the tank. A sheen was noticed on groundwater in the excavation. Three monitoring wells were installed and contaminated soil was removed from the site. The spill was closed on 12/10/1998 not meeting NYSDEC Cleanup Standards.
		NY SPILLS	NY SPILLS: 0300911 On 4/25/2003, 200 gallons of 90 weight gear oil was spilled from an oil tank truck and spread approximately 4 blocks. The spill was cleaned up and closed on 7/30/2003 meeting NYSDEC Cleanup Standards.
Opper's	301 Erie Boulevard West Rome, NY	LTANKS	¼-½-mile NW LTANKS: 9403073 On 6/2/1994, 30 gallons of waste oil was spilled at the site. The spill was closed on 6/7/1994 meeting NYSDEC Cleanup Standards.
		UST HIST UST	UST/HIST UST: 6-600924 The facility formerly contained one 2,000 gallon UST containing #2 fuel oil which is listed as closed-removed.
		SPILLS	SPILLS: 0106797 On 10/1/2001, a leak was discovered in a tank at the site. The spill was closed on 11/23/2001 not meeting NYSDEC Cleanup Standards.
Frank's Sunoco Service Station	612 South James Street Rome, NY	LTANKS	¼-½-mile SW LTANKS: 9400052 On 3/31/1994, two 4,000 gallon and one 1,000 gallon tanks were removed from the site. Holes were observed in the bottoms of the tanks and contaminated soil and groundwater were observed in the excavation. An investigation including occurred but was never finished. The spill remains open.
		UST HIST UST	UST/HIST UST: 6-460656 The facility formerly contained two 4,000 gallon, two 2,000 gallon and one 1,000 gallon USTs containing unlisted materials. All tanks are listed as closed-removed.
NM – Rome Kingsley Ave. MGP	Kingsley Avenue Rome, NY	NY SHWS	¼ -½ -mile NW HW Program ID: 56266 The facility is listed as a former Manufactured Gas Plant (MGP) used to manufacture gas using coal carbonization and the water gas process. The facility ceased full-time production in 1930.

Site	Address	Database	Location & Report Information Summary
East Rome Business Park	600 Railroad Avenue Rome, NY	NY SPILLS NY ENG CONTROLS NY INST CONTROLS NY VCP NY ERP	¼-½-mile ESE NY SPILLS No. 0212777 On 3/25/2003, a heavy sheen was observed at a VCP site. The spill was closed on 11/7/2005 meeting NYSDEC Cleanup Standards. NY ENG CONTROLS Site Code/NY ERP Site Code: 57790, NY INST CONTROLS Site Code: V00077-6. NY VCP Code: This site is part of the former General Cable Facility which contained many large manufacturing and warehouse facilities which were used in the manufacturing and coating of wire until the 1970s. The site has a long history of industrial uses and was contaminated with a variety of hazardous materials including petroleum, asbestos, metals, PCBs, acids, chlorinated solvents and boiler chemicals. The facility formerly included the Canterbury Press parcel (the subject property). An investigation and remediation of the facility has been completed. The site has engineering and institutional controls in place to limit future uses of the property and a soil management plan (SMP) is in place.
Rossi Site Within East Rome Business Park	Mill Street/Railroad Street Rome, NY	NY ERP NY INST CONTROLS	¼-½-mile ESE NY ERP Site Code: 57205, HW Code: B00023. This site is in the core area of the former General Cable Facility. NY INST CONTROLS Site Code: 57205. This site is part of the former General Cable Facility which contained many large manufacturing and warehouse facilities which were used in the manufacturing and coating of wire until the 1970s. The site has a long history of industrial uses and was contaminated with a variety of hazardous materials including petroleum, asbestos, metals, PCBs, acids, chlorinated solvents and boiler chemicals. The facility formerly included the Canterbury Press parcel (the subject property). An investigation and remediation of the facility has been completed. The site has engineering and institutional controls in place to limit future uses of the property and a soil management plan (SMP) is in place.
Rome High Level Pump Station	Erie & Black River Blvd Rome, NY	NY LTANKS UST`	¼ -½ -mile S NY LTANKS No. 9706427 On 8/27/1997, contaminated soil was discovered during a tank removal. A spill investigation was conducted and the spill was closed on 12/12/2006 not meeting NYSDEC Cleanup Standards. UST: 6-600133 The facility formerly contained one 15,000 gallon UST containing diesel. The tank is listed as closed-removed.
Kotary Motors	East Wright Street Rome, NY	LTANKS	¼-½-mile SW LTANKS: 8907789 On 11/6/1989, one 1,000 gallon tank was removed from the site and contaminated soil was observed in the excavation. The spill was closed on 10/26/1995 not meeting NYSDEC Cleanup Standards.
Lee Bates & Sons	736 South James Street Rome, NY	LTANKS	¼-½-mile SW LTANKS: 9507910 On 9/27/1995, an unknown amount of gasoline spilled at the site. The spill lists 90 yards of contaminated soil was discovered. The spill was closed on 1/27/1998 meeting NYSDEC Cleanup Standards.
City of Rome/Inland Fuels/Nolan Hayes	701 Lawrence Street Rome, NY	NY ERP	¼ -½ -mile NNE NY ERP ID: 59127 The site was formerly used for the storage of gasoline and fuel oil and bulk distribution of petroleum products.

Site	Address	Database	Location & Report Information Summary
City of Rome/Inland Fuels/Nolan Hayes (continued)		NY SPILLS	NY SPILLS No. 0902842 On 6/10/2009, two USTs of unknown size and contaminated soil were discovered during an excavation. The cleanup and soil removal is pending. This spill is open.
		NY MOSF	MOSF ID: 6-1240 This facility is an inactive Major Oil Storage Facility (MOSF).
		NY LTANKS	NY LTANKS No. 8401531 On 9/6/1984, 10 gallons of #2 fuel oil was spilled at the site. The spill was closed on 9/6/1984 meeting NYSDEC Cleanup Standards.
		US BROWNFIELDS	US BROWNFIELDS: The site was a PBS facility from 1936 to 1990. The site formerly contained seven petroleum bulk storage tanks that ranged in capacity from 16,000 gallons to 1.15 million gallons. Several documented spills have been recorded and significant subsurface contamination has been documented, due to poor housekeeping practices. A spill consisting of approximately 10,000 gallons of # 2 fuel oil and an unreported amount of gasoline occurred at the site on October 2, 1989. Due to the spill, the EPA initiated a cleanup effort at the site, which resulted in the excavation and off-site disposal of approximately 1,000 to 2,000 cubic yards of petroleum contaminated soil.

A gasoline station, an industrial warehouse and a car wash are currently or were formerly adjoining the subject property. The material threat of migration of hazardous substances to the subsurface at the subject property through groundwater from adjoining properties is considered a REC.

3.04 *Unmapped Listed Sites*

The EDR database search cannot always accurately locate a facility listed in a given database due to incomplete or faulty addresses and/or longitude and latitude coordinates. In these cases, EDR has supplied a list of un-mapped sites. Based upon the information provided and the required search radius for a given database, it is sometimes not possible to determine if an un-mapped site falls within the given search radius or if it may be removed from consideration.

A total of 11 un-mapped sites were provided by EDR based on the site having the same zip code as the subject property or proximity to the subject property. This listing in the EDR Orphan Report did not include references identifying the subject property or properties in close proximity to the subject property.

In order to determine which unmapped sites were within the specified search radii, the site visits conducted by Bergmann included observations to attempt to locate these sites. Street maps of the subject property vicinity were reviewed and Internet yellow and white page searches were conducted. Based upon this review, it appears that the listed “Orphan Sites” are not within close proximity to the subject property and do not likely present an environmental concern based on the information in the EDR report.

3.05 *Additional Record Sources and Interviews*

As part of the due diligence component of this Phase I ESA, Bergmann interviewed the City of Rome representative during the time of the site reconnaissance on August 4, 2015. The following documents the interview:

Mr. Dennis Gillen, Assistant Planner

Mr. Dennis Gillen is an Assistant Planner for the City of Rome. Mr. Gillen manages foreclosed properties owned by the City of Rome. Mr. Gillen stated that the subject property previously operated as the Rome-Turney

Radiator Company and as a tannery. Mr. Gillen stated that a subsurface investigation was previously performed at the subject property by TES and that additional investigations were required by NYSDEC. Mr. Gillen stated that vandals have entered the property on multiple occasions, have stolen items from within the building and have dumped materials into the building.

The potential presence of remaining soil and groundwater contamination at the subject property from a historic spill which was not closed is considered a REC.

The material threat of release of petroleum and/or other hazardous materials associated with historic industrial and manufacturing operations to the subsurface at the subject property is considered a REC.

The material threat of a release of chemicals and wastes associated with historic tanning operations is considered a REC.

Freedom of Information Requests

As part of the background research component of the Phase I ESA, Bergmann Associates contacted State and Local government officials. Written FOIL applications were submitted to US EPA Region 2, the New York State Department of Health (NYSDOH), the New York State Department of Environmental Conservation (NYSDEC) Region 6, the City of Rome, and Oneida County.

US EPA Region 2 Office

Bergmann sent a Freedom of Information Legislation (FOIL) letter to the US EPA Region 2 Freedom of Information Officer requesting information for the subject property. As of the date of this report, no response has been received.

New York State Department of Environmental Conservation

Bergmann sent a FOIL form to the NYSDEC Records Access Officer requesting information for the subject property. Bergmann received a response stating that the request was forwarded on to the NYSDEC Region 6 Records Access Officer and a response will be returned by September 4, 2015.

A disc containing information from the NYSDEC was provided by the City of Rome. The following information was included on the disc:

- A PBS Notice dated October 12, 1987 stating that Rome-Turney Radiator Co. registered two 5,000 gallon USTs containing fuel oil.
- A NYSDEC Spill Report Form for spill number 8802056 dated June 6, 1988 states that two tanks at the subject property failed a tightness test. The tank test was aborted due to air pockets. After digging to vent the tanks, contaminated soil was discovered. The soil was placed on plastic and the excavation was scheduled to continue. On June 7, 1988, free floating product was observed on groundwater in the excavation. On July 21, 1998, the tanks were removed and staged and the hole was filled. One 4" groundwater monitoring well was scheduled to be installed. On April 11, 1989, 48 yards of contaminated soil was removed from the subject property and disposed. The soil disposal paperwork was received on August 31, 1990. On April 12, 1996, the NYSDEC sent a Petroleum Spill Stipulation Agreement to the owner of the subject property. On January 13, 2003, the NYSDEC noted that the investigation at the subject property is incomplete.
- A letter dated June 14, 1988 from Mr. Jack Marsch, Senior Sanitary Engineer at NYSDEC Region 6 to Mr. William Lynch of Rome-Turney Radiator Company regarding spill number 8-02056 stating that as a result of an investigation, the NYSDEC holds Mr. Lynch responsible for the spill and the associated cleanup. The NYSDEC recommends a groundwater investigation and requires disposal of any contaminated soil at the subject property and submittal of proper disposal documentation.

- A Tank Test Report dated July 7, 1988 stating that Rome-Turney Radiator Co. had two 5,000 gallon steel USTs tightness tested on June 9, 1988 by Coccio Brothers Oil Co. The tanks were in the ground for 10-15 years at the time of testing. The tanks both failed the tightness test.
- A letter dated April 7, 1989 from Mr. John Hitchings, President of Industrial Oil Tank Service Corp (Industrial Oil) to Mr. Lynch which verifies that on July 21, 1988, Industrial Oil cleaned two 6,000 gallon #2 fuel oil tanks for closure. The letter states that contaminated soil from the excavation was stockpiled and disposed at a later date.
- A letter dated August 22, 1990 from Mr. William L. Lynch, Jr., president of the Rome-Turney Radiator Company to Mr. David Pickett of the NYSDEC stating that a copy of the paid invoice for soil removal at the subject property was enclosed and that Mr. Lynch did not have knowledge of analysis performed at the property. Attached to the letter is an invoice, analysis results and disposal receipts associated with the tank removal and contaminated soil disposal.
- A letter dated August 27, 1990 from Mr. Lynch to Mr. John Hitchings of Industrial Oil states that Rome-Turney was asked by NYSDEC for documentation associated with the tank removal and contaminated soil disposal and requests the documentation from Industrial Oil.
- A letter dated August 29, 1990 from Mr. Hitchings to Mr. Lynch states that the requested documentation was enclosed with the letter.
- A letter dated August 30, 1990 from Mr. Lynch to Mr. Pickett with an enclosure of the information from Industrial Oil.
- A letter dated June 15, 1993 from Mr. Marsch to Mr. Lynch states that Mr. Lynch was advised on June 14, 1988 to perform a groundwater investigation at the subject property. As of the date of the letter, the NYSDEC did not received a response to their request and was therefore was to be charged all actual costs incurred by New York State for cleanup and removal, all direct and indirect damages, including damages incurred by third parties. Mr. Marsch requests a response by July 1, 1993.
- A fax dated June 17, 1993 from Mr. Doug Ouderkirk of Rome-Turney to Mr. Marsch states that the tank removal and soil disposal at the subject property was performed in accordance with NYSDEC regulations and that it was determined during the investigation that due to groundwater conditions in the area, an observation well was not necessary.
- A letter dated June 17, 1993 from Mr. Neal F. Carrier, Environmental Engineering Technician 2 at NYSDEC to Mr. Lynch states that enclosed with the letter was a list of companies capable of performing groundwater investigations.
- A letter dated June 22, 1993 from Mr. Ouderkirk to Mr. Marsch states that groundwater testing at the time of the spill was considered and a well was left open for investigation for approximately one year. No demand for sampling was received by Rome-Turney. Conversations at the time with Mr. Hitchings revealed that the tank integrity was not breached and that in his opinion, the small amount of oil in the excavation was due to a ruptured line or fitting. The letter requests that the NYSDEC review enclosed files and determine if further information is required. A handwritten note on the letter dated June 25, 1993 from Mr. Marsch to Mr. Ouderkirk states that a groundwater investigation is still required.
- A letter dated June 30, 1993 from Mr. Ouderkirk to Mr. Marsch states that Rome-Turney believes that the original monitoring well was never removed and that Mr. Hitchings was contacted to provide a plot map or description of the well location.
- A message dated July 29, 1993 from Mr. Doug Mendrala of Environmental Lab Services to Mr. Howard R. Mason, Environmental Engineer 1 for NYSDEC Region 6 stating that a hydrocarbon pattern similar to weathered diesel fuel or #2 fuel oil was detected at the subject property and the lab report was to be resubmitted to Rome-Turney, the original comment was missed in typing.
- A letter dated August 12, 1993 from Mr. Ouderkirk to Mr. Marsch states that as per NYSDEC recommendation, the test well was pumped and sampled. The results are attached to the letter. The laboratory results state that <0.1 microliters per liter (ul/L) of kerosene and fuel oil were detected.

- A letter dated January 13, 1995 from Mr. Mason to Mr. Ouderkirk states that NYSDEC has not received any correspondence from either Mr. Ouderkirk or his consultant since the fax dated August 12, 1993 which indicated the presence of "weathered" diesel fuel or #2 fuel oil. The letter requests a status report or a notification of the cause of delay to be submitted immediately.
- A letter dated January 30, 1995 from Mr. Marsch to Mr. Ouderkirk states that the policy of the NYSDEC is to clean up spills and pre-spill conditions and that the spill at the subject property should be investigated and remediated. The investigation should address the extent and degree of soil and groundwater contamination and that once defined, remediation should be initiated to clean up the spill to bring the property into compliance with Spill Technology and Remediation Series (STARS) Petroleum-Contaminated Soil Guidance Policy and groundwater standards. Following remediation, a Professional Engineer must certify that the spill was cleaned up. The owner must also provide access to the spill site for verification. The letter requests an initial investigation report by May 1, 1995 from the contractor.
- A letter dated April 28, 1995 from Mr. Lynch to Mr. Marsch describes a timeline of events related to the spill at the subject property and states that the company was not contacted for approximately five years regarding the spill and assumed the matter was closed. Mr. Lynch states that the area surrounding the subject property may have contributed to the subsurface conditions and that the requirement for costly studies seems unwarranted.
- A letter dated May 1, 1995 from Mr. Marsch to Mr. Lynch states that the actions taken to date are not sufficient to bring the spill to a close and references the requirements in the January 30, 1995 letter.
- A fax dated May 11, 1995 from Mr. Ouderkirk to Mr. Marsch states that a response from Mr. Hitchings was not received and that Mr. Scott Theal from Theal Environmental Services (TES) was hired to perform the investigation and would like to arrange a meeting with Mr. Marsch.
- A fax dated May 22, 1995 from Mr. Ouderkirk to Mr. Marsch states that attached to the fax was a proposal from TES to perform a subsurface investigation. The attached proposal outlines an inspection of the facility including photographs and performance of a records search regarding the design, use and removal of USTs at the subject property. The proposal outlines the performance of a soil gas survey, the installation of up to four groundwater monitoring wells, the collection of one round of groundwater samples and the preparation of a letter report summarizing findings of the investigation.
- A letter dated May 22, 1995 from Mr. Marsch to Mr. Lynch states that the proposal was reviewed and provides comments and recommendations requested to be added to the proposal. The response provides example summary tables and field sampling logs.
- A faxed letter dated June 1, 1995 from Mr. Theal to Mr. Marsch requests access to NYSDEC Region 6 Division of Spills technical files for the subject property.
- A letter dated June 14, 1995 from Randall C. Young, NYSDEC Region 6 Assistant Regional Attorney to Mr. Theal states the cost of record reproduction and that upon payment, records would be forwarded to Mr. Theal.
- A letter dated September 6, 1995 from Mr. Marsch to Mr. Lynch states that Mr. Marsch's May 22, 1995 letter requested a response by September 1, 1995 and that if a response date could not be met by Mr. Lynch, a written notification of the reason for the delay and an expected response date would be appreciated.
- A fax dated October 4, 1995 from Mr. Ouderkirk to Mr. Marsch states that a report should be ready by the week of October 25, 1995.
- A letter dated November 2, 1995 labeled as a Second Reminder from Mr. Marsch to Mr. Lynch states that Mr. Marsch's May 22, 1995 letter requested a response by September 1, 1995 and that if a response date could not be met by Mr. Lynch, a written notification of the reason for the delay and an expected response date would be appreciated.
- A letter dated December 15, 1995 labeled as a Third Reminder from Mr. Marsch to Mr. Lynch states that Mr. Marsch's May 22, 1995 letter requested a response by September 1, 1995 and that if a response

date could not be met by Mr. Lynch, a written notification of the reason for the delay and an expected response date would be appreciated.

- A letter dated February 9, 1996 labeled as a Third Reminder from Mr. Marsch to Mr. Lynch states that Mr. Marsch's May 22, 1995 letter requested a response by September 1, 1995 and that if a response date could not be met by Mr. Lynch, a written notification of the reason for the delay and an expected response date would be appreciated.
- A letter dated March 21, 1996 from Mr. Marsch to Mr. Lynch states that the purpose of the letter was to obtain commitment to clean up and remove the discharge of petroleum at the subject property. Attached to the letter was a NYSDEC Stipulation agreement.
- A letter dated April 8, 1996 from Mr. Lynch to Mr. Marsch states that a Subsurface Investigation was performed in September 1995 by TES and that due to the poor fiscal condition of Rome-Turney in the fall of 1995, the data analysis and report preparation by TES was delayed. Mr. Lynch states that the next phase of work at the subject property would be performed by TES, including the installation of one or more monitoring wells, collection of four quarters of groundwater samples and the removal of any residual waste debris from the investigation. Attached to the letter was a signed copy of the Stipulation agreement.
- A letter dated April 12, 1996 from Mr. Marsch to Mr. Lynch states that attached to the letter is a copy of the signed Stipulation and the approved Corrective Action Plan for the subject property.
- A fax dated May 1, 1996 from Mr. Ouderkirk to Mr. Marsch states that the TES report was due to Rome-Turney that afternoon and that after a review, the report would be sent to Mr. Marsch by the following Monday.
- A fax dated May 6, 1996 from Mr. Theal to Mr. Marsch includes the executive summary of the Subsurface Investigation Report and states that a full copy of the report would be sent to NYSDEC within two days.
- A Subsurface Investigation Report dated May 10, 1996 prepared by TES. This report describes the activities performed at the subject property to characterize the extent, if any, of soil and groundwater contamination related to the historic use and removal of two former USTs at the subject property. The investigation was performed between June 6 and September 12, 1995 and a groundwater sampling event occurred on April 4, 1996. The investigation concluded the following:
    - Two water bearing units or aquifers exist at the subject property and both are impacted by the release of petroleum hydrocarbons.
    - Groundwater in the shallow water table aquifer was impacted as a result of the release of #2 fuel oil from the former USTs at the subject property.
    - Organic vapors were detected in the area west of monitoring well MW-3, and gasoline compounds were detected in groundwater collected from MW-3.
    - If free floating petroleum product is not encountered during future monitoring activities and petroleum hydrocarbons dissipate through natural attenuation, appropriate actions should be taken to close the project file.

  The Subsurface Investigation Report recommended the following:

    - Installation of one additional shallow monitoring well on the west side of the former UST excavation area to further define the relationship between the shallow and deep water bearing units.
    - Continuation of quarterly sampling for a minimum of three more quarters to allow a full evaluation of seasonal drainage patterns that occur throughout the annual hydrologic cycle.
    - Performance of routine maintenance on the flush mount curb boxes in order to preserve the security and structure of the wells.

  - Performance of a FOIL search and review of NYSDEC site records for adjacent petroleum spill sites that may be impacting the subject property in order to identify the potential source of gasoline in the lower water bearing unit.
  - Removal of all drilling debris remaining at the subject property.
  - If warranted, creation and initiation of a corrective action plan near the observation well if future monitoring results indicate that free product and/or high concentrations of total petroleum hydrocarbons (TPH) remain.

- A letter dated May 17, 1996 from Mr. Marsch to Mr. Lynch states that the TES Subsurface Investigation Report was received and provides a list of comments and recommendations which are requested to be addressed in the next submittal. The comments include a request to explain an unexpected northeast groundwater flow direction, a request to define the extent of soil contamination, a request for additional information on field logs, and general corrections on measurements and details in tables. The report asks why no samples results for April 4, 1996 were included.
- A letter dated August 13, 1996 from Mr. Theal to Mr. Marsch states that project delays have prevented the follow-up report from being submitted to NYSDEC. One stated delay is connected to the understanding of groundwater flow patterns at the subject property.
- A letter dated September 13, 1996 from Mr. Marsch to Mr. Lynch states that the letter dated May 17, 1996 requested a response by August 15, 1996. The letter states that the consultant letter dated August 13, 1996 indicates a report delay but does not provide an anticipated submittal date.
- A letter dated December 6, 1996 labeled as a second reminder from Mr. Marsch to Mr. Lynch states that the letter dated May 17, 1996 requested a response by August 15, 1996. The letter states that the consultant letter dated August 13, 1996 indicates a report delay but does not provide an anticipated submittal date.
- A letter dated March 12, 1997 labeled as a third reminder from Mr. Marsch to Mr. Lynch states that the letter dated May 17, 1996 requested a response by August 15, 1996. The letter states that the consultant letter dated August 13, 1996 indicates a report delay but does not provide an anticipated submittal date.
- A FOIL request dated April 7, 1997 from Mr. Theal to Mr. Marsch requests information on a number of spills surrounding the subject property to gain a better understanding of off-site activities within a relative proximity to Rome-Turney. Mr. Theal states that regarding the September 13, 1996 letter, the scope of work recommended in the Subsurface Investigation Report was not yet addressed due to staffing conflicts. A report was scheduled to be submitted on or about June 1, 1997.
- A NYSDEC Spill Report Form created on June 8, 1998 and printed on January 13, 2003 states a general timeline of the information summarized above and that the file was reviewed and need to be completed.
- An Inspection Form dated April 8, 2005 states that the Rome-Turney Radiator Co. was inspected on March 14 and 21, 2005 by NYSDEC. The facility was identified as a generator of hazardous waste. The wastes listed are lead, acetone, xylene and assorted aerosol cans. A notification on the inspection form states that the company ships a lead dross and fluorescent light bulbs and did not complete the necessary documentation.
- A Notice of Violation dated April 11, 2005 from Mr. Edward Blackmer, Regional Solid & Hazardous Materials Engineer for NYSDEC Region 6 to Mr. Lynch stating that the subject property formerly operated as a Conditionally Exempt Small Quantity Generator (CESQG) and that the facility is closed due to a bankruptcy filing. The letter states that the facility is in violation of 6NYCRR Part 371.1(c)(7) with regard to a characteristic hazardous dross. If the facility was to remain closed, the products would be required to be removed under regulatory management.

- A letter dated May 15, 2008 from Mr. Ryan Peach of the Rollerad Corporation to Ms. Carol Bunn of NYSDEC requests environmental information related to the former Rome-Turney Radiator Co., Elegrace Caskets and Nick Rotolo.
- A letter dated May 20, 2008 from Mr. Stephen W. Litwhiler to Mr. Peach states that the FOIL request was received and would be fulfilled within 20 days.
- A letter dated June 11, 2008 from Mr. Litwhiler to Mr. Peach states that the records requested were ready to be reviewed or copied and gives details for arranging pickup.
- A letter dated July 31, 2014 from Mr. Litwhiler to Mr. Daniel Buck of Beebe Construction Services, Inc. states that the materials requested in a Freedom of Information request were ready for review. The letter states that if a response was not received within ten days, the materials would be refiled.

The potential presence of remaining soil and groundwater contamination at the subject property from a historic spill which was not closed is considered a REC.

The material threat of release of petroleum and/or other hazardous materials associated with historic industrial and manufacturing operations to the subsurface at the subject property is considered a REC.

The material threat of release of petroleum and/or other hazardous materials used and stored at the subject property is considered a REC.

New York State Department of Environmental Conservation Region 6 Office

Bergmann sent a FOIL form to the NYSDEC Region 6 Records Access Officer requesting information for the subject property. Bergmann received an email response stating that the request was received by NYSDEC and a response should be expected by August 20, 2015. Bergmann received an email on August 20, 2015 from NYSDEC Region 6 that the requested information in the Utica sub-office is ready to be reviewed or copied. In order to copy the information, a private copy service must be hired. An estimated number of copies available is 359. The City of Rome previously provided files from NYSDEC during the course of this Phase I ESA. Some of the information available at the Utica sub-office may overlap the information previously reviewed by Bergman. A response was sent to NYSDEC Region 6 on August 24, 2015 requesting further information on the data.

New York State Department of Health

Bergmann sent a FOIL form to the New York State Department of Health (NYS DOH) Records Access Officer requesting information for the subject property. Bergmann received a response stating that the NYS DOH received the FOIL request and forwarded the request on to the appropriate department. A response is expected regarding the status of the request by August 20, 2015.

Oneida County

Bergmann sent a FOIL letter to Oneida County Department of Planning requesting information for the subject property. Bergmann received a letter indicating that Oneida County had received the FOIL request and their records do not include information on the subject property.

City of Rome

Bergmann sent a FOIL letter to the City of Rome requesting information for the subject property. Bergmann received a letter indicating that the City of Rome had received the FOIL request and that the Codes Enforcement Office and the Department of Public Works are not in possession of any records corresponding to Bergmann's request. A second letter was received indicating that a final response will be sent by August 19, 2015.

Copies of agency correspondence are included in Appendix C – FOIL Requests/FOIL Responses.

4.0 SUBJECT PROPERTY PHYSICAL SETTING REVIEW

4.01 *Historical Use Information*

Publicly available city directories, topographic maps, Historic Sanborn® maps and historical aerial photographs were reviewed as part of this Phase I ESA. Below is a summary of this review.

4.02 *Topographic Map Review*

Historic Topographic Maps dated 1898, 1947, 1949, 1955 and 1985 were available from EDR. A review of these maps is below.

1898
The subject property is located on the Oriskany, New York 7.5 minute series quadrangle map obtained from EDR. This map is dated 1898. The subject property appears to be undeveloped land. A railroad runs to the north of the subject property. Surrounding properties appear developed.

1947
The subject property is located on the Rome, New York 7.5 minute series quadrangle map obtained from EDR. This map is dated 1947. The subject property is developed with a large building. Surrounding properties appear developed.

1949
The subject property is located on the Rome, New York 7.5 minute series quadrangle map obtained from EDR. This map is dated 1949. The subject property is developed with a large building. Surrounding properties appear developed.

1955
The subject property is located on the Rome, New York 7.5 minute series quadrangle map obtained from EDR. This map is dated 1955. The subject property is developed with a large building. Surrounding properties appear developed.

1985
The subject property is located on the Rome, New York 7.5 minute series quadrangle map obtained from EDR. This map is dated 1985. The subject property is in an area of urban development. Due to the scale of the map, individual site features are not visible.

Copies of the historic topographic maps are included in Appendix D – Historic Topographic Maps.

4.03 *Historic Sanborn® Map Review*

Historic Sanborn® Fire Insurance Maps dated 1884, 1888, 1984, 1899, 1904, 1909, 1914, 1924, 1930, 1949 and 1971 were available for the subject property and surrounding area from EDR. A review of these maps is below.

1884
The subject property appears to be undeveloped land. A railroad right-of-way is located north of the subject property, beyond which is the R.M. Bingham and Co. – manufacturers of carriage bodies and the City Steam Mill. Residential buildings are located south of the subject property. Undeveloped land is located to the east of the subject property. A lumber storage area, a shed, a residential building and the Little Stanwix Saloon are located west of the subject property.

1888
The subject property is developed as the R.M. Bingham and Co. – carriage manufacturing forging department with associated lumber storage piles. A railroad right-of-way is located north of the subject property, beyond which is the remainder of the R.M. Bingham and Co and the City Steam Mill. The P. Schneibles Candle and

Soap Works and residential buildings are located south of the subject property. The Erie Canal is located east of the subject property, beyond which is Whitesboro Street, the Whitesboro Hotel and the J. Atkinson carriage manufacturer. A shed, a residential building and the Little Stanwix Saloon are located to the west of the subject property.

1894

The subject property contains the blacksmith shop for the R.M. Bingham and Co. and a small one-story building. A railroad right-of-way is located north of the subject property, beyond which is the remainder of the R.M. Bingham and Co and the Rome Manufacturing Co. – Copper Kettles. The P. Schneibles Candle and Soap Works and residential buildings are located south of the subject property. The Erie Canal is located east of the subject property, beyond which is Whitesboro Street, the Whitesboro Hotel and the J. Atkinson carriage manufacturer. A shed, a residential building and the Little Stanwix Saloon are located to the west of the subject property.

1899

The subject property contains The Electric Wire Works – a three-story building, an engine house, and one 75 gallon gasoline UST in the northern portion of the property. A railroad right-of-way is located north of the subject property, beyond which are three wholesale grocers and the McRoam Sturges Oil Refinery. The P. Schneibles Candle and Soap Works and residential buildings are located south of the subject property. The Erie Canal is located east of the subject property, beyond which is Whitesboro Street, the Whitesboro Hotel and the J. Atkinson carriage manufacturer. A shed, a residential building, the Little Stanwix Hotel, a barber and a bowling alley are located west of the subject property.

1904

The subject property contains the Utica Industrial Co. – Machine Shop with associated coal house located in the northern portion of the property. A railroad right-of-way is located north of the subject property, beyond which are two grocers. The P. Schneibles Candle and Soap Works and residential buildings are located south of the subject property. The Erie Canal is located east of the subject property, beyond which is Whitesboro Street and the Alex A. Meyer's carriage manufacturer. A shed, a residential building, the Little Stanwix Hotel, a barber and a vacant former bowling alley are located west of the subject property.

1909

The subject property contains the Rome-Turney Radiator Co. with a main building containing an office and storage area, machine shop, tanning department, cutting department, buff room and stock room. A gas plant and oil house are located in the central portion of the property and a gasoline house is located in the southeast corner of the property. The subject property also contains the Bingham Harness Co. Collar Shop building. A railroad right-of-way is located north of the subject property, beyond which are two grocers. A contractor's shed, a vacant general store house and an unlabeled one-story building are located south of the subject property. The Erie Canal is located east of the subject property, beyond which is Whitesboro Street, a railroad station, a tenement and a residential building. A residential building, two sheds and a saloon are located to the west of the subject property.

1914

The subject property contains the Rome-Turney Radiator Co. with a main building containing an office and storage area, machine shop, tanning department, cutting department, buff room, stock room, a buffing department, a storage area and a shipping department. A gas plant, a pump house, a timekeeper building, a dipping building and an oil house are located in the central portion of the property. A gasoline house with one 10,000 gallon tank is located in the southeast corner of the property and a transformer house is located in the southeast corner of the property. A railroad right-of-way is located north of the subject property, beyond which are two grocers. The West End Brewing Company Beer Depot and residential buildings are located south of the subject property. The Erie Canal is located east of the subject property, beyond which is Whitesboro Street, two vacant buildings and two residential buildings. The General Electric radiator shop, a bicycle shop, a residential building, a saloon and two sheds are located to the west of the subject property.

1924
The subject property contains the Rome-Turney Radiator Co. with a main building containing an office and storage area, machine shop, cutting department, buff room, stock room, a buffing department, a storage area, a shipping department and a paint room. A storage building, a dipping building and a garage are located in the central portion of the property. A gasoline pump with one 10,000 gallon tank is located in the southeast corner of the property and a transformer house is located in the southeast corner of the property. A railroad right-of-way is located north of the subject property, beyond which is a meat packing business and a grocer. The West End Brewing Company Beer Depot, two garages and residential buildings are located south of the subject property. The Erie Canal is located east of the subject property, beyond which is Whitesboro Street, a garage, a charcoal storage building and an office. The Rome Hollow & Tube Co. Plant Number 2 is located to the west of the subject property.

1930
The subject property contains the Rome-Turney Radiator Co. with a main building containing an office and storage area, machine shop, cutting department, buff room, stock room, a buffing department, a storage area, a spray painting area and a shipping department. A storage building, a dipping building and a garage are located in the central portion of the property. A gasoline pump with one 10,000 gallon tank is located in the southeast corner of the property and a transformer house is located in the southeast corner of the property. A railroad right-of-way is located north of the subject property, beyond which is a meat packing business, a garage, an automobile service station and a grocer. The West End Brewing Company Beer Depot, two garages and residential buildings are located south of the subject property. The Erie Canal is located east of the subject property, beyond which is Whitesboro Street, a garage, a charcoal storage building and an office. The Kent Co. Inc. – Electric Floor Machine and Vacuum Cleaner manufacturer is located to the west of the subject property.

1949
The subject property contains the Rome-Turney Radiator Co. with a main building containing an office and storage area, machine shop, cutting department, machine room, stock room, tube bending department, shipping department and a box storage area. Two storage buildings, an oil house and a dipping building are located in the central portion of the property. A gasoline pump with one 10,000 gallon tank is located in the southeast corner of the property and a transformer house is located in the southeast corner of the property. A railroad right-of-way is located north of the subject property, beyond which is a wholesale banana building, an auto repair station, an auto sales & service building, a glass shop and a bowling alley. The West End Brewing Company Beer Depot, a garage, a case storage building and residential buildings are located south of the subject property. The Erie Canal is located east of the subject property, beyond which is Whitesboro Street, a garage, a charcoal storage building and an office. The Kent Co. Inc. – Electric Floor Machine and Vacuum Cleaner manufacturer is located to the west of the subject property.

1971
The subject property contains the Rome-Turney Radiator Co. with a main building containing an office and storage area, machine shop, cutting department, machine room, patching and testing area, tube bending department, shipping department and a box storage area. Two storage buildings, an oil house and a dipping building are located in the central portion of the property. A gasoline pump with one 10,000 gallon tank is located in the southeast corner of the property. A railroad right-of-way is located north of the subject property, beyond which is a wholesale grocer building and a filling station. The West End Brewing Company Beer Depot and residential buildings are located south of the subject property. Whitesboro Street is located east of the subject property, beyond which is a garage, an office and residential buidlings. The Kent Co. Inc. – Electric Floor Machine and Vacuum Cleaner manufacturer is located to the west of the subject property.

The material threat of a release of petroleum products to the subsurface at the subject property from the presence of a 10,000 gallon UST containing gasoline on the subject property from at least 1909 to at least 1971 is considered a REC.

The material threat of release of petroleum and/or other hazardous materials associated with historic industrial and manufacturing operations to the subsurface at the subject property is considered a REC.

The material threat of release of petroleum and/or other hazardous materials stored at the subject property to the subsurface at the subject property is considered a REC.

The material threat of migration of hazardous substances or petroleum products to the subsurface at the subject property through groundwater from adjacent industrial and commercial facilities is considered a REC.

Copies of the Historic Sanborn® Fire Insurance Maps are included in Appendix E – Historic Sanborn® Map Report.

4.04 *Historic Aerial Photograph Review*

Aerial photographs dated 1960, 1985, 1989, 1997, 2006, 2008, 2009 and 2011 were available from EDR. A review of these maps is below.

1960
The subject property contains industrial buildings, mainly located on the eastern half of the property. A courtyard and what appears to be a gasoline pump and a parking area or vehicle storage area is located on the western half of the property. Surrounding properties include residential buildings and larger commercial and industrial buildings.

1985
The subject property and surrounding properties appear similar to the 1960 aerial photograph in general; however, due to the quality and scale of the photograph, individual site features are unclear.

1989
The subject property and surrounding properties appear similar to the 1960 aerial photograph. The parking area appears to be cleared out on the western half of the subject property. The property adjoining the subject property to the southwest is vacant. Surrounding properties include residential buildings and larger commercial and industrial buildings.

1997
The subject property and surrounding properties appear similar to the 1989 aerial photograph. Vehicles are parked within the paved courtyard area of the subject property on the northern portion of the property. Surrounding properties include a gasoline station to the north, residential properties and vacant land to the south, a roadway to the east, beyond which is a motel and an industrial or commercial warehouse is located to the west of the subject property.

2006
The subject property and surrounding properties appear similar to the 1997 aerial photograph.

2008
The subject property and surrounding properties appear similar to the 2006 aerial photograph. The gasoline station to the north of the subject property has been replaced with a commercial building.

2009
The subject property appears similar to its current configuration. No significant changes have occurred at the subject property or surrounding properties.

2011
The subject property appears similar to its current configuration. No significant changes have occurred at the subject property or surrounding properties.

Copies of the Aerial Photographs are included in Appendix F – Historic Aerial Photographs.

4.05 *City Directory Image Review*

The subject property was identified on City Directories for the years 1961, 1966, 1971, 1976, 1981, 1987, 1992, 1995, 1999, 2003, 2008 and 2013. The following table describes listing information for the subject property.

Table 3
City Directory Listings for the Subject Property

Year	Listing(s)
1961	Rome-Turney Radiator Co.
1966	Rome-Turney Radiator Co. heating apparatus
1971	Rome-Turney Radiator Co. heating apparatus
1976	Rome-Turney Radiator Co. heating apparatus
1981	Rome-Turney Radiator Co. heating apparatus
1987	Rome-Turney Radiator Co. heating apparatus
1992	Lynch Realty, The Music Factory, Rome-Turney Radiator Co., Serway Brothers Incorporated – Plastic Laminating Division
1995	Lynch Realty, The Music Factory, Rome-Turney Radiator Co., Serway Brothers Incorporated – Plastic Laminating Division
1999	The Music Factory, Rome-Turney Radiator Co.
2003	The Music Factory, Rome-Turney Radiator Co.
2008	Elegrace Casket Inc., Rofin LLC, Rome-Turney Radiator Co.
2013	The Music Factory

Copies of the City Directories are included in Appendix G – City Directory Image Report.

4.06 *Wetland Review*

The NYSDEC Environmental Resource Mapper online application was reviewed to determine the presence of wetlands on our around the subject property. Based on the information obtained through the application, wetlands were not indicated on the subject property. A copy of the Environmental Resource Map is included in Appendix H – NYSDEC Environmental Resource Map.

4.07 *Flood Hazard Boundary Review*

Flood plains delineation has not been conducted. The property is currently an existing developed parcel. A review of the Federal Emergency Management Agency (FEMA) National Flood Insurance Program – Flood Boundary and Floodway Map for the subject property indicates that the subject property is not within a flood zone. A copy of the Flood Insurance Rate Map (FIRM) is included in Appendix I – FEMA Fire Insurance Rate Map.

4.08 *Soil Survey Review, Local Groundwater and Subsurface Characterization*

According to the U.S. Department of Agriculture (USDA) Soil Conservation Services (SCS), soils at the subject property are composed of the Urban Land soil type and the Canandaigua Silt Loam soil type, characterized by silt loam with very slow infiltration rates. Soils are clayey, have a high water table, or are shallow to an impervious layer.

The Federal USGS database lists one public water supply wells within a ½-mile radius of the subject property to the north-northeast.

5.0 INFORMATION GATHERED DURING THE SITE RECONNAISSANCE VISIT

Ms. Megan Borruso and Mr. Jim Marschner, Environmental Specialists from Bergmann conducted a site reconnaissance visit and walk-over of the subject property on August 4, 2015. Photographs taken of the subject property during the site visits are included in the Photographs Section of this report. The Bergmann Associates Site Observation Form is provided in Appendix A.

5.01 *On-Site Buildings and Structures*

At the time of the site visit the subject property contained a large former industrial building, broken into several office, process, production and storage areas.

5.02 *Hazardous Substances in Connection with Identified Uses*

During the August 4, 2015 site visit, staining was visible on the surface of the floor in the former process area. A room which formerly contained tanks was in poor condition, with peeling paint and pitted wall and ceiling surfaces. In the courtyard of the subject property, a number of 55-gallon drums containing unknown materials were observed and on the third floor of the building, a fiberglass vat was observed. Paperwork from the NYSDEC identified Rome-Turney as a CESQG, a handler and transporter of hazardous waste.

The material threat of release of petroleum and/or other hazardous materials stored at the subject property to the subsurface at the subject property is considered a REC.

5.03 *Underground Storage Tanks and Aboveground Storage Tanks*

During the August 4, 2015 site visit, an interview with a City of Rome representative indicated that USTs were removed from the subject property in the early 1990s, and aboveground storage tanks (ASTs) may have been located in a former process area in the central portion of the building.

The material threat of release of petroleum and/or other hazardous materials stored at the subject property to a human receptor and/or the subsurface at the subject property is considered a REC.

5.04 *Indications of Polychlorinated Biphenyls (PCBs)*

During the August 4, 2015 site visit, four pole-mounted transformers were observed at the subject property. Due to their approximate age, these transformers may contain PCBs. Historic mapping also indicated a transformer house on the southeast section of the subject property.

The potential presence of PCB-containing transformers at the subject property is considered a BER.

5.05 *Indications of Solid Waste Disposal*

The building is currently vacant. No solid waste disposal occurs at the subject property at this time. Various debris, including but not limited to household materials, clothing, furniture, building materials, rolls of material, kitchen grease, cardboard, paperwork and office supplies were observed in piles throughout the building at the time of the site reconnaissance. Some of the unknown materials appeared to be dumped in the building from unknown parties and did not appear to be connected with building operations. Solid waste disposal of unknown materials has occurred inside the building at the subject property. This solid waste is considered a REC.

5.06 *Other Conditions or Concerns*

During the site visit, a courtyard area was observed on the west side of the subject property building. The area contained steel framing from a former building or addition to the current building at the subject property. This building may have been demolished or ruined by fire in the past.

6.0 BUSINESS ENVIRONMENTAL RISK CONSIDERATIONS

This Phase I ESA has included an evaluation of factors that could pose a business environmental risk based on the present day (August 2014) use of the property. These issues are supplemental to the ASTM 1527-13 Standard Practice. The following Business Environmental Risks (BERs) were identified during this Phase I ESA:

Potential presence of LBP, ACM and PCBs are considered BERs. Based on the date of construction and items observed during the site reconnaissance, LBP may be present in painted surfaces in the former Rome-Turney Radiator building, ACM may be present in various items throughout the building and PCBs may be present in transformers formerly and currently on the subject property. A Hazardous Waste/Contaminated Materials (HW/CM) survey is recommended prior to renovation or demolition of the building, in accordance with local, State, and Federal regulations. Section 7.1 of this Phase I ESA presents the BERs for the subject property.

6.01 *Environmental Regulatory Compliance*

Bergmann did not complete a regulatory compliance assessment for the subject property; however, the following issues related to regulatory compliance were noted during this Phase I ESA. A Subsurface Investigation was required by the NYSDEC to be completed at the subject property to close Spill Number 8802056. As of the date of this report, the Subsurface Investigation was not completed to the satisfaction of the NYSDEC and this petroleum spill remains active.

Historic mapping of the subject property shows an area on the southern portion of the subject property containing a 10,000 gallon UST from at least 1914 until at least 1971. This tank is not listed on the NYSDEC petroleum bulk storage (PBS) registered tank list for the subject property.

6.02 *Asbestos Containing Materials*

An ACM survey was not conducted as part of this Phase I ESA. Based on the age of the building and items observed within the building during the site reconnaissance, ACM is suspected to exist within building materials. The potential for ACM to exist at the subject property is a BER.

All materials determined or assumed to be asbestos containing must be removed by a licensed asbestos abatement contractor in accordance with New York State Asbestos Regulations 12NYCRR Part 56.

6.03 *Lead Based Paint*

A LBP survey was not conducted as part of this Phase I ESA. Based on the age of the building and items observed during the site reconnaissance, LBP may have been used during construction. The potential presence of LBP at the subject property is considered a BER.

6.04 *On-Site Radon*

The U.S. EPA Action limit for indoor Radon is 4.0 pCi/L. Area Radon information for Oneida County indicates that 86% of living areas screened fall below 4 pCi/L, 13% of living areas screened fall between 4 and ≤20 pCi/L and 1% exceed 20pCi/L. Area Radon information for Oneida County indicates that 69% of basements screened fall below 4 pCi/L, 27% of basements screened fall between ≥4 and ≤20 pCi/L and 4% exceed 20pCi/L.

The potential for radon gas to enter the existing building at the subject property and potential future buildings is considered a REC.

6.05 *Vapor Encroachment*

A vapor encroachment survey (VES) was not conducted as part of this Phase I ESA. The potential for soil vapor encroachment from adjoining properties and soil vapor intrusion into future on-site buildings exists due to the former use of the subject property as an industrial and manufacturing facility with bulk storage of petroleum and hazardous materials.

The potential for soil vapor encroachment and vapor intrusion into the current and future buildings at the subject property is considered a REC.

6.06 *Indoor Air Quality*

Indoor Air Quality was not evaluated as part of this Phase I ESA. Future indoor air quality may be impacted by vapor encroachment and vapor intrusion, as described above.

6.07 *Lead in Drinking Water*

The subject property is connected to a municipal water supply system. Lead in drinking water is not considered to be a risk consideration for the subject property.

6.08 *High Voltage Power Lines*

High voltage power lines were not observed on the subject property.

6.09 *Cultural, Historic and Archeological Resources*

A review of potential adverse impact to cultural, historic and archaeological resources was conducted. Cultural, historic and archaeological resources are not known or have not been identified at or are adjacent to the subject property based on the information reviewed. Therefore, cultural, historic and archaeological resources should not be impacted by the proposed development and are not considered to be a risk consideration.

6.10 *Wetlands and Surface Waters*

The NYSDEC Environmental Resource Mapper online application was reviewed to determine the presence of wetlands on our around the subject property. Wetlands are not indicated on the subject property based on the information obtained through the application.

6.11 *Threatened, Endangered and Other Protected Species*

The NYSDEC Environmental Resource Mapper online application was reviewed to determine the presence of threatened, endangered and other protected species on or around the subject property. Threatened, endangered and other protected species were not indicated on the subject property based on the information obtained through the application.

6.12 *Wildlife Sanctuaries and Other Natural Resource Preserves*

A review of potential adverse impact to wildlife sanctuaries and other natural resource preserves was conducted. Local, State or Federal Sanctuaries or other natural resource preserves are not known or have not been identified at or are adjacent to the subject property.

6.13 *Biological Agents*

Biological agents were not observed within the on-site building or in the outdoor areas of the subject property at the time of the site visit.

6.14 *Mold*

Mold was observed throughout the former Rome-Turney building at the time of the site reconnaissance.

The presence of mold within the building at the subject property is considered a BER.

6.15 *Potential Impacts/Implications of Environmental Issues for Site Development and Construction*

Prior to any building renovation or demolition, a subsurface investigation should be completed to address the active NYSDEC petroleum spill. Contaminated soil and groundwater remediation is likely required to address this spill. A Hazardous Waste/Contaminated Materials (HW/CM) survey should be conducted to identify building materials suspected to contain ACM and LBP. Prior to site occupancy, a radon and soil vapor intrusion survey should be conducted.

7.0 PHASE I ESA FINDINGS AND OPINION

7.01 *Findings*

Bergmann Associates completed a Phase I Environmental Site Assessment (ESA) Report of the former Rome-Turney building at 109 Canal Street in the City of Rome, Oneida County, New York, in conformance with the scope and limitations of ASTM Practice E 1527-13 *Standard Practice for Environmental Site Assessments*. This Phase I ESA was also conducted in accordance with the US EPA All Appropriate Inquiry (AAI).

The following Business Environmental Risks (BERs) were identified for the subject property:

1. Possible presence of Lead Based Paint. Based on the date of construction and items observed during the site reconnaissance, LBP may be present in painted surfaces in the building at the subject property.
2. Asbestos Containing Materials. Based on the date of construction and items observed during the site reconnaissance, ACM may be present within the building at the subject property.
3. Polychlorinated Biphenyls. During the August 4, 2015 site visit, four pole-mounted transformers were observed at the subject property. Due to their approximate age, these transformers may contain PCBs. Historic mapping also indicated a transformer house on the southeast section of the subject property.
4. Mold. Mold was observed throughout the building at the subject property during the time of the site visit.

The following recognized environmental conditions (RECs) were identified for the subject property:

1. Former Industrial Operations. According to historic research and owner-provided information, the property formerly operated as the Rome-Turney Radiator Company and has since been operated by Rome-Turney and multiple other industrial and manufacturing operations dating back to the early 1900s. The material threat of release of petroleum and/or other hazardous materials associated with industrial and manufacturing operations to the subsurface at the subject property is considered a REC.
2. Petroleum and Hazardous Materials Storage. According to historic research and observations made during the site reconnaissance, petroleum and hazardous materials were formerly or are currently stored at the subject property. The material threat of release of petroleum and/or other hazardous materials stored at the subject property to human receptors and/or the subsurface at the subject property is considered a REC.
3. Remaining Soil and Groundwater Contamination. According to historical research, a Subsurface Investigation was required by the NYSDEC to be completed at the subject property to close Spill Number 8802056. As of the date of this report, the Subsurface Investigation was not completed to the satisfaction of the NYSDEC. The potential presence of remaining soil and groundwater contamination at the subject property from a historic spill which was not closed is considered a REC.

4. Adjoining Properties. A gasoline station, industrial properties and a car wash were formerly or are currently adjoining the subject property. The material threat of migration of hazardous substances to the subsurface at the subject property through groundwater and/or vapor encroachment from adjacent properties is considered a REC.
5. Historic Tannery Land Use. According to an interview conducted with the City of Rome representative, the subject property formerly operated as a tannery. The material threat of a release of chemicals and wastes associated with historic tanning operations is considered a REC.
6. Solid Waste Disposal. Solid waste disposal of unknown materials has occurred inside the building at the subject property in various locations. This solid waste is considered a REC.
7. Radon. The potential for radon gas to enter the existing building at the subject property and potential future buildings is considered a REC.
8. Soil Vapor Encroachment. A vapor encroachment survey (VES) was not conducted as part of this Phase I ESA. The potential for soil vapor encroachment into future on-site buildings exists due to the former use of the subject property as an industrial and manufacturing operation and the bulk storage of petroleum and/or hazardous materials. The potential for soil vapor encroachment into the current and future buildings at the subject property is considered a REC.

7.02 *Opinion*

En**v**ironmental site assessments cannot completely eliminate uncertainty regarding the potential for the presence of recognized environmental conditions in connection with a property. In our opinion the recognized environmental conditions at the subject property as described in this Phase I ESA Report have been identified based on our Phase I ESA project work.

In our opinion, the subsurface at the subject property has been impacted by releases of petroleum products and hazardous materials and current and future buildings on the subject property are suspect for potential radon, soil vapor intrusion and soil vapor encroachment, based on the identified RECs above.

7.03 *Recommendations*

Bergmann recommends the performance of a subsurface investigation at the subject property including surface and subsurface explorations to evaluate soil and groundwater quality conditions, to satisfy requirements set forth by the NYSDEC for the subject property and RECs identified in this Phase I ESA. Subsurface explorations may include, but should not be limited to the installation of soil borings, groundwater monitoring wells, and test pits. Bergmann recommends the collection of environmental samples by an environmental professional and the analysis of samples by a New York State Environmental Laboratory Approval Program (NYS ELAP) certified laboratory.

Bergmann recommends the performance of a Hazardous Waste/Contaminated Materials survey to identify materials containing lead-based paint (LBP) and/or asbestos containing materials (ACM) and/or mold within the subject property building prior to occupancy, redevelopment or demolition. If materials are found to be positive for LBP, ACM or mold, Bergmann recommends the removal of such materials in accordance with all federal, state and local regulations. Bergmann also recommends the performance of a radon survey and a soil vapor encroachment survey on current and future buildings at the subject property.

7.04 *Statement of Reliance*

This report is certified to, can be relied upon by, and has been prepared for the exclusive use of the following entities: Bergmann Associates (As City of Rome Engineering Consultant); The City of Rome and their respective successors, assigns, affiliates, and subsidiaries. The named entities above can convey this report to an affiliate, related entity, subsidiary, lender, title insurer, regulatory/city agency or current property owner(s) and their agents, but further dissemination to other parties or persons requires prior written approval from Bergmann Associates.

7.05 *Significant Data Gaps*

Significant data gaps as defined by §312.10 of AAI Final Rule and §12.7 of ASTM E1527-13 include missing or unattainable information that affects the ability of the environmental professional to identify conditions indicative of releases or threatened releases of hazardous substances, and as applicable, pollutants and contaminants, petroleum or petroleum products, or controlled substances, on, at, in, or to the subject property.

Significant data gaps were not identified for this Phase I ESA.

8.0 SIGNATURES

The undersigned environmental professionals conducted this Phase I ESA as employees of Bergmann Associates. Neither the undersigned nor Bergmann Associates warrants information provided by others nor guarantees any future events or results. Neither the undersigned nor Bergmann Associates makes any warranty, guarantee, nor representation whatsoever upon any facts or conditions that for any reason were not observed by the undersigned during the execution of this Updated Phase I ESA.

The statements made in this Phase I ESA are true to the best of our knowledge and belief. We meet the definition of Environmental Professional as defined in §312.10 of the Federal All Appropriate Inquiries (AAI) Rule. We have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the subject property. We have developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.

Megan E. Borruso
_____
Bergmann Associates
Megan Borruso, Environmental Specialist
Phase I ESA Assessment

_____
Bergmann Associates
Stephen J. DeMeo, Senior Geologist
Phase I ESA QA/QC Reviewer


9.0 QUALIFICATIONS

The following summarizes the qualifications of the environmental professionals who conducted this Phase I ESA:

- **Megan Borruso** – Ms. Borruso is an Environmental Specialist with Bergmann Associates and has over 7 years of professional experience. Her responsibilities include the preparation of Phase I and II Environmental Site Assessments, collection of soil, groundwater, air, and soil vapor samples for laboratory analysis, compilation and tabulation of soil and groundwater analytical data. She is also responsible for conducting asbestos inspections and collecting asbestos samples for analysis prior to abatement. Ms. Borruso is also a GIS Analyst responsible for geographic information system (GIS) projects related to environmental work, including map creation and database management. Ms. Borruso has a Bachelor's degree in Geography and Environmental Studies from the State University of New York (SUNY) College at Geneseo and a Master's degree in Geography with an Advanced Certificate in GIS from the City University of New York (CUNY) Hunter College. She possesses a New York State Asbestos Inspector Certification.

- **Stephen J. DeMeo, P.G.** – Mr. DeMeo has over 30 years of experience on a wide range of environmental and geotechnical projects including soil and groundwater investigation and remediation, environmental site assessments, compliance, and risk-based assessments. His remediation experience includes full scale remedial design and implementation, including soil vapor extraction, bioremediation, groundwater pump-and-treat, and low temperature thermal treatment. He has also provided geologic expertise for geotechnical engineering projects involving soil and rock tunnels, pipelines, highways, utilities, dams, and deep foundations. Listed below is selected project experience. Mr. DeMeo is a licensed professional Geologist in the States of Pennsylvania and Delaware.

FIGURES



Bergmann associates
architects // engineers // planners

Phase I ESA – Former Rome-Turney Radiator Co.
109 Canal Street Rome, NY
Figure 1 – Property Location Map

Figure 1

USGS 7.5 Minute Series, Rome NY Quadrangle, 2013



Phase I ESA - Former Rome-Turney Radiator Company: 109 Canal Street Rome, NY

FIGURE 2 - Site Boundary Map

N


0 25 50 100

Feet

Bergmann associates

architects // engineers // planners

J:\Current Projects\Rome\13116.00 CITY OF ROME - STEP 3 ROAR_Reports\Environmental\Phase I ESA 109 Canal Street\Site Plan.mxd



Phase I ESA - Former Rome-Turney Radiator Company: 109 Canal Street Rome, NY

FIGURE 3 - Building Plan

N

0 25 50 100

Feet

Bergmann associates

architects // engineers // planners

J:\Current Projects\Rome\3118.00 CITY OF ROME - STEP 3 NOAA Reports\Environmental\Phase I ESA 109 Canal Street\Site Plan.mxd

PHOTOGRAPHS




General view of subject property from Canal Street.




General view of subject property from west.



General view of receiving & shipping area.



Debris pile in receiving & shipping area.



Robbins & Myers hoist in receiving & shipping area.



Debris in in receiving & shipping area.




Building material in collapsed warehouse section.



Suspect ACM pipe near collapsed warehouse area.



Remainder of warehouse area.



Window in warehouse area.



Empty welding electrodes rods and fluxes drum.



Floor staining and pipe remnants in northwest corner of warehouse.



General view of eastern production shop.



4’x10’ pit in eastern production shop.



Stage, floor staining and Hetron® 922 Resin drum.



Metal floor tiling in eastern production shop.



Floor pit at the end of trench in eastern production area.



Pipe above trench in eastern production area.



Small floor pit in eastern production shop.



Floor spalling in eastern production shop.



General view of western production shop.



Trench in western production shop.



Floor of western production shop.




General view of western production shop west of partition wall.



Floor drain in western production shop.



Former hazardous materials storage room.



Shop foreman office.



Fluorescent light bulb and ballast in shop foreman office.



Kitchenette in shop foreman office area.



Shop foreman office area.



Former tank location in production area.



Ceiling of production area.



Northwest corner of production area.



Floor pit in northwest corner of production area.



Machine room with debris pile – northern half of room.



Machine room – southern half of room.




Elevator with fire doors in machine room.



Empty drum in machine room.



Office area.



Office area.



Carboys in office area.



Floor pit in office area.



General view of second floor office area.



General view of second floor office area.



Vermiculite in ceiling of second floor office area.



Wood molds in plan room.



Household debris above eastern production room.



Fiberglass vat in second floor above eastern production room.



General view of room above plan room (third floor).



General view of room above plan room (third floor).



Courtyard an elevator shaft from south.



Groundwater monitoring well in courtyard of subject property.



Drum in courtyard of subject property.



Drums in courtyard of subject property.



Fire box near driveway on south side of subject property.



Fire standpipe near driveway on south side of subject property.



Pump station north of subject property.



Drugstore north of subject property.



Residential buildings south of subject property.



Vacant lot south of subject property.



Erie Boulevard and hotel east of subject property.



Industrial building west of subject property.

APPENDIX A

SITE FORMS

Bergmann associates
architects // engineers // planners

Interview Form

Site Name Former Rome-Turney
Site Location 109 Canal St. Rome NY

Bergmann Project # 10118.00

Interviewee Dennis Gillen **Date** 8/4/15
Connection to subject property City of Rome Rep.

Asked the interviewee to answer in "good faith and to the extent of their knowledge".

Ownership Rome-Turney From: 1930's To: 200's - late (2008?)

Previous Owners? Tannery. Rollerad.

Occupants or operations onsite? Vacant. Former industrial.

Site Use Vatant

Site History Industrial - Rome Turney Radiator Co.
Rollerad
Casket Company
Tannery.

Any evidence or past use of hazardous substances or petroleum products used or stored on the property?
Yes. Petro. Products in tanks - removed. (2)

Pits, Lagoons or Ponds.	(Y) or N	Pools of Liquid	Y or (N)
Stained Soils	Y or (N)	Odors	Y or (N)
Stressed Vegetation	Y or (N)	Stains or Corrosion	Y or (N)
Solid Waste	(Y) or N Dumping	PCB's	Y or (N) Not known
Waste Water	Y or (N)	Storage Tanks	(Y) or N Former
Wells	Y or (N)	Drums	(Y) or N
Septic System	Y or (N)	Drains or Sumps	(Y) or N

Adjoining property uses? (gas station...) Former gas station to North, Former industrial surrounding property.
(past uses)

Haz Substances or Petrol potential to migrate onto the subject property? Possible from ↑

Materials/Drums buried onsite? Unknown.

Previous use of the property? Industrial

Environmental Cleanup Liens? Unknown

Any known spills/emergency response? Yes - 1 spill - open - NYSDEC requires more investigation

Misc:

Potential buyers - manuf. use possible(?)

Site investigation - NYSDEC EDIL info provided - Renew.

SITE OBSERVATIONS
(Confidential and Private)

Job No.: 10118.00 Date: 8/4/15 Assessor Name: M. Barruso

Property Address: 109 Canal Street - Rome, NY

(Provide a sketch of the property at a minimum)

Persons Present/Title/Tenure: Dennis Gillen, City of Rome
Megan Barruso, Bergmann Assoc.
Josh Maerschner, Bergmann Assoc.

Locality: (Circle one) (Urban), Suburban, Rural
Highly, Moderately, Lightly - Developed
(Industrial), Commercial, Agricultural, Residential, Wooded, Fallow, Vacant

No. of acres: 1.5 Frontage: _____ Depth: _____ Zoning: 710- Manufacturing

GROUND SURFACES:

Fill materials: yes/no/type Unknown.
Debris/Dumping: (yes)/no/type Solid Waste in building - household, bldg materials, furniture, etc.
Spills/Staining: (yes)/no floor staining in Process areas
Stressed Vegetation: yes/(no)
Odors: yes/(no)
Pools of Liquid: (yes)/no In elevator shaft and in floor pit - Production Room.
Pits/Ponds/Lagoons: yes/no Various floor pits.
Wastewater discharge: yes/(no) Unknown for past operations
Sheen (location): Not observed
Trees _____ Landscaping _____ Green Area Small yard on E. Side.

UTILITIES:

Transformers: number: 4
Location on property: East side
(Pole-mounted) or pad-mounted
Client owned or utility owned Unknown.
Suspect PCB-containing equipment: (yes) / no / unknown

Utility services by: Vacant building, no services. Formerly →

Natural gas	X		
Electric	X		
Telephone	X		
Sewer	X	Date of Connection:	Unknown
Septic		Location on Property:	
Water	X	Date of Connection:	
Well		Location on Property:	

BUILDING:

No. of stories Various - 3 max Square Foot 55,000
Age of Construction 1930 (?)
Additions Newer Sections added - unknown date

Structure: block/poured concrete X brick
steel X wood/stick
siding (type)
flat / peaked roof condition Fair.

Current Heating System: None - Vacant
Past Heating System: Natural gas
Floor drains: yes / no discharge point Unknown!
Sump pumps: ~~yes~~ / ~~no~~ discharge point May have had previous - production Area
Catch basins: ~~yes~~ / ~~no~~ discharge point Unknown
Dry wells: yes / ~~no~~ discharge point Unknown

Current on-site operations: Vacant
Past on-site operations: Industrial / Manufacturing
Former Rome - Turney Radiator Co.

ASBESTOS: Former Tannery

Was asbestos evaluated as part of this assessment? Yes No
Does the age of the building suggest the presence of asbestos? Yes No
Has the building been renovated? Yes No Partial - additions.

ACM survey not conducted.

Floor materials: 9" x 9" 12" X 12"
Rolled vinyl flooring stair treads

Ceiling tiles: 1' x 1' 2' x 2'
2' x 4' Spray-on

Drywall/Plaster
Pipe Wrap
Base Cove
Roofing

TSI
Boiler TSI
Transite

Condition of materials:

WASTES - Not currently generated - vacant building

Solid: type _____
container _____
collector _____

Recycling: type _____
container and location _____
collector _____

Other: type _____
container and location _____
collector _____

type _____
container and location _____
collector _____

PERMITS (air, water, etc.):
(copies available)
Unknown.

EQUIPMENT:
5-ton Robbins + Meyers Hoist Shipping / Recieving area.

ADJOINING PROPERTIES:
(Photo's)
North: Walgreens, Pump Station, Railroad
South: Residential, Vacant lot
East: Erie Blvd, Hotel
West: Industrial Bldg.

GENERATORS OR COMPRESSORS (fuel source; spills)
Not observed.

STORAGE TANKS:

AST/UST's Former USTs - 5,000 gal - removed
(Get copies of plans for tank location.)

USTs	Capacity	Product	Location on Property
Tank 1		Unknown	remaining tank (s)
Tank 2			
Tank 3			

Staining, Stressed or Dead Vegetation Not observed

Odors Detected Not observed

Tanks Registered former tanks were registered

(Copies of registrations available)

Any tanks removed from the property yes.

Contractor/date Industrial Oil Co.

HAZARDOUS MATERIALS:

Stored on-site yes. Used on-site Yes

MSDS on-site yes / no

List materials (type, size of containers, spills, odors, etc.)
Resins, ~~acetone~~, lead, acetone, Xylenes, assorted aerosols.

Evidence of Spillage/Leakage:
Yes - Staining on floor surfaces throughout bldg.

ADDITIONAL NOTES:

Recieving / Shipping: Debris pile, Hoist, 2nd debris pile, welding equip.

Warehouse: 1st section collapsed - ± 3 yrs ago.

2nd section - ACM pipe / Window glaze

- Pipe in floor - Process area?

- Cardboard drum - empty

Production Shop - East - Trench along E. wall → pipe above. Pit @ end.

Floor pits, Floor stripping, 55-gal drum - Resin

Staining floor - metal floor tiles 9x15. ACM windows.

Production Shop - West - Trench leading to drain in floor. 8" (2)

Floor staining / mold / debris / vandalism. 4CM windows.

Office / Kitchen - Fluorescent bulbs, mold, bldg. materials.

Locker Rm - vandalized, Ceiling looks pitted in places.

Production Area - Former tank location? Walls + Ceiling stained / pitted / peeling

Floor Pits (2) - water in / Windows.

Machine Rm - Debris, Kitchen grease in carboys, Elevator - Fire doors → goes up 3 floors Each have Fire Doors.

office - Black carboys - Floor pit, household storage

- 2nd Floor - debris - paperwork, office supply - drum.

- Plan Rm - wood molds

Fiberglass Vat in Room above production area - Debris - household + clothing

- 3rd Floor - debris - many windows ACM?

Roof - visible from 3rd Floor - looks ok. - ACM?

Signature of Assessor: Megan E Bergmann

APPENDIX B

EDR DATABASE REPORT



Rome Turney
109 Canal Street
Rome, NY 13440

Inquiry Number: 4366780.2s
July 28, 2015

The EDR Radius Map™ Report with GeoCheck®

EDR® Environmental Data Resources Inc

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	8
Orphan Summary	272
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting SSURGO Soil Map	A-5
Physical Setting Source Map	A-9
Physical Setting Source Map Findings	A-11
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2015 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-13) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

109 CANAL STREET
ROME, NY 13440

COORDINATES

Latitude (North):	43.2084000 - 43° 12' 30.24''
Longitude (West):	75.4583000 - 75° 27' 29.88''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	462770.1
UTM Y (Meters):	4783844.5
Elevation:	439 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	5938529 ROME, NY
Version Date:	2013

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20110716
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
109 CANAL STREET
ROME, NY 13440

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1	ROME TURNEY RADIATOR	109 CANAL ST	LTANKS		TP
A2	ELEGRACE CASKET COMP	109 CANAL ST	FINDS		TP
A3	ROME TURNEY RAD CO	109 CANAL STREET	UST		TP
4	TRAVEL INN	145 EAST WHITESBORO	LTANKS	Higher	131, 0.025, ESE
B5		217 S JAMES ST	EDR US Hist Auto Stat	Higher	239, 0.045, NW
C6	ROME ELECTRONICS, IN	216 ERIE BOULEVARD E	UST, HIST UST	Higher	244, 0.046, SE
B7	BOUTON PHYSICAL THER	221 S JAMES ST	LTANKS	Higher	256, 0.048, WNW
B8	VACANT WAREHOUSE	102-104 FRONT ST	UST	Higher	256, 0.048, NNW
B9	BEHIND WALGREENS	201 SOUTH JAMES STRE	NY Spills	Higher	257, 0.049, NNW
B10	BEHIND WALGREENS	201 SOUTH JAMES STRE	NY Spills	Higher	257, 0.049, NNW
B11	VACANT WAREHOUSE	102-104 FRONT STREET	NY Spills	Higher	262, 0.050, NNW
B12	J A CAR WASH	229 S JAMES ST	RCRA NonGen / NLR, FINDS, ERP, LTANKS, UST, HIST...	Higher	268, 0.051, WNW
B13	J A CAR WASH	229 S JAMES ST	MANIFEST	Higher	268, 0.051, WNW
D14	AM/PM MINI MARKET	NORTH JAMES ST	NY Spills	Higher	292, 0.055, North
B15	ROME F.D.	200 SOUTH JAMES PARK	NY Spills	Higher	300, 0.057, NW
16	VALVOLINE QUICK CHAN	176 BLACK RIVER BLVD	NY Spills	Higher	321, 0.061, ENE
D17	SE CORNER OF JAMES S	131-37 SOUTH JAMES S	BROWNFIELDS	Higher	328, 0.062, North
D18	SUNOCO #0353-2254	131 SOUTH JAMES STRE	NY Spills	Higher	328, 0.062, North
D19	APLUS FACILITY #6000	131 SOUTH JAMES ST	LTANKS	Higher	331, 0.063, North
D20	SUNOCO #0363-2254	131 SOUTH JAMES & ER	UST, HIST UST	Higher	346, 0.066, North
D21	NEW WALGREENS CONSTR	SOUTH JAMES AND ERIE	NY Spills	Higher	353, 0.067, North
D22	AM/PM MINI MART	5 JAMES & ERIE BLVD	LTANKS	Higher	384, 0.073, North
C23	U-HAUL	244 ERIE BLVD EAST	NY Spills	Higher	389, 0.074, SE
C24	U HAUL	244 ERIE BLVD EAST	UST, HIST UST	Higher	389, 0.074, SE
C25	REVERE PRINTING	100 BOUCK STREET	UST	Higher	399, 0.076, SE
C26	REVERE PRINTING INC	100 BOUCK ST	RCRA-CESQG, FINDS, HIST UST, MANIFEST, NY Spills	Higher	399, 0.076, SE
D27	ARCO PETROLEUM PRODU	ST JAMES & ERIE	RCRA NonGen / NLR, MANIFEST	Higher	403, 0.076, NNE
D28	UNKNOWN	SOUTH JAMES ST & ERI	NY Spills	Higher	403, 0.076, NNE
D29	ROUTE 49/69	COR. NYS ROUTE 49 &	NY Spills	Higher	466, 0.088, NNW
E30	AGWAY ROME FEED CO-O	312 S JAMES ST	NY Spills	Lower	475, 0.090, West
E31	ROME AGWAY COOP INC	312 S JAMES ST	RCRA NonGen / NLR, FINDS, MANIFEST	Lower	478, 0.091, West
E32	AGWAY, INC.	312 SOUTH JAMES STRE	UST, HIST UST	Lower	478, 0.091, West
F33	METH LAB DISPOSAL SI	RAILROAD ST / BOUCK	NY Spills	Higher	489, 0.093, East
F34	NIMO EXCAVATION	BOUCK & RAILROAD ST	NY Spills	Higher	490, 0.093, East
G35	KEMP TRUCK REPAIR	CANAL STREET	NY Spills	Higher	580, 0.110, SSE
E36	ROME AGWAY COOP INC	300 WEST STREET	UST, HIST UST, AST, HIST AST	Higher	583, 0.110, West
G37	C.A. KEMP OIL HEATIN	250 ERIE BOULEVARD E	HIST UST, HIST AST	Higher	594, 0.112, SSE
G38	C.A. KEMP OIL HEATIN	250 ERIE BOULEVARD E	UST	Higher	594, 0.112, SSE
G39	C.A. KEMP OIL HEATIN	250 ERIE BOULEVARD E	AST	Higher	594, 0.112, SSE

MAPPED SITES SUMMARY

Target Property Address:
109 CANAL STREET
ROME, NY 13440

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
G40	KEMP OIL HEATING COR	250 ERIE BLVD. EAST	NY Spills	Higher	594, 0.112, SSE
H41	NORSTAR BANK UPSTATE	ROME TRUST OFFICE	UST, HIST UST	Higher	603, 0.114, NNW
E42	NIMO	SO JAMES ST @ LAWREN	NY Spills	Lower	625, 0.118, WSW
E43		319 WEST ST	EDR US Hist Auto Stat	Lower	673, 0.127, West
I44	ROME(C) PUMP STATION	ERIE BLVD. & BLACK R	UST	Higher	712, 0.135, ENE
I45	ROME PUMP STATION	ERIE & BLACK RIVER B	LTANKS	Higher	712, 0.135, ENE
H46	ROME(C) CITY HALL	198 NORTH WASHINGTON	UST, HIST UST	Higher	741, 0.140, NNW
J47	TRANSFIGURATION CHUR	111 RIDGE STREET	UST	Lower	830, 0.157, WSW
K48	ROME IRON GROUP, LTD	412 CANAL STREET	UST	Higher	966, 0.183, SSE
K49	R & S STEEL,LLC	412 CANAL ST	RCRA-SQG, FINDS, MANIFEST	Higher	966, 0.183, SSE
K50	ROME IRON GROUP LTD	416 CANAL ST	RCRA NonGen / NLR, FINDS, MANIFEST	Higher	974, 0.184, SSE
K51		416 CANAL ST	EDR US Hist Auto Stat	Higher	974, 0.184, SSE
52	AGWAY	SOUTH JAMES ST	LTANKS	Lower	987, 0.187, WSW
53	ROME BULK MATERIAL (	LIBERTY PLAZA	SWF/LF	Higher	997, 0.189, NW
K54		428 CANAL ST	EDR US Hist Auto Stat	Lower	998, 0.189, SSE
55	IN FRONT OF PLAZA RE	229 EAST DOMINICK ST	LTANKS	Higher	1001, 0.190, East
J56	TRANSFIGURATION CHUR	111 RIDGE RD	LTANKS	Lower	1026, 0.194, WSW
57	NOLAN,HAYES & ADOLFI	LIBERTY ST-ROME CITY	LTANKS	Higher	1061, 0.201, North
58	SEARS OIL CO	7064 LADO AVE	RCRA-CESQG, FINDS, LTANKS, MANIFEST, NY Spills	Lower	1112, 0.211, East
L59	NIMO - ROME: KINGSLE	KINGSLEY AVENUE	EDR MGP	Lower	1113, 0.211, ESE
60	NYS DOT/BRIDGE MAIN.	WHITESBORO STREET	UST, HIST UST	Higher	1188, 0.225, SSE
61	ROME ANIMAL CONTROL	112 WEST LIBERTY STR	LTANKS	Higher	1236, 0.234, NNE
L62	NIMO, ROME (KINGSLEY	KINGSLEY AVE.	HSWDS	Lower	1244, 0.236, ESE
63	TAMBURINO FACILITY	230 RIDGE STREET	UST, HIST UST, NY Spills	Higher	1269, 0.240, West
M64		120 BLACK RIVER BLV	EDR US Hist Cleaners	Higher	1303, 0.247, ENE
M65	ROME (C) FIRE DEPT.	168 BLACK RIVER BLVD	LTANKS	Higher	1313, 0.249, NE
M66	ROME(C) CENT. FIRE S	158 BLACK RIVER BLVD	LTANKS	Higher	1313, 0.249, NE
67	NM - ROME KINGSLEY A	KINGSLEY AVENUE	SHWS	Lower	1361, 0.258, ESE
68	ROME CITY HALL	LIBERTY ST	LTANKS	Higher	1460, 0.277, North
69	VERIZON NEW YORK INC	137 NORTH WASHINGTON	LTANKS, TANKS	Higher	1563, 0.296, North
N70	FORMER INLAND FUELS	701 LAWRENCE STREET	US BROWNFIELDS	Higher	1587, 0.301, NNE
71	OPPER'S	301 ERIE BLVD WEST	LTANKS, UST, HIST UST, NY Spills	Lower	1611, 0.305, NW
N72	CITY OF ROME PD	301 NORTH JAMES ST	LTANKS	Higher	1718, 0.325, NNE
N73	POLICE STATION	301 N JAMES ST	LTANKS	Higher	1718, 0.325, NNE
O74	FRANK'S SUNOCO SERVI	612 SOUTH JAMES STRE	LTANKS, UST, HIST UST	Lower	1738, 0.329, SW
O75	KOTARY MOTORS	E WRIGHT ST	LTANKS	Lower	1806, 0.342, SW
P76	ROSSI SITE WITHIN EA	MILL STREET/RAILROAD	ERP, INST CONTROL	Higher	1870, 0.354, ESE
P77	EAST ROME BUSINESS P	MILL STREET/RAILROAD	ERP	Higher	1870, 0.354, ESE
78	ROME DPW (INSIDE)	RACE ST	LTANKS	Lower	1892, 0.358, ESE

MAPPED SITES SUMMARY

Target Property Address:
109 CANAL STREET
ROME, NY 13440

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
P79	OLD GENERAL CABLE	MILL ST	CERCLIS	Higher	1901, 0.360, ESE
80	SEARS REALTY CO. INC	201 NORTH GEORGE ST	LTANKS	Higher	1970, 0.373, NNW
81	ROME(C) HIGH LEVEL P	ERIE & BLACK RIVER B	LTANKS	Lower	1988, 0.377, South
82	DECARLIS RES	118 WEST SOUTH	LTANKS	Lower	2023, 0.383, SW
Q83	ROME(C) DPW/VIP TRAN	132 RACE STREET	LTANKS, NY Spills	Lower	2157, 0.409, SE
Q84	ROME CITY OF D P W	132 RACE ST	RCRA-CESQG, FINDS, SWF/LF, HIST UST, AST, NY...	Lower	2170, 0.411, SE
85	GURLEY & FLEET	301 BLACK RIVER BLVD	LTANKS	Higher	2251, 0.426, NE
86	GANESZOORT ELEM. SCH	LIBERTY ST	LTANKS	Higher	2259, 0.428, NNW
87	WALSH RESIDENCE	108 WEST EMBARGO STR	LTANKS	Higher	2259, 0.428, NNE
88	LYNN H. SCOTT, INC.	300 WEST COURT ST	LTANKS, NY Spills	Higher	2325, 0.440, North
89	KEKIS MOBIL SERVICE	400 WEST DOMINICK ST	LTANKS	Higher	2338, 0.443, NW
90	KEMP OIL SITE	PO BOX 803	LTANKS	Lower	2435, 0.461, SE
91	FORMER ROME CABLE SI	421 RIDGE STREET	ERP, NY Spills	Lower	2444, 0.463, WNW
R92	GARCIA RESIDENCE	735 SOUTH JAMES ST	LTANKS	Lower	2511, 0.476, SW
R93	LEE BATES & SONS	736 SOUTH JAMES STRE	LTANKS	Lower	2523, 0.478, SW
94	NIMO - ROME-JAY AND	106 SO. MADISON ST A	EDR MGP	Lower	2526, 0.478, NW
95	EAST ROME INDUSTRIAL	ROME INDUSTRIAL CENT	US BROWNFIELDS	Higher	2614, 0.495, NNE

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 8 of the attached EDR Radius Map report:

Site	Database(s)	EPA ID
ROME TURNEY RADIATOR 109 CANAL ST ROME C, NY	LTANKS Program Number: 8802056 Spill Number/Closed Date: 8802056 / Not Reported Site ID: 225230	N/A
ELEGRACE CASKET COMP 109 CANAL ST ROME, NY 13440	FINDS Registry ID:: 110019481880	N/A
ROME TURNEY RAD CO 109 CANAL STREET ROME C, NY 13440	UST Id/Status:: 6-389331	N/A

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL ---------- National Priority List
Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Federal Delisted NPL site list

Delisted NPL ---------- National Priority List Deletions

Federal CERCLIS list

FEDERAL FACILITY ---------- Federal Facility Site Information listing

Federal CERCLIS NFRAP site List

CERC-NFRAP ---------- CERCLIS No Further Remedial Action Planned

Federal RCRA CORRACTS facilities list

CORRACTS ---------- Corrective Action Report

EXECUTIVE SUMMARY

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Federal RCRA generators list

RCRA-LQG ---------- RCRA - Large Quantity Generators

Federal institutional controls / engineering controls registries

US ENG CONTROLS ---------- Engineering Controls Sites List
US INST CONTROL ---------- Sites with Institutional Controls
LUCIS ---------- Land Use Control Information System

Federal ERNS list

ERNS ---------- Emergency Response Notification System

State- and tribal - equivalent CERCLIS

VAPOR REOPENED ---------- Vapor Intrusion Legacy Site List

State and tribal leaking storage tank lists

HIST LTANKS ---------- Listing of Leaking Storage Tanks
INDIAN LUST ---------- Leaking Underground Storage Tanks on Indian Land

State and tribal registered storage tank lists

TANKS ---------- Storage Tank Faciliy Listing
CBS UST ---------- Chemical Bulk Storage Database
MOSF UST ---------- Major Oil Storage Facilities Database
CBS AST ---------- Chemical Bulk Storage Database
MOSF AST ---------- Major Oil Storage Facilities Database
MOSF ---------- Major Oil Storage Facility Site Listing
CBS ---------- Chemical Bulk Storage Site Listing
INDIAN UST ---------- Underground Storage Tanks on Indian Land
FEMA UST ---------- Underground Storage Tank Listing

State and tribal institutional control / engineering control registries

ENG CONTROLS ---------- Registry of Engineering Controls
RES DECL ---------- Restrictive Declarations Listing

State and tribal voluntary cleanup sites

INDIAN VCP ---------- Voluntary Cleanup Priority Listing
VCP ---------- Voluntary Cleanup Agreements

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Landfill / Solid Waste Disposal Sites

DEBRIS REGION 9 ---------- Torres Martinez Reservation Illegal Dump Site Locations

EXECUTIVE SUMMARY

ODI	Open Dump Inventory
SWRCY	Registered Recycling Facility List
SWTIRE	Registered Waste Tire Storage & Facility List
INDIAN ODI	Report on the Status of Open Dumps on Indian Lands

Local Lists of Hazardous waste / Contaminated Sites

US CDL	Clandestine Drug Labs
DEL SHWS	Delisted Registry Sites
US HIST CDL	National Clandestine Laboratory Register

Local Lists of Registered Storage Tanks

HIST AST	Historical Petroleum Bulk Storage Database

Local Land Records

LIENS 2	CERCLA Lien Information
LIENS	Spill Liens Information

Records of Emergency Release Reports

HMIRS	Hazardous Materials Information Reporting System
NY Hist Spills	SPILLS Database
SPILLS 80	SPILLS 80 data from FirstSearch
SPILLS 90	SPILLS 90 data from FirstSearch

Other Ascertainable Records

DOT OPS	Incident and Accident Data
DOD	Department of Defense Sites
FUDS	Formerly Used Defense Sites
CONSENT	Superfund (CERCLA) Consent Decrees
ROD	Records Of Decision
UMTRA	Uranium Mill Tailings Sites
US MINES	Mines Master Index File
TRIS	Toxic Chemical Release Inventory System
TSCA	Toxic Substances Control Act
FTTS	FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
HIST FTTS	FIFRA/TSCA Tracking System Administrative Case Listing
SSTS	Section 7 Tracking Systems
ICIS	Integrated Compliance Information System
PADS	PCB Activity Database System
MLTS	Material Licensing Tracking System
RADINFO	Radiation Information Database
RAATS	RCRA Administrative Action Tracking System
RMP	Risk Management Plans
UIC	Underground Injection Control Wells
DRYCLEANERS	Registered Drycleaners
SPDES	State Pollutant Discharge Elimination System
AIRS	Air Emissions Data
E DESIGNATION	E DESIGNATION SITE LISTING
INDIAN RESERV	Indian Reservations
SCRD DRYCLEANERS	State Coalition for Remediation of Drycleaners Listing

PCB TRANSFORMER ..... PCB Transformer Registration Database
COAL ASH EPA ..... Coal Combustion Residues Surface Impoundments List
US FIN ASSUR ..... Financial Assurance Information
EPA WATCH LIST ..... EPA WATCH LIST
US AIRS ..... Aerometric Information Retrieval System Facility Subsystem
LEAD SMELTERS ..... Lead Smelter Sites
Financial Assurance ..... Financial Assurance Information Listing
COAL ASH ..... Coal Ash Disposal Site Listing
2020 COR ACTION ..... 2020 Corrective Action Program List
PRP ..... Potentially Responsible Parties
COAL ASH DOE ..... Steam-Electric Plant Operation Data

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA HWS ..... Recovered Government Archive State Hazardous Waste Facilities List
RGA LF ..... Recovered Government Archive Solid Waste Facilities List

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Federal CERCLIS list

CERCLIS: The Comprehensive Environmental Response, Compensation and Liability Information System contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

A review of the CERCLIS list, as provided by EDR, and dated 10/25/2013 has revealed that there is 1 CERCLIS site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
OLD GENERAL CABLE	MILL ST	ESE 1/4 - 1/2 (0.360 mi.)	P79	230

EXECUTIVE SUMMARY

Federal RCRA generators list

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 03/10/2015 has revealed that there is 1 RCRA-SQG site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
R & S STEEL,LLC	***412 CANAL ST***	***SSE 1/8 - 1/4 (0.183 mi.)***	***K49***	***138***

RCRA-CESQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-CESQG list, as provided by EDR, and dated 03/10/2015 has revealed that there are 2 RCRA-CESQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
REVERE PRINTING INC	***100 BOUCK ST***	***SE 0 - 1/8 (0.076 mi.)***	***C26***	***69***
Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
SEARS OIL CO	***7064 LADO AVE***	***E 1/8 - 1/4 (0.211 mi.)***	***58***	***171***

State- and tribal - equivalent CERCLIS

SHWS: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data come from the Department of Environmental Conservation's Inactive Hazardous waste Disposal Sites in New York State.

A review of the SHWS list, as provided by EDR, and dated 06/26/2015 has revealed that there is 1 SHWS site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
NM - ROME KINGSLEY A	KINGSLEY AVENUE	ESE 1/4 - 1/2 (0.258 mi.)	67	194

Class Code: Significant threat to the public health or environment - action required.
Site Code: 56266

State and tribal landfill and/or solid waste disposal site lists

SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the list.

A review of the SWF/LF list, as provided by EDR, and dated 06/24/2015 has revealed that there are 2 SWF/LF sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ROME BULK MATERIAL (	LIBERTY PLAZA	NW 1/8 - 1/4 (0.189 mi.)	53	167
Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
ROME CITY OF D P W	***132 RACE ST***	***SE 1/4 - 1/2 (0.411 mi.)***	***Q84***	***239***

State and tribal leaking storage tank lists

LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the LTANKS list, as provided by EDR, and dated 05/18/2015 has revealed that there are 34 LTANKS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
TRAVEL INN Program Number: 0508864 Spill Number/Closed Date: 0508864 / 11/30/2005 Site ID: 354544	145 EAST WHITESBORO	ESE 0 - 1/8 (0.025 mi.)	4	12
BOUTON PHYSICAL THER Program Number: 0409032 Spill Number/Closed Date: 0409032 / 6/15/2006 Site ID: 333670	221 S JAMES ST	WNW 0 - 1/8 (0.048 mi.)	B7	17
J A CAR WASH Program Number: 9109197 Spill Number/Closed Date: 9109197 / 10/22/2004 Site ID: 230487	***229 S JAMES ST***	***WNW 0 - 1/8 (0.051 mi.)***	***B12***	***26***
APLUS FACILITY #6000 Program Number: 0200885 Program Number: 8702667 Spill Number/Closed Date: 0200885 / 5/28/2002 Spill Number/Closed Date: 8702667 / 3/20/1990 Site ID: 225260 Site ID: 225261	131 SOUTH JAMES ST	N 0 - 1/8 (0.063 mi.)	D19	48
AM/PM MINI MART Program Number: 8500741 Spill Number/Closed Date: 8500741 / 5/28/1985 Site ID: 67857	5 JAMES & ERIE BLVD	N 0 - 1/8 (0.073 mi.)	D22	59
ROME PUMP STATION Program Number: 9201592 Spill Number/Closed Date: 9201592 / 11/12/1992 Site ID: 286462	ERIE & BLACK RIVER B	ENE 1/8 - 1/4 (0.135 mi.)	I45	126

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
IN FRONT OF PLAZA RE Program Number: 9605346 Spill Number/Closed Date: 9605346 / 8/28/1996 Site ID: 132762	229 EAST DOMINICK ST	E 1/8 - 1/4 (0.190 mi.)	55	168
NOLAN,HAYES & ADOLFI Program Number: 8600647 Spill Number/Closed Date: 8600647 / 4/29/1986 Site ID: 273463	LIBERTY ST-ROME CITY	N 1/8 - 1/4 (0.201 mi.)	57	170
ROME ANIMAL CONTROL Program Number: 0507336 Spill Number/Closed Date: 0507336 / 9/19/2005 Site ID: 352730	112 WEST LIBERTY STR	NNE 1/8 - 1/4 (0.234 mi.)	61	181
ROME (C) FIRE DEPT. Program Number: 9400388 Spill Number/Closed Date: 9400388 / 4/12/1994 Site ID: 79276	168 BLACK RIVER BLVD	NE 1/8 - 1/4 (0.249 mi.)	M65	191
ROME(C) CENT. FIRE S Program Number: 8702034 Program Number: 9309113 Spill Number/Closed Date: 8702034 / 4/29/1991 Spill Number/Closed Date: 9309113 / 6/15/1994 Site ID: 123170 Site ID: 68967	158 BLACK RIVER BLVD	NE 1/8 - 1/4 (0.249 mi.)	M66	192
ROME CITY HALL Program Number: 8702026 Spill Number/Closed Date: 8702026 / 9/29/1987 Site ID: 134468	LIBERTY ST	N 1/4 - 1/2 (0.277 mi.)	68	198
VERIZON NEW YORK INC Program Number: 8702204 Program Number: 9212037 Spill Number/Closed Date: 8702204 / 2/23/1990 Spill Number/Closed Date: 9212037 / 2/28/1995 Site ID: 208140 Site ID: 100740	***137 NORTH WASHINGTON***	***N 1/4 - 1/2 (0.296 mi.)***	***69***	***200***
CITY OF ROME PD Program Number: 9410599 Program Number: 9905328 Spill Number/Closed Date: 9410599 / 9/11/1997 Spill Number/Closed Date: 9905328 / 10/21/1999 Site ID: 142002 Site ID: 80997	301 NORTH JAMES ST	NNE 1/4 - 1/2 (0.325 mi.)	N72	213
POLICE STATION Program Number: 8705018 Spill Number/Closed Date: 8705018 / 2/15/1991 Site ID: 230110	301 N JAMES ST	NNE 1/4 - 1/2 (0.325 mi.)	N73	215
SEARS REALTY CO. INC Program Number: 8700903 Spill Number/Closed Date: 8700903 / 11/30/1988 Site ID: 322825	201 NORTH GEORGE ST	NNW 1/4 - 1/2 (0.373 mi.)	80	231
GURLEY & FLEET Program Number: 8907530 Spill Number/Closed Date: 8907530 / 4/1/1994 Site ID: 291093	301 BLACK RIVER BLVD	NE 1/4 - 1/2 (0.426 mi.)	85	254

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
GANESZOORT ELEM. SCH Program Number: 8800715 Spill Number/Closed Date: 8800715 / 11/14/1988 Site ID: 134469	LIBERTY ST	NNW 1/4 - 1/2 (0.428 mi.)	86	256
WALSH RESIDENCE Program Number: 9708408 Spill Number/Closed Date: 9708408 / 2/28/2005 Site ID: 64512	108 WEST EMBARGO STR	NNE 1/4 - 1/2 (0.428 mi.)	87	257
LYNN H. SCOTT, INC. Program Number: 9011756 Spill Number/Closed Date: 9011756 / 12/10/1998 Site ID: 185418	***300 WEST COURT ST***	***N 1/4 - 1/2 (0.440 mi.)***	***88***	***258***
KEKIS MOBIL SERVICE Program Number: 8706960 Spill Number/Closed Date: 8706960 / 2/6/1989 Site ID: 263774	400 WEST DOMINICK ST	NW 1/4 - 1/2 (0.443 mi.)	89	260

Lower Elevation	Address	Direction / Distance	Map ID	Page
AGWAY Program Number: 8605923 Spill Number/Closed Date: 8605923 / 12/11/1989 Site ID: 280900	SOUTH JAMES ST	WSW 1/8 - 1/4 (0.187 mi.)	52	165
TRANSFIGURATION CHUR Program Number: 8601754 Spill Number/Closed Date: 8601754 / 6/21/1986 Site ID: 209398	111 RIDGE RD	WSW 1/8 - 1/4 (0.194 mi.)	J56	169
SEARS OIL CO Program Number: 9002211 Spill Number/Closed Date: 9002211 / 5/25/1990 Site ID: 136265	***7064 LADO AVE***	***E 1/8 - 1/4 (0.211 mi.)***	***58***	***171***
OPPER'S Program Number: 9403073 Spill Number/Closed Date: 9403073 / 6/7/1994 Site ID: 221944	***301 ERIE BLVD WEST***	***NW 1/4 - 1/2 (0.305 mi.)***	***71***	***208***
FRANK'S SUNOCO SERVI Program Number: 9400052 Spill Number/Closed Date: 9400052 / Not Reported Site ID: 250578	***612 SOUTH JAMES STRE***	***SW 1/4 - 1/2 (0.329 mi.)***	***O74***	***217***
KOTARY MOTORS Program Number: 8907789 Spill Number/Closed Date: 8907789 / 10/26/1995 Site ID: 224362	E WRIGHT ST	SW 1/4 - 1/2 (0.342 mi.)	O75	224
ROME DPW (INSIDE) Program Number: 8702144 Spill Number/Closed Date: 8702144 / 6/19/1997 Site ID: 196166	RACE ST	ESE 1/4 - 1/2 (0.358 mi.)	78	229
ROME(C) HIGH LEVEL P Program Number: 9706427 Spill Number/Closed Date: 9706427 / 12/12/2006 Site ID: 286463	ERIE & BLACK RIVER B	S 1/4 - 1/2 (0.377 mi.)	81	232

Lower Elevation	Address	Direction / Distance	Map ID	Page
DECARLIS RES Program Number: 8709652 Spill Number/Closed Date: 8709652 / 2/16/1988 Site ID: 254721	118 WEST SOUTH	SW 1/4 - 1/2 (0.383 mi.)	82	233
ROME(C) DPW/VIP TRAN Program Number: 8805218 Program Number: 8807798 Spill Number/Closed Date: 8805218 / 9/20/1988 Spill Number/Closed Date: 8807798 / 12/27/1988 Site ID: 256663 Site ID: 256664	***132 RACE STREET***	***SE 1/4 - 1/2 (0.409 mi.)***	***Q83***	***235***
KEMP OIL SITE Program Number: 9907653 Spill Number/Closed Date: 9907653 / 9/24/1999 Site ID: 212632	PO BOX 803	SE 1/4 - 1/2 (0.461 mi.)	90	262
GARCIA RESIDENCE Program Number: 0303378 Spill Number/Closed Date: 0303378 / 9/25/2003 Site ID: 153762	735 SOUTH JAMES ST	SW 1/4 - 1/2 (0.476 mi.)	R92	266
LEE BATES & SONS Program Number: 9507910 Spill Number/Closed Date: 9507910 / 1/27/1998 Site ID: 189065	736 SOUTH JAMES STRE	SW 1/4 - 1/2 (0.478 mi.)	R93	268

State and tribal registered storage tank lists

UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the UST list, as provided by EDR, and dated 03/30/2015 has revealed that there are 16 UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ROME ELECTRONICS, IN Id/Status:: 6-600595	***216 ERIE BOULEVARD E***	***SE 0 - 1/8 (0.046 mi.)***	***C6***	***13***
VACANT WAREHOUSE Id/Status:: 6-601127	102-104 FRONT ST	NNW 0 - 1/8 (0.048 mi.)	B8	18
J A CAR WASH Id/Status:: 6-140848	***229 S JAMES ST***	***WNW 0 - 1/8 (0.051 mi.)***	***B12***	***26***
SUNOCO #0363-2254 Id/Status:: 6-065633	***131 SOUTH JAMES & ER***	***N 0 - 1/8 (0.066 mi.)***	***D20***	***50***
U HAUL Id/Status:: 6-022985	***244 ERIE BLVD EAST***	***SE 0 - 1/8 (0.074 mi.)***	***C24***	***62***
REVERE PRINTING Id/Status:: 6-600750	100 BOUCK STREET	SE 0 - 1/8 (0.076 mi.)	C25	67
ROME AGWAY COOP INC Id/Status:: 6-129526	***300 WEST STREET***	***W 0 - 1/8 (0.110 mi.)***	***E36***	***99***

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
C.A. KEMP OIL HEATIN Id/Status:: 6-131172	250 ERIE BOULEVARD E	SSE 0 - 1/8 (0.112 mi.)	G38	113
NORSTAR BANK UPSTATE Id/Status:: 6-600067	***ROME TRUST OFFICE***	***NNW 0 - 1/8 (0.114 mi.)***	***H41***	***120***
ROME(C) PUMP STATION Id/Status:: 6-600133	ERIE BLVD. & BLACK R	ENE 1/8 - 1/4 (0.135 mi.)	I44	124
ROME(C) CITY HALL Id/Status:: 6-433535	***198 NORTH WASHINGTON***	***NNW 1/8 - 1/4 (0.140 mi.)***	***H46***	***128***
ROME IRON GROUP, LTD Id/Status:: 6-432814	412 CANAL STREET	SSE 1/8 - 1/4 (0.183 mi.)	K48	135
NYS DOT/BRIDGE MAIN. Id/Status:: 6-600652	***WHITESBORO STREET***	***SSE 1/8 - 1/4 (0.225 mi.)***	***60***	***176***
TAMBURINO FACILITY Id/Status:: 6-600380	***230 RIDGE STREET***	***W 1/8 - 1/4 (0.240 mi.)***	***63***	***184***

Lower Elevation	Address	Direction / Distance	Map ID	Page
AGWAY, INC. Id/Status:: 6-600881	***312 SOUTH JAMES STRE***	***W 0 - 1/8 (0.091 mi.)***	***E32***	***90***
TRANSFIGURATION CHUR Id/Status:: 6-021873	111 RIDGE STREET	WSW 1/8 - 1/4 (0.157 mi.)	J47	132

AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database.

A review of the AST list, as provided by EDR, and dated 03/30/2015 has revealed that there are 2 AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ROME AGWAY COOP INC Facility Id: 6-129526	***300 WEST STREET***	***W 0 - 1/8 (0.110 mi.)***	***E36***	***99***
C.A. KEMP OIL HEATIN Facility Id: 6-131172	250 ERIE BOULEVARD E	SSE 0 - 1/8 (0.112 mi.)	G39	114

State and tribal institutional control / engineering control registries

INST CONTROL: Environmental Remediation sites that have institutional controls in place.

A review of the INST CONTROL list, as provided by EDR, and dated 06/26/2015 has revealed that there is 1 INST CONTROL site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ROSSI SITE WITHIN EA Site Code: 57205	***MILL STREET/RAILROAD***	***ESE 1/4 - 1/2 (0.354 mi.)***	***P76***	***226***

EXECUTIVE SUMMARY

State and tribal Brownfields sites

ERP: In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a $200 million Environmental Restoration or Brownfields Fund as part of the $1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

A review of the ERP list, as provided by EDR, and dated 06/26/2015 has revealed that there are 4 ERP sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
J A CAR WASH Site Code: 59168	***229 S JAMES ST***	***WNW 0 - 1/8 (0.051 mi.)***	***B12***	***26***
ROSSI SITE WITHIN EA Site Code: 57205	***MILL STREET/RAILROAD***	***ESE 1/4 - 1/2 (0.354 mi.)***	***P76***	***226***
EAST ROME BUSINESS P Site Code: 57199	MILL STREET/RAILROAD	ESE 1/4 - 1/2 (0.354 mi.)	P77	228

Lower Elevation	Address	Direction / Distance	Map ID	Page
FORMER ROME CABLE SI Site Code: 58361	***421 RIDGE STREET***	***WNW 1/4 - 1/2 (0.463 mi.)***	***91***	***263***

BROWNFIELDS: Brownfields Site List

A review of the BROWNFIELDS list, as provided by EDR, and dated 06/26/2015 has revealed that there is 1 BROWNFIELDS site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SE CORNER OF JAMES S Site Code: 356404	131-37 SOUTH JAMES S	N 0 - 1/8 (0.062 mi.)	D17	44

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: The EPA's listing of Brownfields properties from the Cleanups in My Community program, which provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

A review of the US BROWNFIELDS list, as provided by EDR, and dated 03/23/2015 has revealed that there are 2 US BROWNFIELDS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
FORMER INLAND FUELS	701 LAWRENCE STREET	NNE 1/4 - 1/2 (0.301 mi.)	N70	203
EAST ROME INDUSTRIAL	ROME INDUSTRIAL CENT	NNE 1/4 - 1/2 (0.495 mi.)	95	269

Local Lists of Registered Storage Tanks

HIST UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the HIST UST list, as provided by EDR, and dated 01/01/2002 has revealed that there are 12 HIST UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ROME ELECTRONICS, IN Facility Status: 2 PBS Number: 6-600595 Tank Status: 3	***216 ERIE BOULEVARD E***	***SE 0 - 1/8 (0.046 mi.)***	***C6***	***13***
J A CAR WASH Facility Status: 2 PBS Number: 6-140848 Tank Status: 3	***229 S JAMES ST***	***WNW 0 - 1/8 (0.051 mi.)***	***B12***	***26***
SUNOCO #0363-2254 Facility Status: 1 PBS Number: 6-065633 Tank Status: 3	***131 SOUTH JAMES & ER***	***N 0 - 1/8 (0.066 mi.)***	***D20***	***50***
U HAUL Facility Status: 2 PBS Number: 6-022985 Tank Status: 3 Tank Status: 1	***244 ERIE BLVD EAST***	***SE 0 - 1/8 (0.074 mi.)***	***C24***	***62***
REVERE PRINTING INC Facility Status: 2 PBS Number: 6-600750 Tank Status: 3	***100 BOUCK ST***	***SE 0 - 1/8 (0.076 mi.)***	***C26***	***69***
ROME AGWAY COOP INC Facility Status: 2 PBS Number: 6-129526 Tank Status: 6	***300 WEST STREET***	***W 0 - 1/8 (0.110 mi.)***	***E36***	***99***
C.A. KEMP OIL HEATIN Facility Status: 2 PBS Number: 6-131172 Tank Status: 3	***250 ERIE BOULEVARD E***	***SSE 0 - 1/8 (0.112 mi.)***	***G37***	***105***
NORSTAR BANK UPSTATE Facility Status: 2 PBS Number: 6-600067 Tank Status: 4	***ROME TRUST OFFICE***	***NNW 0 - 1/8 (0.114 mi.)***	***H41***	***120***
ROME(C) CITY HALL Facility Status: 1 PBS Number: 6-433535 Tank Status: 6	***198 NORTH WASHINGTON***	***NNW 1/8 - 1/4 (0.140 mi.)***	***H46***	***128***
NYS DOT/BRIDGE MAIN. Facility Status: 2 PBS Number: 6-600652 Tank Status: 3	***WHITESBORO STREET***	***SSE 1/8 - 1/4 (0.225 mi.)***	***60***	***176***
TAMBURINO FACILITY Facility Status: 2 PBS Number: 6-600380 Tank Status: 3 Tank Status: 4	***230 RIDGE STREET***	***W 1/8 - 1/4 (0.240 mi.)***	***63***	***184***

Lower Elevation	Address	Direction / Distance	Map ID	Page
AGWAY, INC.	***312 SOUTH JAMES STRE***	***W 0 - 1/8 (0.091 mi.)***	***E32***	***90***
Facility Status: 2 PBS Number: 6-600881 Tank Status: 3				

Records of Emergency Release Reports

NY Spills: Data collected on spills reported to NYSDEC. is required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

A review of the NY Spills list, as provided by EDR, and dated 05/18/2015 has revealed that there are 18 NY Spills sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
BEHIND WALGREENS Site ID: 469057 Spill Number/Closed Date: 1206069 / 9/19/2012 spillno: 1206069	201 SOUTH JAMES STRE	NNW 0 - 1/8 (0.049 mi.)	B9	23
BEHIND WALGREENS Site ID: 469062 Spill Number/Closed Date: 1206074 / 9/19/2012 spillno: 1206074	201 SOUTH JAMES STRE	NNW 0 - 1/8 (0.049 mi.)	B10	24
VACANT WAREHOUSE Site ID: 362482 Spill Number/Closed Date: 0600485 / 8/1/2007 spillno: 0600485	102-104 FRONT STREET	NNW 0 - 1/8 (0.050 mi.)	B11	25
AM/PM MINI MARKET Site ID: 234511 Spill Number/Closed Date: 8500642 / 5/22/1985 spillno: 8500642	NORTH JAMES ST	N 0 - 1/8 (0.055 mi.)	D14	41
ROME F.D. Site ID: 172265 Spill Number/Closed Date: 8904741 / 8/12/1989 spillno: 8904741	200 SOUTH JAMES PARK	NW 0 - 1/8 (0.057 mi.)	B15	42
VALVOLINE QUICK CHAN Site ID: 103954 Spill Number/Closed Date: 9012064 / 12/12/1995 spillno: 9012064	176 BLACK RIVER BLVD	ENE 0 - 1/8 (0.061 mi.)	16	43
SUNOCO #0353-2254 Site ID: 185023 Spill Number/Closed Date: 8402303 / 7/10/2008 spillno: 8402303	131 SOUTH JAMES STRE	N 0 - 1/8 (0.062 mi.)	D18	45
NEW WALGREENS CONSTR Site ID: 382414 Spill Number/Closed Date: 0702658 / 6/4/2007 spillno: 0702658	SOUTH JAMES AND ERIE	N 0 - 1/8 (0.067 mi.)	D21	58
U-HAUL Site ID: 138902 Spill Number/Closed Date: 9210138 / 12/18/2006 spillno: 9210138	244 ERIE BLVD EAST	SE 0 - 1/8 (0.074 mi.)	C23	60

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
REVERE PRINTING INC	***100 BOUCK ST***	***SE 0 - 1/8 (0.076 mi.)***	***C26***	***69***
Site ID: 241169 Spill Number/Closed Date: 9804875 / 11/6/1998 spillno: 9804875				
UNKNOWN	SOUTH JAMES ST & ERI	NNE 0 - 1/8 (0.076 mi.)	D28	83
Site ID: 202714 Spill Number/Closed Date: 8705966 / 10/15/1987 spillno: 8705966				
ROUTE 49/69	COR. NYS ROUTE 49 &	NNW 0 - 1/8 (0.088 mi.)	D29	84
Site ID: 223285 Spill Number/Closed Date: 9405004 / 7/13/1994 spillno: 9405004				
METH LAB DISPOSAL SI	RAILROAD ST / BOUCK	E 0 - 1/8 (0.093 mi.)	F33	95
Site ID: 468793 Spill Number/Closed Date: 1205822 / 11/14/2012 spillno: 1205822				
NIMO EXCAVATION	BOUCK & RAILROAD ST	E 0 - 1/8 (0.093 mi.)	F34	96
Site ID: 306533 Spill Number/Closed Date: 0304087 / 11/5/2003 spillno: 0304087				
KEMP TRUCK REPAIR	CANAL STREET	SSE 0 - 1/8 (0.110 mi.)	G35	97
Site ID: 314726 Spill Number/Closed Date: 9900354 / 6/8/2005 spillno: 9900354				
KEMP OIL HEATING COR	250 ERIE BLVD. EAST	SSE 0 - 1/8 (0.112 mi.)	G40	117
Site ID: 308675 Site ID: 305042 Spill Number/Closed Date: 9907630 / Not Reported Spill Number/Closed Date: 9410572 / 6/4/1996 spillno: 9410572 spillno: 9907630				

Lower Elevation	Address	Direction / Distance	Map ID	Page
AGWAY ROME FEED CO-O	312 S JAMES ST	W 0 - 1/8 (0.090 mi.)	E30	85
Site ID: 318488 Spill Number/Closed Date: 9104791 / 8/2/1991 spillno: 9104791				
NIMO	SO JAMES ST @ LAWREN	WSW 0 - 1/8 (0.118 mi.)	E42	123
Site ID: 258604 Spill Number/Closed Date: 9807928 / 9/29/1998 spillno: 9807928				

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA)

of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 03/10/2015 has revealed that there are 4 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
J A CAR WASH	***229 S JAMES ST***	***WNW 0 - 1/8 (0.051 mi.)***	***B12***	***26***
ARCO PETROLEUM PRODU	***ST JAMES & ERIE***	***NNE 0 - 1/8 (0.076 mi.)***	***D27***	***81***
ROME IRON GROUP LTD	***416 CANAL ST***	***SSE 1/8 - 1/4 (0.184 mi.)***	***K50***	***155***

Lower Elevation	Address	Direction / Distance	Map ID	Page
ROME AGWAY COOP INC	***312 S JAMES ST***	***W 0 - 1/8 (0.091 mi.)***	***E31***	***86***

HSWDS: The List includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity The latest version of the study is frozen in time. The sites on the study will not automatically be made superfund sites, rather each site will be further evaluated for listing in the registry. So overtime they will be added to the registry or not.

A review of the HSWDS list, as provided by EDR, and dated 01/01/2003 has revealed that there is 1 HSWDS site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
NIMO, ROME (KINGSLEY	KINGSLEY AVE.	ESE 1/8 - 1/4 (0.236 mi.)	L62	183

MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the MANIFEST list, as provided by EDR, and dated 05/01/2015 has revealed that there are 7 MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
J A CAR WASH EPA ID: NYD987032406	229 S JAMES ST	WNW 0 - 1/8 (0.051 mi.)	B13	40
REVERE PRINTING INC EPA ID: NYD987017233	***100 BOUCK ST***	***SE 0 - 1/8 (0.076 mi.)***	***C26***	***69***
ARCO PETROLEUM PRODU EPA ID: NYD982716458	***ST JAMES & ERIE***	***NNE 0 - 1/8 (0.076 mi.)***	***D27***	***81***
R & S STEEL,LLC EPA ID: NYR000110981	***412 CANAL ST***	***SSE 1/8 - 1/4 (0.183 mi.)***	***K49***	***138***
ROME IRON GROUP LTD EPA ID: NYD987029121	***416 CANAL ST***	***SSE 1/8 - 1/4 (0.184 mi.)***	***K50***	***155***

Lower Elevation	Address	Direction / Distance	Map ID	Page
ROME AGWAY COOP INC EPA ID: NYD099892150	***312 S JAMES ST***	***W 0 - 1/8 (0.091 mi.)***	***E31***	***86***

Lower Elevation	Address	Direction / Distance	Map ID	Page
SEARS OIL CO	***7064 LADO AVE***	***E 1/8 - 1/4 (0.211 mi.)***	***58***	***171***
EPA ID: NYD981182579				

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

A review of the EDR MGP list, as provided by EDR, has revealed that there are 2 EDR MGP sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
NIMO - ROME: KINGSLE	KINGSLEY AVENUE	ESE 1/8 - 1/4 (0.211 mi.)	L59	176
NIMO - ROME-JAY AND	106 SO. MADISON ST A	NW 1/4 - 1/2 (0.478 mi.)	94	269

EDR US Hist Auto Stat: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR US Hist Auto Stat list, as provided by EDR, has revealed that there are 4 EDR US Hist Auto Stat sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
Not reported	217 S JAMES ST	NW 0 - 1/8 (0.045 mi.)	B5	13
Not reported	416 CANAL ST	SSE 1/8 - 1/4 (0.184 mi.)	K51	165

Lower Elevation	Address	Direction / Distance	Map ID	Page
Not reported	319 WEST ST	W 1/8 - 1/4 (0.127 mi.)	E43	124
Not reported	428 CANAL ST	SSE 1/8 - 1/4 (0.189 mi.)	K54	167

EXECUTIVE SUMMARY

EDR US Hist Cleaners: EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR US Hist Cleaners list, as provided by EDR, has revealed that there is 1 EDR US Hist Cleaners site within approximately 0.25 miles of the target property.


Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
Not reported	120 BLACK RIVER BLV	ENE 1/8 - 1/4 (0.247 mi.)	M64	191

EXECUTIVE SUMMARY


Due to poor or inadequate address information, the following sites were not mapped. Count: 11 records.

Site Name	Database(s)
NM - ROME JAY/MADISON MGP	RGA HWS
NM - JAY/MADISON - ROME MGP	RGA HWS
ROME DEPT OF TRANSPORTATION	RCRA NonGen / NLR, FINDS, MANIFEST
NIAGARA MOHAWK /GAS REG STA	CERCLIS, RCRA-LQG, MANIFEST
FORMER JET DRY CLEANERS	SHWS
CRASH'S AUTO DUMP	SWF/LF
2 MI EAST OF ROME	LTANKS
ROME INDUSTRIAL PARK	FINDS
ROME WATERFRONT PROJECT	FINDS
NIMO, ROME (MADISON AND JAY)	HSWDS
NIMO, ROME GAS REGULATOR STA.	HSWDS

OVERVIEW MAP - 4366780.2S


W Dominick St
State Hwy 46
Conrail
Madison St
Peterse St
Floyd Ave
Canal St
Canal St
Canal St

DETAIL MAP - 4366780.2S



0 1/16 1/8 1/4 Miles

- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- Sensitive Receptors
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Power transmission lines
- 100-year flood zone
- 500-year flood zone

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: Rome Turney	CLIENT: Bergmann Associates
ADDRESS: 109 Canal Street Rome NY 13440	CONTACT: Megan Borruso
LAT/LONG: 43.2084 / 75.4583	INQUIRY #: 4366780.2s DATE: July 28, 2015 1:37 pm

Copyright © 2015 EDR, Inc. © 2010 Tele Atlas Rel. 07/2009.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Federal NPL site list								
NPL	1.000		0	0	0	0	NR	0
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	TP		NR	NR	NR	NR	NR	0
Federal Delisted NPL site list								
Delisted NPL	1.000		0	0	0	0	NR	0
Federal CERCLIS list								
CERCLIS	0.500		0	0	1	NR	NR	1
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
Federal CERCLIS NFRAP site List								
CERC-NFRAP	0.500		0	0	0	NR	NR	0
Federal RCRA CORRACTS facilities list								
CORRACTS	1.000		0	0	0	0	NR	0
Federal RCRA non-CORRACTS TSD facilities list								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Federal RCRA generators list								
RCRA-LQG	0.250		0	0	NR	NR	NR	0
RCRA-SQG	0.250		0	1	NR	NR	NR	1
RCRA-CESQG	0.250		1	1	NR	NR	NR	2
Federal institutional controls / engineering controls registries								
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROL	0.500		0	0	0	NR	NR	0
LUCIS	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	TP		NR	NR	NR	NR	NR	0
State- and tribal - equivalent CERCLIS								
SHWS	1.000		0	0	1	0	NR	1
VAPOR REOPENED	1.000		0	0	0	0	NR	0
State and tribal landfill and/or solid waste disposal site lists								
SWF/LF	0.500		0	1	1	NR	NR	2
State and tribal leaking storage tank lists								
LTANKS	0.500	1	5	9	20	NR	NR	35
HIST LTANKS	0.500		0	0	0	NR	NR	0
INDIAN LUST	0.500		0	0	0	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
State and tribal registered storage tank lists								
TANKS	0.250		0	0	NR	NR	NR	0
UST	0.250	1	10	6	NR	NR	NR	17
CBS UST	0.250		0	0	NR	NR	NR	0
MOSF UST	0.500		0	0	0	NR	NR	0
AST	0.250		2	0	NR	NR	NR	2
CBS AST	0.250		0	0	NR	NR	NR	0
MOSF AST	0.500		0	0	0	NR	NR	0
MOSF	0.500		0	0	0	NR	NR	0
CBS	0.250		0	0	NR	NR	NR	0
INDIAN UST	0.250		0	0	NR	NR	NR	0
FEMA UST	0.250		0	0	NR	NR	NR	0
State and tribal institutional control / engineering control registries								
ENG CONTROLS	0.500		0	0	0	NR	NR	0
INST CONTROL	0.500		0	0	1	NR	NR	1
RES DECL	0.125		0	NR	NR	NR	NR	0
State and tribal voluntary cleanup sites								
INDIAN VCP	0.500		0	0	0	NR	NR	0
VCP	0.500		0	0	0	NR	NR	0
State and tribal Brownfields sites								
ERP	0.500		1	0	3	NR	NR	4
BROWNFIELDS	0.500		1	0	0	NR	NR	1
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	2	NR	NR	2
Local Lists of Landfill / Solid Waste Disposal Sites								
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
SWRCY	0.500		0	0	0	NR	NR	0
SWTIRE	0.500		0	0	0	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US CDL	TP		NR	NR	NR	NR	NR	0
DEL SHWS	1.000		0	0	0	0	NR	0
US HIST CDL	TP		NR	NR	NR	NR	NR	0
Local Lists of Registered Storage Tanks								
HIST UST	0.250		9	3	NR	NR	NR	12
HIST AST	TP		NR	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
Local Land Records								
LIENS 2	TP		NR	NR	NR	NR	NR	0
LIENS	TP		NR	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	TP		NR	NR	NR	NR	NR	0
NY Spills	0.125		18	NR	NR	NR	NR	18
NY Hist Spills	0.125		0	NR	NR	NR	NR	0
SPILLS 80	0.125		0	NR	NR	NR	NR	0
SPILLS 90	0.125		0	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250		3	1	NR	NR	NR	4
DOT OPS	TP		NR	NR	NR	NR	NR	0
DOD	1.000		0	0	0	0	NR	0
FUDS	1.000		0	0	0	0	NR	0
CONSENT	1.000		0	0	0	0	NR	0
ROD	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
TRIS	TP		NR	NR	NR	NR	NR	0
TSCA	TP		NR	NR	NR	NR	NR	0
FTTS	TP		NR	NR	NR	NR	NR	0
HIST FTTS	TP		NR	NR	NR	NR	NR	0
SSTS	TP		NR	NR	NR	NR	NR	0
ICIS	TP		NR	NR	NR	NR	NR	0
PADS	TP		NR	NR	NR	NR	NR	0
MLTS	TP		NR	NR	NR	NR	NR	0
RADINFO	TP		NR	NR	NR	NR	NR	0
FINDS	TP	1	NR	NR	NR	NR	NR	1
RAATS	TP		NR	NR	NR	NR	NR	0
RMP	TP		NR	NR	NR	NR	NR	0
HSWDS	0.500		0	1	0	NR	NR	1
UIC	TP		NR	NR	NR	NR	NR	0
MANIFEST	0.250		4	3	NR	NR	NR	7
DRYCLEANERS	0.250		0	0	NR	NR	NR	0
SPDES	TP		NR	NR	NR	NR	NR	0
AIRS	TP		NR	NR	NR	NR	NR	0
E DESIGNATION	0.125		0	NR	NR	NR	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	TP		NR	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
US FIN ASSUR	TP		NR	NR	NR	NR	NR	0
EPA WATCH LIST	TP		NR	NR	NR	NR	NR	0
US AIRS	TP		NR	NR	NR	NR	NR	0
LEAD SMELTERS	TP		NR	NR	NR	NR	NR	0
Financial Assurance	TP		NR	NR	NR	NR	NR	0
COAL ASH	0.500		0	0	0	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
PRP	TP		NR	NR	NR	NR	NR	0
COAL ASH DOE	TP		NR	NR	NR	NR	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	1	1	0	NR	2
EDR US Hist Auto Stat	0.250		1	3	NR	NR	NR	4
EDR US Hist Cleaners	0.250		0	1	NR	NR	NR	1
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
RGA HWS	TP		NR	NR	NR	NR	NR	0
RGA LF	TP		NR	NR	NR	NR	NR	0
- Totals --		3	55	31	30	0	0	119

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1 **ROME TURNEY RADIATOR** **LTANKS** **S100964893**
Target **109 CANAL ST** **N/A**
Property **ROME C, NY**

Site 1 of 3 in cluster A

Actual:
439 ft.

LTANKS:

Site ID:	225230
Spill Number/Closed Date:	8802056 / Not Reported
Spill Date:	6/6/1988
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	3313
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	6/6/1988
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	6/7/1988
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	5
Date Entered In Computer:	6/8/1988
Spill Record Last Update:	3/15/2005
Spiller Name:	Not reported
Spiller Company:	ROME TURNEY RADIATOR
Spiller Address:	109 CANAL ST.
Spiller City,St,Zip:	ROME, NY 13440
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	6
DER Facility ID:	185922
DEC Memo:	06/07/88: FREE FLOATING PRODUCT NOTED ON GW, PLAN TO ISOLATE TANKS AND TEST (JM).06/09/88: WILL PUMP OUT TANKS TOMORROW/TANK #001 +.133 GPH/TANK #002 +.128 GPH(DJ).07/21/88: TANKS REMOVED/NO HOLES FOUND/4" WELL TO BE INSTALLED/HOLE FILLED (NC).04/11/89: CONTAMINATED SOIL (48 YDS.) DISPOSED OF. (JM).08/16/90: SPOKE TO BILL LYNCH. STATED CONTAMINATED SOIL REMOVED LAST YEAR BY JOHN HITCHINGS. (DP).08/27/90: SPOKE WITH BILL LYNCH. STATED HE WILL CONTACT JOHN HITCHINGS FOR ADDITIONAL NEEDED PAPERWORK. (DP).08/31/90: SOIL DISPOSAL PAPERWORK RECEIVED. (JM).04/12/1996: STIP (JM)01/13/2003: REVIEWED FILE. NEED TO COMPLETE INVESTIGATION. INCOMPLETE. (DJ)
Remarks:	ATTEMPTING TO DO TANK TEST BUT ABORTED DUE TO AIR POCKETS/AFTER DIGGING TO VENT THE TANKS, FOUND CONT. SOIL/PUTTING ON PLASTIC & WILL CONTINUE TO EXCAV. (2)5000 GAL TANKS MANIFOLDED TOGETHER W/1 VENT

Material:

Site ID:	225230
Operable Unit ID:	917432
Operable Unit:	01
Material ID:	461188
Material Code:	0001A

ROME TURNEY RADIATOR (Continued) **S100964893**

Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Pounds
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 225230
Spill Tank Test: 1534044
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

A2 **ELEGRACE CASKET COMPANY INC** **FINDS** **1007785709**
Target **109 CANAL ST** **N/A**
Property **ROME, NY 13440**

Site 2 of 3 in cluster A

Actual: 439 ft.

FINDS:

Registry ID: 110019481880

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

A3 **ROME TURNEY RAD CO** **UST** **U001847603**
Target **109 CANAL STREET** **N/A**
Property **ROME C, NY 13440**

Site 3 of 3 in cluster A

Actual: 439 ft.

UST:
Id/Status: 6-389331 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 6
Expiration Date: 06/30/1992
UTM X: 462680.25579999998
UTM Y: 4784097.7729900004
Site Type: Unknown

Affiliation Records:
Site Id: 41968

ROME TURNEY RAD CO (Continued) **U001847603**

Affiliation Type:	Facility Owner
Company Name:	ROME TURNEY RAD CO
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	109 CANAL STREET
Address2:	Not reported
City:	ROME
State:	NY
Zip Code:	13440
Country Code:	001
Phone:	(315) 336-2200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	41968
Affiliation Type:	Mail Contact
Company Name:	ROME TURNEY RAD CO
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	109 CANAL STREET
Address2:	Not reported
City:	ROME
State:	NY
Zip Code:	13440
Country Code:	001
Phone:	(315) 336-2200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	41968
Affiliation Type:	On-Site Operator
Company Name:	ROME TURNEY RAD CO
Contact Type:	Not reported
Contact Name:	ROME TURNEY RAD CO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(315) 336-2200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	41968
Affiliation Type:	Emergency Contact
Company Name:	ROME TURNEY RAD CO
Contact Type:	Not reported
Contact Name:	W H ARMITAGE
Address1:	Not reported
Address2:	Not reported

ROME TURNEY RAD CO (Continued) **U001847603**

City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(315) 336-2200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

Tank Number:	001
Tank ID:	118949
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	5000
Install Date:	12/01/1975
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number:	002
Tank ID:	118950
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	5000
Install Date:	12/01/1953
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

ROME TURNEY RAD CO (Continued) **U001847603**

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

---

4 **TRAVEL INN** **LTANKS** **S107417072**
ESE **145 EAST WHITESBORO STREET** **N/A**
< 1/8 **ROME, NY 13440**
0.025 mi.
131 ft.

Relative:
Higher

Actual:
441 ft.

LTANKS:

Site ID:	354544
Spill Number/Closed Date:	0508864 / 11/30/2005
Spill Date:	10/25/2005
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	3313
Investigator:	NFCARRIE
Referred To:	Not reported
Reported to Dept:	10/25/2005
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	10/25/2005
Spill Record Last Update:	12/13/2005
Spiller Name:	HARRY PATEL
Spiller Company:	TRAVEL INN
Spiller Address:	145 EAST WHITESBORO ST
Spiller City,St,Zip:	ROME, NY 13440
Spiller County:	001
Spiller Contact:	HARRY PATEL
Spiller Phone:	(315) 337-9400
Spiller Extention:	Not reported
DEC Region:	6
DER Facility ID:	301893
DEC Memo:	10/25/05: PHONEX FROM JAYN EGGAN, PULLING UST FOUND

TRAVEL INN (Continued) **S107417072**

CONTAMINATION.10/26/05: SITE VISIT, EGGAN DOING CONT. SOIL EXC. ABILITY RESTRICTED BY BUILDING & UTILITIES. 11/16/05: REVIEWED TCR, OK TO CLOSE ONCE SOIL PW RECEIVED.11/29/05 DISPOSAL RECEIPTS RECV'D - 82.67T @ RODMAN LANDFILL. /CLOSED/

Remarks: FOUND CONTAMINATED SOIL WHILE REMOVING TANK

Material:

Site ID:	354544
Operable Unit ID:	1111945
Operable Unit:	01
Material ID:	2101992
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

B5 **EDR US Hist Auto Stat** **1015329542**
NW **217 S JAMES ST** **N/A**
< 1/8 **ROME, NY 13440**
0.045 mi.
239 ft. **Site 1 of 9 in cluster B**

Relative: Higher

Actual: 440 ft.

EDR Historical Auto Stations:

Name:	BODY SHOP HEALTH & FITNESS CENTER THE
Year:	1999
Address:	217 S JAMES ST
Name:	BODY SHOP HEALTH & FITNESS CENTER THE
Year:	2000
Address:	217 S JAMES ST

C6 **ROME ELECTRONICS, INC.** **UST** **U003127312**
SE **216 ERIE BOULEVARD EAST** **HIST UST** **N/A**
< 1/8 **ROME C, NY 13440**
0.046 mi.
244 ft. **Site 1 of 5 in cluster C**

Relative: Higher

Actual: 440 ft.

UST:

Id/Status:	6-600595 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	6
Expiration Date:	07/18/2001
UTM X:	462892.57483
UTM Y:	4783915.3271599999
Site Type:	Manufacturing (Other than Chemical)/Processing

ROME ELECTRONICS, INC. (Continued) **U003127312**

Affiliation Records:

Site Id:	43418
Affiliation Type:	Facility Owner
Company Name:	ROME ELECTRONICS, INC.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	216 ERIE EAST
Address2:	Not reported
City:	ROME
State:	NY
Zip Code:	13440
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	43418
Affiliation Type:	Mail Contact
Company Name:	HALLIGAN REALTY & CONSULTING
Contact Type:	Not reported
Contact Name:	TIMOTHY G. HALLIGAN
Address1:	321 GENESEE STREET
Address2:	Not reported
City:	UICA
State:	NY
Zip Code:	13501
Country Code:	001
Phone:	(315) 724-4760
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	43418
Affiliation Type:	On-Site Operator
Company Name:	ROME ELECTRONICS, INC.
Contact Type:	Not reported
Contact Name:	ROME ELECTRONICS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	43418
Affiliation Type:	Emergency Contact
Company Name:	ROME ELECTRONICS, INC.
Contact Type:	Not reported
Contact Name:	ROME ELECTRONICS

ROME ELECTRONICS, INC. (Continued) **U003127312**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

Tank Number:	1
Tank ID:	123145
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	3000
Install Date:	Not reported
Date Tank Closed:	07/01/1996
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I00 - Overfill - None
B00 - Tank External Protection - None
C03 - Pipe Location - Aboveground/Underground Combination
H00 - Tank Leak Detection - None

HIST UST:

PBS Number:	6-600595
SPDES Number:	Not reported
Emergency Contact:	ROME ELECTRONICS
Emergency Telephone:	(000) 000-0000
Operator:	ROME ELECTRONICS
Operator Telephone:	(000) 000-0000
Owner Name:	ROME ELECTRONICS, INC.
Owner Address:	216 ERIE EAST
Owner City,St,Zip:	ROME, NY 13440
Owner Telephone:	Not reported
Owner Type:	Corporate/Commercial

ROME ELECTRONICS, INC. (Continued) **U003127312**

Owner Subtype:	Not reported
Mailing Name:	HALLIGAN REALTY & CONSULTING
Mailing Address:	321 GENESEE STREET
Mailing Address 2:	Not reported
Mailing City,St,Zip:	UICA, NY 13501
Mailing Contact:	TIMOTHY G. HALLIGAN
Mailing Telephone:	(315) 724-4760
Owner Mark:	First Owner
Facility Status:	2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Facility Addr2:	Not reported
SWIS ID:	3013
Old PBS Number:	Not reported
Facility Type:	OTHER RETAIL SALES
Facility Type:	MANUFACTURING
Inspected Date:	06/18/1996
Inspector:	DP
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	07/18/1996
Expiration Date:	07/18/2001
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	0
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	Minor Data Missing
Tank Screen:	0
Dead Letter:	False
CBS Number:	Not reported
Town or City:	ROME (C)
County Code:	30
Town or City:	13
Region:	6

Tank Id:	1
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	3000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Aboveground/Underground Combination
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	07/01/1996

ROME ELECTRONICS, INC. (Continued) **U003127312**

Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

B7 **BOUTON PHYSICAL THERAPY** **LTANKS** **S107789082**
WNW **221 S JAMES ST** **N/A**
< 1/8 **ROME, NY**
0.048 mi.
256 ft. **Site 2 of 9 in cluster B**

Relative:
Higher

Actual:
440 ft.

LTANKS:

Site ID:	333670
Spill Number/Closed Date:	0409032 / 6/15/2006
Spill Date:	11/16/2004
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	4/11/2006
Cleanup Meets Standard:	True
SWIS:	3313
Investigator:	JDALSANT
Referred To:	Not reported
Reported to Dept:	11/16/2004
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	3/10/2006
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	11/16/2004
Spill Record Last Update:	7/27/2006
Spiller Name:	R. CHRISTOPHER BOUTON
Spiller Company:	BOUTON PHYSICAL THERAPY
Spiller Address:	221 SOUTH JAMES ST.
Spiller City,St,Zip:	ROME, NY
Spiller County:	999
Spiller Contact:	R. CHRISTOPHER BOUTON
Spiller Phone:	315 337-1436
Spiller Extention:	Not reported
DEC Region:	6
DER Facility ID:	268920
DEC Memo:	11/16/04-site visit, 1k tank ho, reportedly not used for at least 50 years. on south side of existing building next to j&a carwash. owner expanding building. todd panashi doing digging. told them to take soil samples & dispose of cont. soil.08/11/05: SENT STATUS QUERY LETTER.03/01/06: CALLED PARAGON WHO STATED THEY MAY HAVE ONLY DONE TANK CLEANING. WILL CHECK FILE AND FAX ALL. PLUMLEY MAY HAVE DONE REST. NC SAYS SOIL MAY STILL BE ON SITE. WILL PERFORM SITE CHECK. (JA)RECEIVED FAX OF LAB FOR SOIL PILE WHICH ALSO HAD BOTTOM COMPOSITE AND WALL COMPOSITE SAMPLES ATTACHED TO IT THAT MEETS STANDARDS. SPILL IS SOIL DISPOSAL ONLY NOW. (JA)03/10/06: SOIL PILE STILL ON SITE UNCOVERED. APPROX 5-7 YD. SOIL REM LETTER SENT. (JA)06/15/06: RECEIVED SOIL DISPOSAL PAPERWORK. 22.66 TONS TRANSPORTED BY EGGAN TO DANC FACILITY, RODMAN ,NY. SPILL CLOSED. (JA)
Remarks:	CALLER STATES THAT WHILE DIGGIN THEY FOUND AN OIL TANK AND CAN SEE

BOUTON PHYSICAL THERAPY (Continued) **S107789082**

SOME STAINING AND CAN SMELL FUEL OIL:

Material:

Site ID:	333670
Operable Unit ID:	1095814
Operable Unit:	01
Material ID:	2112945
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

B8 **VACANT WAREHOUSE** **UST** **U004083000**
NNW **102-104 FRONT ST** **N/A**
< 1/8 **ROME, NY 13440**
0.048 mi.
256 ft. **Site 3 of 9 in cluster B**

Relative:
Higher

Actual:
441 ft.

UST:

Id/Status:	6-601127 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	6
Expiration Date:	03/08/2012
UTM X:	462727.98236999998
UTM Y:	4784175.9784899997
Site Type:	Other

Affiliation Records:

Site Id:	378118
Affiliation Type:	Facility Owner
Company Name:	FIVE POINT DEVEL. ROME NY C/O HDL PROPERTIES GROUP
Contact Type:	PROJECT MANAGER
Contact Name:	SUSAN POISSANT
Address1:	7085 MANLIUS CENTER ROAD
Address2:	Not reported
City:	E. SYRACUSE
State:	NY
Zip Code:	13057
Country Code:	001
Phone:	(315) 671-1500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	3/8/2007

Site Id:	378118
Affiliation Type:	Mail Contact
Company Name:	HDL PROPERTIES GROUP

VACANT WAREHOUSE (Continued) **U004083000**

Contact Type:	Not reported
Contact Name:	MS. SUSAN POISSANT
Address1:	7085 MANLIUS ROAD
Address2:	Not reported
City:	E. SYRACUSE
State:	NY
Zip Code:	13057
Country Code:	001
Phone:	(315) 671-1500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	3/7/2007

Site Id:	378118
Affiliation Type:	On-Site Operator
Company Name:	VACANT WAREHOUSE
Contact Type:	Not reported
Contact Name:	N/A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	N/A
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	3/7/2007

Site Id:	378118
Affiliation Type:	Emergency Contact
Company Name:	HDL PROPERTIES GROUP
Contact Type:	Not reported
Contact Name:	N/A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(315) 671-1500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	3/7/2007

Tank Info:

Tank Number:	001
Tank ID:	216221
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1000
Install Date:	Not reported
Date Tank Closed:	01/17/2007

VACANT WAREHOUSE (Continued) **U004083000**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: CGFREEDM
Last Modified: 03/08/2007

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
I00 - Overfill - None
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None

Tank Number: 002
Tank ID: 216222
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2000
Install Date: Not reported
Date Tank Closed: 01/19/2007
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: CGFREEDM
Last Modified: 03/08/2007

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
I00 - Overfill - None
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None

VACANT WAREHOUSE (Continued) **U004083000**

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None

Tank Number: 003
Tank ID: 220240
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 275
Install Date: Not reported
Date Tank Closed: 06/05/2007
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: RFNOVAK
Last Modified: 11/06/2007

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
I00 - Overfill - None
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None

Tank Number: 004
Tank ID: 220241
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/18/2007
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: RFNOVAK

VACANT WAREHOUSE (Continued) **U004083000**

Last Modified: 11/06/2007

Equipment Records:

I00 - Overfill - None
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None

Tank Number: 005
Tank ID: 220242
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/25/2007
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: RFNOVAK
Last Modified: 11/06/2007

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
I00 - Overfill - None
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None

B9 **BEHIND WALGREENS** **NY Spills** **S112226733**
NNW **201 SOUTH JAMES STREET** **N/A**
< 1/8 **ROME, NY**
0.049 mi.
257 ft. **Site 4 of 9 in cluster B**

Relative:
Higher

Actual:
441 ft.

SPILLS:

Facility ID:	1206069
Facility Type:	ER
DER Facility ID:	423341
Site ID:	469057
DEC Region:	6
Spill Date:	9/19/2012
Spill Number/Closed Date:	1206069 / 9/19/2012
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	3313
Investigator:	RAFURLON
Referred To:	Not reported
Reported to Dept:	9/19/2012
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	9/19/2012
Spill Record Last Update:	9/19/2012
Spiller Name:	TRAVIS BLISS
Spiller Company:	UNKNOWN
Spiller Address:	201 SOUTH JAMES STREET
Spiller City,St,Zip:	ROME, NY
Spiller Company:	999
Contact Name:	TRAVIS BLISS
Contact Phone:	(315) 245-1717
DEC Memo:	9/19/2012:TELECON W/TRAVIS BLISS. CLEANUP COMPLETE. (RF)
Remarks:	Blown line on garbage truck. Clean up is complete.

Material:

Site ID:	469057
Operable Unit ID:	1218957
Operable Unit:	01
Material ID:	2217392
Material Code:	0010
Material Name:	Hydraulic Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

B10
NNW
< 1/8
0.049 mi.
257 ft.

BEHIND WALGREENS
201 SOUTH JAMES STREET
ROME, NY

Site 5 of 9 in cluster B

NY Spills **S112226737**
N/A

Relative:
Higher

Actual:
441 ft.

SPILLS:

Facility ID:	1206074
Facility Type:	ER
DER Facility ID:	423341
Site ID:	469062
DEC Region:	6
Spill Date:	9/19/2012
Spill Number/Closed Date:	1206074 / 9/19/2012
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	3313
Investigator:	RAFURLON
Referred To:	Not reported
Reported to Dept:	9/19/2012
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	9/19/2012
Spill Record Last Update:	9/19/2012
Spiller Name:	TRAVIS BLISS
Spiller Company:	UNKNOWN
Spiller Address:	201 SOUTH JAMES STREET
Spiller City,St,Zip:	ROME, NY
Spiller Company:	999
Contact Name:	TRAVIS BLISS
Contact Phone:	(315) 245-1717
DEC Memo:	DUPLICATE SPILL : SEE 1206069
Remarks:	Blown line on garbage truck. Clean up is complete.

Material:

Site ID:	469062
Operable Unit ID:	1218962
Operable Unit:	01
Material ID:	2217397
Material Code:	0010
Material Name:	Hydraulic Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

B11 **VACANT WAREHOUSE** **NY Spills** **S107787299**
NNW **102-104 FRONT STREET** **N/A**
< 1/8 **ROME, NY**
0.050 mi.
262 ft. **Site 6 of 9 in cluster B**

Relative:
Higher

Actual:
441 ft.

SPILLS:

Facility ID:	0600485
Facility Type:	ER
DER Facility ID:	312743
Site ID:	362482
DEC Region:	6
Spill Date:	4/12/2006
Spill Number/Closed Date:	0600485 / 8/1/2007
Spill Cause:	Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	3313
Investigator:	PGWAITE
Referred To:	Not reported
Reported to Dept:	4/12/2006
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	4/12/2006
Spill Record Last Update:	8/1/2007
Spiller Name:	BRIAN SNOW
Spiller Company:	VACANT WAREHOUSE
Spiller Address:	102-104 FRONT STREET
Spiller City,St,Zip:	ROME, NY
Spiller Company:	001
Contact Name:	BRIAN SNOW
Contact Phone:	(315) 736-0856
DEC Memo:	04/12/06: RESPONDED TO SITE WHICH IS BOUNDED BY JAMES ST ON THE WEST, ERIE BLVD ON THE NORTH AND RAILROAD TRACKS RUNNING NORTHEAST TO SOUTHWEST. THREE BUILDINGS INCLUDED. FORMER SUNOCO STATION WITH ACTIVE SPILL 8402303 ON NORTH SIDE OF FRONT ST., LARGE CLUSTER OF BUILDINGS ON THE SOUTH SIDE OF FRONT ST AND AN OLD WAREHOUSE AT THE END OF FRONT ST. WAREHOUSE HAS POSSIBLE UST UNDER OVERHANG DIRECTLY AT THE END OF FRONT ST. BORING JUST TO THE RIGHT HAD PRODUCT IN IT. PHASE I REVEALED WAREHOUSE WAS AN OIL REFINERY AND METAL RECLAMATION CENTER IN THE PAST. (JA)5/11/2006: RP LETTER TO PHILIP VESCIO. (JD)9/27/06 - Rec'd letter from EMS on behalf of HDL Property Group, clarifying remediation strategy at the proposed Walgreens site.9/29/06 - Letter sent to Susan Poissant, HDL Property group, LLC who represents Walgreens, commenting on the 9/27/06 letter and requesting HDL to state their intentions as to the clean-up of the spill.10/5/06 - Met with Dave Bander EMS and Mr. Vescio onsite to inspect site and discuss spill cleanup.1/13/07 - Rec'd UST Remediation Workplan from EMS.1/16/07 - 1000 gal fuel oil UST removed with approx. 50 cys contaminated soils excavated and stockpiled on-site. Approx. 750 gal water/product mixture pumped from tank and

VACANT WAREHOUSE (Continued) **S107787299**

disposed of by Paragon.1/17/07 - On-site inspection of excavation. Dave Bender, Jim Driscol and Terry from EMS onsite. Was informed that Walgreen's has obtained title to property from Phil Vescio. Was informed that Mr. Vescio has stated that another UST is located nearby, will dig test pit tommorrow to inspect.5/8/07 - Rec'd UST Closure Report for two USTs removed in January 2007. No soil disposal receipts.06/04/2007: SEE SPILL #0702658. ANOTHER 275 GALLON UST FOUND DURING DEMO WORK for Walgreen's. (SR)06/05/2007: TELECON WITH DAVE BENDER, EMS: EXCAVATED 30 YDS OF SOIL. PIDS STARTED AT 50 PPM, DUG CLEAN AT 5 FEET. NO GW ENCOUNTERED. SOIL STAGED ON SITE. 4 SIDEWALLS AND BOTTOM COMPOSITE SAMPLES TAKEN. (SR)6/18/07 - Jim Doyle called to say another 500 gal UST discovered. EMS pulled tank, placed on poly w/little soil. Very low PID on sidewalls. All done. (PW)6/22/07 - Another 550 gal UST found on old Sunoco property. Jim Doyle on-site 6/25/07. (PW)7/31/07 - Rec'd Additional UST Closure Report for remaining three USTs. Soil disposal receipts for the USTs removed in January were included. Spill closed Not Meeting Standards.

Remarks: WHILE DIGGING FOUND CONTAMINATED SOIL': - BRIAN SNOW'S ADDRESS IS 555 FRENCH ROAD SUITE 203 NEW HARTFORD NY 13413

Material:

Site ID:	362482
Operable Unit ID:	1120590
Operable Unit:	01
Material ID:	2110079
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

B12 **J A CAR WASH** **RCRA NonGen / NLR** **1000791723**
WNW **229 S JAMES ST** **FINDS** **NYD987032406**
< 1/8 **ROME, NY 13440** **ERP**
0.051 mi. **LTANKS**
268 ft. **Site 7 of 9 in cluster B** **UST**
HIST UST

Relative:
Higher

Actual:
440 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	J A CAR WASH
Facility address:	229 S JAMES ST ROME, NY 134406745
EPA ID:	NYD987032406
Mailing address:	S JAMES ST ROME, NY 13440
Contact:	Not reported
Contact address:	S JAMES ST ROME, NY 13440
Contact country:	US
Contact telephone:	Not reported

J A CAR WASH (Continued) **1000791723**

Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: JOHN PETTINELLI
Owner/operator address: 814 BRADFORD DR
ROME, NY 13440
Owner/operator country: US
Owner/operator telephone: (315) 336-5458
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: JOHN PETTINELLI
Owner/operator address: 814 BRADFORD DR
ROME, NY 13440
Owner/operator country: US
Owner/operator telephone: (315) 336-5458
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: J A CAR WASH
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: J A CAR WASH
Classification: Not a generator, verified

Date form received by agency: 04/13/1993
Site name: J A CAR WASH
Classification: Large Quantity Generator

J A CAR WASH (Continued) **1000791723**

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D018
. Waste name: BENZENE

Violation Status: No violations found

FINDS:

Registry ID: 110004503635

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ERP:
Site Code: 59168
Program: ERP
HW Code: E633059
Site Class: N
Class N: N
SWIS: 3313
Region: 6
Town: Rome (c)
Acres: .350
Record Added: 09/27/2004
Record Updated: 10/30/2013
Updated By: PRTAYLOR
Site Description: 229 South James Street consists of approximately 15,150 square feet of property located on the east side of South James Street approximately 100 feet south of the intersection with Canal Street. The site once contained a car wash and gasoline filling station but is now vacant with the buildings removed. The site is a relatively flat, rectangular parcel located in a commercial and residential area of the city of Rome, Oneida County, New York. A petroleum spill from underground tank leakage was remediated. Prior uses of the site that appear to have led to site contamination were the former operations as a gasoline filling station. An application to enter into the NYSDEC Environmental Restoration Program for funding to perform an investigation of the site was withdrawn by the City of Rome in August 2005.
Env Problem: Residual petroleum contamination remains at this site from a former spill that was closed October 2004 not meeting standards. See Spill No. 9109197.
Health Problem: Not reported

LTANKS:
Site ID: 230487
Spill Number/Closed Date: 9109197 / 10/22/2004
Spill Date: 11/27/1991
Spill Cause: Tank Test Failure

J A CAR WASH (Continued) **1000791723**

Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Unable/unwilling Responsible Party. Corrective action taken. (ISR)
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	3313
Investigator:	NFCARRIE
Referred To:	Not reported
Reported to Dept:	11/27/1991
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	12/3/1991
Spill Record Last Update:	12/6/2004
Spiller Name:	Not reported
Spiller Company:	JOHN A. PETTTINELLI
Spiller Address:	814 BRADFORD DRIVE
Spiller City,St,Zip:	ROME, NY 13440
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	6
DER Facility ID:	41201
DEC Memo:	Bonnie Riggi ag RALPH MIRABELLO 339-7648 CITY OF ROME7/14/04 wells closed.....7/1/04 called mirabella, first he wanted wells left in place then changed his mind. fax'd NW to close all 4 mw-s & let me know when scheduled.5/24/04 ralph miriabelo city called, city did codes inspection & found several violation, in process of getting permits to demo building, asked what needed from us--nothing4/21/04 final qs of 3 remaining mw's , minor hits.July/august 2003 dig out4/30/03 in process of setting up to do digout4/1/3-Eric called, need trailer in Massena, notifying us of it'sgoing.3/31/3 qrr of q1/03, requested dig out plan by 4/30/033/14/3 veshcio called al ash/ water running onto sidewalk &freezing. site visit,water coming out of mw by front when pump on. I shut pumps off & verified findings withPES who had tecks inroute. PES called later, told them to shut system down untilspring.1/9/3 pes resampled 1/3, @lab 1/7 w/24 hour turn. inf 1434+29mtbe, eff. clean1/2/3 Eric called, pes screwed up. lewis sampled, put in frig & went on vacation.lab did effwithin holding but not inf. told him to resample @no charge & do 24 hourturn at no costto us & include/submit treatment report.12/26/2 PES brought in treatment trailer Oct/nov 02. pump from MW-9sampled inf/eff 12/2/2samples to lab 12/17, w/24 hr TURN1/24/1 fax from watson, doing bi-monthly on 1/25.1/8/1 fax from mike watson, doing bi-monthly checks/system samples 11/16/00/working on q report/problems with pump & meter/ may do heat tape.01/5/1 queried pes re: site visits & system..11/14/00 pes to service system & sample 01/1610/10/00 email from dd/site visit 10/4 inst. seq agent, put orc sockin RW, cleaned air stripper pump etc, .35' in MW-310/03/00 phonex from dave dake-marcor not to work in r-6 any more, will do oct site checks and send mw data. pinned precision,sent last q report & letter06/15/2000 email from dake, gw pump shot, needs replacement-ok'dMon, 15 May 2000

J A CAR WASH (Continued) **1000791723**

Dave,1. Let me review the Feb>April report before deciding onmonthly hi-vac's.2. On May 3 we decided for Marcor to do product bailing during every site visit and drum the product. I think there is a drum in the shed that use to store product from theproduct pump. I think this drum may be somewhat full. Have it checked duringthe next visit and see if it needs to be emptied. In either case use thatdrum to store the bailed product.Wed, 3 May 2000 qs 5/2, System running on arrival and departure.little product in MW-2 (0.02') and in MW-3 (0.07') - therefore not sampled. to put adrumon-site and hand-bail the product wells whenever we are on-site? (yes) Thedrumcontents could be pumped out whenever we are onsite w/ the vac truckdoing the extractionwork. There's probably room for the drum inside the shed. I'm still talking to AuburnArmature regarding the blower starter andwhy the new one didnt work (still hard-wired now- in an emergency you wouldneed to shut off at the breaker panel). Dave dake april 19, 2000 vac'd wellsmarch 22, 2000 vac'd wellsTue, 22 Feb 2000 vac'ng wells TODAY11/27/91: SPOKE WITH JOHN PETTINELLI, HE SAID LEVEL GOING UP & DOWN - DOESN'T KNOW WHAT TO DO, WILL NEED TO RETEST OR TAKE OUT OF SERVICE. (DJ).11/27/91: TANK FAILURE LETTER SENT. (DJ).12/16/91: TANK THAT FAILED TANK TEST REMOVED/3 HOLES NOTED IN TANK (BOTTOM & SIDE) PRODUCT BLEEDING OUT OF BANK & EXCAVATION CONTAM. FROM TOP DOWN. (DP).12/17/91: CONTRACTOR EXCAVATING TRENDS FOR NEW LINES. SOIL CONTAM. (DP).12/22/92: FOLLOW-UP GWI & SOIL DISPOSAL LETTER SENT. (DJ).02/01/93: ACCESS LETTER SENT. (DJ0.03/03/93: MET DOUG HURLBERT - MARCOR - VIEWED SITE SPOTTED 4XMW. (NC).04/20/93: MARCOR MEASURED DT WALL WELLS - BAILED PRODUCT OUT OF MW-3 APPROX. 1 GAL. / NO PRODUCT RECHARGE. (NC).04/28/93: BAILED 6 GALLONS PRODUCT.11/23/94: CONTAMINATED SOIL (109 YDS) DISPOSED OF. (JM).01/17/95: SOIL DISPOSAL PAPERWORK RECEIVED. (JM).08/25/98: PHONE CALL FROM PAUL LAPLANTE 336-1572, P.O. BOX 565, ROME, NY 13442. PURCHASED PROPERTY AT TAX AUCTION FROM COUNTY.04/05/99: SITE VISIT, BAILED 17 GALLONS FROM TANK PIT WELL. GAS ODOR, NO PRODUCT OR SHEEN. COULD DRAW DOWN WITH BAILER, RECOVERY SEEMED ADEQUATE.04/15/99: PHONEX W/ ROB YAGER-MARCOR, DID PUMP DOWN TEST COULD GET 7GPM FROM NEW WELL, INFLUENCED 2&3. HAVENT' BEEN GETTING ANY PRODUCT OUT OF 3 FOR SOME TIME. RECOVERY OF RW IS VERY SLOW. OK'D MOVING DEPRESSION PUMP TO THE NEW WELL AND RUN TO SEE WHAT IT DOES.05/05/99 NANCY MORRELLE 793-8725 WORKING WITH PAUL LAPLANTE WHO IS INTERESTED IN OPERATING CAR WASH. ADVISED HER REMEDIATION WILL TAKE AT LEAST 2-3 MORE YEARS BUT THAT SHOULDNT RESTRICT OPERATION IF THEY WANTED TO. SHE WANTS TO MEET ON SITE SO I CAN SHOW WHAT OUR PLANS ARE.11/18/02: PES MOVED TREATMENT TRAILER TO SITE & SET UP TO PUMP FROM MW-9 & DISCHARGE TO OUR OUTFALL. 11/20/2003: OBSERVED GEO-PROBE WORK BY PRECISION ENV., POSSIBLY LOCATED 2 ADDITIONAL TANKS (ECL).08/18/2003: PES STARTED SOURCE REMOVAL 8/5/03. FOUND 2 ADDITIONAL UST'S ON MR. VESCHIO'S PROPERTY. THEY REMOVED & CLEANED THEM, VESCHIO TO REGISTER THEM & PAY COSTS FOR THIS. CONTINUED DIGGING UNTIL AUGUST 15, 2003. PRODUCT ON GROUNDWATER LATER IN AREA BETWEEN MW-3 & GARAGE. ON 8/18/03 APPEAR TO BE IN PROCESS OF BACKFILLING.10/22/2004: Spill closed. Final ISR submitted. (DJ)

Remarks: SUSPECT AIR POCKET - WILL EXCAVATE, ISOLATE AND RETEST.

Material:

Site ID: 230487
Operable Unit ID: 959352
Operable Unit: 01
Material ID: 417844

J A CAR WASH (Continued) **1000791723**

Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False
Site ID:	230487
Operable Unit ID:	959352
Operable Unit:	01
Material ID:	2096633
Material Code:	1213A
Material Name:	MTBE (METHYL-TERT-BUTYL ETHER)
Case No.:	01634044
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	230487
Spill Tank Test:	1539357
Tank Number:	1
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

UST:

Id/Status:	6-140848 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	6
Expiration Date:	03/24/1997
UTM X:	462673.71625
UTM Y:	4784105.1385899996
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	41677
Affiliation Type:	Facility Owner
Company Name:	JOHN A. PETTINELLI
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	814 BRADFORD DRIVE
Address2:	Not reported
City:	ROME
State:	NY
Zip Code:	13440

J A CAR WASH (Continued) **1000791723**

Country Code:	001
Phone:	(315) 336-5458
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	41677
Affiliation Type:	Mail Contact
Company Name:	JOHN A. PETTINELLI
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	814 BRADFORD DRIVE
Address2:	Not reported
City:	ROME
State:	NY
Zip Code:	13440
Country Code:	001
Phone:	(315) 336-5458
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	41677
Affiliation Type:	On-Site Operator
Company Name:	J A CAR WASH
Contact Type:	Not reported
Contact Name:	JOHN A. PETTINELLI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(315) 337-1094
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	41677
Affiliation Type:	Emergency Contact
Company Name:	JOHN A. PETTINELLI
Contact Type:	Not reported
Contact Name:	DOMINICK PETTINELLI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(315) 337-1094
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

J A CAR WASH (Continued) **1000791723**

Tank Info:

Tank Number:	001
Tank ID:	114977
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	Not reported
Date Tank Closed:	12/01/1991
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	00
Date Test:	05/01/1986
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number:	002
Tank ID:	114978
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	Not reported
Date Tank Closed:	10/01/1993
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	00
Date Test:	05/01/1986
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
A01 - Tank Internal Protection - Epoxy Liner

J A CAR WASH (Continued) **1000791723**

D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 003
Tank ID: 114979
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2000
Install Date: Not reported
Date Tank Closed: 10/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 00
Date Test: 05/01/1986
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 004
Tank ID: 114980
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2000
Install Date: Not reported
Date Tank Closed: 10/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 00
Date Test: 05/01/1986
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT

J A CAR WASH (Continued) **1000791723**

Last Modified: 03/04/2004

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 005
Tank ID: 114981
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2000
Install Date: Not reported
Date Tank Closed: 10/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 00
Date Test: 05/01/1986
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number: 006
Tank ID: 119932
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 12/01/1991
Date Tank Closed: 10/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

J A CAR WASH (Continued) **1000791723**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

B02 - Tank External Protection - Original Sacrificial Anode
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
F05 - Pipe External Protection - Jacketed
J01 - Dispenser - Pressurized Dispenser
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
G04 - Tank Secondary Containment - Double-Walled (Underground)
I03 - Overfill - Automatic Shut-Off

Tank Number: 007
Tank ID: 121076
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2000
Install Date: Not reported
Date Tank Closed: 10/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

I00 - Overfill - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

HIST UST:
PBS Number: 6-140848
SPDES Number: Not reported
Emergency Contact: DOMINICK PETTINELLI
Emergency Telephone: (315) 337-1094
Operator: JOHN A. PETTINELLI
Operator Telephone: (315) 337-1094
Owner Name: JOHN A. PETTINELLI

J A CAR WASH (Continued) **1000791723**

Owner Address:	814 BRADFORD DRIVE
Owner City,St,Zip:	ROME, NY 13440
Owner Telephone:	(315) 336-5458
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Name:	JOHN A. PETTINELLI
Mailing Address:	814 BRADFORD DRIVE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	ROME, NY 13440
Mailing Contact:	Not reported
Mailing Telephone:	(315) 336-5458
Owner Mark:	First Owner
Facility Status:	2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Facility Addr2:	Not reported
SWIS ID:	3013
Old PBS Number:	Not reported
Facility Type:	RETAIL GASOLINE SALES
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	03/09/1992
Expiration Date:	03/24/1997
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	0
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	0
Dead Letter:	False
CBS Number:	Not reported
Town or City:	ROME (C)
County Code:	30
Town or City:	13
Region:	6
Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	4000
Product Stored:	LEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Not reported
Dispenser:	Suction
Date Tested:	05/01/1986

J A CAR WASH (Continued) **1000791723**

Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: 12/01/1991
Test Method: Unknown
Deleted: False
Updated: True
Lat/long: Not reported

Tank Id: 002
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (gals): 4000
Product Stored: UNLEADED GASOLINE
Tank Type: Steel/carbon steel
Tank Internal: Epoxy Liner
Tank External: Not reported
Pipe Location: Underground
Pipe Type: GALVANIZED STEEL
Pipe Internal: Not reported
Pipe External: Not reported
Second Containment: None
Leak Detection: None
Overfill Prot: Not reported
Dispenser: Suction
Date Tested: 05/01/1986
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: 10/01/1993
Test Method: Unknown
Deleted: False
Updated: True
Lat/long: Not reported

Tank Id: 003
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (gals): 2000
Product Stored: UNLEADED GASOLINE
Tank Type: Steel/carbon steel
Tank Internal: Not reported
Tank External: Not reported
Pipe Location: Underground
Pipe Type: GALVANIZED STEEL
Pipe Internal: Not reported
Pipe External: Not reported
Second Containment: None
Leak Detection: None
Overfill Prot: Not reported
Dispenser: Suction
Date Tested: 05/01/1986
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: 10/01/1993

J A CAR WASH (Continued) **1000791723**

Test Method:	Unknown
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	004
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	2000
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Underground
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Not reported
Dispenser:	Suction
Date Tested:	05/01/1986
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	10/01/1993
Test Method:	Unknown
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	005
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	2000
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Underground
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Not reported
Dispenser:	Suction
Date Tested:	05/01/1986
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	10/01/1993
Test Method:	Unknown
Deleted:	False
Updated:	True

J A CAR WASH (Continued) **1000791723**

Lat/long: Not reported

Tank Id: 007
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (gals): 2000
Product Stored: LEADED GASOLINE
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Underground
Pipe Type: Not reported
Pipe Internal: Not reported
Pipe External: Not reported
Second Containment: Not reported
Leak Detection: Not reported
Overfill Prot: Not reported
Dispenser: Not reported
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: Minor Data Missing
Date Closed: 10/01/1993
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

B13 **J A CAR WASH** **MANIFEST S117563507**
WNW **229 S JAMES ST** **N/A**
< 1/8 **ROME, NY 13440**
0.051 mi.
268 ft. **Site 8 of 9 in cluster B**

Relative:
Higher

Actual:
440 ft.

NY MANIFEST:
EPA ID: NYD987032406
Country: USA
Location Address 1: S ST JAMES ST
Location Address 2: Not reported
Location City: ROME
Location State: NY
Location Zip Code: 13440
Location Zip Code 4: Not reported

Mailing Info:
Name: J A CAR WASH
Contact: JOHN A PETTINELLI
Address: S JAMES ST
City/State/Zip: ROME, NY 13440
Country: USA
Phone: 315-337-1094

Manifest:

Document ID: NYB5867874
Manifest Status: Completed copy
Trans1 State ID: NYHU5857

J A CAR WASH (Continued) **S117563507**

Trans2 State ID:	Not reported
Generator Ship Date:	10/13/1993
Trans1 Recv Date:	10/13/1993
Trans2 Recv Date:	/ /
TSD Site Recv Date:	10/13/1993
Part A Recv Date:	11/09/1993
Part B Recv Date:	10/28/1993
Generator EPA ID:	NYD987032406
Trans1 EPA ID:	NYD986941607
Trans2 EPA ID:	Not reported
TSDF ID:	NYD095577342
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	03086
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1993

Document ID:	NYB5867883
Manifest Status:	Completed copy
Trans1 State ID:	NYAU5857
Trans2 State ID:	Not reported
Generator Ship Date:	10/18/1993
Trans1 Recv Date:	10/18/1993
Trans2 Recv Date:	/ /
TSD Site Recv Date:	10/18/1993
Part A Recv Date:	/ /
Part B Recv Date:	11/04/1993
Generator EPA ID:	NYD987032406
Trans1 EPA ID:	NYD986941607
Trans2 EPA ID:	Not reported
TSDF ID:	NYD095577342
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	02338
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1993

D14 **AM/PM MINI MARKET** **NY Spills** **S102163714**
North **NORTH JAMES ST** **N/A**
< 1/8 **ROME C, NY**
0.055 mi.
292 ft. **Site 1 of 10 in cluster D**

Relative:
Higher

Actual:
442 ft.

SPILLS:

Facility ID:	8500642
Facility Type:	ER
DER Facility ID:	193178
Site ID:	234511
DEC Region:	6
Spill Date:	5/22/1985
Spill Number/Closed Date:	8500642 / 5/22/1985

AM/PM MINI MARKET (Continued) **S102163714**

Spill Cause:	Human Error
Spill Class:	Not reported
SWIS:	3300
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	5/22/1985
CID:	Not reported
Water Affected:	MOHAWK RIVER
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	5/22/1985
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	Not reported
Spill Record Last Update:	12/2/2003
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was " "10/12/95: This is additional information about material spilled from the translation of the old spill file: DRY CHEM FIRE-LBS
Remarks:	Not reported

Material:

Tank Test:

B15
NW
< 1/8
0.057 mi.
300 ft.

Relative: Higher

Actual: 440 ft.

ROME F.D. **NY Spills** **S102162518**
200 SOUTH JAMES PARK LOT **N/A**
ROME C, NY

Site 9 of 9 in cluster B

SPILLS:

Facility ID:	8904741
Facility Type:	ER
DER Facility ID:	144986
Site ID:	172265
DEC Region:	6
Spill Date:	8/12/1989
Spill Number/Closed Date:	8904741 / 8/12/1989
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	3300
Investigator:	NFCARRIE
Referred To:	Not reported
Reported to Dept:	8/12/1989
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Passenger Vehicle

ROME F.D. (Continued) **S102162518**

Spill Notifier:	Fire Department
Cleanup Ceased:	8/12/1989
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	Not reported
Spill Record Last Update:	12/2/2003
Spiller Name:	Not reported
Spiller Company:	GERALD DODGE
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Not reported
Remarks:	8/12/89 - FEUL TANK RUPTURE / FIRE DEPT. FLUSHED INTO SEWER /

Material:

Site ID:	172265
Operable Unit ID:	932346
Operable Unit:	01
Material ID:	448773
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

16
ENE
< 1/8
0.061 mi.
321 ft.

VALVOLINE QUICK CHANGE **NY Spills** **S102160785**
176 BLACK RIVER BLVD **N/A**
ROME C, NY

Relative:
Higher

Actual:
444 ft.

SPILLS:

Facility ID:	9012064
Facility Type:	ER
DER Facility ID:	91899
Site ID:	103954
DEC Region:	6
Spill Date:	2/19/1991
Spill Number/Closed Date:	9012064 / 12/12/1995
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	3300
Investigator:	NFCARRIE
Referred To:	Not reported
Reported to Dept:	2/19/1991

VALVOLINE QUICK CHANGE (Continued) **S102160785**

CID:	Not reported
Water Affected:	TRIB. OF MOHAWK
Spill Source:	Commercial/Industrial
Spill Notifier:	Fire Department
Cleanup Ceased:	6/6/1992
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2/25/1991
Spill Record Last Update:	12/13/1995
Spiller Name:	Not reported
Spiller Company:	VALVOLINE QUICK CHANGE
Spiller Address:	115 TWIN OAKS DRIVE
Spiller City,St,Zip:	SYRACUSE, NY 13012
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Not reported
Remarks:	MATERIAL LEAKING OUT OF BUILDING & GOING INTO SEWER. NO ACTION TAKEN AS OF YET.

Material:

Site ID:	103954
Operable Unit ID:	951930
Operable Unit:	01
Material ID:	428571
Material Code:	0016A
Material Name:	NON PCB OIL
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

D17 **SE CORNER OF JAMES ST & ERIE BLVD** **BROWNFIELDS** **S113916465**
North **131-37 SOUTH JAMES STREET** **N/A**
< 1/8 **ROME, NY 13440**
0.062 mi.
328 ft. **Site 2 of 10 in cluster D**

Relative: Higher

Actual: 442 ft.

BROWNFIELDS:

Program:	BCP
Site Code:	356404
Acres:	1.000
HW Code:	C633071
SWIS:	3313
Town:	Rome (c)
Update By:	DACROSBY
Site Description:	This BCP Application was for remediation of the property to allow for development of a new Walgreens Drug Store. The application has been denied. This site is located at 131-37 South James Street in the City

SE CORNER OF JAMES ST & ERIE BLVD (Continued) **S113916465**

of Rome and is approximately 1 acre in size. The BCP application was denied in 2006 because the current owner was already addressing the site in the DEC Spill Program.

Env Problem: Not reported
Health Problem: Not reported

D18 **SUNOCO #0353-2254** **NY Spills** **S107410216**
North **131 SOUTH JAMES STREET** **N/A**
< 1/8 **ROME, NY**
0.062 mi.
328 ft. **Site 3 of 10 in cluster D**

Relative:
Higher

Actual:
442 ft.

SPILLS:

Facility ID:	8402303
Facility Type:	ER
DER Facility ID:	154780
Site ID:	185023
DEC Region:	6
Spill Date:	11/27/1984
Spill Number/Closed Date:	8402303 / 7/10/2008
Spill Cause:	Equipment Failure
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	3313
Investigator:	JCDOYLE
Referred To:	Not reported
Reported to Dept:	11/27/1984
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Fire Department
Cleanup Ceased:	6/17/2008
Cleanup Meets Std:	False
Last Inspection:	8/22/2007
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	9/22/1986
Spill Record Last Update:	7/10/2008
Spiller Name:	Not reported
Spiller Company:	arco
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MASON"2004/02/19 - Both Spill_Time and RCVD_Time were previously blank and replaced with "00:00" to fix a data translation problem... Bob Corcoran11/18/88: RESPONSE, STATUS REQUEST FORWARDED TO MR. SWANBERG FOR HANDLING (JM).12/06/88: OFFICE MEETING/SWANBERG (ARCO) AND MARTIN (ROUX) WILL DO MONTHLY GWO MEASUREMENTS AND 1/4 SAMPLING/PROPOSAL & WORK SCHEDULE TO BE SUBMITTED (JM).03/15/89: IX & HEWETT, ROUX ASSOCIATES MEASURED & SAMPLED WELLS/ RW1A - THIN FILM & OW7. 03' PRODUCT NOT SAMPLED (NC).05/02/89: ROUX ASSOC. RAN DRAWDOWN TESTS AND RECOVERY TESTS (NC).11/15/89: RECOVERY SYSTEM FIRED UP/DEPRESSION & RECOVERY PUMP/PROCESSING THRU 4X CARBON DRUMS/NC.02/05/91: ROUX ASSOCIATES SAMPLING. (NC).08/07/91: ROUX

SUNOCO #0353-2254 (Continued) **S107410216**

BAILED & SAMPLED/.02 FEET PRODUCT MW 3 & 7/RECOVERY WELL CLEAR. (NC).02/06/92: ROUX SAMPLED/REPORT NO PRODUCT LAYER ANY WELL/EGGAN ON SITE REPAIRING RECOVERY PUMP. (NC).01/04/93: JOHN CEPLO ROUX - SYSTEM BACK IN SERVICE 12/29/92 - TO Q SAMPLE FEB. (NC).08/30/95: CONTAMINATED SOIL (380 YDS) DISPOSED OF (JM).10/24/95: SOIL DISPOSAL PAPERWORK RECEIVED (JM).11/23/04: File review: A groundwater pump and treat system was installed in Nov of 1989 and operated through July 1995. The recovery well for the system was located to the west of the station building near a former generation of abandoned in- place USTs. The extent of the contamination was never determined. The last sample from the recovery well had low levels of contamination but nearby MW # 7 still had BTEX levels around 32 ppm. The remaining wells had shown significant BTEX reductions over the 7 years of analysis. MtBE levels were low hundred ppb range. Groundwater is around 14' below grade and doesn't have much gradient. The abandoned tanks and 570 tons of soil were excavated in August of 1995. Post excavation samples of the North, East, and South walls were acceptable. The West wall had significant hits of BTEX totaling 86 ppm with several compounds exceeding TAGM 4046. A bottom sample was not collected for analysis. Soils underlying the tanks were described as fill material down to 12', the native material is glacio fluvial sand and gravel deposits and glacial till. A vapor extraction had been installed after the tank removal and operated until March of 1997. The radius of influence of the system had not been determined nor was any post shutdown monitoring conducted. The vapor point was located along the west wall of the former tank field, but not beyond. The system had single digit levels on the pid for several months before being shut down. Sun and their consultant have asked for closure of the site most recently in a February 15, 1999 letter. We responded in February 19,1999 letter that insufficient evidence was presented to support closure. The site does not appear to represent a significant threat to potential receptors but has not been adequately addressed. (tv)11/23/04: Called Vin Moresco GES. Discussed status of site. Sun has not currently scheduled any project work for the site. I told him the site is not closed and Sun remains responsible. (tv)9/14/2005: PROPOSED SUBSURFACE INVESTIGATION WORKPLAN RECEIVED FROM GES ON 9/12/2005. SOIL BORINGS AND WELL DRILLING OCCURED ON 9/12-13/2005 BEFORE WORKPLAN WAS REVIEWED OR APPROVED. LETTER SENT (JD)2/28/2006: BACK & CO. AND GES ON SITE FOR TANK PULL. 3 - 12,000 GAL FIBERGLASS TANKS. (JD)3/2/2006: DEC REVIEW LETTER OF SUBSURFACE INVESTIGATION REPORT, DATED 1/12/2006 & PREPARED BY GES. (JD) 3/31/2006: REMEDIAL PILOT TEST WORK PLAN SUBMITTED BY GES - WORK TO BE DONE 4/4-5/2006. (JD)4/24/2006: UST CLOSURE REPORT BY GES. 3 -12,000 GAL FIGERGLASS UST'S, PIPING AND DISPENSER ISLAND REMOVED. CONFIRMATORY SOIL SAMPLES INCLUDED. (JD)8/17/2006: 2ND QUARTER SAMPLING REPORT REVIEWED. (JD)12/29/2006: DEC LETTER - REVIEWED PILOT TEST SUMMARY REPORT AND 3RD QUARTER 2006 SITE SUMMARY REPORT. AGREE WITH CONCLUSION OF PILOT TEST REPORT THAT VAPOR ENHANCED GROUNDWATER EXTRACTION (VEGE)AND THE TOTAL PHASE EXTRACTION (TPE) TECHNOLOGIES WOULD NOT BE EFFECTIVE FOR REMEDIATING THIS SITE. (JD)2/6/2007: REVIEWED 4TH QUARTER 2006 PROJECT STATUS REPORT. NEW CONSULTANT - MULRY AND CRESSWELL ENVIRONMENTAL, INC. BEN HAITH 315 294-5648. REMEDIATION ACTION PLAN TO BE SUBMITTED FOR INSTALLATION OF OXYGEN INJECTION SYSTEM IN 2ND QUARTER 2007. (JD)6/13/2007: REVIEWED FIRST QUARTER 2007, QUARTERLY PROJECT STATUS UPDATE REPORT. UPDATED SAMPLING DATA AND INDICATION THAT A RAP WILL BE SUBMITTED 2ND QUARTER, 2007 FOR OXYGEN INJECTION. 6/12/2007 TELEPHONE CONVERSATION

SUNOCO #0353-2254 (Continued) **S107410216**

WITH BILL BROCHU, SUNOCO REGARDING REMEDIAL EXCAVATION AT THIS SITE AND SCREENING TESTS OF OVERBURDEN. (JD) 8/8/2007: REVIEW WORKPLAN AND QUARTERLY STATUS REPORT PREPARED BY MULRY & CRESSWELL. WORKPLAN APPROVED FOR EXCAVATION OF CONTAMINATED SOILS. (JD)8/20/2007: ON SITE WITH BEN HAITH, MULRY & CRESSWELL: SHORING FOR EXCAVATION DELAYED, ETA UNKNOWN. PLAN TO DIG ~10 CLEAN OVERBURDEN, PETROLEUM CONTAMINATED SOILS AT 10-16 FEET. WILL DIG TO 10 PPM HEADSPACE PIDS, OR PROPERTY BOUNDARY. EPA 8260 FINAL SAMPLES.(SR) 8/22/2007: ON SITE WITH BILL BROCHU, SUNOCO AND BEN HAITH AND JIM CRESSWELL, MULRY & CRESSWELL. SHORING INSTALLED AND EXCAVATION OF PETROLEUM IMPACTED SOILS COMPLETED TO APPROXIMATELY 16'. 250 - 300 TONS STORED ON PLASTIC AND COVERED. PLAN TO INSTALL WELL ACROSS SOUTH JAMES STREET. (JD)7/10/2008: REVIEWED SOIL EXCAVATION REPORT PREPARED BY MULRY AND CRESWELL ENVIRONMENTAL AND DATED 1/28/2008. SLIDE RAIL SHORING INSTALLED AND SOILS EXCAVATED AT THE CORNER OF ERIE BLVD AND SOUTH JAMES STREETS TO A DEPTH OF 16'. SOME BOTTOM SOIL SAMPLES EXCEEDED TAGM FOR BENZENE, XYLENE AND MTBE. SOILS REMOVED TO THE MAXIMUM EXTENT PRACTICLE. DISPOSAL RECEIPTS FOR 363.69 TONS OF SOIL TO ONEIDA HERKIMER SOLID WASTE AUTHORITY LANDFILL IN AVA, NY. OFF SITE MONITORING WELL REPORT PREPARED BY MATRIX ENVIRONMENTAL AND DATED 6/17/2008 REVIEWED. DOWNGRADIENT OFF SITE MONITORING WELL SUBURFACE LOG, ANALYTICAL FOR SOIL AND GROUNDWATER WERE ALL NOT DETECTED. NO FURTHER ACTION NEEDED. (JD)

Remarks: Not reported

Material:

Site ID:	185023
Operable Unit ID:	894409
Operable Unit:	01
Material ID:	482127
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False
Site ID:	185023
Operable Unit ID:	894409
Operable Unit:	01
Material ID:	2096433
Material Code:	1213A
Material Name:	MTBE (METHYL-TERT-BUTYL ETHER)
Case No.:	01634044
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

D19 **APLUS FACILITY #60003** **LTANKS** **S100131626**
North **131 SOUTH JAMES ST** **N/A**
< 1/8 **ROME C, NY**
0.063 mi.
331 ft. **Site 4 of 10 in cluster D**

Relative:
Higher

Actual:
442 ft.

LTANKS:

Site ID:	225260
Spill Number/Closed Date:	0200885 / 5/28/2002
Spill Date:	4/23/2002
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	5/3/2002
Cleanup Meets Standard:	True
SWIS:	3300
Investigator:	NFCARRIE
Referred To:	Not reported
Reported to Dept:	4/23/2002
CID:	233
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	4/23/2002
Spill Record Last Update:	5/31/2002
Spiller Name:	BOB JONES
Spiller Company:	ATLANTIC R & M
Spiller Address:	1801 MARKET STREET
Spiller City,St,Zip:	PHILADELPHIA, PA 19103-
Spiller County:	001
Spiller Contact:	YVONNE MONTE
Spiller Phone:	(215) 246-8509
Spiller Extention:	Not reported
DEC Region:	6
DER Facility ID:	185951
DEC Memo:	Not reported
Remarks:	line was tested and failed line is known to be leaking in sump containment contractor is scheduled to do repair soon retest to follow repair

Material:

Site ID:	225260
Operable Unit ID:	851709
Operable Unit:	01
Material ID:	522315
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

APLUS FACILITY #60003 (Continued) **S100131626**

Tank Test:

Site ID:	225260
Spill Tank Test:	1527071
Tank Number:	Not reported
Tank Size:	0
Test Method:	01
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Petro-Tite/Petro Comp

Site ID:	225261
Spill Number/Closed Date:	8702667 / 3/20/1990
Spill Date:	7/2/1987
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Not reported
Cleanup Ceased:	7/3/1987
Cleanup Meets Standard:	True
SWIS:	3300
Investigator:	DIJOHNSO
Referred To:	Not reported
Reported to Dept:	7/2/1987
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	7/2/1987
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	7/3/1987
Spill Record Last Update:	3/22/1990
Spiller Name:	Not reported
Spiller Company:	ATLANTIC REF & MKTG CORP
Spiller Address:	PO BOX 1260
Spiller City,St,Zip:	SOUTHEASTERN, PA 19398
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	6
DER Facility ID:	185951
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "JOHNSON" / / : 7/2/87 - SPOKE W/JOHN MALINOWSKI - DIRECTED HIM TO SHUT DOWN SYSTEM UNTIL REPAIRS AND RETESTING ARE COMPLETED (DJ).07/03/87: CONTRACTOR FOUND UNION AT SUBMERSIBLE "SWEATING." MADE REPAIRS. RETESTED TIGHT - +.006 GPH. (DJ).03/24/89: ATLANTIC SUBMITTED LINE TEST REPORT. (DJ).03/20/90: CLOSED. (DJ).10/12/95: This is additional information about material spilled from the translation of the old spill file: REGULAR LEADED.
Remarks:	-.0135 GPH LINE FAILURE; 12K TANK; PBS #065633; TANK #001(?)

Material:

Site ID:	225261

APLUS FACILITY #60003 (Continued) **S100131626**

Operable Unit ID:	909183
Operable Unit:	01
Material ID:	468936
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Not reported
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	225261
Spill Tank Test:	1531052
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

D20 **SUNOCO #0363-2254** **UST U002260193**
North **131 SOUTH JAMES & ERIE BLVD** **HIST UST N/A**
< 1/8 **ROME, NY 13440**
0.066 mi.
346 ft. **Site 5 of 10 in cluster D**

Relative:
Higher

Actual:
442 ft.

UST:

Id/Status:	6-065633 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	6
Expiration Date:	12/02/2006
UTM X:	462757.40977999999
UTM Y:	4784212.9589799996
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	41245
Affiliation Type:	Facility Owner
Company Name:	ATLANTIC REFINING & MARKETING CORP.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	1801 MARKET STREET, 20/10 PC
Address2:	Not reported
City:	PHILADELPHIA
State:	PA
Zip Code:	19103
Country Code:	001
Phone:	(215) 246-8513
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT

SUNOCO #0363-2254 (Continued) **U002260193**

Date Last Modified: 3/4/2004

Site Id: 41245
Affiliation Type: Mail Contact
Company Name: ATLANTIC REFINING & MARKETING CORP.
Contact Type: Not reported
Contact Name: UST COORDINATOR
Address1: 1801 MARKET STREET
Address2: 20/10 PC
City: PHILADELPHIA
State: PA
Zip Code: 19103
Country Code: 001
Phone: (215) 246-8513
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 41245
Affiliation Type: On-Site Operator
Company Name: SUNOCO #0363-2254
Contact Type: Not reported
Contact Name: RAJA PETROLEUM CORP.
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (315) 339-4881
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 41245
Affiliation Type: Emergency Contact
Company Name: Not reported
Contact Type: Not reported
Contact Name: GRETCHEN TUTTLE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: 7163) 660-221
EMail: Not reported
Fax Number: Not reported
Modified By: BVCAMPBE
Date Last Modified: 7/6/2010

Tank Info:

Tank Number: 001
Tank ID: 113697

SUNOCO #0363-2254 (Continued) **U002260193**

Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 12000
Install Date: 12/01/1984
Date Tank Closed: 02/28/2006
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 21
Date Test: 04/14/2005
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: DIJOHNSO
Last Modified: 03/14/2006

Equipment Records:

C02 - Pipe Location - Underground/On-ground
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
F05 - Pipe External Protection - Jacketed
G00 - Tank Secondary Containment - None
J01 - Dispenser - Pressurized Dispenser
H05 - Tank Leak Detection - In-Tank System (ATG)
B00 - Tank External Protection - None
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I01 - Overfill - Float Vent Valve

Tank Number: 002
Tank ID: 113698
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 12000
Install Date: 12/01/1984
Date Tank Closed: 02/28/2006
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 21
Date Test: 04/14/2005
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: DIJOHNSO
Last Modified: 03/14/2006

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
C02 - Pipe Location - Underground/On-ground
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
F05 - Pipe External Protection - Jacketed
G00 - Tank Secondary Containment - None

SUNOCO #0363-2254 (Continued) **U002260193**

J01 - Dispenser - Pressurized Dispenser
B00 - Tank External Protection - None
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I01 - Overfill - Float Vent Valve

Tank Number:	003
Tank ID:	113699
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	12000
Install Date:	12/01/1984
Date Tank Closed:	02/28/2006
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	21
Date Test:	04/14/2005
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	DIJOHNSO
Last Modified:	03/14/2006

Equipment Records:

C02 - Pipe Location - Underground/On-ground
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
F05 - Pipe External Protection - Jacketed
G00 - Tank Secondary Containment - None
J01 - Dispenser - Pressurized Dispenser
H05 - Tank Leak Detection - In-Tank System (ATG)
B00 - Tank External Protection - None
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I01 - Overfill - Float Vent Valve

Tank Number:	004
Tank ID:	122116
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	Not reported
Date Tank Closed:	08/01/1995
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

SUNOCO #0363-2254 (Continued) **U002260193**

Equipment Records:

A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number:	005
Tank ID:	122117
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	Not reported
Date Tank Closed:	08/01/1995
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number:	006
Tank ID:	122118
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	Not reported
Date Tank Closed:	08/01/1995
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

SUNOCO #0363-2254 (Continued) **U002260193**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number: 007
Tank ID: 122119
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 6000
Install Date: Not reported
Date Tank Closed: 08/01/1995
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:
I00 - Overfill - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

HIST UST:
PBS Number: 6-065633
SPDES Number: Not reported
Emergency Contact: LARRY BALLAY
Emergency Telephone: (800) 786-9494
Operator: RAJA PETROLEUM CORP.
Operator Telephone: (315) 339-4881
Owner Name: ATLANTIC REFINING & MARKETING CORP.

SUNOCO #0363-2254 (Continued) **U002260193**

Owner Address:	1801 MARKET STREET, 20/10 PC
Owner City,St,Zip:	PHILADELPHIA, PA 19103
Owner Telephone:	(215) 246-8513
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Name:	ATLANTIC REFINING & MARKETING CORP.
Mailing Address:	1801 MARKET STREET
Mailing Address 2:	20/10 PC
Mailing City,St,Zip:	PHILADELPHIA, PA 19103
Mailing Contact:	UST COORDINATOR
Mailing Telephone:	(215) 246-8513
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2:	Not reported
SWIS ID:	3013
Old PBS Number:	Not reported
Facility Type:	RETAIL GASOLINE SALES
Inspected Date:	06/20/1995
Inspector:	HM
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	10/29/2001
Expiration Date:	12/02/2006
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	36000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	No Missing Data
Dead Letter:	False
CBS Number:	Not reported
Town or City:	ROME (C)
County Code:	30
Town or City:	13
Region:	6

Tank Id:	004
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	4000
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	Not reported
Leak Detection:	Not reported
Overfill Prot:	Not reported
Dispenser:	Not reported

SUNOCO #0363-2254 (Continued) **U002260193**

Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	08/01/1995
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	005
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	4000
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	Not reported
Leak Detection:	Not reported
Overfill Prot:	Not reported
Dispenser:	Not reported
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	08/01/1995
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	006
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	4000
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	Not reported
Leak Detection:	Not reported
Overfill Prot:	Not reported
Dispenser:	Not reported
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing

SUNOCO #0363-2254 (Continued) **U002260193**

Date Closed:	08/01/1995
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	007
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	6000
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	Not reported
Leak Detection:	Not reported
Overfill Prot:	Not reported
Dispenser:	Not reported
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	08/01/1995
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

D21 **NEW WALGREENS CONSTRUCTION SITE** **NY Spills** **S108637799**
North **SOUTH JAMES AND ERIE** **N/A**
< 1/8 **ROME, NY**
0.067 mi.
353 ft. **Site 6 of 10 in cluster D**

Relative:
Higher

Actual:
443 ft.

SPILLS:

Facility ID:	0702658
Facility Type:	ER
DER Facility ID:	331829
Site ID:	382414
DEC Region:	6
Spill Date:	6/4/2007
Spill Number/Closed Date:	0702658 / 6/4/2007
Spill Cause:	Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	3313
Investigator:	screichi
Referred To:	Not reported
Reported to Dept:	6/4/2007
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other

NEW WALGREENS CONSTRUCTION SITE (Continued) **S108637799**

Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	6/4/2007
Spill Record Last Update:	6/6/2007
Spiller Name:	UNKNOWN
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	001
Contact Name:	SAM CONVENTINO
Contact Phone:	(315) 569-6333
DEC Memo:	06/05/2007: REDUNDANT SPILL. SEE SPILL # 0600485. (SR)
Remarks:	FOUND A TANK WHILE DIGGING CAN SMELL IT BUT CANT SEE ANYTHING: WOULD LIKE SOMEONE TO CHECK IT OUT

Material:

Site ID:	382414
Operable Unit ID:	1139813
Operable Unit:	01
Material ID:	2129856
Material Code:	0012A
Material Name:	Kerosene
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

D22 **AM/PM MINI MART** **LTANKS** **S102676890**
North **5 JAMES & ERIE BLVD** **N/A**
< 1/8 **ROME C, NY**
0.073 mi.
384 ft. **Site 7 of 10 in cluster D**

Relative:
Higher

Actual:
445 ft.

LTANKS:

Site ID:	67857
Spill Number/Closed Date:	8500741 / 5/28/1985
Spill Date:	5/24/1985
Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Not reported
Cleanup Ceased:	5/28/1985
Cleanup Meets Standard:	True
SWIS:	3300
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	5/24/1985
CID:	Not reported
Water Affected:	MOHAWK RIVER

AM/PM MINI MART (Continued) **S102676890**

Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	Not reported
Spill Record Last Update:	12/2/2003
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller City,St,Zip:	***Update***, ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	6
DER Facility ID:	64784
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was " " Not reported
Remarks:	Not reported

Material:

Site ID:	67857
Operable Unit ID:	895087
Operable Unit:	01
Material ID:	482655
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	4
Units:	Not reported
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

C23 **U-HAUL** **NY Spills** **S102161556**
SE **244 ERIE BLVD EAST** **N/A**
< 1/8 **ROME, NY**
0.074 mi.
389 ft. **Site 2 of 5 in cluster C**

Relative:
Higher

Actual:
440 ft.

SPILLS:

Facility ID:	9210138
Facility Type:	ER
DER Facility ID:	118763
Site ID:	138902
DEC Region:	6
Spill Date:	11/24/1992
Spill Number/Closed Date:	9210138 / 12/18/2006
Spill Cause:	Equipment Failure
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	3313

U-HAUL (Continued) **S102161556**

Investigator:	JCDOYLE
Referred To:	Not reported
Reported to Dept:	11/24/1992
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	DEC
Cleanup Ceased:	9/6/2006
Cleanup Meets Std:	True
Last Inspection:	6/7/2006
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	12/4/1992
Spill Record Last Update:	12/18/2006
Spiller Name:	ROBERT FRALEY, ENV. MGR.
Spiller Company:	AMERCO REAL ESTATE COMPANY
Spiller Address:	2727 NORTH CENTRAL AVE, SUITE 500
Spiller City,St,Zip:	PHOENIX, AZ 85004
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "JOHNSON"01/28/93: CONTAMINATED SOIL (70 YDS) DISPOSED OF. (JM).12/22/94: SOIL DISPOSED OF. (JM).12/22/94: SOIL DISPOSAL PAPERWORK RECEIVED - 104.4 TONS(JM).07/23/1996: STIP SIGNED. (JM)01/13/2003: REVIEWED FILE. CONTRACTOR HIRED TO PERFORM INVESTIGATION BUT NO WORK DONE. (DJ)2/1/2006: FILE REVIEW, TELECON W/ ROB FRALEY, ENV MGR - AMERCO STILL OWNS PROPERTY, FAXED INFORMATION (602)277-5824 AND SENT LETTER REQUESTING ACTION ON APPROVED CAP. (JD)05/05/2006: REMINDER LETTER SENT. (JD)5/19/2006: SUBSURFACE INVESTIGATION WORK PLAN DATED 5/16/2006 BY ERM - APPROVED. (JD)12/15/2006: REVIEWED SITE CHARTERIZAATION ACTIVITIES REPORT FOR UHAUL DATED 9/6/2006 AND PREPARED BY ERM, DEWITT. 9 BORINGS, 3 NEW MONITORING WELLS, 11 SOIL SAMPLES, 6 GW SAMPLES. ALL ANALYTICAL RESULTS NON DETECT. 1994 SOIL DISPOSAL RECEIPTS FOR 104.4 TONS AT SUGAR CREEK, GENEVA NY. ADDITIONAL REMEDIATION WORK MAY HAVE OCCURRED BETWEEN 1996 AND 2006 BUT NO DOCUMENTATION IS AVAILABLE. NO FURTHER ACTION NEEDED. CLOSE SPILL. (JD)
Remarks:	CONTAMINATION NOTED AROUND MANWAYS & FILLS & UNDER BOTH 6000'S. ALSO NOTED OLD PIPING W/FUEL OIL IN THEM, BUT TANKS GASOLINE.

Material:

Site ID:	138902
Operable Unit ID:	976598
Operable Unit:	01
Material ID:	407142
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Pounds
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

U-HAUL (Continued) **S102161556**

Tank Test:
- Site ID: 138902
- Spill Tank Test: 1540909
- Tank Number: Not reported
- Tank Size: 0
- Test Method: 00
- Leak Rate: 0
- Gross Fail: Not reported
- Modified By: Spills
- Last Modified: 10/1/2004
- Test Method: Unknown

C24 **U HAUL** **UST** **U001847189**
SE **244 ERIE BLVD EAST** **HIST UST** **N/A**
< 1/8 **ROME C, NY 13440**
0.074 mi.
389 ft. **Site 3 of 5 in cluster C**

Relative:
Higher

Actual:
440 ft.

UST:
- Id/Status: 6-022985 / Unregulated/Closed
- Program Type: PBS
- Region: STATE
- DEC Region: 6
- Expiration Date: 09/19/1996
- UTM X: 462905.12121000001
- UTM Y: 4783873.2327399999
- Site Type: Trucking/Transportation/Fleet Operation

Affiliation Records:
- Site Id: 41058
- Affiliation Type: Facility Owner
- Company Name: U HAUL OF NORTHEASTERN NY
- Contact Type: Not reported
- Contact Name: Not reported
- Address1: 139 BROADWAY
- Address2: Not reported
- City: ALBANY
- State: NY
- Zip Code: 12202
- Country Code: 001
- Phone: (518) 449-8511
- EMail: Not reported
- Fax Number: Not reported
- Modified By: THKNIZEK
- Date Last Modified: 12/1/2010

- Site Id: 41058
- Affiliation Type: Mail Contact
- Company Name: U HAUL OF NORTHEASTERN NY
- Contact Type: Not reported
- Contact Name: Not reported
- Address1: 139 BROADWAY
- Address2: Not reported
- City: ALBANY
- State: NY
- Zip Code: 12202
- Country Code: 001

U HAUL (Continued) **U001847189**

Phone:	(518) 449-8511
EMail:	Not reported
Fax Number:	Not reported
Modified By:	THKNIZEK
Date Last Modified:	12/1/2010

Site Id:	41058
Affiliation Type:	On-Site Operator
Company Name:	U HAUL
Contact Type:	Not reported
Contact Name:	U HAUL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NY
Zip Code:	Not reported
Country Code:	001
Phone:	(315) 339-3110
EMail:	Not reported
Fax Number:	Not reported
Modified By:	THKNIZEK
Date Last Modified:	12/1/2010

Site Id:	41058
Affiliation Type:	Emergency Contact
Company Name:	U HAUL OF NORTHEASTERN NY
Contact Type:	Not reported
Contact Name:	JAME SERVELLO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(315) 735-0786
EMail:	Not reported
Fax Number:	Not reported
Modified By:	THKNIZEK
Date Last Modified:	12/1/2010

Tank Info:

Tank Number:	001
Tank ID:	113131
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	6000
Install Date:	Not reported
Date Tank Closed:	11/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	05
Date Test:	05/01/1987

U HAUL (Continued) **U001847189**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number: 002
Tank ID: 113132
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 6000
Install Date: Not reported
Date Tank Closed: 11/01/1992
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 05
Date Test: 05/01/1987
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number: 003
Tank ID: 113133
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 1000
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground

U HAUL (Continued) **U001847189**

Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

HIST UST:

PBS Number: 6-022985
SPDES Number: Not reported
Emergency Contact: JAME SERVELLO
Emergency Telephone: (315) 735-0786
Operator: U HAUL
Operator Telephone: (315) 339-3110
Owner Name: U HAUL OF NORTHEASTERN NY
Owner Address: 139 BROADWAY
Owner City,St,Zip: ALBANY, NY 12202
Owner Telephone: (518) 449-8511
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Name: U HAUL OF NORTHEASTERN NY
Mailing Address: 139 BROADWAY
Mailing Address 2: Not reported
Mailing City,St,Zip: ALBANY, NY 12202
Mailing Contact: Not reported
Mailing Telephone: (518) 449-8511
Owner Mark: First Owner
Facility Status: 2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Facility Addr2: Not reported
SWIS ID: 3013
Old PBS Number: Not reported
Facility Type: TRUCKING/TRANSPORTATION
Inspected Date: Not reported
Inspector: Not reported
Inspection Result: Not reported
Federal ID: Not reported
Certification Flag: False
Certification Date: 11/25/1991
Expiration Date: 09/19/1996
Renew Flag: False

U HAUL (Continued) **U001847189**

Renewal Date:	Not reported
Total Capacity:	1000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	No Missing Data
Dead Letter:	False
CBS Number:	Not reported
Town or City:	ROME (C)
County Code:	30
Town or City:	13
Region:	6

Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	6000
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	05/01/1987
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	11/01/1992
Test Method:	Ainlay
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	002
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	6000
Product Stored:	LEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction

U HAUL (Continued) **U001847189**

Date Tested:	05/01/1987
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	11/01/1992
Test Method:	Ainlay
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	003
Tank Location:	UNDERGROUND
Tank Status:	In Service
Install Date:	Not reported
Capacity (gals):	1000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

C25 **REVERE PRINTING** **UST** **U004199206**
SE **100 BOUCK STREET** **N/A**
< 1/8 **ROME C, NY 13440**
0.076 mi.
399 ft. **Site 4 of 5 in cluster C**

Relative:
Higher

Actual:
440 ft.

UST:

Id/Status:	6-600750 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	6
Expiration Date:	11/03/2003
UTM X:	462929.82256
UTM Y:	4783876.9610400004
Site Type:	Utility (Other than Municipal)

Tank Info:

Tank Number:	1
Tank ID:	124233
Tank Status:	Closed - Removed
Material Name:	Closed - Removed

REVERE PRINTING (Continued) **U004199206**

Capacity Gallons:	2000
Install Date:	Not reported
Date Tank Closed:	08/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Tank Number:	2
Tank ID:	124234
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	500
Install Date:	Not reported
Date Tank Closed:	08/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Tank Number:	3
Tank ID:	124235
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	6000
Install Date:	Not reported
Date Tank Closed:	08/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

C26 **REVERE PRINTING INC** **RCRA-CESQG** **1000790245**
SE **100 BOUCK ST** **FINDS** **NYD987017233**
< 1/8 **ROME, NY 13440** **HIST UST**
0.076 mi. **MANIFEST**
399 ft. **Site 5 of 5 in cluster C** **NY Spills**

Relative: Higher

Actual: 440 ft.

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	REVERE PRINTING INC
Facility address:	100 BOUCK ST ROME, NY 13440
EPA ID:	NYD987017233
Mailing address:	BOUCK ST ROME, NY 13440
Contact:	KEVIN MALLARD
Contact address:	BOUCK ST ROME, NY 13440
Contact country:	US
Contact telephone:	(315) 339-2224
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	LAKES DEVELOPMENT LTD PARTNERSHIP
Owner/operator address:	100 BOUCK ST ROME, NY 13440
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	LAKES DEVELOPMENT LTD PARTNERSHIP
Owner/operator address:	100 BOUCK ST ROME, NY 13440
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

REVERE PRINTING INC (Continued) **1000790245**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: REVERE PRINTING INC
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 10/07/1992
Site name: REVERE PRINTING INC
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

FINDS:

Registry ID: 110004495804

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HIST UST:
PBS Number: 6-600750
SPDES Number: Not reported
Emergency Contact: RUSSELL MALLARD
Emergency Telephone: (315) 339-2224
Operator: N/A
Operator Telephone: (315) 339-2224
Owner Name: RICHARD PETROSKI
Owner Address: 6417 ANDEREGG DRIVE
Owner City,St,Zip: ROME, NY 13440
Owner Telephone: (315) 336-3784
Owner Type: Corporate/Commercial

REVERE PRINTING INC (Continued) **1000790245**

Owner Subtype:	Not reported
Mailing Name:	RICHARD PETROSKI
Mailing Address:	6417 ANDEREGG DRIVE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	ROME, NY 13440
Mailing Contact:	Not reported
Mailing Telephone:	(315) 336-3784
Owner Mark:	First Owner
Facility Status:	2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Facility Addr2:	Not reported
SWIS ID:	3013
Old PBS Number:	Not reported
Facility Type:	UTILITY
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	11/04/1998
Expiration Date:	11/03/2003
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	0
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	Minor Data Missing
Tank Screen:	0
Dead Letter:	False
CBS Number:	Not reported
Town or City:	ROME (C)
County Code:	30
Town or City:	13
Region:	6

Tank Id:	1
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	2000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	08/01/1998
Test Method:	Not reported

REVERE PRINTING INC (Continued) **1000790245**

Deleted: False
Updated: True
Lat/long: Not reported

Tank Id: 2
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (gals): 500
Product Stored: UNKNOWN
Tank Type: Other
Tank Internal: None
Tank External: None
Pipe Location: Underground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: None
Second Containment: None
Leak Detection: None
Overfill Prot: None
Dispenser: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: 08/01/1998
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

Tank Id: 3
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (gals): 6000
Product Stored: KEROSENE
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Underground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: None
Second Containment: None
Leak Detection: None
Overfill Prot: None
Dispenser: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: 08/01/1998
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

REVERE PRINTING INC (Continued) **1000790245**

NY MANIFEST:

EPA ID:	NYD987017233
Country:	USA
Location Address 1:	100 BOUCK ST
Location Address 2:	Not reported
Location City:	ROME
Location State:	NY
Location Zip Code:	13440
Location Zip Code 4:	Not reported

Mailing Info:

Name:	REVERE PRINTING
Contact:	K MALLARD
Address:	100 BOUCK ST
City/State/Zip:	ROME, NY 13440
Country:	USA
Phone:	315-339-2224

Manifest:

Document ID:	NYC6856020
Manifest Status:	Not reported
Trans1 State ID:	NY18096JB
Trans2 State ID:	Not reported
Generator Ship Date:	11/11/2002
Trans1 Recv Date:	11/11/2002
Trans2 Recv Date:	11/19/2002
TSD Site Recv Date:	11/20/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987017233
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	MOD095038998
TSDF ID:	KYD053348108
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00060
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2002

Document ID:	NJA1635467
Manifest Status:	Completed copy
Trans1 State ID:	NYGV7044
Trans2 State ID:	NJDEPS869
Generator Ship Date:	04/07/1993
Trans1 Recv Date:	04/07/1993
Trans2 Recv Date:	04/12/1993
TSD Site Recv Date:	04/13/1993
Part A Recv Date:	04/15/1993
Part B Recv Date:	04/30/1993
Generator EPA ID:	NYD987017233
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	ILD051060408

REVERE PRINTING INC (Continued) **1000790245**

TSDF ID:	NJD002182897
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00459
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1993

Document ID:	MAM9665420
Manifest Status:	Not reported
Trans1 State ID:	NYLJ5601
Trans2 State ID:	Not reported
Generator Ship Date:	06/27/2001
Trans1 Recv Date:	06/27/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/09/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987017233
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	Not reported
TSDF ID:	MAD982755639
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00270
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Year:	2001

Document ID:	NJA3205444
Manifest Status:	Not reported
Trans1 State ID:	08690
Trans2 State ID:	H10364
Generator Ship Date:	01/10/2001
Trans1 Recv Date:	01/10/2001
Trans2 Recv Date:	01/11/2001
TSD Site Recv Date:	01/16/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987017233
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	SCR000074591
TSDF ID:	NJD002182897
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00125
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2001

REVERE PRINTING INC (Continued) **1000790245**

Document ID:	NJA4012335
Manifest Status:	Not reported
Trans1 State ID:	08690
Trans2 State ID:	Not reported
Generator Ship Date:	12/11/2001
Trans1 Recv Date:	12/11/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/18/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987017233
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00125
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2001

Document ID:	MAM6208570
Manifest Status:	Not reported
Trans1 State ID:	NYLJ5601
Trans2 State ID:	Not reported
Generator Ship Date:	10/19/2000
Trans1 Recv Date:	10/19/2000
Trans2 Recv Date:	10/23/2000
TSD Site Recv Date:	10/31/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987017233
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	SCR000074591
TSDF ID:	MAD982755639
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00270
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Year:	2000

Document ID:	NJA3082557
Manifest Status:	Not reported
Trans1 State ID:	08690
Trans2 State ID:	H10364
Generator Ship Date:	05/03/2000
Trans1 Recv Date:	05/03/2000
Trans2 Recv Date:	05/04/2000
TSD Site Recv Date:	05/09/2000
Part A Recv Date:	Not reported

REVERE PRINTING INC (Continued) **1000790245**

Part B Recv Date: Not reported
Generator EPA ID: NYD987017233
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: SCR000074591
TSDF ID: NJD002182897
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00125
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2000

Document ID: NJA3046822
Manifest Status: Not reported
Trans1 State ID: 08690
Trans2 State ID: H10364
Generator Ship Date: 08/27/1999
Trans1 Recv Date: 08/27/1999
Trans2 Recv Date: 08/30/1999
TSD Site Recv Date: 09/01/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD987017233
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: SCD987574647
TSDF ID: NJD002182897
Waste Code: D001 - NON-LISTED IGNITABLE WASTES
Quantity: 00129
Units: P - Pounds
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 1999

Document ID: MAJ4823430
Manifest Status: Not reported
Trans1 State ID: ILP256377
Trans2 State ID: Not reported
Generator Ship Date: 01/13/1998
Trans1 Recv Date: 01/13/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/26/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD987017233
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: MAD982755639
Waste Code: D011 - SILVER 5.0 MG/L TCLP
Quantity: 00142
Units: P - Pounds
Number of Containers: 001

REVERE PRINTING INC (Continued) **1000790245**

Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Year:	1998

Document ID:	NJA2791029
Manifest Status:	Not reported
Trans1 State ID:	08690
Trans2 State ID:	H10364
Generator Ship Date:	10/16/1998
Trans1 Recv Date:	10/16/1998
Trans2 Recv Date:	10/19/1998
TSD Site Recv Date:	10/23/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987017233
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID:	NJD002182897
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00235
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1998

Document ID:	NJA2663797
Manifest Status:	Completed copy
Trans1 State ID:	08690
Trans2 State ID:	Not reported
Generator Ship Date:	02/12/1997
Trans1 Recv Date:	02/12/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	02/14/1997
Part A Recv Date:	02/28/1997
Part B Recv Date:	02/26/1997
Generator EPA ID:	NYD987017233
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00235
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1997

Document ID:	NJA2080705
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPE086

REVERE PRINTING INC (Continued) **1000790245**

Trans2 State ID:	Not reported
Generator Ship Date:	03/13/1996
Trans1 Recv Date:	03/13/1996
Trans2 Recv Date:	/ /
TSD Site Recv Date:	03/19/1996
Part A Recv Date:	03/25/1996
Part B Recv Date:	04/05/1996
Generator EPA ID:	NYD987017233
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00234
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00277
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1996

Document ID:	NJA2148645
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPE086
Trans2 State ID:	Not reported
Generator Ship Date:	05/31/1995
Trans1 Recv Date:	05/31/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	06/06/1995
Part A Recv Date:	06/12/1995
Part B Recv Date:	06/22/1995
Generator EPA ID:	NYD987017233
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00234
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1995

Document ID:	NJA2148699
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPE086
Trans2 State ID:	Not reported
Generator Ship Date:	07/20/1995

REVERE PRINTING INC (Continued) **1000790245**

Trans1 Recv Date: 07/20/1995
Trans2 Recv Date: / /
TSD Site Recv Date: 07/28/1995
Part A Recv Date: 08/01/1995
Part B Recv Date: 08/14/1995
Generator EPA ID: NYD987017233
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID: NJD002182897
Waste Code: D011 - SILVER 5.0 MG/L TCLP
Quantity: 00280
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1995

Document ID: TXA0906345
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: NYGV7044
Trans2 State ID: 41853
Generator Ship Date: 11/04/1994
Trans1 Recv Date: 11/04/1994
Trans2 Recv Date: 11/15/1994
TSD Site Recv Date: 11/17/1994
Part A Recv Date: 12/07/1994
Part B Recv Date: 01/03/1995
Generator EPA ID: NYD987017233
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: ARD981908551
TSDF ID: TXD077603371
Waste Code: D011 - SILVER 5.0 MG/L TCLP
Quantity: 00509
Units: P - Pounds
Number of Containers: 001
Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1994

Document ID: NJA1829160
Manifest Status: Completed copy
Trans1 State ID: NYGV7044
Trans2 State ID: 08690
Generator Ship Date: 08/26/1994
Trans1 Recv Date: 08/26/1994
Trans2 Recv Date: 08/31/1994
TSD Site Recv Date: 09/01/1994
Part A Recv Date: / /
Part B Recv Date: 09/19/1994
Generator EPA ID: NYD987017233
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: ILD984908202
TSDF ID: NJD002182897

REVERE PRINTING INC (Continued) **1000790245**

Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00429
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1994

Document ID:	MAQ2268400
Manifest Status:	Not reported
Trans1 State ID:	NY18096JB
Trans2 State ID:	T465GLNJ
Generator Ship Date:	06/25/2002
Trans1 Recv Date:	06/25/2002
Trans2 Recv Date:	07/09/2002
TSD Site Recv Date:	07/10/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987017233
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	NJD071629976
TSDF ID:	MAD982755639
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Quantity:	00275
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Year:	2002

SPILLS:

Facility ID:	9804875
Facility Type:	ER
DER Facility ID:	198290
Site ID:	241169
DEC Region:	6
Spill Date:	7/20/1998
Spill Number/Closed Date:	9804875 / 11/6/1998
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	3313
Investigator:	NFCARRIE
Referred To:	Not reported
Reported to Dept:	7/20/1998
CID:	323
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False

REVERE PRINTING INC (Continued) **1000790245**

Remediation Phase: 0
Date Entered In Computer: 7/20/1998
Spill Record Last Update: 6/19/2013
Spiller Name: RICHARD PETROSKI
Spiller Company: RICHARD PETROSKI
Spiller Address: 6417 ANDEREGG DRIVE
Spiller City,St,Zip: ROME, NY 13440-
Spiller Company: 001
Contact Name: RUSSELL MALLORD
Contact Phone: Not reported
DEC Memo: Not reported
Remarks: TANK WILL BE REMOVED AND SOIL WILL BE STOCKPILED.

Material:
Site ID: 241169
Operable Unit ID: 1065924
Operable Unit: 01
Material ID: 319637
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

D27 **ARCO PETROLEUM PRODUCTS CO** **RCRA NonGen / NLR** **1000326449**
NNE **ST JAMES & ERIE** **MANIFEST** **NYD982716458**
< 1/8 **ROME, NY 13440**
0.076 mi.
403 ft. **Site 8 of 10 in cluster D**

Relative:
Higher

Actual:
446 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: ARCO PETROLEUM PRODUCTS CO
Facility address: ST JAMES & ERIE
ROME, NY 13440
EPA ID: NYD982716458
Mailing address: S FLOWER ST
LOS ANGELES, NY 90071
Contact: Not reported
Contact address: S FLOWER ST
LOS ANGELES, NY 90071
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: A PLUS MINI-MARKET

ARCO PETROLEUM PRODUCTS CO (Continued) **1000326449**

Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: A PLUS MINI-MARKET
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: ARCO PETROLEUM PRODUCTS CO
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: ARCO PETROLEUM PRODUCTS CO
Classification: Not a generator, verified

Date form received by agency: 10/18/1988
Site name: ARCO PETROLEUM PRODUCTS CO
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

NY MANIFEST:
EPA ID: NYD982716458
Country: USA

ARCO PETROLEUM PRODUCTS CO (Continued) **1000326449**

Location Address 1: ST JAMES STATION ERIE BLVD
Location Address 2: Not reported
Location City: ROME
Location State: NY
Location Zip Code: 13440
Location Zip Code 4: Not reported

Mailing Info:
Name: ARCO PRODUCTS COMPANY
Contact: WALTER HUFFORD
Address: EXEC OFFICE LINK
City/State/Zip: MALVERN 5 GREAT VLY PKWY, PA 19355
Country: USA
Phone: 215-648-3903

Manifest:

Document ID: NYB1855332
Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID: 45873VNY
Trans2 State ID: Not reported
Generator Ship Date: 08/03/1990
Trans1 Recv Date: 08/03/1990
Trans2 Recv Date: / /
TSD Site Recv Date: 08/03/1990
Part A Recv Date: 09/13/1990
Part B Recv Date: 09/11/1990
Generator EPA ID: NYD982716458
Trans1 EPA ID: NYD000708271
Trans2 EPA ID: Not reported
TSDF ID: NYD043815703
Waste Code: F003 - UNKNOWN
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 090
Year: 1990

D28 **UNKNOWN** **NY Spills** **S102569776**
NNE **SOUTH JAMES ST & ERIE BLV** **N/A**
< 1/8 **ROME C, NY**
0.076 mi.
403 ft. **Site 9 of 10 in cluster D**

Relative:
Higher

Actual:
446 ft.

SPILLS:
Facility ID: 8705966
Facility Type: ER
DER Facility ID: 168612
Site ID: 202714
DEC Region: 6
Spill Date: 10/15/1987
Spill Number/Closed Date: 8705966 / 10/15/1987
Spill Cause: Equipment Failure
Spill Class: Not reported
SWIS: 3300
Investigator: AJMARSCH

UNKNOWN (Continued) **S102569776**

Referred To:	Not reported
Reported to Dept:	10/15/1987
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Fire Department
Cleanup Ceased:	10/15/1987
Cleanup Meets Std:	True
Last Inspection:	10/15/1987
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	Not reported
Spill Record Last Update:	12/2/2003
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Not reported
Remarks:	CONTAINED ON PAVEMENT/MUCH MATERIAL TRACKED ALONG RD BY TRAFFIC/CITY DPW APPLIED SAND & SWEEPER TO PICK UP LATER TONIGHT.

Material:

Site ID:	202714
Operable Unit ID:	909784
Operable Unit:	01
Material ID:	464986
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	4
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

D29 **ROUTE 49/69** **NY Spills** **S102163911**
NNW **COR. NYS ROUTE 49 & 69** **N/A**
< 1/8 **W. ROME C, NY**
0.088 mi.
466 ft. **Site 10 of 10 in cluster D**

Relative:
Higher

Actual:
440 ft.

SPILLS:

Facility ID:	9405004
Facility Type:	ER
DER Facility ID:	184623
Site ID:	223285
DEC Region:	6
Spill Date:	7/12/1994
Spill Number/Closed Date:	9405004 / 7/13/1994
Spill Cause:	Unknown

ROUTE 49/69 (Continued) **S102163911**

Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	3300
Investigator:	NFCARRIE
Referred To:	Not reported
Reported to Dept:	7/12/1994
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Local Agency
Cleanup Ceased:	7/13/1994
Cleanup Meets Std:	True
Last Inspection:	7/13/1994
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	Not reported
Spill Record Last Update:	12/2/2003
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Not reported
Remarks:	NEAR GAS STATION - CITGO - NYNEX WAS PLACING CONDUIT, & NOTICED ODOR.

Material:

Site ID:	223285
Operable Unit ID:	999283
Operable Unit:	01
Material ID:	381608
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Not reported
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

E30 **AGWAY ROME FEED CO-OP** **NY Spills** **S102160945**
West **312 S JAMES ST** **N/A**
< 1/8 **ROME C, NY**
0.090 mi.
475 ft. **Site 1 of 6 in cluster E**

Relative:
Lower

Actual:
438 ft.

SPILLS:

Facility ID:	9104791
Facility Type:	ER
DER Facility ID:	256713
Site ID:	318488
DEC Region:	6

AGWAY ROME FEED CO-OP (Continued) **S102160945**

Spill Date:	8/2/1991
Spill Number/Closed Date:	9104791 / 8/2/1991
Spill Cause:	Housekeeping
Spill Class:	Not reported
SWIS:	3300
Investigator:	MASON
Referred To:	Not reported
Reported to Dept:	8/2/1991
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	8/2/1991
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	Not reported
Spill Record Last Update:	12/2/2003
Spiller Name:	Not reported
Spiller Company:	AGWAY ROME FEED CO-OP
Spiller Address:	312 S. JAMES STREET
Spiller City,St,Zip:	ROME, NY 13440
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MASON"08/02/91: REMARKS CONT. - WASHED HANDS AT HOME/STILL SMELLED PRODUCT/NOTIFIED ROME CITY SAFETY OFFICE. 08/02/91: PER MGR. SOME SULFUR (YELLOW) ON FLOOR, NOT PINK/NO SPILL, ODORS TYPICAL OF CHEMICALS STORED/HAS NOT RECEIVED CUSTOMER COMPLAINT/CLOSED/WAINWRIGHT HAS INFO. (HM).10/12/95: This is additional information about material spilled from the translation of the old spill file: UNKNOWN PEST/HERB.
Remarks:	HEAVY DUST ON COUNTER & STACKS OF BAGS OF PRODUCT, BLACK STAIN ON FLOOR NEAR WHERE TILES HAD BEEN REMOVED/HEAVY CHEMICAL ODOR IN AISLE/METALLIC TASTE IN MOUTH/CUSTOMER GOT DUST ON HANDS(SEE HISTORY)

Material:

Tank Test:

E31 **ROME AGWAY COOP INC** **RCRA NonGen / NLR** **1000547819**
West **312 S JAMES ST** **FINDS** **NYD099892150**
< 1/8 **ROME, NY 13440** **MANIFEST**
0.091 mi.
478 ft. **Site 2 of 6 in cluster E**

Relative:
Lower

Actual:
438 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	ROME AGWAY COOP INC
Facility address:	312 S JAMES ST ROME, NY 13440
EPA ID:	NYD099892150
Mailing address:	PO BOX 4933 SYRACUSE, NY 13221

ROME AGWAY COOP INC (Continued) **1000547819**

Contact: Not reported
Contact address: PO BOX 4933
SYRACUSE, NY 13221
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: AGWAY INC
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: AGWAY INC
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: ROME AGWAY COOP INC
Classification: Not a generator, verified

Date form received by agency: 07/14/1999
Site name: ROME AGWAY COOP INC
Classification: Small Quantity Generator

ROME AGWAY COOP INC (Continued) **1000547819**

Violation Status: No violations found

FINDS:

Registry ID: 110009469315

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID:	NYD099892150
Country:	USA
Location Address 1:	312 S JAMES ST
Location Address 2:	Not reported
Location City:	ROME
Location State:	NY
Location Zip Code:	13440
Location Zip Code 4:	Not reported

Mailing Info:

Name:	ROME AGWAY INC
Contact:	ROME AGWAY INC
Address:	312 S JAMES ST
City/State/Zip:	ROME, NY 13440
Country:	USA
Phone:	315-337-5220

Manifest:

Document ID:	NYC4619147
Manifest Status:	Not reported
Trans1 State ID:	NYNF6576
Trans2 State ID:	HQ23216
Generator Ship Date:	02/26/1998
Trans1 Recv Date:	02/26/1998
Trans2 Recv Date:	03/04/1998
TSD Site Recv Date:	03/05/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD099892150
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	MOD095038998
TSDF ID:	KYD053348108
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00248
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1998

ROME AGWAY COOP INC (Continued) **1000547819**

Document ID:	NYC4366675
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NYGV7044
Trans2 State ID:	12138PNY
Generator Ship Date:	07/02/1997
Trans1 Recv Date:	07/02/1997
Trans2 Recv Date:	07/07/1997
TSD Site Recv Date:	07/08/1997
Part A Recv Date:	07/30/1997
Part B Recv Date:	07/30/1997
Generator EPA ID:	NYD099892150
Trans1 EPA ID:	NYD980769947
Trans2 EPA ID:	NYD980769947
TSDF ID:	KYD053348108
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00240
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1997

Document ID:	NJA2253491
Manifest Status:	Completed copy
Trans1 State ID:	NJDEPE086
Trans2 State ID:	Not reported
Generator Ship Date:	03/11/1996
Trans1 Recv Date:	03/11/1996
Trans2 Recv Date:	/ /
TSD Site Recv Date:	03/15/1996
Part A Recv Date:	03/20/1996
Part B Recv Date:	03/28/1996
Generator EPA ID:	NYD099892150
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00239
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1996

Document ID:	NJA2259689
Manifest Status:	Completed after the designated time period for a TSDF to get a copy to the DEC
Trans1 State ID:	NJDEPE086
Trans2 State ID:	Not reported
Generator Ship Date:	08/27/1996
Trans1 Recv Date:	08/27/1996
Trans2 Recv Date:	/ /
TSD Site Recv Date:	09/04/1996
Part A Recv Date:	09/12/1996

ROME AGWAY COOP INC (Continued) **1000547819**

Part B Recv Date:	09/25/1996
Generator EPA ID:	NYD099892150
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00240
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1996

Document ID:	NJA2663744
Manifest Status:	Completed copy
Trans1 State ID:	08690
Trans2 State ID:	Not reported
Generator Ship Date:	01/31/1997
Trans1 Recv Date:	01/31/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	02/07/1997
Part A Recv Date:	02/19/1997
Part B Recv Date:	02/24/1997
Generator EPA ID:	NYD099892150
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID:	NJD002182897
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00248
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1997

E32 **AGWAY, INC.** **UST** **U003758176**
West **312 SOUTH JAMES STREET** **HIST UST** **N/A**
< 1/8 **ROME C, NY 13440**
0.091 mi.
478 ft. **Site 3 of 6 in cluster E**

Relative:
Lower

Actual:
438 ft.

UST:

Id/Status:	6-600881 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	6
Expiration Date:	12/12/2005
UTM X:	462603.38757999998
UTM Y:	4784035.00459
Site Type:	Other Wholesale/Retail Sales

Affiliation Records:

Site Id:	43703
Affiliation Type:	Facility Owner
Company Name:	AGWAY, INC.

AGWAY, INC. (Continued) **U003758176**

Contact Type:	Not reported
Contact Name:	Not reported
Address1:	P.O BOX 4741
Address2:	Not reported
City:	SYRACUSE
State:	NY
Zip Code:	13221-4741
Country Code:	001
Phone:	(314) 449-6504
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	43703
Affiliation Type:	Mail Contact
Company Name:	AGWAY, INC.
Contact Type:	Not reported
Contact Name:	ROBERT T. CLARKE
Address1:	P.O BOX 4741
Address2:	Not reported
City:	SYRACUSE
State:	NY
Zip Code:	13221-4741
Country Code:	001
Phone:	(314) 449-6504
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	43703
Affiliation Type:	On-Site Operator
Company Name:	AGWAY, INC.
Contact Type:	Not reported
Contact Name:	AGWAY, INC.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(314) 449-6504
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	43703
Affiliation Type:	Emergency Contact
Company Name:	AGWAY, INC.
Contact Type:	Not reported
Contact Name:	ROBERT T. CLARKE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN

AGWAY, INC. (Continued) **U003758176**

Zip Code:	Not reported
Country Code:	001
Phone:	(314) 449-6504
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

Tank Number:	3
Tank ID:	124930
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	3000
Install Date:	Not reported
Date Tank Closed:	12/12/2000
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
H00 - Tank Leak Detection - None

Tank Number:	4
Tank ID:	124931
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	500
Install Date:	Not reported
Date Tank Closed:	12/12/2000
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported

AGWAY, INC. (Continued) **U003758176**

Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
H00 - Tank Leak Detection - None

HIST UST:

PBS Number:	6-600881
SPDES Number:	Not reported
Emergency Contact:	ROBERT T. CLARKE
Emergency Telephone:	(314) 449-6504
Operator:	AGWAY, INC.
Operator Telephone:	(314) 449-6504
Owner Name:	AGWAY, INC.
Owner Address:	P.O BOX 4741
Owner City,St,Zip:	SYRACUSE, NY 13221-4741
Owner Telephone:	(314) 449-6504
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Name:	AGWAY, INC.
Mailing Address:	P.O BOX 4741
Mailing Address 2:	Not reported
Mailing City,St,Zip:	SYRACUSE, NY 13221-4741
Mailing Contact:	ROBERT T. CLARKE
Mailing Telephone:	(314) 449-6504
Owner Mark:	First Owner
Facility Status:	2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Facility Addr2:	Not reported
SWIS ID:	3013
Old PBS Number:	Not reported
Facility Type:	OTHER RETAIL SALES
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	12/14/2000
Expiration Date:	12/12/2005
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	0
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	0
Dead Letter:	False
CBS Number:	Not reported
Town or City:	ROME (C)

AGWAY, INC. (Continued) **U003758176**

County Code: 30
Town or City: 13
Region: 6

Tank Id: 3
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (gals): 3000
Product Stored: LEADED GASOLINE
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: Painted/Asphalt Coating
Pipe Location: None
Pipe Type: NONE
Pipe Internal: None
Pipe External: None
Second Containment: None
Leak Detection: None
Overfill Prot: None
Dispenser: 0
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: 12/12/2000
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

Tank Id: 4
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (gals): 500
Product Stored: USED OIL
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: Painted/Asphalt Coating
Pipe Location: None
Pipe Type: NONE
Pipe Internal: None
Pipe External: None
Second Containment: None
Leak Detection: None
Overfill Prot: None
Dispenser: 0
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: 12/12/2000
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

F33 **METH LAB DISPOSAL SITE** **NY Spills** **S112226567**
East **RAILROAD ST / BOUCK ST INTERSECTION** **N/A**
< 1/8 **ROME, NY**
0.093 mi.
489 ft. **Site 1 of 2 in cluster F**

Relative:
Higher

Actual:
440 ft.

SPILLS:

Facility ID:	1205822
Facility Type:	ER
DER Facility ID:	423080
Site ID:	468793
DEC Region:	6
Spill Date:	9/11/2012
Spill Number/Closed Date:	1205822 / 11/14/2012
Spill Cause:	Deliberate
Spill Class:	Known release that creates a file or hazard. DEC Response. Unknown Responsible Party. Corrective action taken. (ISR)
SWIS:	3313
Investigator:	RAFURLON
Referred To:	Not reported
Reported to Dept:	9/11/2012
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Police Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	9/11/2012
Spill Record Last Update:	2/12/2014
Spiller Name:	TROOPER IVAN CHINIKAILO
Spiller Company:	METH LAB
Spiller Address:	RAILROAD ST / BOUCK ST INTERSECTION
Spiller City,St,Zip:	ROME, NY
Spiller Company:	999
Contact Name:	TROOPER IVAN CHINIKAILO
Contact Phone:	(315) 558-2888
DEC Memo:	onsite w/
Remarks:	Meth lab found in a field near above intersection. NYSP requesting a response for clean-up.

Material:

Site ID:	468793
Operable Unit ID:	1218707
Operable Unit:	01
Material ID:	2217121
Material Code:	9999
Material Name:	Other - Meth Lab
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Gallons
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	False

METH LAB DISPOSAL SITE (Continued) **S112226567**

Tank Test:

F34 **NIMO EXCAVATION** **NY Spills** **S106016251**
East **BOUCK & RAILROAD ST** **N/A**
< 1/8 **ROME C, NY**
0.093 mi.
490 ft. **Site 2 of 2 in cluster F**

Relative:
Higher

Actual:
440 ft.

SPILLS:

Facility ID:	0304087
Facility Type:	ER
DER Facility ID:	247563
Site ID:	306533
DEC Region:	6
Spill Date:	7/18/2003
Spill Number/Closed Date:	0304087 / 11/5/2003
Spill Cause:	Unknown
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Unknown Responsible Party. Corrective action taken. (ISR)
SWIS:	3300
Investigator:	JDALSANT
Referred To:	Not reported
Reported to Dept:	7/18/2003
CID:	199
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	True
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	7/18/2003
Spill Record Last Update:	6/20/2005
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller City,St,Zip:	NY
Spiller Company:	999
Contact Name:	STEVE ROBY
Contact Phone:	(315) 796-2403
DEC Memo:	07/18/2003: EXCAVATION HAS PRODUCT BUBBLING OUT OF GROUND. HIRE OP-TECH TO RESPOND MONDAY WITH VAC TRUCK (JA). 07/21/2003: VACUUMED EXCAVATION, WATER AND PRODUCT RECHARGING (JA). 07/22/2003: SET UP FRAC TANK (JA). 07/30/03: DISCHARGE FRAC TANK. (JA) 08/07/03: LOAD AND DISPOSE SOIL. (JA) 10/16/03: INITIATE FINAL ISR. (JA) 11/05/2003: FINAL ISR SUBMITTED. COMPLETE (DJ).10/18/04: received letter from Rome Water Pollution control stating they never received money for discharge of FRAc tank. Sent Letter to Op-Tech to pay or produce receipts.06/20/05: call Hal Piger (branch mngr) at Op-tech who stated that the outstanding balance had been paid. Called Bruce Clifford of Rome WPC who confirmed check # 66840 received 11/05/04 in the amount of $535.44.
Remarks:	while doing an excavation - a unk quantity of contaminated soil wasfound - unk source at this time - soil and ground water impacted

NIMO EXCAVATION (Continued) **S106016251**

Material:

Site ID:	306533
Operable Unit ID:	872344
Operable Unit:	01
Material ID:	504952
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

G35 **KEMP TRUCK REPAIR** **NY Spills** **S103936072**
SSE **CANAL STREET** **N/A**
< 1/8 **ROME, NY**
0.110 mi.
580 ft. **Site 1 of 5 in cluster G**

Relative:
Higher

Actual:
440 ft.

SPILLS:

Facility ID:	9900354
Facility Type:	ER
DER Facility ID:	253745
Site ID:	314726
DEC Region:	6
Spill Date:	4/9/1999
Spill Number/Closed Date:	9900354 / 6/8/2005
Spill Cause:	Deliberate
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	3313
Investigator:	NFCARRIE
Referred To:	Not reported
Reported to Dept:	4/9/1999
CID:	185
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	1/12/2000
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	4/9/1999
Spill Record Last Update:	6/20/2005
Spiller Name:	CLAIR KEMP
Spiller Company:	CLAIR A. KEMP
Spiller Address:	6371 PLEASANT DRIVE
Spiller City,St,Zip:	ROME, NY 13440-
Spiller Company:	001
Contact Name:	JENNY KEMP

KEMP TRUCK REPAIR (Continued) **S103936072**

Contact Phone: (315) 337-0980
DEC Memo: 9/28/99: ERNIE LUCANTONIO & I MET CLAIR KEMP ON SITE. OBSERVED A GARDEN HOSE RUNNING OUTSIDE BUILDING FROM GARAGE SUMP DRAIN. SUMP CONTAINED OILY WATER, GROUND STAINED & GRASS KILLED. ADVISED MR. KEMP TO STOP ANY MORE DISCHARGES & TO CLEANUP CONTAMINATED SOIL (DJ).12/21/99: SENT INVESTIGATION, CLEANUP LETTER (DJ).01/12/2000: SITE VISIT - LETTER SENT (NC)06/08/05: RP DECEASED, PROPERTY NOW OWNED BY OTHERS. CLOSED NMSS.
Remarks: Caller is a former employee of Kemp Oil. He was aware of the company allowing the dumping of petroleum products from the tank trucks inside the garage and then deliberately pumping it outside. He advises that the ground behind the garage is all black.

Material:
Site ID: 314726
Operable Unit ID: 1075129
Operable Unit: 01
Material ID: 557910
Material Code: 0012A
Material Name: Kerosene
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False
Site ID: 314726
Operable Unit ID: 1075129
Operable Unit: 01
Material ID: 557908
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False
Site ID: 314726
Operable Unit ID: 1075129
Operable Unit: 01
Material ID: 557909
Material Code: 0008
Material Name: Diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

E36
West
< 1/8
0.110 mi.
583 ft.

ROME AGWAY COOP INC
300 WEST STREET
ROME C, NY 13440

Site 4 of 6 in cluster E

Database(s): UST, HIST UST, AST, HIST AST

EDR ID Number: U003077238
EPA ID Number: N/A

Relative:
Higher

Actual:
439 ft.

UST:

Id/Status:	6-129526 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	6
Expiration Date:	03/24/1992
UTM X:	462566.57535
UTM Y:	4784076.9642399997
Site Type:	Unknown

Affiliation Records:

Site Id:	41592
Affiliation Type:	Facility Owner
Company Name:	AGWAY INC.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	5814 BRIDGE STREET
Address2:	Not reported
City:	EAST SYRACUSE
State:	NY
Zip Code:	13057
Country Code:	001
Phone:	(315) 449-7994
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	41592
Affiliation Type:	Mail Contact
Company Name:	AGWAY INC.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	5814 BRIDGE STREET
Address2:	Not reported
City:	EAST SYRACUSE
State:	NY
Zip Code:	13057
Country Code:	001
Phone:	(315) 449-7994
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	41592
Affiliation Type:	On-Site Operator
Company Name:	ROME AGWAY COOP INC
Contact Type:	Not reported
Contact Name:	ROME AGWAY COOP INC.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN

ROME AGWAY COOP INC (Continued) **U003077238**

Zip Code:	Not reported
Country Code:	001
Phone:	(315) 797-8970
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	41592
Affiliation Type:	Emergency Contact
Company Name:	AGWAY INC.
Contact Type:	Not reported
Contact Name:	PAUL BRZUSZKIEWICZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(315) 337-5220
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

Tank Number:	001
Tank ID:	118800
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	1000
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

ROME AGWAY COOP INC (Continued) **U003077238**

HIST UST:

PBS Number:	6-129526
SPDES Number:	Not reported
Emergency Contact:	PAUL BRZUSZKIEWICZ
Emergency Telephone:	(315) 337-5220
Operator:	ROME AGWAY COOP INC.
Operator Telephone:	(315) 797-8970
Owner Name:	AGWAY INC.
Owner Address:	5814 BRIDGE STREET
Owner City,St,Zip:	EAST SYRACUSE, NY 13057
Owner Telephone:	(315) 449-7994
Owner Type:	Not reported
Owner Subtype:	Not reported
Mailing Name:	AGWAY INC.
Mailing Address:	5814 BRIDGE STREET
Mailing Address 2:	Not reported
Mailing City,St,Zip:	EAST SYRACUSE, NY 13057
Mailing Contact:	Not reported
Mailing Telephone:	(315) 449-7994
Owner Mark:	First Owner
Facility Status:	2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Facility Addr2:	Not reported
SWIS ID:	3013
Old PBS Number:	Not reported
Facility Type:	Not reported
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	03/24/1987
Expiration Date:	03/24/1992
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	0
FAMT:	True
Facility Screen:	Minor Data Missing
Owner Screen:	Minor Data Missing
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	ROME (C)
County Code:	30
Town or City:	13
Region:	6

Tank Id:	001
Tank Location:	UNDERGROUND
Tank Status:	Closed Before April 1, 1991
Install Date:	Not reported
Capacity (gals):	1000
Product Stored:	DIESEL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported

ROME AGWAY COOP INC (Continued) **U003077238**

Pipe Type:	GALVANIZED STEEL
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Not reported
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	False
Lat/long:	Not reported

AST:

Region:	STATE
DEC Region:	6
Site Status:	Unregulated/Closed
Facility Id:	6-129526
Program Type:	PBS
UTM X:	462566.57535
UTM Y:	4784076.9642399997
Expiration Date:	03/24/1992
Site Type:	Unknown

Affiliation Records:

Site Id:	41592
Affiliation Type:	Facility Owner
Company Name:	AGWAY INC.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	5814 BRIDGE STREET
Address2:	Not reported
City:	EAST SYRACUSE
State:	NY
Zip Code:	13057
Country Code:	001
Phone:	(315) 449-7994
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	41592
Affiliation Type:	Mail Contact
Company Name:	AGWAY INC.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	5814 BRIDGE STREET
Address2:	Not reported
City:	EAST SYRACUSE
State:	NY
Zip Code:	13057
Country Code:	001
Phone:	(315) 449-7994

ROME AGWAY COOP INC (Continued) **U003077238**

EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 41592
Affiliation Type: On-Site Operator
Company Name: ROME AGWAY COOP INC
Contact Type: Not reported
Contact Name: ROME AGWAY COOP INC.
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (315) 797-8970
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 41592
Affiliation Type: Emergency Contact
Company Name: AGWAY INC.
Contact Type: Not reported
Contact Name: PAUL BRZUSZKIEWICZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (315) 337-5220
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 002
Tank Id: 118801
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Location: 3

ROME AGWAY COOP INC (Continued) **U003077238**

Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed Prior to Micro Conversion, 03/91
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	03/04/2004
Material Name:	#2 Fuel Oil (On-Site Consumption)

HIST AST:

PBS Number:	6-129526
SWIS Code:	3013
Operator:	ROME AGWAY COOP INC.
Facility Phone:	(315) 797-8970
Facility Addr2:	Not reported
Facility Type:	Not reported
Emergency:	PAUL BRZUSZKIEWICZ
Emergency Tel:	(315) 337-5220
Old PBSNO:	Not reported
Date Inspected:	Not reported
Inspector:	Not reported
Result of Inspection:	Not reported
Owner Name:	AGWAY INC.
Owner Address:	5814 BRIDGE STREET
Owner City,St,Zip:	EAST SYRACUSE, NY 13057
Federal ID:	Not reported
Owner Tel:	(315) 449-7994
Owner Type:	Not reported
Owner Subtype:	Not reported
Mailing Contact:	Not reported
Mailing Name:	AGWAY INC.
Mailing Address:	5814 BRIDGE STREET
Mailing Address 2:	Not reported
Mailing City,St,Zip:	EAST SYRACUSE, NY 13057
Mailing Telephone:	(315) 449-7994
Owner Mark:	First Owner
Facility Status:	2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Certification Flag:	False
Certification Date:	03/24/1987
Expiration:	03/24/1992
Renew Flag:	False
Renew Date:	Not reported
Total Capacity:	0
FAMT:	True
Facility Screen:	Minor Data Missing
Owner Screen:	Minor Data Missing
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	ROME (C)
County Code:	30

ROME AGWAY COOP INC (Continued) **U003077238**

Town or City Code:	13
Region:	6
Tank ID:	002
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Tank Status:	Closed Before April 1, 1991
Install Date:	Not reported
Capacity (Gal):	275
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe Internal:	Not reported
Pipe External:	Not reported
Tank Containment:	None
Leak Detection:	0
Overfill Protection:	4
Dispenser Method:	Gravity
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	False
SPDES Number:	Not reported
Lat/Long:	Not reported

G37 **C.A. KEMP OIL HEATING CORPORATION** **HIST UST** **U003077247**
SSE **250 ERIE BOULEVARD EAST** **HIST AST** **N/A**
< 1/8 **ROME C, NY 13440**
0.112 mi.
594 ft. **Site 2 of 5 in cluster G**

Relative:
Higher

Actual:
440 ft.

HIST UST:

PBS Number:	6-131172
SPDES Number:	Not reported
Emergency Contact:	CLAIR A. KEMP
Emergency Telephone:	(315) 337-4099
Operator:	CLAIR A. KEMP
Operator Telephone:	(315) 337-0980
Owner Name:	CLAIR A. KEMP
Owner Address:	8848 PLEASANT DRIVE
Owner City,St,Zip:	ROME, NY 13440
Owner Telephone:	(315) 337-4099
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Name:	C.A. KEMP OIL HEATING CORPORATION
Mailing Address:	250 ERIE BOULEVARD EAST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	ROME, NY 13440
Mailing Contact:	CLAIR A. KEMP
Mailing Telephone:	(315) 337-0980
Owner Mark:	First Owner
Facility Status:	2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.

C.A. KEMP OIL HEATING CORPORATION (Continued) **U003077247**

Facility Addr2:	Not reported
SWIS ID:	3013
Old PBS Number:	Not reported
Facility Type:	STORAGE TERMINAL/PETROLEUM DISTRIBUTOR
Inspected Date:	11/08/1994
Inspector:	DJ
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	03/10/1997
Expiration Date:	03/24/2002
Renew Flag:	False
Renewal Date:	11/13/2001
Total Capacity:	0
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	0
Dead Letter:	False
CBS Number:	Not reported
Town or City:	ROME (C)
County Code:	30
Town or City:	13
Region:	6

Tank Id:	6
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	06/01/1980
Capacity (gals):	1000
Product Stored:	LEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	Painted/Asphalt Coating
Pipe Location:	Aboveground/Underground Combination
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Second Containment:	Remote Impounding Area
Leak Detection:	Other
Overfill Prot:	Product Level Gauge
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	09/23/1999
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	7
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	05/01/1984
Capacity (gals):	1000

C.A. KEMP OIL HEATING CORPORATION (Continued) **U003077247**

Product Stored:	DIESEL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	Painted/Asphalt Coating
Pipe Location:	Aboveground/Underground Combination
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Second Containment:	Remote Impounding Area
Leak Detection:	Other
Overfill Prot:	Product Level Gauge
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

HIST AST:

PBS Number:	6-131172
SWIS Code:	3013
Operator:	CLAIR A. KEMP
Facility Phone:	(315) 337-0980
Facility Addr2:	Not reported
Facility Type:	STORAGE TERMINAL/PETROLEUM DISTRIBUTOR
Emergency:	CLAIR A. KEMP
Emergency Tel:	(315) 337-4099
Old PBSNO:	Not reported
Date Inspected:	11/08/1994
Inspector:	DJ
Result of Inspection:	Not reported
Owner Name:	CLAIR A. KEMP
Owner Address:	8848 PLEASANT DRIVE
Owner City,St,Zip:	ROME, NY 13440
Federal ID:	Not reported
Owner Tel:	(315) 337-4099
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Contact:	CLAIR A. KEMP
Mailing Name:	C.A. KEMP OIL HEATING CORPORATION
Mailing Address:	250 ERIE BOULEVARD EAST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	ROME, NY 13440
Mailing Telephone:	(315) 337-0980
Owner Mark:	First Owner
Facility Status:	2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Certification Flag:	False
Certification Date:	03/10/1997
Expiration:	03/24/2002
Renew Flag:	False
Renew Date:	11/13/2001
Total Capacity:	0
FAMT:	True

C.A. KEMP OIL HEATING CORPORATION (Continued) **U003077247**

Facility Screen: No Missing Data
Owner Screen: No Missing Data
Tank Screen: 0
Dead Letter: False
CBS Number: Not reported
Town or City: ROME (C)
County Code: 30
Town or City Code: 13
Region: 6

Tank ID: 1
Tank Location: ABOVEGROUND
Tank Status: Closed-Removed
Install Date: 09/01/1972
Capacity (Gal): 15000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: 0
Tank External: 1
Pipe Location: Aboveground/Underground Combination
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 1
Tank Containment: Remote Impounding Area
Leak Detection: 9
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: 09/23/1999
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

Tank ID: 10
Tank Location: ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Tank Status: Closed-Removed
Install Date: 12/01/1972
Capacity (Gal): 300
Product Stored: UNLEADED GASOLINE
Tank Type: Steel/carbon steel
Tank Internal: 0
Tank External: 1
Pipe Location: Aboveground/Underground Combination
Pipe Type: GALVANIZED STEEL
Pipe Internal: None
Pipe External: 1
Tank Containment: 8
Leak Detection: 9
Overfill Protection: 6
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported

C.A. KEMP OIL HEATING CORPORATION (Continued) **U003077247**

Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

Tank ID: 11
Tank Location: ABOVEGROUND
Tank Status: Closed-Removed
Install Date: 06/01/1993
Capacity (Gal): 300
Product Stored: KEROSENE
Tank Type: Steel/carbon steel
Tank Internal: 0
Tank External: 1
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 1
Tank Containment: 8
Leak Detection: 0
Overfill Protection: 6
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

Tank ID: 12
Tank Location: ABOVEGROUND
Tank Status: Closed-Removed
Install Date: 06/01/1993
Capacity (Gal): 300
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: 0
Tank External: 1
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 1
Tank Containment: 8
Leak Detection: 0
Overfill Protection: 6
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data

C.A. KEMP OIL HEATING CORPORATION (Continued) **U003077247**

Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

Tank ID: 2
Tank Location: ABOVEGROUND
Tank Status: Closed-Removed
Install Date: 09/01/1972
Capacity (Gal): 15000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: 0
Tank External: 1
Pipe Location: Aboveground/Underground Combination
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 1
Tank Containment: Remote Impounding Area
Leak Detection: 9
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: 09/23/1999
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

Tank ID: 3
Tank Location: ABOVEGROUND
Tank Status: Closed-Removed
Install Date: 09/01/1972
Capacity (Gal): 15000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: 0
Tank External: 1
Pipe Location: Aboveground/Underground Combination
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 1
Tank Containment: Remote Impounding Area
Leak Detection: 9
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: 09/23/1999

C.A. KEMP OIL HEATING CORPORATION (Continued) **U003077247**

Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

Tank ID: 4
Tank Location: ABOVEGROUND
Tank Status: Closed-Removed
Install Date: 09/01/1972
Capacity (Gal): 15000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: 0
Tank External: 1
Pipe Location: Aboveground/Underground Combination
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 1
Tank Containment: Remote Impounding Area
Leak Detection: 9
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: 09/23/1999
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

Tank ID: 5
Tank Location: ABOVEGROUND
Tank Status: Closed-Removed
Install Date: 09/01/1972
Capacity (Gal): 20000
Product Stored: KEROSENE
Tank Type: Steel/carbon steel
Tank Internal: 0
Tank External: 1
Pipe Location: Aboveground/Underground Combination
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 1
Tank Containment: Remote Impounding Area
Leak Detection: 9
Overfill Protection: 4
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: 09/23/1999
Test Method: Not reported

C.A. KEMP OIL HEATING CORPORATION (Continued) **U003077247**

Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

Tank ID: 8
Tank Location: ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Tank Status: Closed-Removed
Install Date: 12/01/1972
Capacity (Gal): 500
Product Stored: DIESEL
Tank Type: Steel/carbon steel
Tank Internal: 0
Tank External: 1
Pipe Location: Aboveground/Underground Combination
Pipe Type: GALVANIZED STEEL
Pipe Internal: None
Pipe External: 1
Tank Containment: 8
Leak Detection: 9
Overfill Protection: 6
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Not reported
Deleted: False
Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

Tank ID: 9
Tank Location: ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Tank Status: Closed-Removed
Install Date: 12/01/1972
Capacity (Gal): 500
Product Stored: KEROSENE
Tank Type: Steel/carbon steel
Tank Internal: 0
Tank External: 1
Pipe Location: Aboveground/Underground Combination
Pipe Type: GALVANIZED STEEL
Pipe Internal: None
Pipe External: 1
Tank Containment: 8
Leak Detection: 9
Overfill Protection: 6
Dispenser Method: Suction
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: Not reported
Test Method: Not reported
Deleted: False

C.A. KEMP OIL HEATING CORPORATION (Continued) **U003077247**

Updated: True
SPDES Number: Not reported
Lat/Long: Not reported

G38 **C.A. KEMP OIL HEATING CORPORATION** **UST** **U004199163**
SSE **250 ERIE BOULEVARD EAST** **N/A**
< 1/8 **ROME C, NY 13440**
0.112 mi.
594 ft. **Site 3 of 5 in cluster G**

Relative:
Higher

Actual:
440 ft.

UST:
Id/Status: 6-131172 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 6
Expiration Date: 03/24/2002
UTM X: 462920.24367
UTM Y: 4783820.5066499999
Site Type: Storage Terminal/Petroleum Distributor

Tank Info:

Tank Number: 6
Tank ID: 114857
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1000
Install Date: 06/01/1980
Date Tank Closed: 09/23/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Tank Number: 7
Tank ID: 114858
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1000
Install Date: 05/01/1984
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

G39 **C.A. KEMP OIL HEATING CORPORATION** **AST** **A100382703**
SSE **250 ERIE BOULEVARD EAST** **N/A**
< 1/8 **ROME C, NY 13440**
0.112 mi.
594 ft. **Site 4 of 5 in cluster G**

Relative:
Higher

Actual:
440 ft.

AST:

Region:	STATE
DEC Region:	6
Site Status:	Unregulated/Closed
Facility Id:	6-131172
Program Type:	PBS
UTM X:	462920.24367
UTM Y:	4783820.5066499999
Expiration Date:	03/24/2002
Site Type:	Storage Terminal/Petroleum Distributor

Tank Info:

Tank Number:	1
Tank Id:	114852
Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	09/01/1972
Capacity Gallons:	15000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	09/23/1999
Register:	True
Modified By:	TRANSLAT
Last Modified:	03/04/2004
Material Name:	Not reported

Tank Number:	10
Tank Id:	114861
Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	12/01/1972
Capacity Gallons:	300
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	03/04/2004
Material Name:	Not reported

Tank Number:	11
Tank Id:	120050
Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed

C.A. KEMP OIL HEATING CORPORATION (Continued) **A100382703**

Pipe Model:	Not reported
Install Date:	06/01/1993
Capacity Gallons:	300
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	03/04/2004
Material Name:	Not reported

Tank Number:	12
Tank Id:	120051
Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	06/01/1993
Capacity Gallons:	300
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	03/04/2004
Material Name:	Not reported

Tank Number:	2
Tank Id:	114853
Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	09/01/1972
Capacity Gallons:	15000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	09/23/1999
Register:	True
Modified By:	TRANSLAT
Last Modified:	03/04/2004
Material Name:	Not reported

Tank Number:	3
Tank Id:	114854
Tank Location:	1
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	09/01/1972
Capacity Gallons:	15000

C.A. KEMP OIL HEATING CORPORATION (Continued) **A100382703**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 09/23/1999
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: Not reported

Tank Number: 4
Tank Id: 114855
Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 09/01/1972
Capacity Gallons: 15000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 09/23/1999
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: Not reported

Tank Number: 5
Tank Id: 114856
Tank Location: 1
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 09/01/1972
Capacity Gallons: 20000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 09/23/1999
Register: True
Modified By: TRANSLAT
Last Modified: 03/04/2004
Material Name: Not reported

Tank Number: 8
Tank Id: 114859
Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 12/01/1972
Capacity Gallons: 500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported

C.A. KEMP OIL HEATING CORPORATION (Continued) **A100382703**

Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	03/04/2004
Material Name:	Not reported

Tank Number:	9
Tank Id:	114860
Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	12/01/1972
Capacity Gallons:	500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	03/04/2004
Material Name:	Not reported

G40 **KEMP OIL HEATING CORP.** **NY Spills** **S104278274**
SSE **250 ERIE BLVD. EAST** **N/A**
< 1/8 **ROME C, NY**
0.112 mi.
594 ft. **Site 5 of 5 in cluster G**

Relative:
Higher

Actual:
440 ft.

SPILLS:

Facility ID:	9907630
Facility Type:	ER
DER Facility ID:	246409
Site ID:	305042
DEC Region:	6
Spill Date:	9/23/1999
Spill Number/Closed Date:	9907630 / Not Reported
Spill Cause:	Unknown
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	3313
Investigator:	JDALSANT
Referred To:	Not reported
Reported to Dept:	9/24/1999
CID:	322
Water Affected:	Not reported
Spill Source:	Non Major Facility > 1,100 gal
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	1/12/2000
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	1
Date Entered In Computer:	9/24/1999
Spill Record Last Update:	9/8/2010
Spiller Name:	CLAIR A. KEMP

KEMP OIL HEATING CORP. (Continued) **S104278274**

Spiller Company:	CLAIR A. KEMP
Spiller Address:	6371 PLEASANT DRIVE
Spiller City,St,Zip:	ROME, NY 13440-
Spiller Company:	001
Contact Name:	CLAIR A. KEMP
Contact Phone:	(315) 337-0980
DEC Memo:	09/24/99: ARRIVE AT SITE AT 1000 HRS TO SEE WORKERS CUTTING TANKS, MR. KEMP INFORMS ME THAT A TOTAL OF SEVEN TANKS WERE REMOVED. SOME MINOR CONTAMINATION EVIDENT ON SURFACE. PID READINGS OF 2.5 TO 18.0 PPM. VERN HARRIS DOING CUTTING AND WILL EXCAVATE CONTAMINATION. ABSCOPE WILL OBSERVE & DO SAMPLING. 1400 -DRIVE BY SITE, ABSCOPE HAS ARRIVED, BEGINNING WORK. 1530 - AT SITE AGAIN TO SEE EXCAVATION AT EAST END OF TRAILER, ABOUT 15 FT DEEP - APPROX. 60 - 80 TON OF SOIL. WILL TALK WITH ABSCOPE TO DETERMINE EXTENT OF PROBLEM (ECL). 09/27/99: 1030 - MADE VIDEO OF SITE, SOIL PILE PID READINGS 17.0 TO 900+ PPM, FREE PRODUCT IS VISIBLE COMING OUT OF WEST WALL OF EXCAVATION, STRONG PETROLEUM ODORS (ECL). 09/28/99: SITE CHECK W/DON JOHNSON, EXCAVATION STILL OPEN - PHOTO'S TAKEN (ECL). 10/08/99: SOIL, TCR SENT (ECL). 11/9/99: SENT LETTER REQUESTING TCR & SITE ASSESSMENT (DJ). 01/12/2000: SITE VISIT - PILES UNCOVERED/EXCAVATION STILL OPEN (NC). 9/8/2010: spill reassigned to Jerry Alsante
Remarks:	caller hung up prior to completing entire form - 5 tanks wereremoved yesturday and while removing tanks 1 fell over spillinggasoline

Material:

Site ID:	305042
Operable Unit ID:	1086213
Operable Unit:	01
Material ID:	300325
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	9410572
Facility Type:	ER
DER Facility ID:	249276
Site ID:	308675
DEC Region:	6
Spill Date:	11/8/1994
Spill Number/Closed Date:	9410572 / 6/4/1996
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	3300
Investigator:	AJMARSCH
Referred To:	Not reported
Reported to Dept:	11/8/1994
CID:	Not reported

KEMP OIL HEATING CORP. (Continued) **S104278274**

Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	6/4/1996
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	12/30/1994
Spill Record Last Update:	6/10/1996
Spiller Name:	Not reported
Spiller Company:	C.A. KEMP OIL HEATING
Spiller Address:	250 ERIE BLVD. EAST
Spiller City,St,Zip:	ROME, NY 13440
Spiller Company:	001
Contact Name:	Not reported
Contact Phone:	Not reported
DEC Memo:	Not reported
Remarks:	SPILL ON WOOD SURFACE - DON JOHNSON WAS AT SITE.

Material:

Site ID:	308675
Operable Unit ID:	1004496
Operable Unit:	01
Material ID:	376438
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Pounds
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False
Site ID:	308675
Operable Unit ID:	1004496
Operable Unit:	01
Material ID:	376439
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	308675
Spill Tank Test:	1543325
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported

KEMP OIL HEATING CORP. (Continued) **S104278274**

Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

H41 **NORSTAR BANK UPSTATE NEW YORK** **UST** **U001848056**
NNW **ROME TRUST OFFICE** **HIST UST** **N/A**
< 1/8 **ROME C, NY 13440**
0.114 mi.
603 ft. **Site 1 of 2 in cluster H**

Relative:
Higher

Actual:
439 ft.

UST:
Id/Status: 6-600067 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 6
Expiration Date: 09/19/1996
UTM X: 462593.58120999997
UTM Y: 4784488.3628000002
Site Type: Other

Affiliation Records:
Site Id: 42891
Affiliation Type: Facility Owner
Company Name: NORSTAR BANK UPSTATE NEW YORK
Contact Type: Not reported
Contact Name: Not reported
Address1: 268 GENESEE STREET
Address2: Not reported
City: UTICA
State: NY
Zip Code: 13502
Country Code: 001
Phone: (315) 798-2445
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 42891
Affiliation Type: Mail Contact
Company Name: NORSTAR BANK UPSTATE NEW YORK
Contact Type: Not reported
Contact Name: FACILITIES MANAGEMENT
Address1: 268 GENESEE STREET
Address2: Not reported
City: UTICA
State: NY
Zip Code: 13502
Country Code: 001
Phone: (315) 798-2445
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 42891
Affiliation Type: On-Site Operator

NORSTAR BANK UPSTATE NEW YORK (Continued) **U001848056**

Company Name:	NORSTAR BANK UPSTATE NEW YORK
Contact Type:	Not reported
Contact Name:	ANN HOPKINS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(315) 338-6800
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	42891
Affiliation Type:	Emergency Contact
Company Name:	NORSTAR BANK UPSTATE NEW YORK
Contact Type:	Not reported
Contact Name:	FACILITIES MANAGEMENT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(315) 798-2445
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

Tank Number:	1
Tank ID:	119682
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	10000
Install Date:	Not reported
Date Tank Closed:	11/01/1991
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

NORSTAR BANK UPSTATE NEW YORK (Continued) **U001848056**

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

HIST UST:

PBS Number:	6-600067
SPDES Number:	Not reported
Emergency Contact:	FACILITIES MANAGEMENT
Emergency Telephone:	(315) 798-2445
Operator:	ANN HOPKINS
Operator Telephone:	(315) 338-6800
Owner Name:	NORSTAR BANK UPSTATE NEW YORK
Owner Address:	268 GENESEE STREET
Owner City,St,Zip:	UTICA, NY 13502
Owner Telephone:	(315) 798-2445
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Name:	NORSTAR BANK UPSTATE NEW YORK
Mailing Address:	268 GENESEE STREET
Mailing Address 2:	Not reported
Mailing City,St,Zip:	UTICA, NY 13502
Mailing Contact:	FACILITIES MANAGEMENT
Mailing Telephone:	(315) 798-2445
Owner Mark:	First Owner
Facility Status:	2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Facility Addr2:	200 LIBERTY PLAZA
SWIS ID:	3013
Old PBS Number:	Not reported
Facility Type:	OTHER
Inspected Date:	Not reported
Inspector:	Not reported
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	09/19/1991
Expiration Date:	09/19/1996
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	0
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	0
Dead Letter:	False
CBS Number:	Not reported
Town or City:	ROME (C)
County Code:	30
Town or City:	13
Region:	6
Tank Id:	1
Tank Location:	UNDERGROUND

NORSTAR BANK UPSTATE NEW YORK (Continued) **U001848056**

Tank Status:	Closed-In Place
Install Date:	Not reported
Capacity (gals):	10000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	11/01/1991
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

E42 **NIMO** **NY Spills** **S103484804**
WSW **SO JAMES ST @ LAWRENCE ST** **N/A**
< 1/8 **ROME C, NY**
0.118 mi.
625 ft. **Site 5 of 6 in cluster E**

Relative:
Lower

Actual:
437 ft.

SPILLS:

Facility ID:	9807928
Facility Type:	ER
DER Facility ID:	211629
Site ID:	258604
DEC Region:	6
Spill Date:	9/28/1998
Spill Number/Closed Date:	9807928 / 9/29/1998
Spill Cause:	Equipment Failure
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	3300
Investigator:	JDALSANT
Referred To:	Not reported
Reported to Dept:	9/29/1998
CID:	211
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	9/29/1998
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	9/29/1998
Spill Record Last Update:	9/30/1998

NIMO (Continued) **S103484804**

Spiller Name: CHRIS READ
Spiller Company: NIMO
Spiller Address: 300 ERIE BLVD WEST
Spiller City,St,Zip: SYRACUSE, NY
Spiller Company: 001
Contact Name: CHRIS READ
Contact Phone: (315) 428-3631
DEC Memo: Not reported
Remarks: HYDRAULIC LINE FAILURE - SPILL CLEANED UP

Material:
Site ID: 258604
Operable Unit ID: 1069108
Operable Unit: 01
Material ID: 315467
Material Code: 0010
Material Name: Hydraulic Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 7
Units: Gallons
Recovered: 7
Resource Affected: Not reported
Oxygenate: False

Tank Test:

E43 **EDR US Hist Auto Stat** **1015420507**
West **319 WEST ST** **N/A**
1/8-1/4 **ROME, NY 13440**
0.127 mi.
673 ft. **Site 6 of 6 in cluster E**

Relative:
Lower

Actual:
438 ft.

EDR Historical Auto Stations:
Name: DUTCHS BODY SHOP
Year: 2008
Address: 319 WEST ST

I44 **ROME(C) PUMP STATION** **UST** **U003031172**
ENE **ERIE BLVD. & BLACK RIVER BLVD.** **N/A**
1/8-1/4 **ROME C, NY 13440**
0.135 mi.
712 ft. **Site 1 of 2 in cluster I**

Relative:
Higher

Actual:
445 ft.

UST:
Id/Status: 6-600133 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 6
Expiration Date: 04/28/2002
UTM X: 462767.78986000002
UTM Y: 4784210.3500499995
Site Type: Other

Affiliation Records:
Site Id: 42957

ROME(C) PUMP STATION (Continued) **U003031172**

Affiliation Type:	Facility Owner
Company Name:	CITY OF ROME
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	CITY HALL
Address2:	Not reported
City:	ROME
State:	NY
Zip Code:	13440
Country Code:	001
Phone:	(315) 336-6000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	42957
Affiliation Type:	Mail Contact
Company Name:	ROME WASTEWATER TREATMENT
Contact Type:	Not reported
Contact Name:	F. RICHARD GIFFORD
Address1:	7180 EAST DOMINICK STREET
Address2:	Not reported
City:	ROME
State:	NY
Zip Code:	13440
Country Code:	001
Phone:	(315) 339-7775
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	42957
Affiliation Type:	On-Site Operator
Company Name:	ROME(C) PUMP STATION
Contact Type:	Not reported
Contact Name:	F. RICHARD GIFFORD
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(315) 339-7775
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	42957
Affiliation Type:	Emergency Contact
Company Name:	CITY OF ROME
Contact Type:	Not reported
Contact Name:	POLICE
Address1:	Not reported
Address2:	Not reported

ROME(C) PUMP STATION (Continued) **U003031172**

City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(315) 337-3311
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

Tank Number:	2
Tank ID:	120088
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1500
Install Date:	07/01/1972
Date Tank Closed:	08/01/1997
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	01
Date Test:	05/01/1992
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None

I45 **ROME PUMP STATION** **LTANKS** **S101856368**
ENE **ERIE & BLACK RIVER BLVD** **N/A**
1/8-1/4 **ROME C, NY**
0.135 mi.
712 ft. **Site 2 of 2 in cluster I**

Relative:
Higher

Actual:
445 ft.

LTANKS:

Site ID:	286462
Spill Number/Closed Date:	9201592 / 11/12/1992
Spill Date:	5/8/1992
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release that creates potential for fire or hazard. (Highly Improbable)
Cleanup Ceased:	6/15/1992

ROME PUMP STATION (Continued) **S101856368**

Cleanup Meets Standard:	True
SWIS:	3300
Investigator:	DIJOHNSO
Referred To:	Not reported
Reported to Dept:	5/8/1992
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	5/13/1992
Spill Record Last Update:	3/31/1993
Spiller Name:	Not reported
Spiller Company:	WWTP
Spiller Address:	7180 EAST DOMINICK ST.
Spiller City,St,Zip:	ROME, NY 13440
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	6
DER Facility ID:	232169
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "JOHNSON"05/13/92: SPOKE WITH DICK GIFFORD, SAID THAT TANK PASSED RETEST-FOUND MANWAY IN TANK-AIR POCKET CAUSE OF FIRST FAILURE/HE WILL SEND IN REPORT. (DJ).06/05/92: SENT LETTER REQUESTING TANK TEST RESULTS. (DJ).06/15/92: RECEIVED TANK TEST REPORT, PASSED RETEST ON 5/11/92, - .041SPH. (DJ).11/12/92: COMPLETE. (DJ).
Remarks:	EX. TOP INVERT RETEST.

Material:

Site ID:	286462
Operable Unit ID:	968872
Operable Unit:	01
Material ID:	412891
Material Code:	0008
Material Name:	Diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	286462
Spill Tank Test:	1539976
Tank Number:	002
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills

ROME PUMP STATION (Continued) **S101856368**

Last Modified: 10/1/2004
Test Method: Unknown

H46 **ROME(C) CITY HALL** **UST** **U003031157**
NNW **198 NORTH WASHINGTON STREET** **HIST UST** **N/A**
1/8-1/4 **ROME C, NY 13440**
0.140 mi.
741 ft. **Site 2 of 2 in cluster H**

Relative:
Higher

Actual:
439 ft.

UST:
Id/Status: 6-433535 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 6
Expiration Date: 04/19/2013
UTM X: 462797.76426000003
UTM Y: 4784610.3183899997
Site Type: Municipality (Incl. Waste Water Treatment Plants, Utilities, Swimming Pools, etc.)

Affiliation Records:
Site Id: 42237
Affiliation Type: Facility Owner
Company Name: CITY OF ROME
Contact Type: COMMISSIONER OF PUBLIC WORKS
Contact Name: FRANK D. TALLARINO
Address1: 198 NORTH WASHINGTON STREET
Address2: Not reported
City: ROME
State: NY
Zip Code: 13440
Country Code: 001
Phone: (315) 336-6000
EMail: FTALLARINO@ROMECITYGOV.COM
Fax Number: Not reported
Modified By: JDALSANT
Date Last Modified: 3/28/2012

Site Id: 42237
Affiliation Type: Mail Contact
Company Name: CITY OF ROME
Contact Type: COMMISSIONER OF PUBLIC WORKS
Contact Name: FRANK D. TALLARINO
Address1: 198 NORTH WASHINGTON STREET
Address2: Not reported
City: ROME
State: NY
Zip Code: 13440
Country Code: 001
Phone: (315) 336-6000
EMail: FTALLARINO@ROMECITYGOV.COM
Fax Number: Not reported
Modified By: JDALSANT
Date Last Modified: 3/28/2012

Site Id: 42237
Affiliation Type: On-Site Operator
Company Name: ROME(C) CITY HALL

ROME(C) CITY HALL (Continued) **U003031157**

Contact Type:	Not reported
Contact Name:	CITY OF ROME
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NY
Zip Code:	Not reported
Country Code:	001
Phone:	(315) 336-6000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JDALSANT
Date Last Modified:	3/28/2012

Site Id:	42237
Affiliation Type:	Emergency Contact
Company Name:	CITY OF ROME
Contact Type:	Not reported
Contact Name:	FRANK TALLARINO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(315) 339-7625
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JDALSANT
Date Last Modified:	3/28/2012

Tank Info:

Tank Number:	001
Tank ID:	116994
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	6000
Install Date:	10/01/1987
Date Tank Closed:	05/01/2012
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	RFNOVAK
Last Modified:	05/03/2012

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring

ROME(C) CITY HALL (Continued) **U003031157**

I02 - Overfill - High Level Alarm
B02 - Tank External Protection - Original Sacrificial Anode
A00 - Tank Internal Protection - None
D10 - Pipe Type - Copper
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	002
Tank ID:	116995
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	6000
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

HIST UST:

PBS Number:	6-433535
SPDES Number:	Not reported
Emergency Contact:	CITY OF ROME
Emergency Telephone:	(315) 336-6000
Operator:	CITY OF ROME
Operator Telephone:	(315) 336-6000
Owner Name:	CITY OF ROME PUBLIC WORKS
Owner Address:	198 NORTH WASHINGTON STREET
Owner City,St,Zip:	ROME, NY 13440
Owner Telephone:	(315) 336-6000
Owner Type:	Local Government
Owner Subtype:	Not reported
Mailing Name:	CITY OF ROME PUBLIC WORKS
Mailing Address:	198 NORTH WASHINGTON STREET
Mailing Address 2:	3RD FLOOR, CITY HALL
Mailing City,St,Zip:	ROME, NY 13440

ROME(C) CITY HALL (Continued) **U003031157**

Mailing Contact:	ROBERT COMIS
Mailing Telephone:	(315) 336-6000
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2:	198 NORTH WASHINGTON STREET
SWIS ID:	3013
Old PBS Number:	Not reported
Facility Type:	OTHER
Inspected Date:	10/10/1995
Inspector:	HM
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	02/27/1998
Expiration Date:	04/19/2003
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	6000
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	Minor Data Missing
Dead Letter:	False
CBS Number:	Not reported
Town or City:	ROME (C)
County Code:	30
Town or City:	13
Region:	6

Tank Id:	002
Tank Location:	UNDERGROUND
Tank Status:	Closed Before April 1, 1991
Install Date:	Not reported
Capacity (gals):	6000
Product Stored:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	None
Leak Detection:	None
Overfill Prot:	Not reported
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	Not reported
Test Method:	Not reported
Deleted:	False
Updated:	False
Lat/long:	Not reported

J47 **TRANSFIGURATION CHURCH** **UST** **U003070106**
WSW **111 RIDGE STREET** **N/A**
1/8-1/4 **ROME C, NY 13440**
0.157 mi.
830 ft. **Site 1 of 2 in cluster J**

Relative:
Lower

Actual:
437 ft.

UST:

Id/Status:	6-021873 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	6
Expiration Date:	09/02/2001
UTM X:	462497.20415000001
UTM Y:	4784003.9386099996
Site Type:	School

Affiliation Records:

Site Id:	41030
Affiliation Type:	Facility Owner
Company Name:	TRANSFIGURATION CHURCH
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	111 RIDGE ST
Address2:	Not reported
City:	ROME
State:	NY
Zip Code:	13440
Country Code:	001
Phone:	(315) 336-1152
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	41030
Affiliation Type:	Mail Contact
Company Name:	TRANSFIGURATION CHURCH
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	111 RIDGE ST
Address2:	Not reported
City:	ROME
State:	NY
Zip Code:	13440
Country Code:	001
Phone:	(315) 336-1152
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	41030
Affiliation Type:	On-Site Operator
Company Name:	TRANSFIGURATION CHURCH
Contact Type:	Not reported
Contact Name:	TRANSFIGURATION CHURCH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN

TRANSFIGURATION CHURCH (Continued) **U003070106**

Zip Code:	Not reported
Country Code:	001
Phone:	(315) 336-1152
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	41030
Affiliation Type:	Emergency Contact
Company Name:	TRANSFIGURATION CHURCH
Contact Type:	Not reported
Contact Name:	TRANSFIGURATION CHURCH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(315) 336-1152
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

Tank Number:	001
Tank ID:	113062
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	8000
Install Date:	06/01/1959
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

TRANSFIGURATION CHURCH (Continued) **U003070106**

Tank Number: 002
Tank ID: 113063
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 1000
Install Date: 07/01/1986
Date Tank Closed: 08/01/1996
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D10 - Pipe Type - Copper
G00 - Tank Secondary Containment - None
I05 - Overfill - Vent Whistle
J02 - Dispenser - Suction Dispenser
B02 - Tank External Protection - Original Sacrificial Anode
H00 - Tank Leak Detection - None

Tank Number: 003
Tank ID: 113064
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 1000
Install Date: 07/01/1986
Date Tank Closed: 08/01/1996
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D10 - Pipe Type - Copper
G00 - Tank Secondary Containment - None

TRANSFIGURATION CHURCH (Continued) **U003070106**

I05 - Overfill - Vent Whistle
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
B02 - Tank External Protection - Original Sacrificial Anode

K48 **ROME IRON GROUP, LTD.** **UST** **1000554053**
SSE **412 CANAL STREET** **N/A**
1/8-1/4 **ROME C, NY 13440**
0.183 mi.
966 ft. **Site 1 of 5 in cluster K**

Relative:
Higher

Actual:
439 ft.

UST:

Id/Status:	6-432814 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	6
Expiration Date:	03/28/2003
UTM X:	462878.77601999999
UTM Y:	4783678.1163400002
Site Type:	Manufacturing (Other than Chemical)/Processing

Affiliation Records:

Site Id:	42217
Affiliation Type:	Facility Owner
Company Name:	ROME IRON GROUP
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	P.O. BOX 4390
Address2:	Not reported
City:	ROME
State:	NY
Zip Code:	13440
Country Code:	001
Phone:	(315) 339-9000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	THKNIZEK
Date Last Modified:	6/19/2008

Site Id:	42217
Affiliation Type:	Mail Contact
Company Name:	ROME IRON GROUP
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	P.O. BOX 4390
Address2:	Not reported
City:	ROME
State:	NY
Zip Code:	13440
Country Code:	001
Phone:	(315) 339-9000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	THKNIZEK
Date Last Modified:	6/19/2008

Site Id:	42217
Affiliation Type:	On-Site Operator

ROME IRON GROUP, LTD. (Continued) **1000554053**

Company Name:	ROME IRON GROUP, LTD.
Contact Type:	Not reported
Contact Name:	ROME IRON GROUP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NY
Zip Code:	Not reported
Country Code:	001
Phone:	(315) 339-9000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	THKNIZEK
Date Last Modified:	6/19/2008

Site Id:	42217
Affiliation Type:	Emergency Contact
Company Name:	ROME IRON GROUP
Contact Type:	Not reported
Contact Name:	MIKE FATIUK
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(315) 337-3647
EMail:	Not reported
Fax Number:	Not reported
Modified By:	THKNIZEK
Date Last Modified:	6/19/2008

Tank Info:

Tank Number:	1
Tank ID:	116929
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1000
Install Date:	12/01/1940
Date Tank Closed:	05/02/2002
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	RFNOVAK
Last Modified:	10/22/2008

Equipment Records:

A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping

ROME IRON GROUP, LTD. (Continued) **1000554053**

G00 - Tank Secondary Containment - None
I00 - Overfill - None
B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None

Tank Number: 2
Tank ID: 116930
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 2000
Install Date: 12/01/1973
Date Tank Closed: 05/02/2002
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 00
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: RFNOVAK
Last Modified: 10/22/2008

Equipment Records:

H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None

Tank Number: 3
Tank ID: 116931
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1000
Install Date: 12/01/1974
Date Tank Closed: 05/02/2002
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: RFNOVAK
Last Modified: 10/22/2008

ROME IRON GROUP, LTD. (Continued) **1000554053**

Equipment Records:

A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
I00 - Overfill - None
B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None

Tank Number:	4
Tank ID:	116932
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	1000
Install Date:	12/01/1940
Date Tank Closed:	05/02/2002
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	RFNOVAK
Last Modified:	10/22/2008

Equipment Records:

A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
H00 - Tank Leak Detection - None

K49 **R & S STEEL,LLC** **RCRA-SQG** **1006810426**
SSE **412 CANAL ST** **FINDS** **NYR000110981**
1/8-1/4 **ROME, NY 13440** **MANIFEST**
0.183 mi.
966 ft. **Site 2 of 5 in cluster K**

Relative:
Higher

Actual:
439 ft.

RCRA-SQG:

Date form received by agency:	12/07/2009
Facility name:	R&S STEEL LLC
Facility address:	412 CANAL ST ROME, NY 13440
EPA ID:	NYR000110981
Mailing address:	CANAL ST ROME, NY 13440
Contact:	DAVID A MCKERROW JR
Contact address:	CANAL ST ROME, NY 13440

R & S STEEL,LLC (Continued) **1006810426**

Contact country: US
Contact telephone: (315) 281-0123
Contact email: Not reported
EPA Region: 02
Land type: Private
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: R & S STEEL LLC
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 12/01/2001
Owner/Op end date: Not reported

Owner/operator name: RICHIE PAUL THOMAS RAULLI
Owner/operator address: MORAGAN RD
CLAY, NY 13078
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 12/01/2001
Owner/Op end date: Not reported

Owner/operator name: R & S STEEL LLC
Owner/operator address: CANAL ST
ROME, NY 13440
Owner/operator country: US
Owner/operator telephone: (315) 281-0123
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 12/23/2002
Owner/Op end date: Not reported

Owner/operator name: R & S STEEL LLC
Owner/operator address: CANAL ST
ROME, NY 13440
Owner/operator country: US
Owner/operator telephone: (315) 281-0123
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 12/23/2002
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No

R & S STEEL,LLC (Continued) **1006810426**

Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Historical Generators:
Date form received by agency: 01/01/2007
Site name: R&S STEEL LLC
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 01/01/2006
Site name: R&S STEEL LLC
Classification: Small Quantity Generator

Date form received by agency: 12/23/2002
Site name: R&S STEEL LLC
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL

R & S STEEL,LLC (Continued) **1006810426**

ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 05/22/2008
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 10/28/2003
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110014367185

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region

R & S STEEL,LLC (Continued) **1006810426**

that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

NY MANIFEST:

EPA ID:	NYR000110981
Country:	USA
Location Address 1:	412 CANAL STREET
Location Address 2:	Not reported
Location City:	ROME
Location State:	NY
Location Zip Code:	13440
Location Zip Code 4:	Not reported

Mailing Info:

Name:	R S STEEL
Contact:	DAVID RIENZO
Address:	412 CANAL STREET
City/State/Zip:	ROME, NY 13440
Country:	USA
Phone:	315-281-0123

Manifest:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD013277454
Trans2 State ID:	Not reported
Generator Ship Date:	11/07/2014
Trans1 Recv Date:	11/07/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/07/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000110981
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD013277454
Waste Code:	Not reported
Quantity:	701
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	007694582FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported

R & S STEEL,LLC (Continued) **1006810426**

Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD013277454
Trans2 State ID: Not reported
Generator Ship Date: 08/15/2014
Trans1 Recv Date: 08/15/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/15/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000110981
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD013277454
Waste Code: Not reported
Quantity: 55
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 1
Year: 2014
Manifest Tracking Num: 007694208FLE
Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H141

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD013277454
Trans2 State ID: Not reported
Generator Ship Date: 05/01/2014
Trans1 Recv Date: 05/01/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/01/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000110981
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID: NYD013277454
Waste Code: Not reported
Quantity: 40
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1

R & S STEEL,LLC (Continued) **1006810426**

Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2014
Manifest Tracking Num:	006703224FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD013277454
Trans2 State ID:	Not reported
Generator Ship Date:	02/10/2015
Trans1 Recv Date:	02/10/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/10/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000110981
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD013277454
Waste Code:	Not reported
Quantity:	55
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2015
Manifest Tracking Num:	007692930FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD013277454

R & S STEEL,LLC (Continued) **1006810426**

Trans2 State ID:	Not reported
Generator Ship Date:	02/13/2009
Trans1 Recv Date:	02/13/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/13/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000110981
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD013277454
Waste Code:	Not reported
Quantity:	110.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	003595134JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD013277454
Trans2 State ID:	Not reported
Generator Ship Date:	11/20/2009
Trans1 Recv Date:	11/20/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/20/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000110981
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD013277454
Waste Code:	Not reported
Quantity:	2305.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	003599428JJK
Import Ind:	N

R & S STEEL,LLC (Continued) **1006810426**

Export Ind:	N
Discr Quantity Ind:	Y
Discr Type Ind:	Y
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD013277454
Trans2 State ID:	Not reported
Generator Ship Date:	12/11/2009
Trans1 Recv Date:	12/11/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/11/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000110981
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD013277454
Waste Code:	Not reported
Quantity:	700.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2009
Manifest Tracking Num:	003599455JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD013277454
Trans2 State ID:	Not reported
Generator Ship Date:	09/08/2011
Trans1 Recv Date:	09/08/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/08/2011
Part A Recv Date:	Not reported

R & S STEEL,LLC (Continued) **1006810426**

Part B Recv Date:	Not reported
Generator EPA ID:	NYR000110981
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD013277454
Waste Code:	Not reported
Quantity:	475.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	004912273FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD013277454
Trans2 State ID:	Not reported
Generator Ship Date:	12/08/2011
Trans1 Recv Date:	12/08/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/08/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000110981
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD013277454
Waste Code:	Not reported
Quantity:	500.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	004919722FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N

R & S STEEL,LLC (Continued) **1006810426**

Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD013277454
Trans2 State ID:	Not reported
Generator Ship Date:	06/02/2011
Trans1 Recv Date:	06/02/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/02/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000110981
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD013277454
Waste Code:	Not reported
Quantity:	450.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2011
Manifest Tracking Num:	003565877FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD013277454
Trans2 State ID:	Not reported
Generator Ship Date:	06/02/2008
Trans1 Recv Date:	06/02/2008
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/02/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000110981
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD013277454
Waste Code:	Not reported

R & S STEEL,LLC (Continued) **1006810426**

Quantity:	110.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	003594675JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD013277454
Trans2 State ID:	Not reported
Generator Ship Date:	08/29/2008
Trans1 Recv Date:	08/29/2008
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/29/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000110981
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD013277454
Waste Code:	Not reported
Quantity:	110.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2008
Manifest Tracking Num:	003594909JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

R & S STEEL,LLC (Continued) **1006810426**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD013277454
Trans2 State ID:	Not reported
Generator Ship Date:	09/06/2012
Trans1 Recv Date:	09/06/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/06/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000110981
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD013277454
Waste Code:	Not reported
Quantity:	55.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	004060263JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD013277454
Trans2 State ID:	Not reported
Generator Ship Date:	03/09/2012
Trans1 Recv Date:	03/09/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/09/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000110981
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD013277454
Waste Code:	Not reported
Quantity:	500.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0

R & S STEEL,LLC (Continued) **1006810426**

Year:	2012
Manifest Tracking Num:	004999208FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD013277454
Trans2 State ID:	Not reported
Generator Ship Date:	12/06/2012
Trans1 Recv Date:	12/06/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/06/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000110981
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD013277454
Waste Code:	Not reported
Quantity:	110.0
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	005716850FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD013277454
Trans2 State ID:	Not reported
Generator Ship Date:	06/07/2012
Trans1 Recv Date:	06/07/2012

R & S STEEL,LLC (Continued) **1006810426**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/07/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000110981
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD013277454
Waste Code:	Not reported
Quantity:	756.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Year:	2012
Manifest Tracking Num:	005160203FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD013277454
Trans2 State ID:	Not reported
Generator Ship Date:	05/10/2013
Trans1 Recv Date:	05/10/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/10/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000110981
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD013277454
Waste Code:	Not reported
Quantity:	110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	006031779FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N

R & S STEEL,LLC (Continued) **1006810426**

Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD013277454
Trans2 State ID:	Not reported
Generator Ship Date:	11/14/2013
Trans1 Recv Date:	11/14/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/14/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000110981
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD013277454
Waste Code:	Not reported
Quantity:	55
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2013
Manifest Tracking Num:	006031554FLE
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD013277454
Trans2 State ID:	Not reported
Generator Ship Date:	04/13/2007
Trans1 Recv Date:	04/13/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/13/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000110981
Trans1 EPA ID:	Not reported

R & S STEEL,LLC (Continued) **1006810426**

Trans2 EPA ID:	Not reported
TSDF ID:	NYD013277454
Waste Code:	Not reported
Quantity:	110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2007
Manifest Tracking Num:	000342369JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported
Mgmt Method Type Code:	H141

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD013277454
Trans2 State ID:	Not reported
Generator Ship Date:	11/09/2007
Trans1 Recv Date:	11/09/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/09/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000110981
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID:	NYD013277454
Waste Code:	Not reported
Quantity:	110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Year:	2007
Manifest Tracking Num:	003595502JJK
Import Ind:	N
Export Ind:	N
Discr Quantity Ind:	N
Discr Type Ind:	N
Discr Residue Ind:	N
Discr Partial Reject Ind:	N
Discr Full Reject Ind:	N
Manifest Ref Num:	Not reported
Alt Fac RCRA Id:	Not reported
Alt Fac Sign Date:	Not reported

R & S STEEL,LLC (Continued) **1006810426**

Mgmt Method Type Code: H141

K50 **ROME IRON GROUP LTD THE** **RCRA NonGen / NLR** **1000791403**
SSE **416 CANAL ST** **FINDS** **NYD987029121**
1/8-1/4 **ROME, NY 13440** **MANIFEST**
0.184 mi.
974 ft. **Site 3 of 5 in cluster K**

Relative:
Higher

Actual:
439 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	ROME IRON GROUP LTD THE
Facility address:	416 CANAL ST ROME, NY 134404390
EPA ID:	NYD987029121
Mailing address:	PO BOX 4390 CANAL ST ROME, NY 134424390
Contact:	JONATHAN KNAUTH
Contact address:	PO BOX 4390 CANAL ST ROME, NY 134424390
Contact country:	US
Contact telephone:	(315) 337-9000
Contact email:	Not reported
EPA Region:	02
Land type:	Private
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	THE ROME IRON GROUP LTD
Owner/operator address:	CANAL ST PO BOX 4390 ROME, NY 13442
Owner/operator country:	US
Owner/operator telephone:	(315) 337-9000
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	THE ROME IRON GROUP LTD
Owner/operator address:	CANAL ST PO BOX 4390 ROME, NY 13442
Owner/operator country:	US
Owner/operator telephone:	(315) 337-9000
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No

ROME IRON GROUP LTD THE (Continued) **1000791403**

Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: ROME IRON GROUP LTD THE
Classification: Not a generator, verified

Date form received by agency: 02/09/1993
Site name: ROME IRON GROUP LTD THE
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - Manifest
Date violation determined: 08/16/1993
Date achieved compliance: 08/26/1993
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/16/1993
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

ROME IRON GROUP LTD THE (Continued) **1000791403**

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 01/13/1993
Date achieved compliance: 03/08/1993
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 03/02/1993
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: 2500
Paid penalty amount: 2500

Evaluation Action Summary:
Evaluation date: 07/27/1993
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Manifest
Date achieved compliance: 08/26/1993
Evaluation lead agency: State

Evaluation date: 01/13/1993
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Generators - General
Date achieved compliance: 03/08/1993
Evaluation lead agency: State

FINDS:

Registry ID: 110004501502

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:
EPA ID: NYD987029121
Country: USA
Location Address 1: P O BOX 4390 CANAL ST
Location Address 2: Not reported
Location City: ROME
Location State: NY
Location Zip Code: 13442
Location Zip Code 4: Not reported

Mailing Info:
Name: ROME IRON GROUP
Contact: ROME IRON GROUP
Address: P O BOX 4390 CANAL ST
City/State/Zip: ROME, NY 13442
Country: USA
Phone: 315-337-9000

ROME IRON GROUP LTD THE (Continued) **1000791403**

Manifest:

Document ID:	NYG3208392
Manifest Status:	Not reported
Trans1 State ID:	87030JC
Trans2 State ID:	Not reported
Generator Ship Date:	12/14/2001
Trans1 Recv Date:	12/14/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/17/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987029121
Trans1 EPA ID:	NYD013277454
Trans2 EPA ID:	Not reported
TSDF ID:	NYD013277454
Waste Code:	F003 - UNKNOWN
Quantity:	00220
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2001

Document ID:	MIA3622179
Manifest Status:	Completed copy
Trans1 State ID:	PP8404NY
Trans2 State ID:	87992ZNY
Generator Ship Date:	07/29/1994
Trans1 Recv Date:	07/29/1994
Trans2 Recv Date:	08/01/1994
TSD Site Recv Date:	08/03/1994
Part A Recv Date:	08/08/1994
Part B Recv Date:	08/16/1994
Generator EPA ID:	NYD987029121
Trans1 EPA ID:	NYD986903904
Trans2 EPA ID:	NYD986903904
TSDF ID:	MID096963194
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Year:	1994

Document ID:	NYG1820817
Manifest Status:	Not reported
Trans1 State ID:	EZ1099
Trans2 State ID:	Not reported
Generator Ship Date:	08/25/2000
Trans1 Recv Date:	08/25/2000
Trans2 Recv Date:	Not reported

ROME IRON GROUP LTD THE (Continued) **1000791403**

TSD Site Recv Date:	08/25/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987029121
Trans1 EPA ID:	NYD013277454
Trans2 EPA ID:	Not reported
TSDF ID:	NYD013277454
Waste Code:	F005 - UNKNOWN
Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2000

Document ID:	NYG1120716
Manifest Status:	Not reported
Trans1 State ID:	HU7905
Trans2 State ID:	Not reported
Generator Ship Date:	05/25/1999
Trans1 Recv Date:	05/25/1999
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/25/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987029121
Trans1 EPA ID:	NYD013277454
Trans2 EPA ID:	Not reported
TSDF ID:	NYD013277454
Waste Code:	F003 - UNKNOWN
Quantity:	00220
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1999

Document ID:	NYG1123551
Manifest Status:	Not reported
Trans1 State ID:	AM8365
Trans2 State ID:	Not reported
Generator Ship Date:	02/05/1999
Trans1 Recv Date:	02/05/1999
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/05/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987029121
Trans1 EPA ID:	NYD013277454
Trans2 EPA ID:	Not reported
TSDF ID:	NYD013277454
Waste Code:	F003 - UNKNOWN
Quantity:	00220

ROME IRON GROUP LTD THE (Continued) **1000791403**

Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1999

Document ID:	NYG1414701
Manifest Status:	Not reported
Trans1 State ID:	MX3142
Trans2 State ID:	Not reported
Generator Ship Date:	12/30/1998
Trans1 Recv Date:	12/30/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/30/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987029121
Trans1 EPA ID:	NYD013277454
Trans2 EPA ID:	Not reported
TSDF ID:	NYD013277454
Waste Code:	F003 - UNKNOWN
Quantity:	00220
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1998

Document ID:	NYG1390491
Manifest Status:	Not reported
Trans1 State ID:	HU7905
Trans2 State ID:	Not reported
Generator Ship Date:	07/14/1998
Trans1 Recv Date:	07/14/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/14/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987029121
Trans1 EPA ID:	NYD013277454
Trans2 EPA ID:	Not reported
TSDF ID:	NYD013277454
Waste Code:	F003 - UNKNOWN
Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	1998

Document ID:	NYG0222543

ROME IRON GROUP LTD THE (Continued) **1000791403**

Manifest Status:	Completed copy
Trans1 State ID:	AM8365
Trans2 State ID:	Not reported
Generator Ship Date:	05/14/1997
Trans1 Recv Date:	05/14/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	05/14/1997
Part A Recv Date:	05/22/1997
Part B Recv Date:	05/23/1997
Generator EPA ID:	NYD987029121
Trans1 EPA ID:	NYD013277454
Trans2 EPA ID:	Not reported
TSDF ID:	NYD013277454
Waste Code:	F003 - UNKNOWN
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1997

Document ID:	NYG0343071
Manifest Status:	Completed copy
Trans1 State ID:	MX3142
Trans2 State ID:	Not reported
Generator Ship Date:	10/17/1997
Trans1 Recv Date:	10/17/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	10/17/1997
Part A Recv Date:	11/13/1997
Part B Recv Date:	11/04/1997
Generator EPA ID:	NYD987029121
Trans1 EPA ID:	NYD013277454
Trans2 EPA ID:	Not reported
TSDF ID:	NYD013277454
Waste Code:	F003 - UNKNOWN
Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100
Year:	1997

Document ID:	NYB7664112
Manifest Status:	Completed copy
Trans1 State ID:	MX3142
Trans2 State ID:	Not reported
Generator Ship Date:	01/17/1996
Trans1 Recv Date:	01/17/1996
Trans2 Recv Date:	/ /
TSD Site Recv Date:	01/17/1996
Part A Recv Date:	01/31/1996
Part B Recv Date:	01/25/1996

ROME IRON GROUP LTD THE (Continued) **1000791403**

Generator EPA ID:	NYD987029121
Trans1 EPA ID:	NYD013277454
Trans2 EPA ID:	Not reported
TSDF ID:	NYD013277454
Waste Code:	F003 - UNKNOWN
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1996

Document ID:	NYB7702776
Manifest Status:	Completed copy
Trans1 State ID:	HU7905
Trans2 State ID:	Not reported
Generator Ship Date:	07/26/1996
Trans1 Recv Date:	07/26/1996
Trans2 Recv Date:	/ /
TSD Site Recv Date:	07/26/1996
Part A Recv Date:	08/08/1996
Part B Recv Date:	08/09/1996
Generator EPA ID:	NYD987029121
Trans1 EPA ID:	NYD013277454
Trans2 EPA ID:	Not reported
TSDF ID:	NYD013277454
Waste Code:	F003 - UNKNOWN
Quantity:	00275
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	005
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1996

Document ID:	NYB7296516
Manifest Status:	Completed copy
Trans1 State ID:	EZ1099
Trans2 State ID:	Not reported
Generator Ship Date:	11/01/1996
Trans1 Recv Date:	11/01/1996
Trans2 Recv Date:	/ /
TSD Site Recv Date:	11/01/1996
Part A Recv Date:	11/18/1996
Part B Recv Date:	11/21/1996
Generator EPA ID:	NYD987029121
Trans1 EPA ID:	NYD013277454
Trans2 EPA ID:	Not reported
TSDF ID:	NYD013277454
Waste Code:	F003 - UNKNOWN
Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels

ROME IRON GROUP LTD THE (Continued) **1000791403**

Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100
Year: 1996

Document ID: NYB6840873
Manifest Status: Completed copy
Trans1 State ID: HU7905
Trans2 State ID: Not reported
Generator Ship Date: 07/18/1995
Trans1 Recv Date: 07/18/1995
Trans2 Recv Date: / /
TSD Site Recv Date: 07/18/1995
Part A Recv Date: 07/27/1995
Part B Recv Date: 07/28/1995
Generator EPA ID: NYD987029121
Trans1 EPA ID: NYD013277454
Trans2 EPA ID: Not reported
TSDF ID: NYD013277454
Waste Code: F003 - UNKNOWN
Quantity: 00110
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 002
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 1995

Document ID: NYB6844644
Manifest Status: Completed copy
Trans1 State ID: HU7905
Trans2 State ID: Not reported
Generator Ship Date: 03/03/1995
Trans1 Recv Date: 03/03/1995
Trans2 Recv Date: / /
TSD Site Recv Date: 03/03/1995
Part A Recv Date: 03/14/1995
Part B Recv Date: 03/15/1995
Generator EPA ID: NYD987029121
Trans1 EPA ID: NYD013277454
Trans2 EPA ID: Not reported
TSDF ID: NYD013277454
Waste Code: F003 - UNKNOWN
Quantity: 00055
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 001
Container Type: DM - Metal drums, barrels
Handling Method: R Material recovery of more than 75 percent of the total material.
Specific Gravity: 100
Year: 1995

Document ID: NYB4313358
Manifest Status: Completed copy
Trans1 State ID: NYHU7905
Trans2 State ID: Not reported

ROME IRON GROUP LTD THE (Continued) **1000791403**

Generator Ship Date:	05/06/1994
Trans1 Recv Date:	05/06/1994
Trans2 Recv Date:	/ /
TSD Site Recv Date:	05/06/1994
Part A Recv Date:	05/16/1994
Part B Recv Date:	05/17/1994
Generator EPA ID:	NYD987029121
Trans1 EPA ID:	NYD013277454
Trans2 EPA ID:	Not reported
TSDF ID:	NYD013277454
Waste Code:	F003 - UNKNOWN
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1994

Document ID:	NYB6681132
Manifest Status:	Completed copy
Trans1 State ID:	EZ1099
Trans2 State ID:	Not reported
Generator Ship Date:	11/04/1994
Trans1 Recv Date:	11/04/1994
Trans2 Recv Date:	/ /
TSD Site Recv Date:	11/04/1994
Part A Recv Date:	11/15/1994
Part B Recv Date:	11/15/1994
Generator EPA ID:	NYD987029121
Trans1 EPA ID:	NYD013277454
Trans2 EPA ID:	Not reported
TSDF ID:	NYD013277454
Waste Code:	F003 - UNKNOWN
Quantity:	00220
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1994

Document ID:	NYB4539879
Manifest Status:	Completed copy
Trans1 State ID:	EZ1099
Trans2 State ID:	Not reported
Generator Ship Date:	02/18/1994
Trans1 Recv Date:	02/18/1994
Trans2 Recv Date:	/ /
TSD Site Recv Date:	02/18/1994
Part A Recv Date:	02/28/1994
Part B Recv Date:	03/01/1994
Generator EPA ID:	NYD987029121
Trans1 EPA ID:	NYD013277454
Trans2 EPA ID:	Not reported

ROME IRON GROUP LTD THE (Continued) **1000791403**

TSDF ID:	NYD013277454
Waste Code:	F003 - UNKNOWN
Quantity:	00220
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Year:	1994

Document ID:	NYG2482893
Manifest Status:	Not reported
Trans1 State ID:	EZ1099
Trans2 State ID:	Not reported
Generator Ship Date:	06/16/2000
Trans1 Recv Date:	06/16/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/16/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987029121
Trans1 EPA ID:	NYD013277454
Trans2 EPA ID:	Not reported
TSDF ID:	NYD013277454
Waste Code:	F005 - UNKNOWN
Quantity:	00165
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	003
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Year:	2000

K51 **EDR US Hist Auto Stat** **1015483197**
SSE **416 CANAL ST** **N/A**
1/8-1/4 **ROME, NY 13440**
0.184 mi.
974 ft. **Site 4 of 5 in cluster K**

Relative:
Higher

EDR Historical Auto Stations:

Name:	PROLINE AUTOMOTIVE
Year:	2002
Address:	416 CANAL ST

Actual:
439 ft.

---

52 **AGWAY** **LTANKS** **S100167275**
WSW **SOUTH JAMES ST** **N/A**
1/8-1/4 **ROME C, NY**
0.187 mi.
987 ft.

Relative:
Lower

LTANKS:

Site ID:	280900
Spill Number/Closed Date:	8605923 / 12/11/1989
Spill Date:	12/17/1986
Spill Cause:	Tank Failure

Actual:
433 ft.

AGWAY (Continued) **S100167275**

Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Not reported
Cleanup Ceased:	6/3/1987
Cleanup Meets Standard:	True
SWIS:	3300
Investigator:	DIJOHNSO
Referred To:	Not reported
Reported to Dept:	12/17/1986
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	DEC
Last Inspection:	12/18/1986
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	12/22/1986
Spill Record Last Update:	12/14/1989
Spiller Name:	Not reported
Spiller Company:	AGWAY - TONY MIETEL
Spiller Address:	BOX 469
Spiller City,St,Zip:	ROME, NY 13440
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	6
DER Facility ID:	228103
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "JOHNSON" / / : 12/18/86 - CLARENCE WILL INSTALL MONITORING WELL AND PILE CONTAMINATED SOIL ON PLASTIC (DJ).06/03/87: CONTAMINATED SOIL (40 YDS.) DISPOSED OF (JM).12/05/89: SOIL DISPOSAL PAPERWORK SUBMITTED. (JM).12/11/89: CLOSED (JM).12/13/89: RECEIVED SOIL PAPERWORK.CLOSED (AC).
Remarks:	TANKS PULLED BY CLARENCE YOCUM-CLEANED BY HITCHINGS. TANKS FULL OF HOLES-SHEEN ON GROUNDWATER-APPROX. 4’ DEEP

Material:

Site ID:	280900
Operable Unit ID:	902759
Operable Unit:	01
Material ID:	475066
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Not reported
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

53
NW
1/8-1/4
0.189 mi.
997 ft.

ROME BULK MATERIAL (C)
LIBERTY PLAZA
ROME, NY 13440

SWF/LF **S103276768**
N/A

Relative:
Higher

Actual:
439 ft.

SWF/LF:

Flag:	INACTIVE
Region Code:	6
Phone Number:	3153366000
Owner Name:	City of Rome
Owner Type:	Municipal
Owner Address:	Liberty Plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	Rome, NY 13440
Owner Email:	Not reported
Owner Phone:	3153366000
Contact Name:	Not reported
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Transfer station - permit
Activity Number:	[33T05]
Active:	No
East Coordinate:	0
North Coordinate:	0
Accuracy Code:	Not reported
Regulatory Status:	None
Waste Type:	Not reported
Authorization #:	Not reported
Authorization Date:	04/05/1994
Expiration Date:	Not reported

K54
SSE
1/8-1/4
0.189 mi.
998 ft.

428 CANAL ST
ROME, NY 13440

Site 5 of 5 in cluster K

EDR US Hist Auto Stat **1015490703**
N/A

Relative:
Lower

Actual:
438 ft.

EDR Historical Auto Stations:

Name:	PROLINE AUTOMOTIVE
Year:	2003
Address:	428 CANAL ST
Name:	PROLINE AUTOMOTIVE
Year:	2004
Address:	428 CANAL ST
Name:	PROLINE AUTOMOTIVE
Year:	2009
Address:	428 CANAL ST
Name:	PROLINE AUTOMOTIVE
Year:	2010
Address:	428 CANAL ST

55
East
1/8-1/4
0.190 mi.
1001 ft.

IN FRONT OF PLAZA RESTAUR
229 EAST DOMINICK ST
UTICA, NY

LTANKS **S102233907**
N/A

Relative:
Higher

Actual:
439 ft.

LTANKS:

Site ID:	132762
Spill Number/Closed Date:	9605346 / 8/28/1996
Spill Date:	7/25/1996
Spill Cause:	Tank Failure
Spill Source:	Unknown
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. No DEC Response. No corrective action required.
Cleanup Ceased:	7/25/1996
Cleanup Meets Standard:	True
SWIS:	3300
Investigator:	NFCARRIE
Referred To:	Not reported
Reported to Dept:	7/25/1996
CID:	297
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	7/25/1996
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	7/25/1996
Spill Record Last Update:	9/4/1996
Spiller Name:	R. COMIS
Spiller Company:	CITY OF ROME
Spiller Address:	CITY HALL
Spiller City,St,Zip:	ROME, NY 13440-
Spiller County:	001
Spiller Contact:	GEORGE ROSSI
Spiller Phone:	(315) 337-2660
Spiller Extention:	Not reported
DEC Region:	6
DER Facility ID:	114275
DEC Memo:	Not reported
Remarks:	COMPLAINANTS COMPANY WAS HIRED BY THE CITY FOR STREET REPAIR AND FOUND A TANK UNDER THE PAVEMENT IT HAS BEEN LEAKING WHATEVER IT CONTAINED INTO THE GROUND - COMP BELIEVES IT IS EITHER GAS OR FUEL OIL IN THE TANK - CLENA UP CREW HAS NOT BEEN CONTACTED YET - COMP WOULD LIKE A DEC RESPONSE AS SOON AS POSSIBLE

Material:

Site ID:	132762
Operable Unit ID:	1036201
Operable Unit:	01
Material ID:	348094
Material Code:	0066A
Material Name:	UNKNOWN PETROLEUM
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No

IN FRONT OF PLAZA RESTAUR (Continued) **S102233907**

Resource Affected: Not reported
Oxygenate: False

Tank Test:

J56 **TRANSFIGURATION CHURCH** **LTANKS** **S100144074**
WSW **111 RIDGE RD** **N/A**
1/8-1/4 **ROME C, NY**
0.194 mi.
1026 ft. **Site 2 of 2 in cluster J**

Relative:
Lower

Actual:
435 ft.

LTANKS:
Site ID: 209398
Spill Number/Closed Date: 8601754 / 6/21/1986
Spill Date: 6/13/1986
Spill Cause: Tank Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Not reported
Cleanup Ceased: 6/21/1986
Cleanup Meets Standard: True
SWIS: 3300
Investigator: DIJOHNSO
Referred To: Not reported
Reported to Dept: 6/13/1986
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 6/27/1986
Spill Record Last Update: 7/24/1986
Spiller Name: Not reported
Spiller Company: TRANSFIGURATION CHURCH
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 6
DER Facility ID: 173636
DEC Memo: Not reported
Remarks: Not reported

Material:
Site ID: 209398
Operable Unit ID: 899206
Operable Unit: 01
Material ID: 478238
Material Code: 0001A
Material Name: #2 Fuel Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0

TRANSFIGURATION CHURCH (Continued) **S100144074**

Units: Not reported
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

57
North
1/8-1/4
0.201 mi.
1061 ft.

Relative:
Higher

Actual:
452 ft.

NOLAN,HAYES & ADOLFI **LTANKS** **S102676897**
LIBERTY ST-ROME CITY HALL **N/A**
ROME C, NY

LTANKS:
Site ID: 273463
Spill Number/Closed Date: 8600647 / 4/29/1986
Spill Date: 4/28/1986
Spill Cause: Tank Overfill
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Not reported
Cleanup Ceased: 4/29/1986
Cleanup Meets Standard: True
SWIS: 3300
Investigator: AJMARSCH
Referred To: Not reported
Reported to Dept: 4/28/1986
CID: Not reported
Water Affected: Not reported
Spill Notifier: Local Agency
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 5/19/1986
Spill Record Last Update: 9/9/1986
Spiller Name: Not reported
Spiller Company: NOLAN HAYS & ADOLFI
Spiller Address: Not reported
Spiller City,St,Zip: ZZ
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 6
DER Facility ID: 222473
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "JM" / / : SPILR.EXCAV.CONTAM.SOIL&CLEAN STORM CATCH BASINS.
Remarks: NOLAN HAYS&ADOLFI WILL START CLEANUP BY PUTTING DOWN SPEEDI-DRY

Material:
Site ID: 273463
Operable Unit ID: 898448
Operable Unit: 01
Material ID: 480794
Material Code: 0001A
Material Name: #2 Fuel Oil

NOLAN,HAYES & ADOLFI (Continued) **S102676897**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

58
East
1/8-1/4
0.211 mi.
1112 ft.

SEARS OIL CO
7064 LADO AVE
ROME, NY 13440

RCRA-CESQG **1000369103**
FINDS **NYD981182579**
LTANKS
MANIFEST
NY Spills

Relative:
Lower

Actual:
435 ft.

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	SEARS OIL CO INC
Facility address:	7064 LADO AVE ROME, NY 13440
EPA ID:	NYD981182579
Mailing address:	BLACK RIVER BLVD ROME, NY 13440
Contact:	Not reported
Contact address:	BLACK RIVER BLVD ROME, NY 13440
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	SEARS OIL CO INC
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported

SEARS OIL CO (Continued) **1000369103**

Owner/Op end date: Not reported

Owner/operator name: SEARS OIL CO INC
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: SEARS OIL CO INC
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 04/19/1995
Site name: SEARS OIL CO INC
Classification: Not a generator, verified

. Waste code: NONE
. Waste name: None

Date form received by agency: 02/06/1986
Site name: SEARS OIL CO INC
Classification: Small Quantity Generator

. Waste code: K052
. Waste name: TANK BOTTOMS (LEADED) FROM THE PETROLEUM REFINING INDUSTRY.

Violation Status: No violations found

FINDS:

Registry ID: 110004402290

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of

SEARS OIL CO (Continued) **1000369103**

events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

LTANKS:

Site ID:	136265
Spill Number/Closed Date:	9002211 / 5/25/1990
Spill Date:	5/25/1990
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Cleanup Ceased:	5/25/1990
Cleanup Meets Standard:	True
SWIS:	3300
Investigator:	DIJOHNSO
Referred To:	Not reported
Reported to Dept:	5/25/1990
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	Not reported
Spill Record Last Update:	12/2/2003
Spiller Name:	Not reported
Spiller Company:	SEARS OIL COMPANY
Spiller Address:	BLACK RIVER BLVD.
Spiller City,St,Zip:	ROME, NY 13440
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	6
DER Facility ID:	116767
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "JOHNSON"05/25/90: 1650 SPOKE TO SEARS OIL, CONFIRMED CLEANUP BY DRIVER. INDICATED SPILL ONLY ABOUT 1 GALLON. COMPLETE. (DJ).
Remarks:	JERRY HOWARD, DRIVER, OVERFILLED TANK. USED SORBENTS TO CLEAN UP.

SEARS OIL CO (Continued) **1000369103**

Material:

Site ID:	136265
Operable Unit ID:	942067
Operable Unit:	01
Material ID:	436968
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

NY MANIFEST:

EPA ID:	NYD981182579
Country:	USA
Location Address 1:	7064 LADO AVE
Location Address 2:	Not reported
Location City:	ROME
Location State:	NY
Location Zip Code:	13440
Location Zip Code 4:	Not reported

Mailing Info:

Name:	SEARS OIL COMPANY INC
Contact:	SEARS OIL COMPANY INC
Address:	1914 BLACK RIVER ROAD
City/State/Zip:	ROME, NY 13440
Country:	USA
Phone:	315-337-1232

Manifest:

Document ID:	MIA8177399
Manifest Status:	Not reported
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	08/12/2003
Trans1 Recv Date:	08/12/2003
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/13/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981182579
Trans1 EPA ID:	PAD987358587
Trans2 EPA ID:	Not reported
TSDF ID:	MID096963194
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Quantity:	00550
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	010

SEARS OIL CO (Continued) **1000369103**

Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 01.00
Year: 2003

SPILLS:
Facility ID: 8904665
Facility Type: ER
DER Facility ID: 78048
Site ID: 84900
DEC Region: 6
Spill Date: 8/10/1989
Spill Number/Closed Date: 8904665 / 8/22/1990
Spill Cause: Equipment Failure
Spill Class: Not reported
SWIS: 3300
Investigator: AJMARSCH
Referred To: Not reported
Reported to Dept: 8/10/1989
CID: Not reported
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: Responsible Party
Cleanup Ceased: 8/15/1990
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: True
Remediation Phase: 0
Date Entered In Computer: 8/17/1989
Spill Record Last Update: 8/24/1990
Spiller Name: Not reported
Spiller Company: SEARS OIL CO.
Spiller Address: 1914 BLACK RIVER BLVD
Spiller City,St,Zip: ROME, NY
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Not reported
Remarks: SEEPAGE AT GAS PUMP POSSIBLY THREADING PROBLEM ON RISER PIPE. RECOVRY SYSTEM BEING INSTALLED. JACK MARSCH WAS FIRST NOTIFIED BY SPILER.

Material:
Site ID: 84900
Operable Unit ID: 929931
Operable Unit: 01
Material ID: 448702
Material Code: 0008
Material Name: Diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Not reported
Recovered: No
Resource Affected: Not reported
Oxygenate: False

SEARS OIL CO (Continued) **1000369103**

Tank Test:

L59
ESE
1/8-1/4
0.211 mi.
1113 ft.

NIMO - ROME: KINGSLEY AVENUE MGP **EDR MGP** **1008408032**
KINGSLEY AVENUE **N/A**
ROME, NY 13440

Site 1 of 2 in cluster L

Relative:
Lower

Actual:
433 ft.

Manufactured Gas Plants:

The site is located south of East Dominick Street, bordering a historic commercial and residential district, about 2,000 feet north of the confluence of the Mohawk River with the New York State Barge Canal. It is bounded by the Genesee and Mohawk Valley Railroad to the north and the Mohawk River forms the western boundary of the site. Whitesboro Street terminates near the southern boundary of the site. The city of Rome Department of Public Works facility is located to the east. Residential properties are near the site entrance on Kingsley Avenue. The site is approximately 21.6 acres in area. Source: ROD

60
SSE
1/8-1/4
0.225 mi.
1188 ft.

NYS DOT/BRIDGE MAIN. FACILITY **UST** **U003312996**
WHITESBORO STREET **HIST UST** **N/A**
ROME C, NY 13440

Relative:
Higher

Actual:
440 ft.

UST:

Id/Status:	6-600652 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	6
Expiration Date:	05/21/2002
UTM X:	463001.36622999999
UTM Y:	4783648.7198099997
Site Type:	Other

Affiliation Records:

Site Id:	43475
Affiliation Type:	Facility Owner
Company Name:	NYS DOT
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	STATE CAMPUS BUILDING 5
Address2:	Not reported
City:	ALBANY
State:	NY
Zip Code:	12232
Country Code:	001
Phone:	(518) 457-6195
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	43475
Affiliation Type:	Mail Contact
Company Name:	NYS DEPT. OF TRANSPORTATION
Contact Type:	Not reported

NYS DOT/BRIDGE MAIN. FACILITY (Continued) **U003312996**

Contact Name:	KATHY LOCONTI
Address1:	207 GENESEE STREET
Address2:	Not reported
City:	UTICA
State:	NY
Zip Code:	13501
Country Code:	001
Phone:	(315) 793-2498
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	43475
Affiliation Type:	On-Site Operator
Company Name:	NYS DOT/BRIDGE MAIN. FACILITY
Contact Type:	Not reported
Contact Name:	NYS DOT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(315) 793-2498
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	43475
Affiliation Type:	Emergency Contact
Company Name:	NYS DOT
Contact Type:	Not reported
Contact Name:	KATHY LOCONTI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(315) 793-2498
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

Tank Number:	1
Tank ID:	123644
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1000
Install Date:	Not reported
Date Tank Closed:	06/01/1997
Registered:	True

NYS DOT/BRIDGE MAIN. FACILITY (Continued) **U003312996**

Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number: 2
Tank ID: 123645
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1000
Install Date: Not reported
Date Tank Closed: 06/01/1997
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number: 3
Tank ID: 123646

NYS DOT/BRIDGE MAIN. FACILITY (Continued) **U003312996**

Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1000
Install Date:	Not reported
Date Tank Closed:	06/01/1997
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0012
Common Name of Substance:	Kerosene [#1 Fuel Oil] (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

HIST UST:

PBS Number:	6-600652
SPDES Number:	Not reported
Emergency Contact:	KATHY LOCONTI
Emergency Telephone:	(315) 793-2498
Operator:	NYS DOT
Operator Telephone:	(315) 793-2498
Owner Name:	NYS DOT
Owner Address:	STATE CAMPUS BUILDING 5
Owner City,St,Zip:	ALBANY, NY 12232
Owner Telephone:	(518) 457-6195
Owner Type:	State Government
Owner Subtype:	NYS Department of Transportation
Mailing Name:	NYS DEPT. OF TRANSPORTATION
Mailing Address:	207 GENESEE STREET
Mailing Address 2:	Not reported
Mailing City,St,Zip:	UTICA, NY 13501
Mailing Contact:	KATHY LOCONTI
Mailing Telephone:	(315) 793-2498
Owner Mark:	First Owner
Facility Status:	2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Facility Addr2:	Not reported
SWIS ID:	3013
Old PBS Number:	Not reported
Facility Type:	OTHER
Inspected Date:	Not reported
Inspector:	Not reported

NYS DOT/BRIDGE MAIN. FACILITY (Continued) **U003312996**

Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	05/22/1997
Expiration Date:	05/21/2002
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	0
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	Minor Data Missing
Tank Screen:	0
Dead Letter:	False
CBS Number:	Not reported
Town or City:	ROME (C)
County Code:	30
Town or City:	13
Region:	6

Tank Id:	1
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	1000
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	06/01/1997
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	2
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	1000
Product Stored:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	GALVANIZED STEEL

NYS DOT/BRIDGE MAIN. FACILITY (Continued) **U003312996**

Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	06/01/1997
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	3
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	1000
Product Stored:	KEROSENE
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	06/01/1997
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

---

61 **ROME ANIMAL CONTROL UNIT** **LTANKS** **S107410558**
NNE **112 WEST LIBERTY STREET** **N/A**
1/8-1/4 **ROME, NY**
0.234 mi.
1236 ft.

Relative:
Higher

Actual:
454 ft.

LTANKS:

Site ID:	352730
Spill Number/Closed Date:	0507336 / 9/19/2005
Spill Date:	9/19/2005
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	9/19/2005

ROME ANIMAL CONTROL UNIT (Continued) **S107410558**

Cleanup Meets Standard:	True
SWIS:	3313
Investigator:	JDALSANT
Referred To:	Not reported
Reported to Dept:	9/19/2005
CID:	444
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	9/19/2005
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	9/19/2005
Spill Record Last Update:	11/21/2005
Spiller Name:	DAN STOWELL
Spiller Company:	GRIFFITH ENERGY TERMINAL
Spiller Address:	760 BROKS AVE
Spiller City,St,Zip:	ROCHESTER, NY
Spiller County:	001
Spiller Contact:	DAN G.
Spiller Phone:	(315) 339-7761
Spiller Extention:	Not reported
DEC Region:	6
DER Facility ID:	300032
DEC Memo:	09/19/05: OIL COMPANY OVERFILLED TANK. SPRAYED OUTSIDE AT VENT ONTO SIDE OF BLDG, INTO WINDOW WELL AND ON GROUND. OUTSIDE CLEANED UP AS MUCH AS POSSIBLE. OVERFLOWED FROM FITTINGS ON TANK IN CELLER. SPEEDI-DRY USED FOR CLEANUP IS IN TRASH BAG. ADDITIONAL SPEEDI-DRY AND DEODORIZER PUT DOWN TO BE PICKED UP LATER. NON-TRACKABLE AMOUNT OF DEBRIS GENERATED. SPILL CLOSED. (JA)
Remarks:	OVERFILL, AND IS ALL CLEANED UP:

Material:

Site ID:	352730
Operable Unit ID:	1110206
Operable Unit:	01
Material ID:	2100223
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3
Units:	Gallons
Recovered:	3
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

L62 **NIMO, ROME (KINGSLEY AVE.)** **HSWDS** **S108146970**
ESE **KINGSLEY AVE.** **N/A**
1/8-1/4 **ROME, NY 13340**
0.236 mi.
1244 ft. **Site 2 of 2 in cluster L**

Relative:
Lower

Actual:
436 ft.

HSWDS:

Facility ID:	Not reported
Region:	6
Facility Status:	Y
Owner Type:	Publ Utily
Owner:	Niagara Mohawk
Owner Address:	300 Erie Blvd. West
Owner Phone:	(315)474-1511
Operator Type:	Publ Utily
Operator:	Same
Operator:	Same
Operator Phone:	Same
EPA ID:	NYD980664221
Registry:	Not on NYS Registry of Inactive Haz Waste Disposal Sites
Registry Site ID:	None
RCRA Permitted:	Unknown
Site Code:	Coal Gasification Plant
Owner City State:	Syracuse
Operator City State:	Not reported
Quadrange:	Rome, New York
Latitude:	43 12 23 N
Longitude:	75 27 10 W
Acres:	22.30
Operator Date:	1852
Close Date:	1923
Completed:	FDSI
Active:	Unknown
PCB's Disposed:	No
Pesticides Disposed:	No
Metals Disposed:	Yes
Asbestos Disposed:	No
Volatile Organic Compounds Disposed:	Yes
Semi Volatile Organic Compounds Disposed:	Yes
Analytical Info Exists for Air:	Not reported
Analytical Info Exists for Ground:	Groundwater
Analytical Info Exists for Surface:	Surface Water
Analytical Info Exists for Sediments:	Not reported
Analytical Info Exists for Surface:	Surface Soil
Analytical Info Exists for Substance:	Subsurface
Analytical Info Exists for Waste:	Not reported
Analytical Info Exists for Leachate:	Not reported
Analytical Info Exists for EP Toxicity:	Not reported
Analytical Info Exists for TCLP:	Not reported
Threat to Environment/Public Health:	Environmental/Public
Surface Water Contamination:	Yes
Surface Water Body Class:	Unknown
Groundwater Contamination:	No
Groundwater Classification:	Principal
Drinking Water Contamination:	Yes
Drinking Water Supply is Active:	Unknown
Any Known Fish or Wildlife:	Unknown
Hazardous Exposure:	Unknown
Site Has Controlled Acess:	No

NIMO, ROME (KINGSLEY AVE.) (Continued) **S108146970**

Ambient Air Contamination:	No
Direct Contact:	Yes
EPA Hazardous Ranking System Score:	38
Inventory:	F
Nefrap:	Not reported
Mailing:	Not reported
Tax Map No:	Not reported
Qualify:	0
Next Action:	Not reported
Agencies:	Not reported
Air:	Not reported
Building:	Not reported
Site Desc:	Not reported
Drink:	Not reported
Eptox:	Not reported
Fish:	Not reported
Ground:	Not reported
Ground Desc:	Not reported
Hazardous Threat:	Not reported
Haz Threat Desc:	Not reported
Leachate:	Not reported
Preparer:	Not reported
Sediment:	Not reported
Soil:	Not reported
Surface:	Not reported
Status:	Not reported
Surface Soil:	Not reported
Surface:	Not reported
TCLP:	Not reported
Waste:	Not reported

63
West
1/8-1/4
0.240 mi.
1269 ft.

TAMBURINO FACILITY
230 RIDGE STREET
ROME C, NY 13440

UST **U002034587**
HIST UST **N/A**
NY Spills

Relative:
Higher

Actual:
439 ft.

UST:

Id/Status:	6-600380 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	6
Expiration Date:	10/27/1999
UTM X:	462372.93557999999
UTM Y:	4784140.0025699995
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	43203
Affiliation Type:	Facility Owner
Company Name:	GENE TAMBURINO
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	225 RIDGE STREET
Address2:	Not reported
City:	ROME
State:	NY
Zip Code:	13440

TAMBURINO FACILITY (Continued) **U002034587**

Country Code:	001
Phone:	(315) 339-0152
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	43203
Affiliation Type:	Mail Contact
Company Name:	GENE TAMBURINO
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	225 RIDGE STREET
Address2:	Not reported
City:	ROME
State:	NY
Zip Code:	13440
Country Code:	001
Phone:	(315) 339-0152
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	43203
Affiliation Type:	On-Site Operator
Company Name:	TAMBURINO FACILITY
Contact Type:	Not reported
Contact Name:	GENE TAMBURINO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(315) 339-0152
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	43203
Affiliation Type:	Emergency Contact
Company Name:	GENE TAMBURINO
Contact Type:	Not reported
Contact Name:	GENE TAMBURINO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(315) 339-0152
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

TAMBURINO FACILITY (Continued) **U002034587**

Tank Info:

Tank Number:	1
Tank ID:	121519
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	3000
Install Date:	08/01/1977
Date Tank Closed:	11/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	ZZ
Date Test:	12/01/1976
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
I00 - Overfill - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None

Tank Number:	2
Tank ID:	121520
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1000
Install Date:	08/01/1977
Date Tank Closed:	11/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	ZZ
Date Test:	12/01/1976
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser

TAMBURINO FACILITY (Continued) **U002034587**

D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
I00 - Overfill - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None

Tank Number:	3
Tank ID:	121521
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	Not reported
Date Tank Closed:	11/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
I00 - Overfill - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None

Tank Number:	4
Tank ID:	121522
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	11/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT

TAMBURINO FACILITY (Continued) **U002034587**

Last Modified: 03/04/2004

Equipment Records:

F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
I00 - Overfill - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None

HIST UST:

PBS Number:	6-600380
SPDES Number:	Not reported
Emergency Contact:	GENE TAMBURINO
Emergency Telephone:	(315) 339-0152
Operator:	GENE TAMBURINO
Operator Telephone:	(315) 339-0152
Owner Name:	GENE TAMBURINO
Owner Address:	225 RIDGE STREET
Owner City,St,Zip:	ROME, NY 13440
Owner Telephone:	(315) 339-0152
Owner Type:	Corporate/Commercial
Owner Subtype:	Not reported
Mailing Name:	GENE TAMBURINO
Mailing Address:	225 RIDGE STREET
Mailing Address 2:	Not reported
Mailing City,St,Zip:	ROME, NY 13440
Mailing Contact:	Not reported
Mailing Telephone:	(315) 339-0152
Owner Mark:	First Owner
Facility Status:	2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Facility Addr2:	Not reported
SWIS ID:	3013
Old PBS Number:	Not reported
Facility Type:	RETAIL GASOLINE SALES
Inspected Date:	06/29/1995
Inspector:	HM
Inspection Result:	Not reported
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	10/27/1994
Expiration Date:	10/27/1999
Renew Flag:	False
Renewal Date:	Not reported
Total Capacity:	0
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	Minor Data Missing
Tank Screen:	0
Dead Letter:	False
CBS Number:	Not reported
Town or City:	ROME (C)
County Code:	30

TAMBURINO FACILITY (Continued) **U002034587**

Town or City:	13
Region:	6
Tank Id:	3
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	2000
Product Stored:	LEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	11/01/1999
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	4
Tank Location:	UNDERGROUND
Tank Status:	Closed-In Place
Install Date:	Not reported
Capacity (gals):	550
Product Stored:	USED OIL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Suction
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	11/01/1999
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

TAMBURINO FACILITY (Continued) **U002034587**

SPILLS:

Facility ID:	9909336
Facility Type:	ER
DER Facility ID:	220934
Site ID:	271442
DEC Region:	6
Spill Date:	11/1/1999
Spill Number/Closed Date:	9909336 / 11/14/2001
Spill Cause:	Unknown
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	3300
Investigator:	JDALSANT
Referred To:	Not reported
Reported to Dept:	11/1/1999
CID:	382
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	1/24/2000
Cleanup Meets Std:	True
Last Inspection:	11/1/1999
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	11/1/1999
Spill Record Last Update:	11/27/2001
Spiller Name:	GENE TAMBURINO
Spiller Company:	GENE TAMBURINO
Spiller Address:	225 RIDGE STREET
Spiller City,St,Zip:	ROME, NY 13440-
Spiller Company:	001
Contact Name:	GENE TAMBURINO
Contact Phone:	(315) 339-0152
DEC Memo:	Not reported
Remarks:	CONTAMINATED SOIL FOUND DURING THE REMOVAL OF 3 TANKS - 1 (3000_ 2 (2000) 1 (550) BEING LEFT IN GROUND. PBS NUMBER 6-600380

Material:

Site ID:	271442
Operable Unit ID:	1083938
Operable Unit:	01
Material ID:	298427
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

M64
ENE
1/8-1/4
0.247 mi.
1303 ft.

EDR US Hist Cleaners **1014980962**
N/A

120 BLACK RIVER BLVD N
ROME, NY 13440

Site 1 of 3 in cluster M

Relative:
Higher

Actual:
443 ft.

EDR Historical Cleaners:

Name:	COLONIAL LAUNDROMATS
Year:	2010
Address:	120 BLACK RIVER BLVD N
Name:	COLONIAL LAUNDROMATS
Year:	2011
Address:	120 BLACK RIVER BLVD N
Name:	COLONIAL LAUNDROMATS
Year:	2012
Address:	120 BLACK RIVER BLVD N

M65
NE
1/8-1/4
0.249 mi.
1313 ft.

ROME (C) FIRE DEPT. **LTANKS** **S101103222**
168 BLACK RIVER BLVD. **N/A**
ROME C, NY

Site 2 of 3 in cluster M

Relative:
Higher

Actual:
445 ft.

LTANKS:

Site ID:	79276
Spill Number/Closed Date:	9400388 / 4/12/1994
Spill Date:	4/8/1994
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	4/12/1994
Cleanup Meets Standard:	True
SWIS:	3300
Investigator:	PICKETT
Referred To:	Not reported
Reported to Dept:	4/8/1994
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Federal Government
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	Not reported
Spill Record Last Update:	12/2/2003
Spiller Name:	Not reported
Spiller Company:	CITY OF ROME
Spiller Address:	CITY HALL
Spiller City,St,Zip:	ROME, NY 13440
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	6
DER Facility ID:	73697
DEC Memo:	Not reported
Remarks:	EPA #233954 CO. H.D. WAS ALSO NOTIFIED BY ANONYMOUS OCT. 15, 1993

ROME (C) FIRE DEPT. (Continued) **S101103222**

TANK PULLED AT SITE & SOIL STOCKPILED - SOIL IS STILL STOCKPILED & UNCOVERED.

Material:

Site ID:	79276
Operable Unit ID:	994109
Operable Unit:	01
Material ID:	387705
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	120
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

M66 **ROME(C) CENT. FIRE STA.** **LTANKS** **S100781997**
NE **158 BLACK RIVER BLVD** **N/A**
1/8-1/4 **ROME, NY**
0.249 mi.
1313 ft. **Site 3 of 3 in cluster M**

Relative:
Higher

Actual:
445 ft.

LTANKS:

Site ID:	123170
Spill Number/Closed Date:	8702034 / 4/29/1991
Spill Date:	6/10/1987
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Cleanup Ceased:	1/5/1989
Cleanup Meets Standard:	True
SWIS:	3300
Investigator:	DIJOHNSO
Referred To:	Not reported
Reported to Dept:	6/10/1987
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	6/17/1987
Spill Record Last Update:	5/1/1991
Spiller Name:	Not reported
Spiller Company:	CITY OF ROME
Spiller Address:	CITY HALL, LIBERTY PLAZA
Spiller City,St,Zip:	ROME, NY 13440
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported

ROME(C) CENT. FIRE STA. (Continued) **S100781997**

DEC Region: 6
DER Facility ID: 106768
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "JOHNSON"01/04/89: EXC DOWN EAST END OF TK/LOOSE SAND WENT DOWN 8-10' SAMPLED SOIL/NO ODOR NOTED/TK OPENED & CLEANED/CANNOT REMOVE AS 2" GAS MAIN RUNS OVER TOP OF WEST END (NC).04/18/91: RECEIVED TEST REPORTS FOR 6/10/87 & 6/16/87 TESTS/TANK FAILED IN ISOLATION ON 6/16/87 - CLOSED IN PLACE 1/3-1/5/89. (DJ).
Remarks: -1.10 GPH, 10K - SYSTEM FAILURE - TO RETEST TOMORROW

Material:
Site ID: 123170
Operable Unit ID: 906358
Operable Unit: 01
Material ID: 471914
Material Code: 0008
Material Name: Diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Not reported
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:
Site ID: 123170
Spill Tank Test: 1530942
Tank Number: Not reported
Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

Site ID: 68967
Spill Number/Closed Date: 9309113 / 6/15/1994
Spill Date: 10/20/1993
Spill Cause: Tank Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: 5/16/1994
Cleanup Meets Standard: True
SWIS: 3300
Investigator: PICKETT
Referred To: Not reported
Reported to Dept: 10/20/1993
CID: Not reported
Water Affected: Not reported
Spill Notifier: DEC
Last Inspection: Not reported
Recommended Penalty: False

ROME(C) CENT. FIRE STA. (Continued) **S100781997**

UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	10/28/1993
Spill Record Last Update:	6/23/1994
Spiller Name:	Not reported
Spiller Company:	CITY OF ROME
Spiller Address:	CITY HALL
Spiller City,St,Zip:	ROME, NY 13440
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	6
DER Facility ID:	106768
DEC Memo:	Not reported
Remarks:	DURING TANK REMOVAL CONTAM. NOTED IN BOTTOM OF EXCAVATION. 1-3000 DIESEL & 1-3000 GASOLINE REMOVED & HOLES NOTED IN BOTH TANKS.

Material:

Site ID:	68967
Operable Unit ID:	990657
Operable Unit:	01
Material ID:	391779
Material Code:	0008
Material Name:	Diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Not reported
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	68967
Spill Tank Test:	1542132
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

67
ESE
1/4-1/2
0.258 mi.
1361 ft.

NM - ROME KINGSLEY AVE. MGP **SHWS** **S105586402**
KINGSLEY AVENUE **N/A**
ROME, NY 13440

Relative:
Lower

Actual:
436 ft.

SHWS:

Program:	HW
Site Code:	56266
Classification:	Significant threat to the public health or environment - action required.

NM - ROME KINGSLEY AVE. MGP (Continued) **S105586402**

Region: 6
Acres: 11.600
HW Code: 633043
Record Add: 11/18/1999
Record Upd: 11/25/2014
Updated By: AMOMOROG
Site Description: Location: The Niagara Mohawk Kingsley Avenue Site is located in a suburban area, in the city of Rome, Oneida County, New York. The site is located south of East Dominick Street, bordering a commercial and residential district, and is about 2,000 feet north of the confluence of the Mohawk River and the New York State Barge Canal. Site Features: The Kingsley Avenue site is an open grassy field bounded by the Genesee and Mohawk Valley Railroad to the north and the Mohawk River to the west. The City of Rome Public Works facility is located to the east. Residential properties are present near the site entrance along Kinglsey Avenue. The site is completely surrounded by chain link fencing with locked entrances.Current Zoning/Use(s): The site is currently (mostly) inactive except for a small area used as a natural gas regulator station and an adjacent electrical substation. The site is zoned for commercial use. The surrounding parcels are currently used for a combination of commercial, light industrial and residential. Historical Use(s): This MGP site was used to manufacture gas by using coal carbonization and the water gas process. Full time gas manufacturing ended in 1930. The retort house and relief holder were decommissioned between 1938 and 1941. By the year 1949, all gas manufacturing equipment had been removed, and the central building was converted to a service and maintenance facility. The building was eventually demolished in 1994. Interim Remedial Measures (IRMs) were conducted on the site in 1994 and 1995. These IRMs involved the removal of non aqueous phase liquid (NAPL) from a subsurface pipeline that was broken during the decommissioning of the concentrator house and also to remove MGP residuals from the purifier area. The site is included in Niagara Mohawk's (NM) multi-site Consent Order for MGP sites. A Phase I Remedial Investigation (RI) was completed by NM in April of 1996, and the Phase II RI was completed in February of 1999. A Record of Decision for OU1, the MGP plant, was signed in March 2002. The remedy specified in the ROD is excavation and off-site disposal of the contaminated soil in the MGP hot spots, construction of a cap over the site and constructing a barrier wall along the river. The OU1 Remedial Design was approved in August 2006, and Phase 1 construction began in May 2007. Phase 1 includes the relocation of utilities, excavation of 3 small areas of contamination, and the construction of access roads for future work. Phase 2 construction, which includes excavation of the major source areas, was completed in 2008. Phase 3, which includes the installation of a hydraulic barrier wall, began in 2009 and was completed in 2010. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. The former manufactured gas plant (MGP) location, which is owned by National Grid (formerly Niagara Mohawk), has been designated Operable Unit 1 (OU1). OU2 consists of an approximately 2-acre area between the National Grid property and the Mohawk River. Additionally, OU2 includes the area beneath the Mohawk River and the property west of the Mohawk to East Whitesboro Street. OU2 encompasses of

NM - ROME KINGSLEY AVE. MGP (Continued) **S105586402**

	approximately 20 acres. Groundwater and soil vapor sampling was conducted as part of the OU2 FS and was completed in December 2008. The ROD for OU2 was signed in March 2009. Installation of monitoring and NAPL recovery wells was completed in 2010.Site Geology and Hydrogeology: Soil borings and monitoring well installations indicate that nearly all surficial soils have been altered due to historic operations at the site. This fill unit is approximately 8 feet thick and consists of a reworked and regraded brown silty sand mixed with miscellaneous debris including coal, ash, bricks, mortar and concrete. Below the fill is a unit of alluvial sand, gravel and cobbles ranging in thickness from 4 to 32 feet. Below the alluvial sand and gravel unit is the lacustrine silt, sand and clay ranging in thickness from 47 to 58 feet. Till was encountered below this unit and bedrock was not encountered. The depth of groundwater ranges from 5 to 10 feet below grade. Shallow groundwater on-site is subject to seasonal vertical fluctuations of up to 5 feet and generally flows toward the Mohawk River. Deep groundwater flow is to the west.
Env Problem:	OU1 - Groundwater at this site is contaminated by MGP wastes at levels greatly exceeding Part 703 standards. NAPL is present in several monitoring wells. Sediments in the Mohawk River backwater area, located southwest of the site, are contaminated at elevated levels. A sediment removal effort was conducted in the back water area of the peninsula and completed in 2011.OU2 - Site contamination has impacted the groundwater resource in the overburden soils. This groundwater is not a source of drinking water and current data supports that these levels are declining.
Health Problem:	The former plant site (OU1) has contaminated soil that will be removed or covered to prevent people from coming into contact with it. The site is currently fenced. Public water serves the area, so exposures to contaminated groundwater are not expected. The potential for soil vapor intrusion to impact on-site structures will be evaluated after remediation. Off-site (OU2), no soil contamination or evidence of soil vapor leaving the site was found.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	1917
Disp Term:	1941
Lat/Long:	43:12:23:0 / 75:27:12:0
Dell:	False
Record Add:	11/18/1999 12:00:00 PM
Record Upd:	10/17/2012 3:26:00 PM
Updated By:	ldennist
Own Op:	Disp. Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Niagara Mohawk Power Corporation
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	NY
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	CHARLES WILLARD
Owner Company:	NIAGARA MOHAWK POWER CORPORATION

NM - ROME KINGSLEY AVE. MGP (Continued) **S105586402**

Owner Address:	300 ERIE BOULEVARD WEST
Owner Addr2:	Not reported
Owner City,St,Zip:	SYRACUSE, NY 13202
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	E
Owner Name:	Not reported
Owner Company:	Niagara Mohawk Power Corporation
Owner Address:	300 Erie Blvd. West
Owner Addr2:	Not reported
Owner City,St,Zip:	Syracuse, NY 13202
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	E
Owner Name:	Not reported
Owner Company:	Niagara Mohawk Power Corporation
Owner Address:	300 Erie Blvd. West
Owner Addr2:	Not reported
Owner City,St,Zip:	Syracuse, NY 13202
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	CHARLES POST
Owner Company:	NYSDEC
Owner Address:	625 BROADWAY
Owner Addr2:	Not reported
Owner City,St,Zip:	ALBANY, NY 12233-7014
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	NIAGARA MOHAWK POWER CORPORATION
Owner Address:	300 ERIE BOULEVARD WEST
Owner Addr2:	Not reported
Owner City,St,Zip:	SYRACUSE, NY 13202
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	JERVIS PUBLIC LIBRARY
Owner Address:	613 NORTH WASHINGTON ST
Owner Addr2:	Not reported
Owner City,St,Zip:	ROME, NY 13440
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	STEPHEN LITWHILER
Owner Company:	NYSDEC
Owner Address:	317 WASHINGTON STREET
Owner Addr2:	Not reported
Owner City,St,Zip:	WATERTOWN, NY 13204
Owner Country:	United States of America
HW Code:	633043
Waste Type:	COAL TAR PITCH VOLATILES
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	633043

NM - ROME KINGSLEY AVE. MGP (Continued) **S105586402**

Waste Type:	BENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	633043
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	633043
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	633043
Waste Type:	ETHYLBENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	633043
Waste Type:	MANUFACTURED GAS PLANT (MGP) WASTES (D018)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	633043
Waste Type:	COAL TAR
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	633043
Waste Type:	COAL TAR
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	633043
Waste Type:	COAL TAR
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	NYD980664221
Cross Ref Type Code:	05
Cross Ref Type:	EPA Site ID
Record Added Date:	5/10/2001 4:31:00 PM
Record Updated:	2/24/2005 3:54:00 PM
Updated By:	REGTRANS

68
North
1/4-1/2
0.277 mi.
1460 ft.

ROME CITY HALL **LTANKS** **S100144341**
LIBERTY ST **N/A**
ROME C, NY

Relative:
Higher

Actual:
452 ft.

LTANKS:

Site ID:	134468
Spill Number/Closed Date:	8702026 / 9/29/1987
Spill Date:	6/10/1987
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Cleanup Ceased:	9/29/1987
Cleanup Meets Standard:	True
SWIS:	3300
Investigator:	DIJOHNSO
Referred To:	Not reported
Reported to Dept:	6/10/1987
CID:	Not reported

ROME CITY HALL (Continued) **S100144341**

Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	6/17/1987
Spill Record Last Update:	1/19/1988
Spiller Name:	Not reported
Spiller Company:	CITY OF ROME
Spiller Address:	LIBERTY ST
Spiller City,St,Zip:	ROME, NY 13440
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	6
DER Facility ID:	115549
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "JOHNSON" / / : 9/29/87 - SOIL DISPOSAL COMPLETE (JM).
Remarks:	-.284 GPH, 7500 GAL TANK, FUEL OIL - WILL EXCAVATE & RETEST

Material:

Site ID:	134468
Operable Unit ID:	908654
Operable Unit:	01
Material ID:	471907
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Not reported
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	134468
Spill Tank Test:	1530938
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

69
North
1/4-1/2
0.296 mi.
1563 ft.

VERIZON NEW YORK INC-NY-83211
137 NORTH WASHINGTON STREET
ROME C, NY 13440

LTANKS **S100167299**
TANKS **N/A**

Relative:
Higher

Actual:
454 ft.

LTANKS:

Site ID:	208140
Spill Number/Closed Date:	8702204 / 2/23/1990
Spill Date:	6/17/1987
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	2/23/1990
Cleanup Meets Standard:	True
SWIS:	3300
Investigator:	AJMARSCH
Referred To:	Not reported
Reported to Dept:	6/17/1987
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	6/19/1987
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	6/24/1987
Spill Record Last Update:	3/1/1990
Spiller Name:	Not reported
Spiller Company:	NY TEL
Spiller Address:	137 NORTH WASHINGTON ST
Spiller City,St,Zip:	ROME, NY 13440
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	6
DER Facility ID:	172697
DEC Memo:	Not reported
Remarks:	-.388 GPH, TANK #001, 6000 GAL, ISOLATED

Material:

Site ID:	208140
Operable Unit ID:	908751
Operable Unit:	01
Material ID:	468510
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Not reported
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	208140

VERIZON NEW YORK INC-NY-83211 (Continued) **S100167299**

Spill Tank Test:	1530973
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

Site ID:	100740
Spill Number/Closed Date:	9212037 / 2/28/1995
Spill Date:	1/21/1993
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	2/1/1995
Cleanup Meets Standard:	True
SWIS:	3300
Investigator:	DIJOHNSO
Referred To:	Not reported
Reported to Dept:	1/21/1993
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1/28/1993
Spill Record Last Update:	3/3/1995
Spiller Name:	Not reported
Spiller Company:	NEW YORK TELEPHONE
Spiller Address:	158 STATE ST., ROOME 400A
Spiller City,St,Zip:	ALBANY, NY 12207
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	6
DER Facility ID:	172697
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "JOHNSON"01/21/93: LEFT MESSAGE FOR MIKE MULLANEY. (DJ).01/21/93: SPOKE W/FENLEY & NICOL. TANK TESTED YESTERDAY - INCONCLUSIVE - DID NOT INCLUDE ALL LINES. PLANNING TO RETEST, WILL ADVISE OF SCHEDULE. (DJ).01/21/93: SPOKE WITH MIKE MULLANEY - NEEDS TO GET BACK TO RETEST ASAP OR ELSE EMPTY TANK. (DJ).01/22/93: MARK HALL CALLED TO CONFIRM THAT THEY WILL BE BACK ON TUESDAY TO RETEST. (DJ).01/27/93: SPOKE WITH MIKE MULLANEY - TANK UNCOVERED - LOOKS OKAY - WILL ATTEMPT RETEST. DID NOT SEE ANY SIGNS OF CONTAMINATION. (DJ).02/01/93: SPOKE W/LEW REALS-NYTEL-TANK UNCOVERED-FOUND CRACK IN DRESSER COUPLING ABOVE VENT WHISTLE. WILL TEST IN ISOLATION TOMORROW, RETEST SYSTEM ON WEDNESDAY. (DJ).02/03/93: SPOKE WITH LEW REALES, NYT AND HE INDICATED TANK PASSED IN ISOLATION -.004 GPH. (DJ).02/10/93: MARK, FENLY & NICOL INDICATED TANK FAILED SYSTEM RETEST, WAS RE-ISOLATED AND FAILED

VERIZON NEW YORK INC-NY-83211 (Continued) **S100167299**

ISOLATED RETEST. NY TEL. TOLD HIM TO EMPTY TANK AND SCHEDULE CLOSURE. (DJ).02/12/93: SENT TANK TEST FAILURE/GWI LETTER. (DJ).03/23/93: TANK PULLED - NO HOLES FOUND - SOME SOIL 5-15 YARDS REMOVED FROM BOTTOM - DUG CLEAN. (NC).02/01/95: DISPOSED OF 17.59 T SOIL (DJ).02/01/95: CONTAMINATED SOIL (12 YDS) DISPOSED OF. (JM).02/03/95: SOIL FOLLOWUP LETTER SENT. (DJ).02/17/95: RECEIVED SOIL DISPOSAL DOCUMENTATION. COMPLETE (DJ).02/17/95: SOIL DISPOSAL PAPERWORK RECEIVED. (JM).

Remarks: WILL EXCAVATE, ISOLATE & RETEST.

Material:

Site ID:	100740
Operable Unit ID:	976597
Operable Unit:	01
Material ID:	405415
Material Code:	0008
Material Name:	Diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Not reported
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	100740
Spill Tank Test:	1541088
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

TANKS:

Facility Id:	6-414565
Region:	STATE
DEC Region:	6
Site Status:	Active
Program Type:	PBS
Expiration Date:	06/30/2017
UTM X:	462769.21960000001
UTM Y:	4784589.3740499998

N70
NNE
1/4-1/2
0.301 mi.
1587 ft.

FORMER INLAND FUELS SITE/MARTIN STREET TERMINAL SITE
701 LAWRENCE STREET AND LAWRENCE AND MARTIN STREET 2 PARCELS
CITY OF ROME, NY 13440

US BROWNFIELDS **1014477372**
N/A

Site 1 of 3 in cluster N

Relative:
Higher

Actual:
457 ft.

US BROWNFIELDS:

Recipient name:	Rome, City of
Grant type:	Assessment
Property name:	FORMER INLAND FUELS SITE/MARTIN STREET TERMINAL SITE
Property #:	242.082-001-031, 258.002-1-7
Parcel size:	2.85
Property Description:	The 701 Lawrence Street site has historically been used as a petroleum bulk storage facility beginning circa 1936 and lasting until May 1990. The City AssessorGs records list Socony Mobil Oil Co. as the owner of seven 7 petroleum bulk storage tanks that ranged in capacity from 16,000 gallons to 1.15 million gallons. The tanks were decommissioned in May 1990. In addition to Socony Vacuum Oil Co., Inc. and Socony Mobil Oil Co., past owners of the property include Ralph Nolan, the Nolan Corporation, Inland Fuels, Inc., and the City of Rome. As of December 2002, the property was owned by Garrett Russitano. Several documented spills have been recorded at the 701 Lawrence Street location, and significant subsurface contamination has been documented, due to poor housekeeping practices. The Lawrence and Martin Street site was utilized as a major oil storage facility beginning circa 1947 and lasting until 1990. According to City AsessorGs records, the subject parcel at one time contained a total of 14 petroleum bulk storage tanks ranging in size from 24,000 gallons to 1 million gallons. According to NYSDEC records, a spill consisting of approximately 10,000 gallons of No. 2 fuel oil and an unreported amount of gasoline occurred at the site on October 2, 1989. Due to the spill, the EPA initiated a cleanup effort at the site, which resulted in the excavation and off site disposal of approximately 1,000 to 2,000 cubic yards of petroleum contaminated soil. According to the June 23, 2000 EPA Pollution Report, GBased on field observations during the UST removal, free flowing oil/waste oil was noted. Additionally, a perched water table was identified at the depth of the USTs and, based on topography, appears to drain into the stream running adjacent to the site. In addition when the fence contractor was installing the fence, the workers noted heavy staining as well as a strong odor of petroleum.G
Latitude:	43.2128473
Longitude:	-75.4557303
HCM label:	Interpolation-Photo
Map scale:	NA
Point of reference:	Entrance Point of a Facility or Station
Datum:	North American Datum of 1983
ACRES property ID:	129107
Start date:	Not reported
Completed date:	Not reported
Acres cleaned up:	Not reported
Cleanup funding:	Not reported
Cleanup funding source:	Not reported
Assessment funding:	40000
Assessment funding source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	Not reported

FORMER INLAND FUELS SITE/MARTIN STREET TERMINAL SITE (Continued) **1014477372**

Assessment funding entity:	EPA
Cleanup funding entity:	Not reported
Grant type:	P
Accomplishment type:	Phase II Environmental Assessment
Accomplishment count:	1
Cooperative agreement #:	97285504
Ownership entity:	Government
Current owner:	City of Rome
Did owner change:	N
Cleanup required:	Unknown
Video available:	No
Photo available:	Yes
Institutional controls required:	U
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	No
State/tribal program date:	06/15/2007 00:00:00
State/tribal program ID:	E633063
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Y
Asbestos cleaned:	Y
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Y
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Y
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Y
Petro products cleaned:	Not reported
Sediments found:	Y
Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Y
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported

FORMER INLAND FUELS SITE/MARTIN STREET TERMINAL SITE (Continued) **1014477372**

Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	2.85
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	2.85
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	N
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported

Recipient name:	Rome, City of
Grant type:	Assessment
Property name:	FORMER INLAND FUELS SITE/MARTIN STREET TERMINAL SITE
Property #:	242.082-001-031, 258.002-1-7
Parcel size:	2.85
Property Description:	The 701 Lawrence Street site has historically been used as a petroleum bulk storage facility beginning circa 1936 and lasting until May 1990. The City AssessorGs records list Socony Mobil Oil Co. as the owner of seven 7 petroleum bulk storage tanks that ranged in capacity from 16,000 gallons to 1.15 million gallons. The tanks were decommissioned in May 1990. In addition to Socony Vacuum Oil Co., Inc. and Socony Mobil Oil Co., past owners of the property include Ralph Nolan, the Nolan Corporation, Inland Fuels, Inc., and the City of Rome. As of December 2002, the property was owned by Garrett Russitano. Several documented spills have been recorded at the 701 Lawrence Street location, and significant subsurface contamination

FORMER INLAND FUELS SITE/MARTIN STREET TERMINAL SITE (Continued) **1014477372**

has been documented, due to poor housekeeping practices. The Lawrence and Martin Street site was utilized as a major oil storage facility beginning circa 1947 and lasting until 1990. According to City AsessorGs records, the subject parcel at one time contained a total of 14 petroleum bulk storage tanks ranging in size from 24,000 gallons to 1 million gallons. According to NYSDEC records, a spill consisting of approximately 10,000 gallons of No. 2 fuel oil and an unreported amount of gasoline occurred at the site on October 2, 1989. Due to the spill, the EPA initiated a cleanup effort at the site, which resulted in the excavation and off site disposal of approximately 1,000 to 2,000 cubic yards of petroleum contaminated soil. According to the June 23, 2000 EPA Pollution Report, GBased on field observations during the UST removal, free flowing oil/waste oil was noted. Additionally, a perched water table was identified at the depth of the USTs and, based on topography, appears to drain into the stream running adjacent to the site. In addition when the fence contractor was installing the fence, the workers noted heavy staining as well as a strong odor of petroleum.G

Latitude:	43.2128473
Longitude:	-75.4557303
HCM label:	Interpolation-Photo
Map scale:	NA
Point of reference:	Entrance Point of a Facility or Station
Datum:	North American Datum of 1983
ACRES property ID:	129107
Start date:	Not reported
Completed date:	Not reported
Acres cleaned up:	Not reported
Cleanup funding:	Not reported
Cleanup funding source:	Not reported
Assessment funding:	571520
Assessment funding source:	State/Tribal Funding (non-section 128(a))
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	Not reported
Assessment funding entity:	NYSDEC
Cleanup funding entity:	Not reported
Grant type:	P
Accomplishment type:	Phase II Environmental Assessment
Accomplishment count:	1
Cooperative agreement #:	97285504
Ownership entity:	Government
Current owner:	City of Rome
Did owner change:	N
Cleanup required:	Unknown
Video available:	No
Photo available:	Yes
Institutional controls required:	U
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	No
State/tribal program date:	06/15/2007 00:00:00
State/tribal program ID:	E633063

FORMER INLAND FUELS SITE/MARTIN STREET TERMINAL SITE (Continued) **1014477372**

State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Y
Asbestos cleaned:	Y
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Y
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Y
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Y
Petro products cleaned:	Not reported
Sediments found:	Y
Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Y
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	2.85
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	2.85
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	N
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported

FORMER INLAND FUELS SITE/MARTIN STREET TERMINAL SITE (Continued) **1014477372**

Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported

71
NW
1/4-1/2
0.305 mi.
1611 ft.

OPPER'S
301 ERIE BLVD WEST
ROME C, NY 13440

LTANKS **U003800503**
UST **N/A**
HIST UST
NY Spills

Relative:
Lower

Actual:
438 ft.

LTANKS:

Site ID:	221944
Spill Number/Closed Date:	9403073 / 6/7/1994
Spill Date:	6/2/1994
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	6/7/1994
Cleanup Meets Standard:	True
SWIS:	3300
Investigator:	PICKETT
Referred To:	Not reported
Reported to Dept:	6/2/1994
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	6/8/1994
Spill Record Last Update:	6/8/1994
Spiller Name:	Not reported
Spiller Company:	MONRO MUFFLER & BRAKE CO.
Spiller Address:	301 ERIE BLVD. WEST
Spiller City,St,Zip:	ROME, NY 13440
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported

OPPER'S (Continued) **U003800503**

DEC Region: 6
DER Facility ID: 183569
DEC Memo: Not reported
Remarks: SPEEDI-DRI APPLIED - ROME F.D. TO COMPLETE CLEANUP.

Material:
Site ID: 221944
Operable Unit ID: 996880
Operable Unit: 01
Material ID: 383244
Material Code: 0022
Material Name: Waste Oil/Used Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 30
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

UST:
Id/Status: 6-600924 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 6
Expiration Date: 09/21/2006
UTM X: 462436.34843000001
UTM Y: 4784472.4867599998
Site Type: Other Wholesale/Retail Sales

Affiliation Records:
Site Id: 43746
Affiliation Type: Facility Owner
Company Name: JACK D. OPPER
Contact Type: Not reported
Contact Name: Not reported
Address1: 301 ERIE BLVD WEST
Address2: Not reported
City: ROME
State: NY
Zip Code: 13440
Country Code: 001
Phone: (315) 337-5100
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 43746
Affiliation Type: Mail Contact
Company Name: OPPERS
Contact Type: Not reported
Contact Name: JACK D. OPPER

OPPER'S (Continued) **U003800503**

Address1: 301 ERIE BLVD WEST
Address2: Not reported
City: ROME
State: NY
Zip Code: 13440
Country Code: 001
Phone: (315) 337-5100
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 43746
Affiliation Type: On-Site Operator
Company Name: OPPERS
Contact Type: Not reported
Contact Name: JACK D. OPPER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (315) 337-5100
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 43746
Affiliation Type: Emergency Contact
Company Name: JACK D. OPPER
Contact Type: Not reported
Contact Name: JACK D. OPPER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (315) 337-5100
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Tank Info:

Tank Number: 1
Tank ID: 125125
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2000
Install Date: Not reported
Date Tank Closed: 10/01/2001
Registered: True
Tank Location: Underground

OPPER'S (Continued) **U003800503**

Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D10 - Pipe Type - Copper
G00 - Tank Secondary Containment - None
B01 - Tank External Protection - Painted/Asphalt Coating
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
I00 - Overfill - None
H00 - Tank Leak Detection - None

HIST UST:

PBS Number: 6-600924
SPDES Number: Not reported
Emergency Contact: JACK D. OPPER
Emergency Telephone: (315) 337-5100
Operator: JACK D. OPPER
Operator Telephone: (315) 337-5100
Owner Name: JACK D. OPPER
Owner Address: 301 ERIE BLVD WEST
Owner City,St,Zip: ROME, NY 13440
Owner Telephone: (315) 337-5100
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Name: OPPER'S
Mailing Address: 301 ERIE BLVD WEST
Mailing Address 2: Not reported
Mailing City,St,Zip: ROME, NY 13440
Mailing Contact: JACK D. OPPER
Mailing Telephone: (315) 337-5100
Owner Mark: First Owner
Facility Status: 2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Facility Addr2: Not reported
SWIS ID: 3013
Old PBS Number: Not reported
Facility Type: OTHER RETAIL SALES
Inspected Date: Not reported
Inspector: Not reported
Inspection Result: Not reported
Federal ID: Not reported
Certification Flag: False
Certification Date: 09/25/2001
Expiration Date: 09/21/2006
Renew Flag: False
Renewal Date: Not reported
Total Capacity: 0

OPPER'S (Continued) **U003800503**

FAMT: True
Facility Screen: No Missing Data
Owner Screen: No Missing Data
Tank Screen: 0
Dead Letter: False
CBS Number: Not reported
Town or City: ROME (C)
County Code: 30
Town or City: 13
Region: 6

Tank Id: 1
Tank Location: UNDERGROUND
Tank Status: Closed-Removed
Install Date: Not reported
Capacity (gals): 2000
Product Stored: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: Painted/Asphalt Coating
Pipe Location: Underground
Pipe Type: FIBERGLASS COATED STEEL
Pipe Internal: None
Pipe External: None
Second Containment: None
Leak Detection: None
Overfill Prot: None
Dispenser: 0
Date Tested: Not reported
Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: 10/01/2001
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

SPILLS:
Facility ID: 0106797
Facility Type: ER
DER Facility ID: 149901
Site ID: 178494
DEC Region: 6
Spill Date: 10/1/2001
Spill Number/Closed Date: 0106797 / 11/23/2001
Spill Cause: Unknown
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS: 3300
Investigator: LUCANTONIO
Referred To: Not reported
Reported to Dept: 10/1/2001
CID: 270
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Responsible Party
Cleanup Ceased: 10/16/2001

OPPER'S (Continued) **U003800503**

Cleanup Meets Std:	False
Last Inspection:	10/1/2001
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	10/1/2001
Spill Record Last Update:	11/26/2001
Spiller Name:	CALLER
Spiller Company:	JACK OPPER
Spiller Address:	301 ERIE BLVD WEST
Spiller City,St,Zip:	ROME, NY 13440-
Spiller Company:	001
Contact Name:	JACK OPPER
Contact Phone:	(315) 337-5100
DEC Memo:	Not reported
Remarks:	while removing a tank a leak was discovered dec rep on scene

Material:

Site ID:	178494
Operable Unit ID:	844996
Operable Unit:	01
Material ID:	531647
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

N72 **CITY OF ROME PD** **LTANKS** **S104191617**
NNE **301 NORTH JAMES ST** **N/A**
1/4-1/2 **ROME C, NY**
0.325 mi.
1718 ft. **Site 2 of 3 in cluster N**

Relative:
Higher

Actual:
457 ft.

LTANKS:

Site ID:	142002
Spill Number/Closed Date:	9410599 / 9/11/1997
Spill Date:	11/8/1994
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	9/11/1997
Cleanup Meets Standard:	True
SWIS:	3300
Investigator:	PICKETT
Referred To:	Not reported
Reported to Dept:	11/8/1994
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	DEC

CITY OF ROME PD (Continued) **S104191617**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	11/10/1994
Spill Record Last Update:	9/16/1997
Spiller Name:	Not reported
Spiller Company:	CITY OF ROME
Spiller Address:	CITY HALL
Spiller City,St,Zip:	ROME, NY 13440
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	6
DER Facility ID:	121225
DEC Memo:	Not reported
Remarks:	REMOVED 5,000 GAL. UG F.O. TANK & NOTED NUMEROUS HOLES IN BOTTOM OF TK-CHECKED SOIL UNDER TK & IS CONTAMINATED-SOIL HAD PETRO. ODOR & HAD POSITIVE HNU READING.

Material:

Site ID:	142002
Operable Unit ID:	1004524
Operable Unit:	01
Material ID:	376469
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Pounds
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	142002
Spill Tank Test:	1543328
Tank Number:	003
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

Site ID:	80997
Spill Number/Closed Date:	9905328 / 10/21/1999
Spill Date:	8/3/1999
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.

CITY OF ROME PD (Continued) **S104191617**

Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	3300
Investigator:	NFCARRIE
Referred To:	Not reported
Reported to Dept:	8/3/1999
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	8/3/1999
Spill Record Last Update:	10/22/1999
Spiller Name:	CALLER
Spiller Company:	CITY OF ROME PD
Spiller Address:	301 NORTH JAMES ST
Spiller City,St,Zip:	ROME, NY
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	6
DER Facility ID:	74994
DEC Memo:	Not reported
Remarks:	CALLER REPORTED 550 GAL U/G TANK REMOVED. CONTAMINATION FOUND.

Material:

Site ID:	80997
Operable Unit ID:	1083919
Operable Unit:	01
Material ID:	301629
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

N73 **POLICE STATION** **LTANKS** **S100158916**
NNE **301 N JAMES ST** **N/A**
1/4-1/2 **ROME C, NY**
0.325 mi.
1718 ft. **Site 3 of 3 in cluster N**

Relative:
Higher

Actual:
457 ft.

LTANKS:

Site ID:	230110
Spill Number/Closed Date:	8705018 / 2/15/1991
Spill Date:	9/15/1987
Spill Cause:	Tank Test Failure

POLICE STATION (Continued) **S100158916**

Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Cleanup Ceased:	1/3/1989
Cleanup Meets Standard:	True
SWIS:	3300
Investigator:	DIJOHNSO
Referred To:	Not reported
Reported to Dept:	9/16/1987
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	9/25/1987
Spill Record Last Update:	2/15/1991
Spiller Name:	Not reported
Spiller Company:	CITY OF ROME
Spiller Address:	CITY HALL
Spiller City,St,Zip:	ROME, NY 13440
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	6
DER Facility ID:	189661
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "JOHNSON"09/18/87: TANK RETESTED TIGHT IN ISOLATION/-.030 GPH (DJ).01/03/89: TK OPENED 3 PLACED & CLEANED/CANNOT PULL AS NIMO & TEL CABLES RUN OVER TOP OF TK/EXC SO.END 10'DEEP SAMPLED DIRT/CAN'T EXC NO.END BLDG & PLUMBING/CUT TK OPEN & SAMPLED/NO PROD OR ODOR/NO GW FOUND (NC).01/03/89: INTERFACE SERVICES EMPTIED TANK ABOUT 200 GAL/NO WATER IN TK/NIMO & NYTEL LINES RUN OVER TOP OF TANK/WILL EXCAVATE EACH END OF TK/WANT TO FILL IN PLACE (NC).02/15/91: REVIEWED TEST REPORTS & FIELD LOGS - COMPLETE. (DJ).
Remarks:	10K TANK SYS. TAILED PETRO-TIGHT AT -.155 GPH TO EXCAVATE, ISOLATE, & RETEST; D. JOHNSON @ SCENE

Material:

Site ID:	230110
Operable Unit ID:	911330
Operable Unit:	01
Material ID:	467624
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Not reported
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	230110

POLICE STATION (Continued) **S100158916**

Spill Tank Test:	1531631
Tank Number:	002
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

O74 **FRANK'S SUNOCO SERVICES** **LTANKS** **U000386496**
SW **612 SOUTH JAMES STREET** **UST** **N/A**
1/4-1/2 **ROME C, NY 13440** **HIST UST**
0.329 mi.
1738 ft. **Site 1 of 2 in cluster O**

Relative:
Lower

Actual:
430 ft.

LTANKS:

Site ID:	250578
Spill Number/Closed Date:	9400052 / Not Reported
Spill Date:	3/31/1994
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Unable/unwilling Responsible Party. Corrective action taken. (ISR)
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	3313
Investigator:	JDALSANT
Referred To:	Not reported
Reported to Dept:	3/31/1994
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	DEC
Last Inspection:	Not reported
Recommended Penalty:	True
UST Involvement:	True
Remediation Phase:	5
Date Entered In Computer:	4/4/1994
Spill Record Last Update:	6/27/2013
Spiller Name:	Not reported
Spiller Company:	FRANK E. RUSCITO
Spiller Address:	612 SOUTH JAMES STREET
Spiller City,St,Zip:	ROME, NY 13440
Spiller County:	001
Spiller Contact:	unknown
Spiller Phone:	(315) 656-2533
Spiller Extention:	Not reported
DEC Region:	6
DER Facility ID:	205398
DEC Memo:	9/17/04 gregg smith life science called re what analysis to run, nw asked for 502.2 stars but not on contract, told him to do 8021 w/mtbe&tba9/7/4-told dave to do another qs04/22/04 DAVE MOHLER REVIEWING FILE....04/12/04: ADDED NW & LSL TO PIN, SENT LETTER TO DICAPRIO TO REVIEW FILE & SUBMIT CAP.1/12/1 ag-schrempf requested copy of file. we just did it in the summer andsent to donna ross, told him so, to get back to me.12/7/00 new ag Tom Schrempf 518 474-171810/23/00 finished exc. backfilling & putting down crusher

FRANK'S SUNOCO SERVICES (Continued) **U000386496**

run.10/20/00 found unknown 1k ust at corner of building10/19/00 on site exc. 5 trucks to go, found unknown ust in front of bldg./exc.contractor to clean and remove tomorrow. 10/17/00 phonex thisam, at site digging.... site visit, 5 tt's removed esmilimiting us to 200 tons/ day or 5 truck loads.rear neighbor visited, upset wants us to dig hislawn and tear down his house. told him we couldn'tmon. 10/2/00 fax from eric,/site has been digsafed/to geoprobe next week/asked to use phoenix less than less than not sure if we can use them, stick with CES....Wed, 27 Sep 2000 told pes to digFri, 7 Jul 2000 reviewed pes proposal with don&gary. asked pes for proposal to dig andhaul.Tue, 16 May 2000 letter to bill bortinski, buying property/ he asked for letter saying ok by us to operate a business/ may be interested in assuming cleanup. cell #335-8300 fax 709-01765/8/00 PES accepts job, news story in sentinel-site has been purchased by anotherSTATUS-QS, DOING VAC TEST4/14/2k drive by site/ garage operating cars around buildingWed, 9 Mar 2000 to do vac. testTue, 22 Feb 2000 vac test todayjan 25/00 queried 3x vendors if they have portable hivac system. eps recomends hi vac base on vac testsThu, 27 Jan 2000 phonex w/tim-dup bill for aug vac. to adjust, asked him to continue doin vac. for now8/31/99 q399 report, did qs & hivac on july 28, 1999. wait for vac report.9/28/99-vac, ext. mw's data oct 6Fri, 21 Apr 2000 pinned pes/sent work authorization/letter to
eps.**********
**********08/08/95: CONTAMINATED SOIL (23 YDS) DISPOSED OF (JM).03/13/98: RECEIVED COPY OF LETTER FROM LISA KWONG, AAG- REQUESTING ACESS FROM RP. (NC)10/08/98: EPS REPLACED MW 3, DID GEOPROBE BORINGS (NC).01/07/99: REVIEWED GEO PROBE REPOERT & Q4 REPORT OK TO DO HVE PILOT TEST. DON'T QS IN Q199 (NC).07/12/99 PHONEX/LISA-SETTING UP JESMOREVAC-TO TAKE PRE AND POST SAMPLES & USE PRE AS QUARTERLY SAMPLING. NC04/19/05: NW contractor since April 2004.06/26/13: Performed site check. Building still there. For sale sign in window.(JA)

Remarks: CONTAMINATED SOIL NOTED DURING REMOVAL OF UNDERGROUND TANKS. 2-4000 & 1-1000 REMOVED SO FAR & HOLES NOTED IN ALL 3 TANKS. PRODUCT & HEAVY SHEEN NOTED ON GW IN EXCAVATION. ECAV. CONTAMINATED.

Material:

Site ID:	250578
Operable Unit ID:	997624
Operable Unit:	01
Material ID:	387381
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Pounds
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	250578
Spill Tank Test:	1542588
Tank Number:	Not reported

FRANK'S SUNOCO SERVICES (Continued) **U000386496**

Tank Size: 0
Test Method: 00
Leak Rate: 0
Gross Fail: Not reported
Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

UST:
Id/Status: 6-460656 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 6
Expiration Date: 10/14/1998
UTM X: 462339.33786000003
UTM Y: 4783706.0708100004
Site Type: Other

Affiliation Records:
Site Id: 42434
Affiliation Type: Facility Owner
Company Name: FRANK E. RUSCITO
Contact Type: Not reported
Contact Name: Not reported
Address1: 612 SOUTH JAMES STREET
Address2: Not reported
City: ROME
State: NY
Zip Code: 13440
Country Code: 001
Phone: (315) 336-3502
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 42434
Affiliation Type: Mail Contact
Company Name: FRANKS SUNOCO SERVICE
Contact Type: Not reported
Contact Name: FRANK E. RUSCITO
Address1: 612 SOUTH JAMES STREET
Address2: Not reported
City: ROME
State: NY
Zip Code: 13440
Country Code: 001
Phone: (315) 336-3502
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 3/4/2004

Site Id: 42434
Affiliation Type: On-Site Operator
Company Name: FRANKS SUNOCO SERVICES

FRANK'S SUNOCO SERVICES (Continued) **U000386496**

Contact Type:	Not reported
Contact Name:	FRANK E. RUSCITO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(315) 336-3666
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Site Id:	42434
Affiliation Type:	Emergency Contact
Company Name:	FRANK E. RUSCITO
Contact Type:	Not reported
Contact Name:	MR. JOHN RUSCITO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(315) 337-1782
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	3/4/2004

Tank Info:

Tank Number:	001
Tank ID:	117553
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	12/01/1963
Date Tank Closed:	04/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other

Tightness Test Method:	05
Date Test:	08/01/1988
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None

FRANK'S SUNOCO SERVICES (Continued) **U000386496**

J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number: 002
Tank ID: 117554
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 12/01/1963
Date Tank Closed: 04/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: 05
Date Test: 08/01/1988
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number: 003
Tank ID: 117555
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2000
Install Date: 12/01/1963
Date Tank Closed: 04/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: 05
Date Test: 08/01/1988
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT

FRANK'S SUNOCO SERVICES (Continued) **U000386496**

Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

Tank Number: 004
Tank ID: 117556
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2000
Install Date: 12/01/1963
Date Tank Closed: 04/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: 05
Date Test: 08/01/1988
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 005
Tank ID: 121343
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1000
Install Date: Not reported
Date Tank Closed: 04/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

FRANK'S SUNOCO SERVICES (Continued) **U000386496**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 03/04/2004

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
I00 - Overfill - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None

HIST UST:

PBS Number: 6-460656
SPDES Number: Not reported
Emergency Contact: MR. JOHN RUSCITO
Emergency Telephone: (315) 337-1782
Operator: FRANK E. RUSCITO
Operator Telephone: (315) 336-3666
Owner Name: FRANK E. RUSCITO
Owner Address: 612 SOUTH JAMES STREET
Owner City,St,Zip: ROME, NY 13440
Owner Telephone: (315) 336-3502
Owner Type: Corporate/Commercial
Owner Subtype: Not reported
Mailing Name: FRANK'S SUNOCO SERVICE
Mailing Address: 612 SOUTH JAMES STREET
Mailing Address 2: Not reported
Mailing City,St,Zip: ROME, NY 13440
Mailing Contact: FRANK E. RUSCITO
Mailing Telephone: (315) 336-3502
Owner Mark: First Owner
Facility Status: 2 - Unregulated by PBS (the total capacity is less than 1,101 gallons) and Subpart 360-14.
Facility Addr2: Not reported
SWIS ID: 3013
Old PBS Number: Not reported
Facility Type: OTHER
Inspected Date: Not reported
Inspector: Not reported
Inspection Result: Not reported
Federal ID: Not reported
Certification Flag: False
Certification Date: 09/22/1993
Expiration Date: 10/14/1998
Renew Flag: False
Renewal Date: Not reported
Total Capacity: 0
FAMT: True
Facility Screen: No Missing Data
Owner Screen: Minor Data Missing

FRANK'S SUNOCO SERVICES (Continued) **U000386496**

Tank Screen:	0
Dead Letter:	False
CBS Number:	Not reported
Town or City:	ROME (C)
County Code:	30
Town or City:	13
Region:	6
Tank Id:	005
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	1000
Product Stored:	EMPTY
Tank Type:	Steel/carbon steel
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Not reported
Pipe Type:	Not reported
Pipe Internal:	Not reported
Pipe External:	Not reported
Second Containment:	Not reported
Leak Detection:	Not reported
Overfill Prot:	Not reported
Dispenser:	Not reported
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	Minor Data Missing
Date Closed:	04/01/1994
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

O75 **KOTARY MOTORS** **LTANKS** **S100131786**
SW **E WRIGHT ST** **N/A**
1/4-1/2 **ROME C, NY**
0.342 mi.
1806 ft. **Site 2 of 2 in cluster O**

Relative:
Lower

Actual:
428 ft.

LTANKS:

Site ID:	224362
Spill Number/Closed Date:	8907789 / 10/26/1995
Spill Date:	11/6/1989
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Unable/unwilling Responsible Party. Corrective action taken. (ISR)
Cleanup Ceased:	10/26/1995
Cleanup Meets Standard:	False
SWIS:	3300
Investigator:	NFCARRIE
Referred To:	Not reported
Reported to Dept:	11/6/1989
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	DEC
Last Inspection:	Not reported

KOTARY MOTORS (Continued) **S100131786**

Recommended Penalty:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	11/10/1989
Spill Record Last Update:	5/20/2002
Spiller Name:	Not reported
Spiller Company:	KOTARY MOTORS
Spiller Address:	515 S. JAMES ST.
Spiller City,St,Zip:	ROME, NY 13440
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	6
DER Facility ID:	185435
DEC Memo:	Not reported
Remarks:	1K TANK PULLED, HAD CONTAMINATED SOIL AROUND BED. PLACED ON AND COVERED WITH PLASTIC.

Material:

Site ID:	224362
Operable Unit ID:	935400
Operable Unit:	01
Material ID:	444569
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	224362
Spill Tank Test:	1536369
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

P76 **ROSSI SITE WITHIN EAST ROME BUSINESS PAR** **ERP** **S110137797**
ESE **MILL STREET/RAILROAD STREET** **INST CONTROL** **N/A**
1/4-1/2 **ROME, NY 13440**
0.354 mi.
1870 ft. **Site 1 of 3 in cluster P**

Relative:
Higher

Actual:
441 ft.

ERP:

Site Code:	57205
Program:	ERP
HW Code:	B00023
Site Class:	C
Class N:	C
SWIS:	3313
Region:	6
Town:	Rome (c)
Acres:	2.600
Record Added:	10/28/2003
Record Updated:	02/03/2015
Updated By:	PRTAYLOR
Site Description:	This 2.6 acre site is in the core area of the former General Cable Facility which encompassed over 200 acres at its peak of operations. This is the second parcel to be investigated as part of the 17.4 acre East Rome Business Park. The General Cable site has a long history of industrial use and is contaminated with a variety of hazardous materials. The site contained many large manufacturing and warehouse facilities which were used in the manufacturing and coating of wire. Operations ceased in the 1970's. The property was purchased by Charles Gaetano in 1970 and for almost 25 years the site sat vacant except for storage of construction equipment and materials. The site was investigated and remediated and is now available for commercial use.
Env Problem:	The primary contaminants of concerns were asbestos, PCBs and petroleum. Metals and SVOC contamination also exist at the site. All affected media including soil and sediment has been remediated and no further action is required. Residual metals and SVOCs remain at the site, but at levels that do not require removal or a deed restriction. The site is suitable for commercial use.
Health Problem:	Direct contact exposure to site related contaminants is not expected because contaminated surface soils have been removed. NYSDOH and NYSDEC evaluated the need to determine the potential for soil vapor intrusion into the structures on or near the site and no additional investigation was necessary. If during future re-development of the site, contamination is discovered, NYSDOH and NYSDEC should be notified at which time further investigations may be necessary.

INST CONTROL:

Site Code:	57205
Control Name:	Deed Restriction
HW Code:	B00023
Control Code:	A
Control Type:	INST
Dt record added:	12/11/2009
Dt rec updated:	03/12/2010
Updated By:	psouderk
Site Code:	57205
Site Description:	This 2.6 acre site is in the core area of the former General Cable Facility which encompassed over 200 acres at its peak of operations. This is the second parcel to be investigated as part of the 17.4 acre East Rome Business Park. The General Cable site has a long history of

ROSSI SITE WITHIN EAST ROME BUSINESS PAR (Continued) **S110137797**

industrial use and is contaminated with a variety of hazardous materials. The site contained many large manufacturing and warehouse facilities which were used in the manufacturing and coating of wire. Operations ceased in the 1970's. The property was purchased by Charles Gaetano in 1970 and for almost 25 years the site sat vacant except for storage of construction equipment and materials. The site was investigated and remediated and is now available for commercial use.

Env Problem: The primary contaminants of concerns were asbestos, PCBs and petroleum. Metals and SVOC contamination also exist at the site. All affected media including soil and sediment has been remediated and no further action is required. Residual metals and SVOCs remain at the site, but at levels that do not require removal or a deed restriction. The site is suitable for commercial use.

Health Problem: Direct contact exposure to site related contaminants is not expected because contaminated surface soils have been removed. NYSDOH and NYSDEC evaluated the need to determine the potential for soil vapor intrusion into the structures on or near the site and no additional investigation was necessary. If during future re-development of the site, contamination is discovered, NYSDOH and NYSDEC should be notified at which time further investigations may be necessary.

Site Code: 57205
Control Name: Landuse Restriction
HW Code: B00023
Control Code: 25
Control Type: INST
Dt record added: 12/11/2009
Dt rec updated: 03/12/2010
Updated By: psouderk
Site Code: 57205
Site Description: This 2.6 acre site is in the core area of the former General Cable Facility which encompassed over 200 acres at its peak of operations. This is the second parcel to be investigated as part of the 17.4 acre East Rome Business Park. The General Cable site has a long history of industrial use and is contaminated with a variety of hazardous materials. The site contained many large manufacturing and warehouse facilities which were used in the manufacturing and coating of wire. Operations ceased in the 1970's. The property was purchased by Charles Gaetano in 1970 and for almost 25 years the site sat vacant except for storage of construction equipment and materials. The site was investigated and remediated and is now available for commercial use.

Env Problem: The primary contaminants of concerns were asbestos, PCBs and petroleum. Metals and SVOC contamination also exist at the site. All affected media including soil and sediment has been remediated and no further action is required. Residual metals and SVOCs remain at the site, but at levels that do not require removal or a deed restriction. The site is suitable for commercial use.

Health Problem: Direct contact exposure to site related contaminants is not expected because contaminated surface soils have been removed. NYSDOH and NYSDEC evaluated the need to determine the potential for soil vapor intrusion into the structures on or near the site and no additional investigation was necessary. If during future re-development of the site, contamination is discovered, NYSDOH and NYSDEC should be notified at which time further investigations may be necessary.

P77 **EAST ROME BUSINESS PARK** **ERP** **S106906531**
ESE **MILL STREET/RAILROAD STREET** **N/A**
1/4-1/2 **ROME C, NY 13440**
0.354 mi.
1870 ft. **Site 2 of 3 in cluster P**

Relative:
Higher

Actual:
441 ft.

ERP:

Site Code:	57199
Program:	ERP
HW Code:	B00010
Site Class:	C
Class N:	C
SWIS:	3313
Region:	6
Town:	Rome (c)
Acres:	2.770
Record Added:	10/28/2003
Record Updated:	01/13/2012
Updated By:	PRTAYLOR
Site Description:	This 2.77 acre site is in the core area of the former General Cable Facility which encompassed over 200 acres at its peak of operations. This is the first Parcel to be investigated as part of the 17.4 acre East Rome Business Park. The site contained many large manufacturing and warehouse facilities which were used in the manufacturing and coating of wire. The operations ceased in the 1970's and the property was purchased by Charles Gaetano in 1970. For almost 25 years the site sat vacant and was only used for storage of construction equipment and materials. The General Cable site has a long history of industrial uses and was contaminated with a variety of hazardous materials including petroleum, asbestos, metals, PCBs, Acids, Solvents and boiler chemicals.A Site Investigation / Remedial Action Report was completed and subsequently the site was remediated and is now the new roadway for the East Rome Industrial Park. The remediation included the removal of underground storage tanks, a heavily contaminated boiler house, underground piping, tunnels and fuel lines. Multiple buildings were demolished and asbestos abatement was conducted.
Env Problem:	The Site was the heart of the former General Cable Facility. Miles of underground pipe galleries, fuel lines, steam lines, tunnels and walkways were cleaned and removed. A larger boiler house sat in the middle of the site and over six - 10,000 gallon fuel tanks were removed along with asbestos covered boilers, transformers and thousands of tons of contaminated soil and debris. Some Residual level of metals, VOCs and SVOCs remained at the site at levels above the Soil Clean up Objectives. However the levels of residual contamination did not require removal and deed restrictions and a soil management plan are in place. Groundwater use restrictions are also in place. The site is now the new road system for the East Rome Industrial Park.
Health Problem:	Direct contact exposure to site related contaminants is not expected because contaminated surface soils have been removed. NYSDOH and NYSDEC evaluated the need to determine the potential for soil vapor intrusion into the structures on or near the site and concluded no additional investigation was necessary. If during future re-development of the site, contamination is discovered, NYSDOH and NYSDEC should be notified at which time further investigations may be necessary.

78
ESE
1/4-1/2
0.358 mi.
1892 ft.

ROME DPW (INSIDE)
RACE ST
ROME C, NY

LTANKS **S100131624**
N/A

Relative:
Lower

Actual:
434 ft.

LTANKS:

Site ID:	196166
Spill Number/Closed Date:	8702144 / 6/19/1997
Spill Date:	6/15/1987
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	6/19/1997
Cleanup Meets Standard:	False
SWIS:	3300
Investigator:	AJMARSCH
Referred To:	Not reported
Reported to Dept:	6/15/1987
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	6/24/1987
Spill Record Last Update:	6/20/1997
Spiller Name:	Not reported
Spiller Company:	CITY OF ROME
Spiller Address:	CITY HALL, LIBERTY PLAZA
Spiller City,St,Zip:	ROME, NY 13440
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	6
DER Facility ID:	163425
DEC Memo:	Not reported
Remarks:	-0.324 GPH, 2.5K, PLAN TO DIG UP TANK AND DISCONNECT; 2 TANKS, 4000 GAL EA., 1@ -.105 GPH; 1@ -.355 GPH

Material:

Site ID:	196166
Operable Unit ID:	906437
Operable Unit:	01
Material ID:	472022
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Pounds
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

ROME DPW (INSIDE) (Continued) **S100131624**

Tank Test:
- Site ID: 196166
- Spill Tank Test: 1530961
- Tank Number: Not reported
- Tank Size: 0
- Test Method: 00
- Leak Rate: 0
- Gross Fail: Not reported
- Modified By: Spills
- Last Modified: 10/1/2004
- Test Method: Unknown

P79 **OLD GENERAL CABLE** **CERCLIS** **1000996376**
ESE **MILL ST** **NY0001119403**
1/4-1/2 **ROME, NY 13440**
0.360 mi.
1901 ft. **Site 3 of 3 in cluster P**

Relative:
Higher

Actual:
442 ft.

CERCLIS:
- Site ID: 0204001
- EPA ID: NY0001119403
- Facility County: ONEIDA
- Short Name: OLD GENERAL CABLE
- Congressional District: 25
- IFMS ID: Not reported
- SMSA Number: 8680
- USGC Hydro Unit: 02020004
- Federal Facility: Not a Federal Facility
- DMNSN Number: 0.00000
- Site Orphan Flag: N
- RCRA ID: Not reported
- USGS Quadrangle: Not reported
- Site Init By Prog: Not reported
- NFRAP Flag: Not reported
- Parent ID: Not reported
- RST Code: Not reported
- EPA Region: 02
- Classification: Not reported
- Site Settings Code: Not reported
- NPL Status: Not on the NPL
- DMNSN Unit Code: Not reported
- RBRAC Code: Not reported
- RResp Fed Agency Code: Not reported
- Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information
- Non NPL Status Date: 02/11/09
- Site Fips Code: 36065
- CC Concurrence Date: / /
- CC Concurrence FY: Not reported
- Alias EPA ID: Not reported
- Site FUDS Flag: Not reported

- Alias Comments: Not reported
- Site Description: Not reported

CERCLIS Assessment History:

- Action Code: 001

OLD GENERAL CABLE (Continued) **1000996376**

Action:	DISCOVERY
Date Started:	/ /
Date Completed:	07/06/95
Priority Level:	Not reported
Operable Unit:	SITEWIDE
Primary Responsibility:	State, Fund Financed
Planning Status:	Not reported
Urgency Indicator:	Not reported
Action Anomaly:	Not reported

Action Code:	001
Action:	PRELIMINARY ASSESSMENT
Date Started:	10/01/96
Date Completed:	02/11/09
Priority Level:	NFRAP-Site does not qualify for the NPL based on existing information
Operable Unit:	SITEWIDE
Primary Responsibility:	State, Fund Financed
Planning Status:	Not reported
Urgency Indicator:	Not reported
Action Anomaly:	Not reported

80
NNW
1/4-1/2
0.373 mi.
1970 ft.

SEARS REALTY CO. INC. **LTANKS** **S100144302**
201 NORTH GEORGE ST **N/A**
ROME C, NY

Relative:
Higher

Actual:
451 ft.

LTANKS:

Site ID:	322825
Spill Number/Closed Date:	8700903 / 11/30/1988
Spill Date:	5/1/1987
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Not reported
Cleanup Ceased:	11/30/1988
Cleanup Meets Standard:	True
SWIS:	3300
Investigator:	DIJOHNSO
Referred To:	Not reported
Reported to Dept:	5/1/1987
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	DEC
Last Inspection:	11/30/1988
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	5/4/1987
Spill Record Last Update:	12/5/1988
Spiller Name:	Not reported
Spiller Company:	SEARS REALTY CO., INC.
Spiller Address:	1914 BLACK RIVER BLVD
Spiller City,St,Zip:	ROME, NY 13440
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported

SEARS REALTY CO. INC. (Continued) **S100144302**

Spiller Extention: Not reported
DEC Region: 6
DER Facility ID: 260050
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "JOHNSON" / / : 5/1/87-PBS #127620-(3)3000 GAL TANKS EXCAV.-ONE TANK HAD HOLES IN IT. CONT.-SOIL TO BE STORED UNTIL DISPOSAL-K.WOOD & H.SEARS @ SITE (DJ).11/30/88: STATION OUT OF SERVICE A LONG TIME/MINOR SOIL CONTAMINATION/COMPLETE (JM).
Remarks: Not reported

Material:
Site ID: 322825
Operable Unit ID: 907387
Operable Unit: 01
Material ID: 470875
Material Code: 0009
Material Name: Gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

81
South
1/4-1/2
0.377 mi.
1988 ft.

Relative:
Lower

Actual:
431 ft.

ROME(C) HIGH LEVEL PUMP STATION **LTANKS** **S102660320**
ERIE & BLACK RIVER BLVD **N/A**
ROME, NY

LTANKS:
Site ID: 286463
Spill Number/Closed Date: 9706427 / 12/12/2006
Spill Date: 8/27/1997
Spill Cause: Tank Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased: 11/9/2006
Cleanup Meets Standard: False
SWIS: 3313
Investigator: JCDOYLE
Referred To: Not reported
Reported to Dept: 8/27/1997
CID: 205
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: 12/29/2005
Recommended Penalty: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 8/27/1997
Spill Record Last Update: 12/13/2006

ROME(C) HIGH LEVEL PUMP STATION (Continued) **S102660320**

Spiller Name:	FRANK TALLARINO
Spiller Company:	CITY OF ROME
Spiller Address:	198 N. WASHINGTON ST.
Spiller City,St,Zip:	ROME, NY 13440-
Spiller County:	001
Spiller Contact:	DAVID A. MARINO
Spiller Phone:	(315) 339-7775
Spiller Extention:	Not reported
DEC Region:	6
DER Facility ID:	291925
DEC Memo:	12/10/97: REVIEWED SAR DATED 9/23/97. SENT LETTER REQUESTING GWI (DJ).07/14/1998: RESPONDED TO GWI PROPOSAL BY S&W. (DJ)07/06/2004: REVIEWED FILE. INADEQUATE INVESTIGATION. DID NOT ENCOUNTER GW WITH BORINGS. NO FIELD READINGS OR LAB ANALYTICAL RESULTS SUBMITTED. INCOMPLETE. (DJ)05/12/2005: SENT TALLARINO LETTER FOR ADDITIONAL GWI. (JD) 6/23/2005: MET DON SORBELLO, S&W, FRANK TALLARINO, COMMISIONER PUBLIC WORKS ON-SITE TO DISCUSS WELL LOCATIONS AND INVESTIGATION PROPOSAL. (JD & DJ)5/11/2006: REVIEW LETTER FOR 4/14/2006 SUBSURFACE INVESTIGATION REPORT. (JD)9/29/2006: 3RD QUARTER GW REPORT REVIEWED. RESULTS ALL NON DETECT. (JD)12/12/2006: REVIEWED 4TH QUARTER GW SAMPLING REPORT. MW-1 = ND OR VERY LOW LEVELS, MW-2, MW-3 = ALL ND. PROPERLY CLOSE WELLS. SPILL CLOSURE LETTER (JD)
Remarks:	puller found contamination on ground.

Material:

Site ID:	286463
Operable Unit ID:	1052637
Operable Unit:	01
Material ID:	332014
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

82
SW
1/4-1/2
0.383 mi.
2023 ft.

Relative:
Lower

Actual:
429 ft.

DECARLIS RES **LTANKS** **S100144618**
118 WEST SOUTH **N/A**
ROME C, NY

LTANKS:

Site ID:	254721
Spill Number/Closed Date:	8709652 / 2/16/1988
Spill Date:	2/16/1988
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Not reported
Cleanup Ceased:	2/16/1988
Cleanup Meets Standard:	True

DECARLIS RES (Continued) **S100144618**

SWIS:	3300
Investigator:	DIJOHNSO
Referred To:	Not reported
Reported to Dept:	2/16/1988
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	2/16/1988
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	Not reported
Spill Record Last Update:	12/2/2003
Spiller Name:	Not reported
Spiller Company:	ANDREW DECARLIS
Spiller Address:	Not reported
Spiller City,St,Zip:	ZZ
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	6
DER Facility ID:	208631
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "JOHNSON" / / : 2/16/88-VISITED SITE,USED SPEEDI-DRI ON BSMT FLOOR & SECOND APPLICA WILL BE CLEANED UP TOMORROW/SUMP LOOKS OK/COMPLETE (DJ).
Remarks:	275 GAL TANK SPRUNG LEAK IN CELLAR/SOME PROD MAY HAVE PUMPED TO SEWER MAIN VIA SUMPUMP/SORBENT USED ON REMAINDER OF PRODUCT.

Material:

Site ID:	254721
Operable Unit ID:	914704
Operable Unit:	01
Material ID:	461446
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Q83 **ROME(C) DPW/VIP TRANS.** **LTANKS** **S100158666**
SE **132 RACE STREET** **NY Spills** **N/A**
1/4-1/2 **ROME C, NY**
0.409 mi.
2157 ft. **Site 1 of 2 in cluster Q**

Relative:
Lower

Actual:
434 ft.

LTANKS:

Site ID:	256663
Spill Number/Closed Date:	8805218 / 9/20/1988
Spill Date:	9/16/1988
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	Not reported
Cleanup Ceased:	9/16/1988
Cleanup Meets Standard:	True
SWIS:	3300
Investigator:	CHERUBIN
Referred To:	Not reported
Reported to Dept:	9/16/1988
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	9/20/1988
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	Not reported
Spill Record Last Update:	12/2/2003
Spiller Name:	Not reported
Spiller Company:	SEARS OIL CO
Spiller Address:	1914 BLACK RIVER BLVD.
Spiller City,St,Zip:	ROME, NY 13440
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	6
DER Facility ID:	192864
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "CHERUBIN"09/20/88: SPOKE TO GARY RODGERS, SAID CLEANUP COMPLETE/BUBBLEOVER DURING FILL UP (AC).
Remarks:	SOAKED UP WITH PADS/LEFT STAIN ON BLACKTOP

Material:

Site ID:	256663
Operable Unit ID:	920366
Operable Unit:	01
Material ID:	457128
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	Yes
Resource Affected:	Not reported
Oxygenate:	False

ROME(C) DPW/VIP TRANS. (Continued) **S100158666**

Tank Test:

Site ID:	256663
Spill Tank Test:	1534627
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

Site ID:	256664
Spill Number/Closed Date:	8807798 / 12/27/1988
Spill Date:	12/24/1988
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	Not reported
Cleanup Ceased:	12/27/1988
Cleanup Meets Standard:	True
SWIS:	3300
Investigator:	MASON
Referred To:	Not reported
Reported to Dept:	12/24/1988
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	12/27/1988
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	Not reported
Spill Record Last Update:	12/2/2003
Spiller Name:	Not reported
Spiller Company:	SEARS OIL
Spiller Address:	1914 BLACK RIVER BLVD.
Spiller City,St,Zip:	ROME, NY 13440
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	6
DER Facility ID:	192864
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MASON"12/27/88: PER TEL CONVERSATION WITH GARY ROGERS 12/27/88/PADS USED TO REMOVE ALL PRODUCT FROM BLACKTOP & PUDDLES OF WATER/CLEANUP COMPLETE (HM).
Remarks:	USED PADS TO CLEAN UP

Material:

Site ID:	256664
Operable Unit ID:	923276
Operable Unit:	01
Material ID:	452575
Material Code:	0001A

ROME(C) DPW/VIP TRANS. (Continued) **S100158666**

Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

SPILLS:

Facility ID:	9700481
Facility Type:	ER
DER Facility ID:	192864
Site ID:	234076
DEC Region:	6
Spill Date:	4/10/1997
Spill Number/Closed Date:	9700481 / 6/18/1997
Spill Cause:	Human Error
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	3300
Investigator:	DIJOHNSO
Referred To:	Not reported
Reported to Dept:	4/10/1997
CID:	205
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	4/10/1997
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	4/10/1997
Spill Record Last Update:	6/20/1997
Spiller Name:	RICHARD HORNER
Spiller Company:	CITY OF ROME
Spiller Address:	ON THE MALL
Spiller City,St,Zip:	ROME, NY 13440-
Spiller Company:	001
Contact Name:	CITY OF ROME
Contact Phone:	(315) 339-7664
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "JOHNSON"04/10/97: SPOKE W/JAYN EGGAN, TANK PULLED - LOOKS OKAY, THEY HAVE APPROX. 1/2 DRUM OF SOIL FROM AROUND FILL FOR DISPOSAL. TOLD HER TO CALL IN SPILL (DJ).06/18/97: REVIEWED CLOSURE REPORT DATED 4/30/97 AND RECEIVED 5/20/97. CLOSED (DJ).
Remarks:	55 GAL DRUM USED TO CATCH OIL OVERFILLS, HAD A LEAK.

Material:

Site ID:	234076
Operable Unit ID:	1046785
Operable Unit:	01

ROME(C) DPW/VIP TRANS. (Continued) **S100158666**

Material ID: 337077
Material Code: 0022
Material Name: Waste Oil/Used Oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 0
Units: Gallons
Recovered: No
Resource Affected: Not reported
Oxygenate: False

Tank Test:

Facility ID: 8604572
Facility Type: ER
DER Facility ID: 167437
Site ID: 201255
DEC Region: 6
Spill Date: 10/17/1986
Spill Number/Closed Date: 8604572 / 10/17/1986
Spill Cause: Equipment Failure
Spill Class: Not reported
SWIS: 3300
Investigator: AJMARSCH
Referred To: Not reported
Reported to Dept: 10/17/1986
CID: Not reported
Water Affected: Not reported
Spill Source: Tank Truck
Spill Notifier: Responsible Party
Cleanup Ceased: 10/17/1986
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 10/20/1986
Spill Record Last Update: 11/21/1986
Spiller Name: Not reported
Spiller Company: SEARS OIL
Spiller Address: 1914 BLACK RIVER BLVD
Spiller City,St,Zip: ROME, NY 13440
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was "JM" / / : 10/17/86 - COMPLETE.
Remarks: DELIVERY TRUCK #1, SEARS CLEANED UP

Material:
Site ID: 201255
Operable Unit ID: 901508
Operable Unit: 01
Material ID: 473814
Material Code: 0008
Material Name: Diesel

ROME(C) DPW/VIP TRANS. (Continued) **S100158666**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Q84 **ROME CITY OF D P W** **RCRA-CESQG** **1000457836**
SE **132 RACE ST** **FINDS** **NYD986931152**
1/4-1/2 **ROME, NY 13440** **SWF/LF**
0.411 mi. **HIST UST**
2170 ft. **Site 2 of 2 in cluster Q** **AST**
NY Spills

Relative:
Lower

Actual:
434 ft.

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	ROME CITY OF D P W
Facility address:	132 RACE ST ROME, NY 134406840
EPA ID:	NYD986931152
Mailing address:	RACE ST ROME, NY 13440
Contact:	Not reported
Contact address:	RACE ST ROME, NY 13440
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	CITY OF ROME
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	(212) 555-1212
Legal status:	Private

ROME CITY OF D P W (Continued) **1000457836**

Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: CITY OF ROME
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: ROME CITY OF D P W
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 07/08/1999
Site name: ROME CITY OF D P W
Classification: Not a generator, verified

Date form received by agency: 05/09/1994
Site name: ROME, CITY OF DPW
Classification: Large Quantity Generator

Date form received by agency: 11/19/1990
Site name: ROME CITY OF D P W
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - Manifest
Date violation determined: 04/01/1992
Date achieved compliance: 05/08/1992

ROME CITY OF D P W (Continued) **1000457836**

Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/01/1992
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 04/01/1992
Date achieved compliance: 04/30/1992
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/01/1992
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 03/11/1992
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 04/30/1992
Evaluation lead agency: State

Evaluation date: 03/11/1992
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Manifest
Date achieved compliance: 05/08/1992
Evaluation lead agency: State

FINDS:

Registry ID: 110004456268

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

SWF/LF:
Flag: ACTIVE
Region Code: 6
Phone Number: 3153397774
Owner Name: Frank Tallarino
Owner Type: Municipal
Owner Address: 198 N. Washington Street

ROME CITY OF D P W (Continued) **1000457836**

Owner Addr2:	Not reported
Owner City,St,Zip:	Rome, NY 13440
Owner Email:	Not reported
Owner Phone:	3153397625
Contact Name:	John A. Gerace Jr.
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	jgerace@romecitygov.com
Contact Phone:	3153397774
Activity Desc:	Transfer station - registration
Activity Number:	[33R05]
Active:	Yes
East Coordinate:	436637
North Coordinate:	4783594
Accuracy Code:	Not reported
Regulatory Status:	Registration
Waste Type:	Not reported
Authorization #:	33R05
Authorization Date:	05/13/2015
Expiration Date:	Not reported

Flag:	INACTIVE
Region Code:	6
Phone Number:	3153397635
Owner Name:	City of Rome
Owner Type:	Municipal
Owner Address:	Department of Public Works
Owner Addr2:	Not reported
Owner City,St,Zip:	Rome, NY 13440
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	Not reported
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	C&D processing - registration
Activity Number:	[33W01]
Active:	No
East Coordinate:	463433
North Coordinate:	4783624
Accuracy Code:	4.3 - Utilization of Digital Orthophoto Quads
Regulatory Status:	Registration
Waste Type:	Not reported
Authorization #:	Not reported
Authorization Date:	06/12/1996
Expiration Date:	Not reported

Flag:	INACTIVE
Region Code:	6
Phone Number:	3153397774
Owner Name:	Frank Tallarino
Owner Type:	Municipal
Owner Address:	198 N. Washington Street
Owner Addr2:	Not reported

ROME CITY OF D P W (Continued) **1000457836**

Owner City,St,Zip:	Rome, NY 13440
Owner Email:	Not reported
Owner Phone:	3153397625
Contact Name:	John A. Gerace Jr.
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	jgerace@romecitygov.com
Contact Phone:	3153397774
Activity Desc:	Transfer station - registration
Activity Number:	[33R05]
Active:	No
East Coordinate:	463136
North Coordinate:	4783817
Accuracy Code:	4.2 - Utilization of GIS and existing spatial data
Regulatory Status:	Registration
Waste Type:	Not reported
Authorization #:	33R05
Authorization Date:	12/30/1999
Expiration Date:	Not reported

HIST UST:

PBS Number:	6-433500
SPDES Number:	Not reported
Emergency Contact:	RICHARD HORNER
Emergency Telephone:	(315) 337-0494
Operator:	RICHARD HORNER
Operator Telephone:	(315) 339-7785
Owner Name:	CITY OF ROME
Owner Address:	ON THE MALL
Owner City,St,Zip:	ROME, NY 13440
Owner Telephone:	(315) 339-7764
Owner Type:	Local Government
Owner Subtype:	Not reported
Mailing Name:	CITY OF ROME
Mailing Address:	132 RACE STREET
Mailing Address 2:	Not reported
Mailing City,St,Zip:	ROME, NY 13440
Mailing Contact:	RICHARD HORNER
Mailing Telephone:	(315) 339-7785
Owner Mark:	First Owner
Facility Status:	1 - Active PBS facility, i.e. total capacity of the PBS tanks is greater than 1,100 gallons, regardless if Subpart 360-14 tanks exist or not at the facility.
Facility Addr2:	Not reported
SWIS ID:	3013
Old PBS Number:	Not reported
Facility Type:	OTHER
Inspected Date:	04/21/1997
Inspector:	DP
Inspection Result:	1
Federal ID:	Not reported
Certification Flag:	False
Certification Date:	03/26/1998
Expiration Date:	04/19/2003
Renew Flag:	False
Renewal Date:	Not reported

ROME CITY OF D P W (Continued) **1000457836**

Total Capacity:	2925
FAMT:	True
Facility Screen:	No Missing Data
Owner Screen:	No Missing Data
Tank Screen:	No Missing Data
Dead Letter:	False
CBS Number:	Not reported
Town or City:	ROME (C)
County Code:	30
Town or City:	13
Region:	6

Tank Id:	1
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	550
Product Stored:	USED OIL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Aboveground/Underground Combination
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	Gravity
Date Tested:	Not reported
Next Test Date:	Not reported
Missing Data for Tank:	No Missing Data
Date Closed:	04/01/1997
Test Method:	Not reported
Deleted:	False
Updated:	True
Lat/long:	Not reported

Tank Id:	8
Tank Location:	UNDERGROUND
Tank Status:	Closed-Removed
Install Date:	Not reported
Capacity (gals):	550
Product Stored:	USED OIL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	None
Second Containment:	None
Leak Detection:	None
Overfill Prot:	None
Dispenser:	0
Date Tested:	Not reported

ROME CITY OF D P W (Continued) **1000457836**

Next Test Date: Not reported
Missing Data for Tank: No Missing Data
Date Closed: 03/01/1999
Test Method: Not reported
Deleted: False
Updated: True
Lat/long: Not reported

AST:
Region: STATE
DEC Region: 6
Site Status: Active
Facility Id: 6-433500
Program Type: PBS
UTM X: 463426.01507999998
UTM Y: 4783619.6225399999
Expiration Date: 04/19/2018
Site Type: Municipality (Incl. Waste Water Treatment Plants, Utilities, Swimming Pools, etc.)

Affiliation Records:
Site Id: 42234
Affiliation Type: Facility Owner
Company Name: CITY OF ROME
Contact Type: EQUIPMENT MANAGER
Contact Name: ARTHUR E. GOLDEN III
Address1: 198 N. WASHINGTON ST.
Address2: Not reported
City: ROME
State: NY
Zip Code: 13440
Country Code: 001
Phone: (315) 336-6000
EMail: Not reported
Fax Number: Not reported
Modified By: SCREICHI
Date Last Modified: 12/27/2013

Site Id: 42234
Affiliation Type: Mail Contact
Company Name: CITY OF ROME
Contact Type: Not reported
Contact Name: EQUIP. MAIN. MANAGER
Address1: 132 RACE STREET
Address2: Not reported
City: ROME
State: NY
Zip Code: 13440
Country Code: 001
Phone: (315) 339-7785
EMail: AGOLDEN@ROMEGOV.COM
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 2/19/2008

Site Id: 42234
Affiliation Type: On-Site Operator
Company Name: ROME(C) DPW/VIP TRANSPORTATION

ROME CITY OF D P W (Continued) **1000457836**

Contact Type:	Not reported
Contact Name:	ROME(C) DPW
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NY
Zip Code:	Not reported
Country Code:	001
Phone:	(315) 339-7785
EMail:	Not reported
Fax Number:	Not reported
Modified By:	SCREICHI
Date Last Modified:	12/27/2013

Site Id:	42234
Affiliation Type:	Emergency Contact
Company Name:	CITY OF ROME
Contact Type:	Not reported
Contact Name:	ROME(C) DPW
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(315) 339-7785
EMail:	Not reported
Fax Number:	Not reported
Modified By:	SCREICHI
Date Last Modified:	12/27/2013

Tank Info:

Tank Number:	2
Tank Id:	123638
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
K01 - Spill Prevention - Catch Basin

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/01/1994

ROME CITY OF D P W (Continued) **1000457836**

Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	CGFREEDM
Last Modified:	04/12/2013
Material Name:	Waste Oil/Used Oil

Tank Number:	3
Tank Id:	123639
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	11/01/1994
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	CGFREEDM
Last Modified:	04/12/2013
Material Name:	Lube Oil

Tank Number:	4
Tank Id:	123640
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None

ROME CITY OF D P W (Continued) **1000457836**

J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/01/1993
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	CGFREEDM
Last Modified:	04/12/2013
Material Name:	Lube Oil

Tank Number:	5
Tank Id:	123641
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	07/01/1995
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	CGFREEDM
Last Modified:	04/12/2013
Material Name:	Lube Oil

ROME CITY OF D P W (Continued) **1000457836**

Tank Number: 6
Tank Id: 123642
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
E01 - Piping Secondary Containment - Diking (Aboveground)
I04 - Overfill - Product Level Gauge (A/G)
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I03 - Overfill - Automatic Shut-Off

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 07/01/1995
Capacity Gallons: 1000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: CGFREEDM
Last Modified: 04/12/2013
Material Name: Diesel

Tank Number: 6A
Tank Id: 223619
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None

Tank Location: 3
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service

ROME CITY OF D P W (Continued) **1000457836**

Pipe Model:	Not reported
Install Date:	06/09/2008
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	CGFREEDM
Last Modified:	04/12/2013
Material Name:	Diesel

Tank Number:	7
Tank Id:	221668
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L09 - Piping Leak Detection - Exempt Suction Piping
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/01/2004
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	CGFREEDM
Last Modified:	04/12/2013
Material Name:	Lube Oil

Tank Number:	7
Tank Id:	123643
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None

ROME CITY OF D P W (Continued) **1000457836**

J02 - Dispenser - Suction Dispenser
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None

Tank Location:	3
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	06/01/1993
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	04/01/1997
Register:	True
Modified By:	TRANSLAT
Last Modified:	03/04/2004
Material Name:	Waste Oil/Used Oil

SPILLS:

Facility ID:	0606854
Facility Type:	ER
DER Facility ID:	320109
Site ID:	370270
DEC Region:	6
Spill Date:	9/14/2006
Spill Number/Closed Date:	0606854 / 9/18/2006
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	3313
Investigator:	SCREICHI
Referred To:	Not reported
Reported to Dept:	9/14/2006
CID:	444
Water Affected:	STORM DRAIN
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	9/18/2006
Cleanup Meets Std:	False
Last Inspection:	9/18/2006
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	9/14/2006
Spill Record Last Update:	3/21/2007
Spiller Name:	BUTCH CONOVER
Spiller Company:	ROME DPW
Spiller Address:	132 RACE STREET
Spiller City,St,Zip:	ROME, NY 13440
Spiller Company:	001
Contact Name:	BUTCH CONOVER
Contact Phone:	(315) 339-7773
DEC Memo:	09/14/2006: FOLLLOW UP ON SPILL # 06-06843 -TELECON WITH CALLER AT 10:00 AM- CALLER WAS FISHING AT 9:30 AM ON MOHAWK RIVER IN ROME.

ROME CITY OF D P W (Continued) **1000457836**

NOTICED LARGE PATCHES OF DARK BLUE/PURPLE LIQUID WITH SHEEN FLOWING OVER THE LOW HEAD DAM.(SR)09/14/2006: 10:30 ARRIVED ON SCENE. SHEEN STILL FLOWING OVER DAM. TRACKED SPILL BACK TO ROME CITY DPW. FREE PRODUCT FLOWING INTO STORM SEWER BEHIND DPW GARAGE. SPOKE WITH BUTCH CONOVER, GAVE HIM BAIL OF PADS. DPW WILL STOP FLOW INTO STORM SEWER AND CLEAN-UP USING PADS AND SPEEDY DRY. (SR)09/18/06: STOPPED AT ROME DPW. STORM DRAIN OUT BACK HAS CONES AND ONE 8" BOOM AROUND IT. VERY SLIGHT SHEEN LEFT ON STANDING WATER IN SEWER. SPEEDI-DRY IN LOT HAS BEEN PICKED UP. (JA)

Remarks: SPILLED IN PARKING LOT AND CAUSED A SHEEN ON THE RIVER AND PADS ARE DOWN AND CLEANING UP: JIM FROM DEC WAS ON SCENE

Material:

Site ID:	370270
Operable Unit ID:	1128086
Operable Unit:	01
Material ID:	2117696
Material Code:	0010
Material Name:	Hydraulic Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	0705403
Facility Type:	ER
DER Facility ID:	320109
Site ID:	385708
DEC Region:	6
Spill Date:	8/10/2007
Spill Number/Closed Date:	0705403 / 8/13/2007
Spill Cause:	Equipment Failure
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	3313
Investigator:	jcdoyle
Referred To:	Not reported
Reported to Dept:	8/10/2007
CID:	408
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	8/10/2007
Cleanup Meets Std:	True
Last Inspection:	8/10/2007
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	8/10/2007
Spill Record Last Update:	8/13/2007

ROME CITY OF D P W (Continued) **1000457836**

Spiller Name:	BUTCH CONOVER
Spiller Company:	R0ME DPW
Spiller Address:	132 RACE STREET
Spiller City,St,Zip:	ROME, NY 13440
Spiller Company:	999
Contact Name:	WILLIAM TALLARINO
Contact Phone:	(315) 339-7778
DEC Memo:	8/10/2007: SITE INSPECTION SHOWED 10' X 20' AREA BEHIND DPW GARAGE NEEDED CLEAN UP. SPOKE WITH WILLIAM TALLARINO. SITE INSPECTION AT MOHAWK RIVER - 3 STATE POLICE AND 1 ROME POLICE DEPT SARGENT. THEY HAD A REPORT OF A POSSSIBLE VEHICLE IN THE RIVER OR BARGE CANAL. THEY WERE CONTACTING NYS CANALS IN AN ATTEMPT TO GET A BOAT, ALSO CONSIDERING NYS POLICE DIVERS. NYS POLICE: SARGENT SP MARLY - 736-0121 , ROME POLICE: SGT. JAY DIMAGGIO 339-7780. OBSERVED SHEEN ON MOHAWK RIVER BELOW DAM, NORTHEAST WIND WAS CONCENTRATING SHEEN TO WEST SIDE OF RIVER NEAR FOOT BRIDGE.RETURNED TO DPW YARD, SPEEDY DRY APPLIED AND WAS SPILL WAS BEING CLEANED UP. NO FURTHER ACTION. (JD)
Remarks:	ARE CLEANING MATERIAL UP WITH SPEEDY DRY; JAMES DOYLE WAS ON SCENE;

Material:

Site ID:	385708
Operable Unit ID:	1142970
Operable Unit:	01
Material ID:	2133215
Material Code:	0010
Material Name:	Hydraulic Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Facility ID:	0608921
Facility Type:	ER
DER Facility ID:	320109
Site ID:	372996
DEC Region:	6
Spill Date:	11/3/2006
Spill Number/Closed Date:	0608921 / 11/22/2006
Spill Cause:	Equipment Failure
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	3313
Investigator:	SCREICHI
Referred To:	Not reported
Reported to Dept:	11/3/2006
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	11/3/2006
Cleanup Meets Std:	True

ROME CITY OF D P W (Continued) **1000457836**

Last Inspection:	11/21/2006
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	11/3/2006
Spill Record Last Update:	3/21/2007
Spiller Name:	BUTCH CONOVER
Spiller Company:	ROME CITY DPW
Spiller Address:	132 RACE STREET
Spiller City,St,Zip:	ROME, NY
Spiller Company:	999
Contact Name:	BUTCH CONOVER
Contact Phone:	(315) 339-7773
DEC Memo:	11/3/2006: TELECON WITH BUTCH CONOVER, O.C DPW: TRUCK LOST 2 QTS OF TRANSMISSION FLUID 100 FEET FROM STORM SEWER DRAIN BEHIND GARAGE. ABSORBANT PADS PLACED AROUND DRAIN AND AT VEHICLE.(SR)
Remarks:	ABOUT 2 QUARTS SPILLED DUE TO MALFUNCTION AND IN PROCESS OF CLEANING UP

Material:

Site ID:	372996
Operable Unit ID:	1130724
Operable Unit:	01
Material ID:	2120396
Material Code:	0020A
Material Name:	TRANSFORMER OIL
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

85
NE
1/4-1/2
0.426 mi.
2251 ft.

Relative:
Higher

Actual:
457 ft.

GURLEY & FLEET **LTANKS** **1000790262**
301 BLACK RIVER BLVD **N/A**
ROME C, NY

LTANKS:

Site ID:	291093
Spill Number/Closed Date:	8907530 / 4/1/1994
Spill Date:	10/27/1989
Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	4/1/1994
Cleanup Meets Standard:	True
SWIS:	3300
Investigator:	MASON
Referred To:	Not reported
Reported to Dept:	10/27/1989
CID:	Not reported

GURLEY & FLEET (Continued) **1000790262**

Water Affected:	Not reported
Spill Notifier:	DEC
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	11/2/1989
Spill Record Last Update:	7/31/2000
Spiller Name:	Not reported
Spiller Company:	GURLEY & FLEET
Spiller Address:	301 BLACK RIVER BLVD.
Spiller City,St,Zip:	ROME, NY 13440
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	6
DER Facility ID:	235713
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MASON"01/10/91: FOLLOWUP LETTER SENT. (HM).01/15/91: TC FROM "BILL" AT GURLEY & FLEET/GERALD FLEET PASSED AWAY 1 MONTH AGO, WILL TURN OVER TO ATTY. DICK MCMAHON OF MCMAHON & GROW. (HM).11/25/92: FOLLOW-UP LETTER SENT FOR GWI & SOIL. (DJ).04/01/94: INVESTIGATION COMPLETE. CLOSED. (HM).
Remarks:	CONTAMINATION AROUND FILL AND UNDER TANK APPROX. 13 YDS. SOIL STAGED. TANK WAS PUMPED AFTER ABANDONED 8-9 YRS. AGO AFTER TAKING ON WATER.

Material:

Site ID:	291093
Operable Unit ID:	935146
Operable Unit:	01
Material ID:	444320
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	291093
Spill Tank Test:	1536329
Tank Number:	004
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

86
NNW
1/4-1/2
0.428 mi.
2259 ft.

GANESZOORT ELEM. SCHOOL
LIBERTY ST
ROME C, NY

LTANKS **S100130961**
N/A

Relative:
Higher

Actual:
451 ft.

LTANKS:

Site ID:	134469
Spill Number/Closed Date:	8800715 / 11/14/1988
Spill Date:	4/22/1988
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Cleanup Ceased:	11/14/1988
Cleanup Meets Standard:	True
SWIS:	3300
Investigator:	NFCARRIE
Referred To:	Not reported
Reported to Dept:	4/22/1988
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	11/14/1988
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	5/11/1988
Spill Record Last Update:	11/17/1988
Spiller Name:	Not reported
Spiller Company:	GANESZOORT ELEM. SCHOOL
Spiller Address:	LIBERTY ST.
Spiller City,St,Zip:	ROME, NY 13440
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	6
DER Facility ID:	115549
DEC Memo:	Not reported
Remarks:	LEAK RATE -.320 GPH, 10,000 CAPACITY TANK/INITIAL SYSTEM TEST/PETRO TITE METHOD/EXCAVATE, ISOLATE & RETET

Material:

Site ID:	134469
Operable Unit ID:	917715
Operable Unit:	01
Material ID:	459891
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Not reported
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

GANESZOORT ELEM. SCHOOL (Continued) **S100130961**

Site ID:	134469
Spill Tank Test:	1533727
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

---

87 **WALSH RESIDENCE** **LTANKS** **S104277000**
NNE **108 WEST EMBARGO STREET** **N/A**
1/4-1/2 **ROME C, NY**
0.428 mi.
2259 ft.

Relative:
Higher

Actual:
459 ft.

LTANKS:

Site ID:	64512
Spill Number/Closed Date:	9708408 / 2/28/2005
Spill Date:	10/17/1997
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	3313
Investigator:	NFCARRIE
Referred To:	Not reported
Reported to Dept:	10/17/1997
CID:	257
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	10/17/1997
Spill Record Last Update:	5/13/2005
Spiller Name:	JODI LEFFORT
Spiller Company:	MOHAWK VALLEY OIL, INC.
Spiller Address:	9754 RIVER ROAD
Spiller City,St,Zip:	MARCY, NY 13403-
Spiller County:	001
Spiller Contact:	JEFF WALSH
Spiller Phone:	(315) 337-9574
Spiller Extention:	Not reported
DEC Region:	6
DER Facility ID:	62160
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "DER,U,S,V"10/17/97: EGGAN ON SITE ATTEMPTING TO EXCAVATE ALL CONTAM'D SOIL & DEBRIS. HOME OWNER IS JEFF WALSH, 108 N. EMBARGO ST., ROME, NY 13440 (DP).10/30/97: SPILL LETTER SENT TO MVO AND HOMEOWNER FOR SAR AND SOIL.11/13/97: CONFIRMATORY SAMPLES RECEIVED.01/09/98: REMEDIATION SYSTEM REQUESTED.03/04/99: SENT LETTER TO EGGAN AND MVO REQUESTING DOCUMENTATION FOR DISPOSAL AND FINAL SITE CONDITIONS.

WALSH RESIDENCE (Continued) **S104277000**

(JA)07/02/2003: SENT REMINDER LETTER. INCOMPLETE. (DJ)02/23/05 letter report,disposal receipts, lab data rcvd from eggan.

Remarks: CALLER WAS CALLED TO DO CLEANUP AND HOME OWNER HAD TANK CAPPED OFF SPILL IS INTO BASEMENT DIRT FLOOR

Material:

Site ID:	64512
Operable Unit ID:	1051631
Operable Unit:	01
Material ID:	330386
Material Code:	0001A
Material Name:	#2 Fuel Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

88
North
1/4-1/2
0.440 mi.
2325 ft.

LYNN H. SCOTT, INC.
300 WEST COURT ST
ROME C, NY

LTANKS **S106013476**
NY Spills **N/A**

Relative: Higher

Actual: 456 ft.

LTANKS:

Site ID:	185418
Spill Number/Closed Date:	9011756 / 12/10/1998
Spill Date:	2/8/1991
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	3300
Investigator:	MASON
Referred To:	Not reported
Reported to Dept:	2/8/1991
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	DEC
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2/15/1991
Spill Record Last Update:	12/11/1998
Spiller Name:	Not reported
Spiller Company:	AGWAY INC.
Spiller Address:	5814 BRIDGE STREET
Spiller City,St,Zip:	EAST SYRACUSE, NY 13057
Spiller County:	001

LYNN H. SCOTT, INC. (Continued) **S106013476**

Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	6
DER Facility ID:	155069
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "MASON"06/04/91: 3 X MW DRILLED. 06/20/91: 3 X MW SAMPLED/NEED TO BE SURVEYED YET. (NC).12/10/98: EXCAVATED SOIL DISPOSED OF 10/19/98. PAPERWORK RECEIVED, CLOSED - DOES NOT MEET STATE STANDARDS (HM).
Remarks:	HOLES NOTED IN TANK DURING REMOVAL (1000)-GW HAD FILM OF PRODUCT ON TOP. CONTAMINATION ALSO NOTED AROUND FILL & PUMP.

Material:

Site ID:	185418
Operable Unit ID:	951683
Operable Unit:	01
Material ID:	428282
Material Code:	0008
Material Name:	Diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	185418
Spill Tank Test:	1538241
Tank Number:	001
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

SPILLS:

Facility ID:	0300911
Facility Type:	ER
DER Facility ID:	110631
Site ID:	128233
DEC Region:	6
Spill Date:	4/25/2003
Spill Number/Closed Date:	0300911 / 7/30/2003
Spill Cause:	Unknown
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
SWIS:	3300
Investigator:	NFCARRIE
Referred To:	Not reported
Reported to Dept:	4/25/2003
CID:	405

LYNN H. SCOTT, INC. (Continued) **S106013476**

Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	4/25/2003
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	4/25/2003
Spill Record Last Update:	7/30/2003
Spiller Name:	GARY SCOTT
Spiller Company:	LYNN H. SCOTT, INC.
Spiller Address:	8830 BLOSSVALE ROAD
Spiller City,St,Zip:	BLOSSVALE, NY 13308-
Spiller Company:	001
Contact Name:	KEITH HRYCKEWICZ
Contact Phone:	(315) 765-2500
DEC Memo:	Not reported
Remarks:	caller states that the spill is covering 4 block radius - pd and fd on the scene and working on containment and then clean up - 90 weight gear oil - believed to have spilled from a oil tank truck

Material:

Site ID:	128233
Operable Unit ID:	869035
Operable Unit:	01
Material ID:	508983
Material Code:	0015
Material Name:	Motor Oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	200
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

89
NW
1/4-1/2
0.443 mi.
2338 ft.

KEKIS MOBIL SERVICE **LTANKS** **S100964867**
400 WEST DOMINICK ST **N/A**
ROME C, NY

Relative: Higher

Actual: 444 ft.

LTANKS:

Site ID:	263774
Spill Number/Closed Date:	8706960 / 2/6/1989
Spill Date:	11/12/1987
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. No DEC Response. No corrective action required.
Cleanup Ceased:	11/19/1987
Cleanup Meets Standard:	True

KEKIS MOBIL SERVICE (Continued) **S100964867**

SWIS:	3300
Investigator:	DIJOHNSO
Referred To:	Not reported
Reported to Dept:	11/12/1987
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	11/12/1987
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	11/20/1987
Spill Record Last Update:	6/22/1989
Spiller Name:	Not reported
Spiller Company:	RICHARD D. KEKIS
Spiller Address:	808 LAUREL ST.
Spiller City,St,Zip:	ROME, NY 13440
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	6
DER Facility ID:	215002
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was "JOHNSON" / / : 11/12/87-PULLED (4) 4K TANKS/WATER IN EXCAV HAS PRODUCT ON IT/SOIL CONTAMINATED/CLAY SHELF UNDER TANKS/LOOKS OKAY (DJ).11/19/87: CONTAMINATED SOIL HAULED (JM).11/23/87: SOIL DISPOSAL PAPERWORK SUBMITTED (JM).02/06/89: CLOSED (JM).
Remarks:	PBS #066915

Material:

Site ID:	263774
Operable Unit ID:	912784
Operable Unit:	01
Material ID:	465943
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Not reported
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

Site ID:	263774
Spill Tank Test:	1532284
Tank Number:	Not reported
Tank Size:	0
Test Method:	00
Leak Rate:	0
Gross Fail:	Not reported
Modified By:	Spills
Last Modified:	10/1/2004
Test Method:	Unknown

90
SE
1/4-1/2
0.461 mi.
2435 ft.

KEMP OIL SITE
PO BOX 803
ROME, NY

LTANKS **S104192099**
N/A

Relative:
Lower

Actual:
431 ft.

LTANKS:

Site ID:	212632
Spill Number/Closed Date:	9907653 / 9/24/1999
Spill Date:	9/24/1999
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	False
SWIS:	3313
Investigator:	LUCANTONIO
Referred To:	Not reported
Reported to Dept:	9/24/1999
CID:	389
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	9/24/1999
Spill Record Last Update:	9/29/1999
Spiller Name:	CHRIS MASKELL
Spiller Company:	KEMP OIL
Spiller Address:	250 EIRE BLVD EAST
Spiller City,St,Zip:	ROME, NY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	6
DER Facility ID:	176153
DEC Memo:	Not reported
Remarks:	caller reporting a spill of gasoline from an u/g storage tank clean started with 90 tons stock piled no callback necessary ******** SEE SPILL NUMBER 9907630 **********

Material:

Site ID:	212632
Operable Unit ID:	1081951
Operable Unit:	01
Material ID:	300347
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

KEMP OIL SITE (Continued) **S104192099**

Tank Test:

91
WNW
1/4-1/2
0.463 mi.
2444 ft.

FORMER ROME CABLE SITE, BLD. COMPLEX #1 **ERP** **1010206956**
421 RIDGE STREET **NY Spills** **N/A**
ROME, NY 13441

Relative:
Lower

Actual:
432 ft.

ERP:

Site Code:	58361
Program:	ERP
HW Code:	E633053
Site Class:	A
Class N:	A
SWIS:	3313
Region:	6
Town:	Rome (c)
Acres:	5.000
Record Added:	02/03/2004
Record Updated:	04/29/2015
Updated By:	GWHEITZM
Site Description:	Location: The site consists of the Former Rome Cable Corporation, Building Complex No. 1 (Operable Unit No. 1) and Complex 3 (Operable Unit No. 2), which is approximately 10.2 acres in size and is located in the City of Rome, Oneida County. The site is bounded on the north by New York Central Railroad property, on the east by South Madison Street, on the south by Ridge Street and on the west by Rome Strip Steel.Site Features: The predominant site feature includes several large industrial buildings. The entire site was covered with buildings except for a thin strip of vegetated or paved land around the perimeter of the site. In 2010, Building Complex 3 was razed with the exception of the western tower and the area was covered with clean crushed concrete and sand. The City of Rome Police Department currently uses the tower for the local police radio system antennas. The buildings comprising Building Complex 1 remain on-site and are currently occupied by Owl Wire and Cable LLC. Current Zoning and Land Use: The entire site is currently zoned industrial and is in an Empire Development Zone. Building Complex 1 is currently occupied by the Owl Wire and Cable LLC, which manufactures and spins copper wire for various industrial uses. Past Use of the Site: The Rome Cable facility has been used for the manufacturing and spinning of wire in the City of Rome since the 1920's. Prior uses that have led to site contamination include the use of chlorinated solvents used to clean machines and wire, petroleum used to heat the on-site furnaces and as lubricants, and asbestos containing material used as pipe insulation. Several small petroleum spills have been documented. No previous environmental investigations were conducted prior to the Environmental Restoration Program remedial investigation.Operable Units: The site is divided into two operable units. Operable Unit 1 (OU1) is comprised of Building Complex 1 and consists of nine buildings where the various cable making operations took place. Operable Unit 2 (OU2) is comprised of Building Complex 3 and consisted of six buildings. These buildings were demolished in 2010 following the completion of interim remedial measures to remove wastes and contaminated building materials. The area is now open space with the exception of the tower located on the western end of

FORMER ROME CABLE SITE, BLD. COMPLEX #1 (Continued) **1010206956**

the site. A no further action Record of Decision was issued for OU2 in March 2011.Site Geology and Hydrogeology: The geology at the site consists of fill, which consists of clay and silt with cinders to depths of three to seven feet below ground surface. The fill is underlain by medium sand and gravel with silt to depths of 14-16 feet below ground surface. This layer is underlain by fine sand to depths ranging from 28-35 feet below ground surface. Soft clay with inner bedded fine sand underlies the fine sand unit to depths ranging from 52-59 feet. This layer is underlain by hard sand, gravel, clay and silt to depths of 67-78 feet below grade at which point the Utica Shale bedrock is reached. The silt and clay material exhibit low hydraulic conductivity. Groundwater flow is from northeast to southwest. The depth of groundwater ranges from six to nine feet below the surface.

Env Problem: Soil:Surface soil is located around the perimeter of the site, and were analyzed for semi-volatile organic compounds (SVOCs), polychlorinated biphenyls (PCBs), and metals. The results show that surface soil has been impacted by SVOCs and metals. Contamination may extend off-site as the impacted soil is located on the perimeter of the site. The SVOCs that exceeded commercial soil cleanup objectives (SCOs) are benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, chrysene, Dibenzo(a,h)anthracene, and indeno(1,2,3-c,d)pyrene. The metals arsenic, barium, lead, and mercury also exceeded protection of groundwater SCOs in surface soil. The metal copper exceeds commercial SCOs. Subsurface soil was analyzed for volatile organic compounds (VOCs), SVOCs, PCBs, and metals. The results of the investigation show that subsurface soil is impacted primarily by copper at levels that exceed commercial SCOs. VOC contamination is present in the vicinity of MW-07/B-07, associated with a chlorinated organic groundwater plume that extends off-site. The VOCs acetone, cis-1,2-dichloroethene, trichloroethene, and tetrachloroethene exceed the protection of groundwater SCOs. The VOC impacts are present both on-site and off-site.During delineation of the chlorinated organic groundwater plume, soil impacted by petroleum contamination was discovered in the vicinity of MW-08 and MW-15 that was attributed to a historic on-site fuel tank. Additional soil borings, a test pit, and geophysical survey were completed to assess the extent of the petroleum contamination. Neither a tank nor source material were identified by the investigation. Soil in this area was analyzed for VOCs and SVOCs. Petroleum impacted soil was observed beneath the on-site Building Complex 1 and off-site under Ridge Street, starting at six feet below ground surface. Contamination at select locations exceeds the protection of groundwater SCO, and visual and olfactory observations confirm the presence of petroleum impacts. However, petroleum related organics were not detected in groundwater monitoring wells. Groundwater:On-site monitoring wells were analyzed for VOCs, SVOCs, PCBs, and metals. Off-site monitoring wells were only analyzed for VOCs to delineate the extent of the chlorinated organic plume. Off-site groundwater was not analyzed for metal contamination. On-site groundwater has been impacted by metals and VOC contamination above water quality standards. Off-site groundwater is impacted by site-related (chlorinated) VOCs that exceed groundwater standards. Acetone, benzene, and toluene concentrations were above detection limits in off-site groundwater, but were not widely observed. The VOCs of concern are tetrachloroethene (PCE), trichloroethene (TCE), 1,2-cis-dichloroethene (cis-DCE), and vinyl chloride (VC).Water samples were also collected from indoor sumps

FORMER ROME CABLE SITE, BLD. COMPLEX #1 (Continued) **1010206956**

from Building Complex 1 as a supplement to no-site groundwater data. In general, sump water was very turbid and may not be indicative of groundwater conditions. Samples collected from the sumps were analyzed for VOCs, SVOCs, PCBs, and metals. These results indicate contamination by VOCs, SVOCs, and inorganics (metals) exceeding groundwater quality standards. Polychlorinated biphenyls (PCBs) in one sump also exceeded groundwater quality standards. The sump pumps capture local groundwater to prevent groundwater intrusion into the building basement.Soil Vapor Intrusion:The presence of chlorinated organic groundwater contamination presents a risk for soil vapor intrusion (SVI). The off-site office building located at 421 Ridge Street had a sub-slab depressurization system (SSDS) installed to address SVI concerns as an IRM. SVI was also assessed at five off-site residential properties located adjacent to the plume. The results of this sampling, along with the environmental sampling above, indicated monitoring was warranted at one property and no further action at four properties. All SVI samples were analyzed for VOCs according to USEPA Method TO-15. On-site SVI has not been conducted in Building Complex 1 to date.Based on the remedial investigation (RI) conducted, the primary contaminants of concern in the soils and groundwater are VOCs, SVOCs, and metals. The RI for OU1 indicates that surface soils have been impacted by SVOCs and metals, and subsurface soils have been impacted by copper. A chlorinated organics groundwater plume exists at OU1 and extends off-site into a commercial and residential area. The potential for vapor intrusion from the plume was documented in an off-site commercial building and residential property. On-site groundwater is also impacted by metals contamination. Due to the extensive development across the site no other ecological resources have been impacted other than groundwater.

Health Problem: Access to the site is unrestricted. However, contact with contaminated soil or groundwater is unlikely unless people dig below the ground surface. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for people to inhale site contaminants in indoor air due to soil vapor intrusion in any on-site buildings that are occupied. A sub-slab depressurization system was installed in an adjacent off-site office building to prevent vapors beneath the slab from entering the building. Monitoring is recommended in one additional off-site building that is a residence.

SPILLS:

Facility ID:	0300089
Facility Type:	ER
DER Facility ID:	294948
Site ID:	72319
DEC Region:	6
Spill Date:	3/31/2003
Spill Number/Closed Date:	0300089 / 4/2/2003
Spill Cause:	Equipment Failure
Spill Class:	No spill occured. No DEC Response. No corrective action required.
SWIS:	3313

FORMER ROME CABLE SITE, BLD. COMPLEX #1 (Continued) **1010206956**

Investigator:	JDALSANT
Referred To:	Not reported
Reported to Dept:	4/2/2003
CID:	322
Water Affected:	BARGE CANAL
Spill Source:	Commercial/Industrial
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	4/2/2003
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	4/2/2003
Spill Record Last Update:	6/30/2005
Spiller Name:	C. SHERWOOD
Spiller Company:	ROME CABLE CORPORATION
Spiller Address:	421 RIDGE ST
Spiller City,St,Zip:	ROME, NY 13440-
Spiller Company:	001
Contact Name:	DARYL DOWSLAND
Contact Phone:	(315) 337-3000
DEC Memo:	Not reported
Remarks:	caller states recirclating water system is not working causing a flooding situation in in basement of building #15 - water is being bypassed into the sewer which in turn goes into the barge canal

Material:

Site ID:	72319
Operable Unit ID:	868389
Operable Unit:	01
Material ID:	508164
Material Code:	0064A
Material Name:	UNKNOWN MATERIAL
Case No.:	Not reported
Material FA:	Other
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

R92 **GARCIA RESIDENCE** **LTANKS** **S105999315**
SW **735 SOUTH JAMES ST** **N/A**
1/4-1/2 **ROME C, NY**
0.476 mi.
2511 ft. **Site 1 of 2 in cluster R**

Relative:
Lower

Actual:
423 ft.

LTANKS:

Site ID:	153762
Spill Number/Closed Date:	0303378 / 9/25/2003
Spill Date:	6/30/2003
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response.

GARCIA RESIDENCE (Continued) **S105999315**

	Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	Not reported
Cleanup Meets Standard:	True
SWIS:	3300
Investigator:	NFCARRIE
Referred To:	Not reported
Reported to Dept:	6/30/2003
CID:	252
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	6/30/2003
Recommended Penalty:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	6/30/2003
Spill Record Last Update:	9/26/2003
Spiller Name:	GLORIA GARCIA
Spiller Company:	MR. GARCIA
Spiller Address:	735 SOUTH JAMES ST.LOT 30
Spiller City,St,Zip:	ROME, NY
Spiller County:	001
Spiller Contact:	PATTY WASHBURN
Spiller Phone:	(315) 337-8096
Spiller Extention:	Not reported
DEC Region:	6
DER Facility ID:	130433
DEC Memo:	Not reported
Remarks:	CALLER HAS SPOKEN WITH REGIONAL OFFICE RE SPILL.

Material:

Site ID:	153762
Operable Unit ID:	870481
Operable Unit:	01
Material ID:	504249
Material Code:	0012A
Material Name:	Kerosene
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

R93 **LEE BATES & SONS** **LTANKS** **S102233853**
SW **736 SOUTH JAMES STREET** **N/A**
1/4-1/2 **ROME C, NY**
0.478 mi.
2523 ft. **Site 2 of 2 in cluster R**

Relative:
Lower

Actual:
423 ft.

LTANKS:

Site ID:	189065
Spill Number/Closed Date:	9507910 / 1/27/1998
Spill Date:	9/27/1995
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Cleanup Ceased:	4/21/1997
Cleanup Meets Standard:	True
SWIS:	3300
Investigator:	AJMARSCH
Referred To:	Not reported
Reported to Dept:	9/27/1995
CID:	357
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	9/27/1995
Spill Record Last Update:	1/28/1998
Spiller Name:	EDWARD BATES
Spiller Company:	LEE BATES & SONS, INC.
Spiller Address:	900 N. JAMES STREET
Spiller City,St,Zip:	ROME, NY 13440-
Spiller County:	001
Spiller Contact:	SAME
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	6
DER Facility ID:	157881
DEC Memo:	Not reported
Remarks:	90 yds of contaminated soil - DAVE PICKET WAS ON SIGHT EARLIER TODAY

Material:

Site ID:	189065
Operable Unit ID:	1022527
Operable Unit:	01
Material ID:	362353
Material Code:	0009
Material Name:	Gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	No
Resource Affected:	Not reported
Oxygenate:	False

Tank Test:

94
NW
1/4-1/2
0.478 mi.
2526 ft.

NIMO - ROME-JAY AND MADISON MGP — **EDR MGP** — **1008408033**
106 SO. MADISON ST AND 410/412 ERIE BLVD — **N/A**
ROME, NY 13440

Relative:
Lower

Actual:
437 ft.

Manufactured Gas Plants:
No additional information available

95
NNE
1/4-1/2
0.495 mi.
2614 ft.

EAST ROME INDUSTRIAL PARK (FORMER GENERAL CABLE) — **US BROWNFIELDS** — **1012238586**
ROME INDUSTRIAL CENTER, EAST DOMINICK STREET — **N/A**
ROME, NY 13440

Relative:
Higher

Actual:
459 ft.

US BROWNFIELDS:

Recipient name:	Rome, City of
Grant type:	Assessment
Property name:	EAST ROME INDUSTRIAL PARK (FORMER GENERAL CABLE)
Property #:	Not reported
Parcel size:	17
Property Description:	Not reported
Latitude:	43.215169
Longitude:	-75.453362
HCM label:	Not reported
Map scale:	Not reported
Point of reference:	Not reported
Datum:	Not reported
ACRES property ID:	13190
Start date:	09/30/1999 00:00:00
Completed date:	09/30/1999 00:00:00
Acres cleaned up:	Not reported
Cleanup funding:	Not reported
Cleanup funding source:	Not reported
Assessment funding:	Not reported
Assessment funding source:	Not reported
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	09/30/1999 00:00:00
Assessment funding entity:	Not reported
Cleanup funding entity:	Not reported
Grant type:	N/A
Accomplishment type:	Phase I Environmental Assessment
Accomplishment count:	0
Cooperative agreement #:	99255701
Ownership entity:	Not reported
Current owner:	Not reported
Did owner change:	Not reported
Cleanup required:	Yes
Video available:	Not reported
Photo available:	Not reported
Institutional controls required:	Not reported
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported

EAST ROME INDUSTRIAL PARK (FORMER GENERAL CABLE) (Continued) **1012238586**

IC in place:	Unknown
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Y
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	0
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported

EAST ROME INDUSTRIAL PARK (FORMER GENERAL CABLE) (Continued) **1012238586**

Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported

Count: 11 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
FLOYD	S107416619	2 MI EAST OF ROME	ROUTE 49		LTANKS
FRANKFORT	S103276704	CRASH'S AUTO DUMP	RD#2 HARBOR RD	13440	SWF/LF
ROME	1004758392	ROME DEPT OF TRANSPORTATION	6515 RTE 26 RR #1 BOX 61	13440	RCRA NonGen / NLR, FINDS, MANIFEST
ROME	1007786066	ROME INDUSTRIAL PARK	RT 69	13440	FINDS
ROME	1015731681	NIAGARA MOHAWK /GAS REG STA	KINGSLEY AVE	13440	CERCLIS, RCRA-LQG, MANIFEST
ROME	S114964582	NM - ROME JAY/MADISON MGP	106 SO. MADISON ST & 410/412 E		RGA HWS
ROME	S114964577	NM - JAY/MADISON - ROME MGP	106 SO. MADISON ST & 410/412 E		RGA HWS
ROME	S108146971	NIMO, ROME (MADISON AND JAY)	MADISON AND JAY STREETS	13440	HSWDS
ROME	1016043131	ROME WATERFRONT PROJECT	E OF MILL ST BRIDGE; ON N SHOR	13440	FINDS
ROME	S113916736	FORMER JET DRY CLEANERS	401 1/2 WEST DOMINICK STREET	13440	SHWS
ROME	S108146793	NIMO, ROME GAS REGULATOR STA.	WOODROW AVE		HSWDS

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 03/26/2015
Date Data Arrived at EDR: 04/08/2015
Date Made Active in Reports: 06/22/2015
Number of Days to Update: 75

Source: EPA
Telephone: N/A
Last EDR Contact: 07/09/2015
Next Scheduled EDR Contact: 10/19/2015
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 6
Telephone: 214-655-6659

EPA Region 3
Telephone 215-814-5418

EPA Region 7
Telephone: 913-551-7247

EPA Region 4
Telephone 404-562-8033

EPA Region 8
Telephone: 303-312-6774

EPA Region 5
Telephone 312-886-6686

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 03/26/2015
Date Data Arrived at EDR: 04/08/2015
Date Made Active in Reports: 06/22/2015
Number of Days to Update: 75

Source: EPA
Telephone: N/A
Last EDR Contact: 07/09/2015
Next Scheduled EDR Contact: 10/19/2015
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Federal Delisted NPL site list

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 03/26/2015
Date Data Arrived at EDR: 04/08/2015
Date Made Active in Reports: 06/22/2015
Number of Days to Update: 75

Source: EPA
Telephone: N/A
Last EDR Contact: 07/09/2015
Next Scheduled EDR Contact: 10/19/2015
Data Release Frequency: Quarterly

Federal CERCLIS list

CERCLIS: Comprehensive Environmental Response, Compensation, and Liability Information System

CERCLIS contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 10/25/2013
Date Data Arrived at EDR: 11/11/2013
Date Made Active in Reports: 02/13/2014
Number of Days to Update: 94

Source: EPA
Telephone: 703-412-9810
Last EDR Contact: 05/29/2015
Next Scheduled EDR Contact: 09/07/2015
Data Release Frequency: Quarterly

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 03/26/2015
Date Data Arrived at EDR: 04/08/2015
Date Made Active in Reports: 06/11/2015
Number of Days to Update: 64

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 07/10/2015
Next Scheduled EDR Contact: 10/19/2015
Data Release Frequency: Varies

Federal CERCLIS NFRAP site List

CERCLIS-NFRAP: CERCLIS No Further Remedial Action Planned

Archived sites are sites that have been removed and archived from the inventory of CERCLIS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

Date of Government Version: 10/25/2013
Date Data Arrived at EDR: 11/11/2013
Date Made Active in Reports: 02/13/2014
Number of Days to Update: 94

Source: EPA
Telephone: 703-412-9810
Last EDR Contact: 05/29/2015
Next Scheduled EDR Contact: 09/07/2015
Data Release Frequency: Quarterly

Federal RCRA CORRACTS facilities list

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 03/10/2015
Date Data Arrived at EDR: 03/31/2015
Date Made Active in Reports: 06/11/2015
Number of Days to Update: 72

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 10/12/2015
Data Release Frequency: Quarterly

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 03/10/2015
Date Data Arrived at EDR: 03/31/2015
Date Made Active in Reports: 06/11/2015
Number of Days to Update: 72

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 10/12/2015
Data Release Frequency: Quarterly

Federal RCRA generators list

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 03/10/2015
Date Data Arrived at EDR: 03/31/2015
Date Made Active in Reports: 06/11/2015
Number of Days to Update: 72

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 10/12/2015
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 03/10/2015
Date Data Arrived at EDR: 03/31/2015
Date Made Active in Reports: 06/11/2015
Number of Days to Update: 72

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 10/12/2015
Data Release Frequency: Quarterly

RCRA-CESQG: RCRA - Conditionally Exempt Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 03/10/2015
Date Data Arrived at EDR: 03/31/2015
Date Made Active in Reports: 06/11/2015
Number of Days to Update: 72

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 10/12/2015
Data Release Frequency: Varies

Federal institutional controls / engineering controls registries

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 03/16/2015
Date Data Arrived at EDR: 03/17/2015
Date Made Active in Reports: 06/02/2015
Number of Days to Update: 77

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 06/01/2015
Next Scheduled EDR Contact: 09/14/2015
Data Release Frequency: Varies

US INST CONTROL: Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 03/16/2015
Date Data Arrived at EDR: 03/17/2015
Date Made Active in Reports: 06/02/2015
Number of Days to Update: 77

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 06/01/2015
Next Scheduled EDR Contact: 09/14/2015
Data Release Frequency: Varies

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 05/28/2015
Date Data Arrived at EDR: 05/29/2015
Date Made Active in Reports: 06/11/2015
Number of Days to Update: 13

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 05/18/2015
Next Scheduled EDR Contact: 08/31/2015
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 03/30/2015
Date Data Arrived at EDR: 03/31/2015
Date Made Active in Reports: 06/02/2015
Number of Days to Update: 63

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 10/12/2015
Data Release Frequency: Annually

State- and tribal - equivalent CERCLIS

SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 06/26/2015
Date Data Arrived at EDR: 06/30/2015
Date Made Active in Reports: 07/22/2015
Number of Days to Update: 22

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 08/31/2015
Data Release Frequency: Annually

VAPOR REOPENED: Vapor Intrustion Legacy Site List

New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

Date of Government Version: 11/01/2014
Date Data Arrived at EDR: 11/19/2014
Date Made Active in Reports: 01/12/2015
Number of Days to Update: 54

Source: Department of Environmenal Conservation
Telephone: 518-402-9814
Last EDR Contact: 05/22/2015
Next Scheduled EDR Contact: 08/31/2015
Data Release Frequency: Varies

State and tribal landfill and/or solid waste disposal site lists

SWF/LF: Facility Register

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 06/24/2015
Date Data Arrived at EDR: 07/08/2015
Date Made Active in Reports: 07/22/2015
Number of Days to Update: 14

Source: Department of Environmental Conservation
Telephone: 518-457-2051
Last EDR Contact: 07/06/2015
Next Scheduled EDR Contact: 10/19/2015
Data Release Frequency: Semi-Annually

State and tribal leaking storage tank lists

LTANKS: Spills Information Database

Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 05/18/2015
Date Data Arrived at EDR: 05/21/2015
Date Made Active in Reports: 06/19/2015
Number of Days to Update: 29

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/21/2015
Next Scheduled EDR Contact: 08/31/2015
Data Release Frequency: Varies

HIST LTANKS: Listing of Leaking Storage Tanks

A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 03/30/2015
Date Data Arrived at EDR: 04/28/2015
Date Made Active in Reports: 06/22/2015
Number of Days to Update: 55

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 07/22/2015
Next Scheduled EDR Contact: 11/09/2015
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 04/30/2015
Date Data Arrived at EDR: 05/05/2015
Date Made Active in Reports: 06/22/2015
Number of Days to Update: 48
Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 07/22/2015
Next Scheduled EDR Contact: 11/09/2015
Data Release Frequency: Quarterly

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 03/17/2015
Date Data Arrived at EDR: 05/01/2015
Date Made Active in Reports: 06/22/2015
Number of Days to Update: 52
Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 07/22/2015
Next Scheduled EDR Contact: 11/09/2015
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 09/30/2014
Date Data Arrived at EDR: 03/03/2015
Date Made Active in Reports: 03/13/2015
Number of Days to Update: 10
Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 07/22/2015
Next Scheduled EDR Contact: 11/09/2015
Data Release Frequency: Semi-Annually

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 02/03/2015
Date Data Arrived at EDR: 04/30/2015
Date Made Active in Reports: 06/22/2015
Number of Days to Update: 53
Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 04/03/2015
Next Scheduled EDR Contact: 08/10/2015
Data Release Frequency: Varies

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 01/08/2015
Date Data Arrived at EDR: 01/08/2015
Date Made Active in Reports: 02/09/2015
Number of Days to Update: 32
Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 01/08/2015
Next Scheduled EDR Contact: 05/11/2015
Data Release Frequency: Quarterly

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 02/03/2015
Date Data Arrived at EDR: 02/12/2015
Date Made Active in Reports: 03/13/2015
Number of Days to Update: 29
Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 07/22/2015
Next Scheduled EDR Contact: 11/09/2015
Data Release Frequency: Quarterly

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land
Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 04/30/2015
Date Data Arrived at EDR: 05/29/2015
Date Made Active in Reports: 06/22/2015
Number of Days to Update: 24
Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 07/22/2015
Next Scheduled EDR Contact: 11/09/2015
Data Release Frequency: Varies

State and tribal registered storage tank lists

TANKS: Storage Tank Faciliy Listing

This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

Date of Government Version: 06/24/2015
Date Data Arrived at EDR: 06/29/2015
Date Made Active in Reports: 07/22/2015
Number of Days to Update: 23

Source: Department of Environmental Conservation
Telephone: 518-402-9543
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 10/12/2015
Data Release Frequency: Quarterly

UST: Petroleum Bulk Storage (PBS) Database

Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 03/30/2015
Date Data Arrived at EDR: 04/01/2015
Date Made Active in Reports: 04/15/2015
Number of Days to Update: 14

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 10/12/2015
Data Release Frequency: No Update Planned

CBS UST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 10/24/2005
Next Scheduled EDR Contact: 01/23/2006
Data Release Frequency: No Update Planned

MOSF UST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

AST: Petroleum Bulk Storage

Registered Aboveground Storage Tanks.

Date of Government Version: 03/30/2015
Date Data Arrived at EDR: 04/01/2015
Date Made Active in Reports: 04/15/2015
Number of Days to Update: 14

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 10/12/2015
Data Release Frequency: No Update Planned

CBS AST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF AST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF: Major Oil Storage Facility Site Listing

These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 06/24/2015
Date Data Arrived at EDR: 06/29/2015
Date Made Active in Reports: 07/22/2015
Number of Days to Update: 23

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 10/12/2015
Data Release Frequency: Quarterly

CBS: Chemical Bulk Storage Site Listing

These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

Date of Government Version: 06/24/2015
Date Data Arrived at EDR: 06/29/2015
Date Made Active in Reports: 07/22/2015
Number of Days to Update: 23

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 10/12/2015
Data Release Frequency: Quarterly

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 04/30/2015
Date Data Arrived at EDR: 05/26/2015
Date Made Active in Reports: 06/22/2015
Number of Days to Update: 27

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 07/22/2015
Next Scheduled EDR Contact: 11/09/2015
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 02/03/2015
Date Data Arrived at EDR: 04/30/2015
Date Made Active in Reports: 06/22/2015
Number of Days to Update: 53

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 04/28/2015
Next Scheduled EDR Contact: 08/10/2015
Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 09/23/2014
Date Data Arrived at EDR: 11/25/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 65

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 07/22/2015
Next Scheduled EDR Contact: 11/09/2015
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 03/17/2015
Date Data Arrived at EDR: 05/01/2015
Date Made Active in Reports: 06/22/2015
Number of Days to Update: 52

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 07/22/2015
Next Scheduled EDR Contact: 11/09/2015
Data Release Frequency: Semi-Annually

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 09/30/2014
Date Data Arrived at EDR: 03/03/2015
Date Made Active in Reports: 03/13/2015
Number of Days to Update: 10

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 07/22/2015
Next Scheduled EDR Contact: 11/09/2015
Data Release Frequency: Semi-Annually

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 05/06/2015
Date Data Arrived at EDR: 05/19/2015
Date Made Active in Reports: 06/22/2015
Number of Days to Update: 34

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 07/22/2015
Next Scheduled EDR Contact: 11/09/2015
Data Release Frequency: Quarterly

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 12/14/2014
Date Data Arrived at EDR: 02/13/2015
Date Made Active in Reports: 03/13/2015
Number of Days to Update: 28

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 01/26/2015
Next Scheduled EDR Contact: 05/11/2015
Data Release Frequency: Quarterly

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 04/30/2015
Date Data Arrived at EDR: 05/05/2015
Date Made Active in Reports: 06/22/2015
Number of Days to Update: 48

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 07/22/2015
Next Scheduled EDR Contact: 11/09/2015
Data Release Frequency: Quarterly

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 01/01/2010
Date Data Arrived at EDR: 02/16/2010
Date Made Active in Reports: 04/12/2010
Number of Days to Update: 55

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 07/10/2015
Next Scheduled EDR Contact: 10/28/2015
Data Release Frequency: Varies

State and tribal institutional control / engineering control registries

ENG CONTROLS: Registry of Engineering Controls
Environmental Remediation sites that have engineering controls in place.

Date of Government Version: 06/26/2015
Date Data Arrived at EDR: 06/30/2015
Date Made Active in Reports: 07/22/2015
Number of Days to Update: 22
Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 08/31/2015
Data Release Frequency: Quarterly

INST CONTROL: Registry of Institutional Controls
Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 06/26/2015
Date Data Arrived at EDR: 06/30/2015
Date Made Active in Reports: 07/22/2015
Number of Days to Update: 22
Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 08/31/2015
Data Release Frequency: Quarterly

RES DECL: Restrictive Declarations Listing
A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

Date of Government Version: 11/18/2010
Date Data Arrived at EDR: 06/30/2014
Date Made Active in Reports: 07/21/2014
Number of Days to Update: 21
Source: NYC Department of City Planning
Telephone: 212-720-3401
Last EDR Contact: 06/25/2015
Next Scheduled EDR Contact: 10/05/2015
Data Release Frequency: Varies

ENV RES DECL: Environmental Restrictive Declarations
The Environmental Restrictive Declarations (ERD) listed were recorded in connection with a zoning action against the noted Tax Blocks and Tax Lots, or portion thereof, and are available in the property records on file at the Office of the City Register for Bronx, Kings, New York and Queens counties or at the Richmond County Clerk's office. They contain environmental requirements with respect to hazardous materials, air quality and/or noise in accordance with Section 11-15 of this Resolution.

Date of Government Version: 03/31/2015
Date Data Arrived at EDR: 06/25/2015
Date Made Active in Reports: 07/22/2015
Number of Days to Update: 27
Source: New York City Department of City Planning
Telephone: 212-720-3300
Last EDR Contact: 06/19/2015
Next Scheduled EDR Contact: 10/05/2015
Data Release Frequency: Varies

State and tribal voluntary cleanup sites

INDIAN VCP R1: Voluntary Cleanup Priority Listing
A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 09/29/2014
Date Data Arrived at EDR: 10/01/2014
Date Made Active in Reports: 11/06/2014
Number of Days to Update: 36
Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 10/12/2015
Data Release Frequency: Varies

VCP: Voluntary Cleanup Agreements
New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites.

Date of Government Version: 06/26/2015
Date Data Arrived at EDR: 06/30/2015
Date Made Active in Reports: 07/22/2015
Number of Days to Update: 22

Source: Department of Environmental Conservation
Telephone: 518-402-9711
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 08/31/2015
Data Release Frequency: Semi-Annually

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng

A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 04/20/2009
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

State and tribal Brownfields sites

ERP: Environmental Restoration Program Listing

In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a $200 million Environmental Restoration or Brownfields Fund as part of the $1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

Date of Government Version: 06/26/2015
Date Data Arrived at EDR: 06/30/2015
Date Made Active in Reports: 07/22/2015
Number of Days to Update: 22

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 08/31/2015
Data Release Frequency: Quarterly

BROWNFIELDS: Brownfields Site List

A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 06/26/2015
Date Data Arrived at EDR: 06/30/2015
Date Made Active in Reports: 07/22/2015
Number of Days to Update: 22

Source: Department of Environmental Conservation
Telephone: 518-402-9764
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 08/31/2015
Data Release Frequency: Semi-Annually

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 03/23/2015
Date Data Arrived at EDR: 03/24/2015
Date Made Active in Reports: 06/02/2015
Number of Days to Update: 70

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 06/24/2015
Next Scheduled EDR Contact: 10/05/2015
Data Release Frequency: Semi-Annually

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Local Lists of Landfill / Solid Waste Disposal Sites

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations
A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137
Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 07/22/2015
Next Scheduled EDR Contact: 11/09/2015
Data Release Frequency: No Update Planned

ODI: Open Dump Inventory
An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39
Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SWTIRE: Registered Waste Tire Storage & Facility List
A listing of facilities registered to accept waste tires.

Date of Government Version: 08/01/2006
Date Data Arrived at EDR: 11/15/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 15
Source: Department of Environmental Conservation
Telephone: 518-402-8694
Last EDR Contact: 07/15/2015
Next Scheduled EDR Contact: 11/02/2015
Data Release Frequency: Annually

SWRCY: Registered Recycling Facility List
A listing of recycling facilities.

Date of Government Version: 06/24/2015
Date Data Arrived at EDR: 07/08/2015
Date Made Active in Reports: 07/22/2015
Number of Days to Update: 14
Source: Department of Environmental Conservation
Telephone: 518-402-8705
Last EDR Contact: 07/06/2015
Next Scheduled EDR Contact: 10/19/2015
Data Release Frequency: Semi-Annually

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands
Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52
Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 05/01/2015
Next Scheduled EDR Contact: 08/17/2015
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US CDL: Clandestine Drug Labs
A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 02/25/2015
Date Data Arrived at EDR: 03/10/2015
Date Made Active in Reports: 03/25/2015
Number of Days to Update: 15

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 05/29/2015
Next Scheduled EDR Contact: 09/14/2015
Data Release Frequency: Quarterly

DEL SHWS: Delisted Registry Sites

A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

Date of Government Version: 06/26/2015
Date Data Arrived at EDR: 06/30/2015
Date Made Active in Reports: 07/22/2015
Number of Days to Update: 22

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 08/31/2015
Data Release Frequency: Annually

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 02/25/2015
Date Data Arrived at EDR: 03/10/2015
Date Made Active in Reports: 03/25/2015
Number of Days to Update: 15

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 05/29/2015
Next Scheduled EDR Contact: 09/14/2015
Data Release Frequency: No Update Planned

Local Lists of Registered Storage Tanks

HIST UST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. It is no longer updated due to the sensitive nature of the information involved. See UST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: Varies

HIST AST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capabilities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. No longer updated due to the sensitive nature of the information involved. See AST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: No Update Planned

Local Land Records

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 02/18/2014
Date Data Arrived at EDR: 03/18/2014
Date Made Active in Reports: 04/24/2014
Number of Days to Update: 37

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 07/22/2015
Next Scheduled EDR Contact: 11/09/2015
Data Release Frequency: Varies

LIENS: Spill Liens Information
Lien information from the Oil Spill Fund.

Date of Government Version: 05/08/2015
Date Data Arrived at EDR: 05/12/2015
Date Made Active in Reports: 05/20/2015
Number of Days to Update: 8

Source: Office of the State Comptroller
Telephone: 518-474-9034
Last EDR Contact: 05/08/2015
Next Scheduled EDR Contact: 08/24/2015
Data Release Frequency: Varies

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System
Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 03/30/2015
Date Data Arrived at EDR: 03/31/2015
Date Made Active in Reports: 06/11/2015
Number of Days to Update: 72

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 10/12/2015
Data Release Frequency: Annually

SPILLS: Spills Information Database
Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 05/18/2015
Date Data Arrived at EDR: 05/21/2015
Date Made Active in Reports: 06/19/2015
Number of Days to Update: 29

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/21/2015
Next Scheduled EDR Contact: 08/31/2015
Data Release Frequency: Varies

HIST SPILLS: SPILLS Database
This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 80: SPILLS80 data from FirstSearch
Spills 80 includes those spill and release records available from FirstSearch databases prior to 1990. Typically, they may include chemical, oil and/or hazardous substance spills recorded before 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 80.

Date of Government Version: 11/02/2010
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/07/2013
Number of Days to Update: 63

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 12/14/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/12/2013
Number of Days to Update: 40

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 03/10/2015
Date Data Arrived at EDR: 03/31/2015
Date Made Active in Reports: 06/11/2015
Number of Days to Update: 72

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 06/26/2015
Next Scheduled EDR Contact: 10/12/2015
Data Release Frequency: Varies

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 07/31/2012
Date Data Arrived at EDR: 08/07/2012
Date Made Active in Reports: 09/18/2012
Number of Days to Update: 42

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 05/05/2015
Next Scheduled EDR Contact: 08/17/2015
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 11/10/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 62

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 07/14/2015
Next Scheduled EDR Contact: 10/28/2015
Data Release Frequency: Semi-Annually

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 06/06/2014
Date Data Arrived at EDR: 09/10/2014
Date Made Active in Reports: 09/18/2014
Number of Days to Update: 8

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 07/08/2015
Next Scheduled EDR Contact: 09/21/2015
Data Release Frequency: Varies

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 04/17/2015
Date Made Active in Reports: 06/02/2015
Number of Days to Update: 46

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 06/22/2015
Next Scheduled EDR Contact: 10/12/2015
Data Release Frequency: Varies

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 11/25/2013
Date Data Arrived at EDR: 12/12/2013
Date Made Active in Reports: 02/24/2014
Number of Days to Update: 74

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 06/12/2015
Next Scheduled EDR Contact: 09/21/2015
Data Release Frequency: Annually

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 09/14/2010
Date Data Arrived at EDR: 10/07/2011
Date Made Active in Reports: 03/01/2012
Number of Days to Update: 146

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 05/26/2015
Next Scheduled EDR Contact: 09/07/2015
Data Release Frequency: Varies

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 12/30/2014
Date Data Arrived at EDR: 12/31/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 29

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 06/03/2015
Next Scheduled EDR Contact: 09/14/2015
Data Release Frequency: Semi-Annually

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2013
Date Data Arrived at EDR: 02/12/2015
Date Made Active in Reports: 06/02/2015
Number of Days to Update: 110

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 01/29/2015
Next Scheduled EDR Contact: 06/08/2015
Data Release Frequency: Annually

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2012
Date Data Arrived at EDR: 01/15/2015
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 14

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 06/25/2015
Next Scheduled EDR Contact: 10/05/2015
Data Release Frequency: Every 4 Years

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 05/20/2015
Next Scheduled EDR Contact: 09/07/2015
Data Release Frequency: Quarterly

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 05/20/2015
Next Scheduled EDR Contact: 09/07/2015
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing
A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing
A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

SSTS: Section 7 Tracking Systems
Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 12/10/2010
Date Made Active in Reports: 02/25/2011
Number of Days to Update: 77

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 07/22/2015
Next Scheduled EDR Contact: 11/09/2015
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 01/23/2015
Date Data Arrived at EDR: 02/06/2015
Date Made Active in Reports: 03/09/2015
Number of Days to Update: 31

Source: Environmental Protection Agency
Telephone: 202-564-5088
Last EDR Contact: 07/09/2015
Next Scheduled EDR Contact: 10/28/2015
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 07/01/2014
Date Data Arrived at EDR: 10/15/2014
Date Made Active in Reports: 11/17/2014
Number of Days to Update: 33

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 07/17/2015
Next Scheduled EDR Contact: 10/28/2015
Data Release Frequency: Annually

MLTS: Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 03/31/2015
Date Data Arrived at EDR: 04/09/2015
Date Made Active in Reports: 06/11/2015
Number of Days to Update: 63

Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 06/04/2015
Next Scheduled EDR Contact: 09/21/2015
Data Release Frequency: Quarterly

RADINFO: Radiation Information Database

The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 04/07/2015
Date Data Arrived at EDR: 04/09/2015
Date Made Active in Reports: 06/11/2015
Number of Days to Update: 63

Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 07/09/2015
Next Scheduled EDR Contact: 10/19/2015
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 01/18/2015
Date Data Arrived at EDR: 02/27/2015
Date Made Active in Reports: 03/25/2015
Number of Days to Update: 26

Source: EPA
Telephone: (212) 637-3000
Last EDR Contact: 06/10/2015
Next Scheduled EDR Contact: 09/21/2015
Data Release Frequency: Quarterly

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 02/01/2015
Date Data Arrived at EDR: 02/13/2015
Date Made Active in Reports: 03/25/2015
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 07/22/2015
Next Scheduled EDR Contact: 11/09/2015
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2011
Date Data Arrived at EDR: 02/26/2013
Date Made Active in Reports: 04/19/2013
Number of Days to Update: 52

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 05/29/2015
Next Scheduled EDR Contact: 09/07/2015
Data Release Frequency: Biennially

HSWDS: Hazardous Substance Waste Disposal Site Inventory

The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 01/01/2003
Date Data Arrived at EDR: 10/20/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9564
Last EDR Contact: 05/26/2009
Next Scheduled EDR Contact: 08/24/2009
Data Release Frequency: No Update Planned

UIC: Underground Injection Control Wells

A listing of enhanced oil recovery underground injection wells.

Date of Government Version: 06/05/2015
Date Data Arrived at EDR: 06/11/2015
Date Made Active in Reports: 07/22/2015
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-8056
Last EDR Contact: 06/11/2015
Next Scheduled EDR Contact: 09/21/2015
Data Release Frequency: Quarterly

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 05/01/2015
Date Data Arrived at EDR: 05/06/2015
Date Made Active in Reports: 05/20/2015
Number of Days to Update: 14

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 05/06/2015
Next Scheduled EDR Contact: 08/17/2015
Data Release Frequency: Annually

DRYCLEANERS: Registered Drycleaners

A listing of all registered drycleaning facilities.

Date of Government Version: 07/02/2015
Date Data Arrived at EDR: 07/13/2015
Date Made Active in Reports: 07/22/2015
Number of Days to Update: 9

Source: Department of Environmental Conservation
Telephone: 518-402-8403
Last EDR Contact: 06/11/2015
Next Scheduled EDR Contact: 09/28/2015
Data Release Frequency: Varies

SPDES: State Pollutant Discharge Elimination System

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 06/10/2015
Date Data Arrived at EDR: 06/19/2015
Date Made Active in Reports: 07/22/2015
Number of Days to Update: 33

Source: Department of Environmental Conservation
Telephone: 518-402-8233
Last EDR Contact: 06/09/2015
Next Scheduled EDR Contact: 08/10/2015
Data Release Frequency: No Update Planned

AIRS: Air Emissions Data

Point source emissions inventory data.

Date of Government Version: 04/17/2015
Date Data Arrived at EDR: 04/23/2015
Date Made Active in Reports: 05/20/2015
Number of Days to Update: 27

Source: Department of Environmental Conservation
Telephone: 518-402-8452
Last EDR Contact: 04/27/2015
Next Scheduled EDR Contact: 08/10/2015
Data Release Frequency: Annually

E DESIGNATION: E DESIGNATION SITE LISTING

The (E (Environmental)) designation would ensure that sampling and remediation take place on the subject properties, and would avoid any significant impacts related to hazardous materials at these locations. The (E) designations would require that the fee owner of the sites conduct a testing and sampling protocol, and remediation where appropriate, to the satisfaction of the NYCDEP before the issuance of a building permit by the Department of Buildings pursuant to the provisions of Section 11-15 of the Zoning Resolution (Environmental Requirements). The (E) designations also include a mandatory construction-related health and safety plan which must be approved by NYCDEP.

Date of Government Version: 05/27/2015
Date Data Arrived at EDR: 06/25/2015
Date Made Active in Reports: 07/22/2015
Number of Days to Update: 27

Source: New York City Department of City Planning
Telephone: 718-595-6658
Last EDR Contact: 06/19/2015
Next Scheduled EDR Contact: 10/05/2015
Data Release Frequency: Varies

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 12/08/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 34

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 07/14/2015
Next Scheduled EDR Contact: 10/28/2015
Data Release Frequency: Semi-Annually

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 03/07/2011
Date Data Arrived at EDR: 03/09/2011
Date Made Active in Reports: 05/02/2011
Number of Days to Update: 54

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 05/21/2015
Next Scheduled EDR Contact: 08/31/2015
Data Release Frequency: Varies

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 02/06/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 339

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 07/14/2015
Next Scheduled EDR Contact: 10/28/2015
Data Release Frequency: N/A

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 10/25/2013
Date Data Arrived at EDR: 10/17/2014
Date Made Active in Reports: 10/20/2014
Number of Days to Update: 3

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 05/14/2015
Next Scheduled EDR Contact: 08/24/2015
Data Release Frequency: Quarterly

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 11/25/2014
Date Data Arrived at EDR: 11/26/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 64

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 07/07/2015
Next Scheduled EDR Contact: 10/19/2015
Data Release Frequency: Varies

Financial Assurance 1: Financial Assurance Information Listing

Financial assurance information.

Date of Government Version: 04/07/2015
Date Data Arrived at EDR: 04/09/2015
Date Made Active in Reports: 05/11/2015
Number of Days to Update: 32

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 07/06/2015
Next Scheduled EDR Contact: 10/19/2015
Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 04/22/2013
Date Data Arrived at EDR: 03/03/2015
Date Made Active in Reports: 03/09/2015
Number of Days to Update: 6

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 05/14/2015
Next Scheduled EDR Contact: 08/24/2015
Data Release Frequency: Varies

COAL ASH: Coal Ash Disposal Site Listing

A listing of coal ash disposal site locations.

Date of Government Version: 07/05/2015
Date Data Arrived at EDR: 07/08/2015
Date Made Active in Reports: 07/22/2015
Number of Days to Update: 14

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 07/06/2015
Next Scheduled EDR Contact: 10/19/2015
Data Release Frequency: Varies

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 05/07/2015
Next Scheduled EDR Contact: 08/24/2015
Data Release Frequency: Quarterly

US AIRS MINOR: Air Facility System Data

A listing of minor source facilities.

Date of Government Version: 10/16/2014
Date Data Arrived at EDR: 10/31/2014
Date Made Active in Reports: 11/17/2014
Number of Days to Update: 17

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 06/22/2015
Next Scheduled EDR Contact: 10/22/2015
Data Release Frequency: Annually

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/16/2014
Date Data Arrived at EDR: 10/31/2014
Date Made Active in Reports: 11/17/2014
Number of Days to Update: 17

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 06/22/2015
Next Scheduled EDR Contact: 10/05/2015
Data Release Frequency: Annually

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 03/09/2015
Date Data Arrived at EDR: 03/10/2015
Date Made Active in Reports: 03/25/2015
Number of Days to Update: 15

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 05/14/2015
Next Scheduled EDR Contact: 08/31/2015
Data Release Frequency: Quarterly

Financial Assurance 2: Financial Assurance Information Listing

A listing of financial assurance information for hazardous waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 10/01/2014
Date Data Arrived at EDR: 01/06/2015
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 23

Source: Department of Environmental Conservation
Telephone: 518-402-8712
Last EDR Contact: 05/18/2015
Next Scheduled EDR Contact: 08/31/2015
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List

A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 07/01/2014
Date Data Arrived at EDR: 09/10/2014
Date Made Active in Reports: 10/20/2014
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 06/12/2015
Next Scheduled EDR Contact: 09/21/2015
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database

The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 02/01/2011
Date Data Arrived at EDR: 10/19/2011
Date Made Active in Reports: 01/10/2012
Number of Days to Update: 83

Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 05/01/2015
Next Scheduled EDR Contact: 08/10/2015
Data Release Frequency: Varies

COAL ASH DOE: Steam-Electric Plant Operation Data

A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 08/07/2009
Date Made Active in Reports: 10/22/2009
Number of Days to Update: 76

Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 07/13/2015
Next Scheduled EDR Contact: 10/28/2015
Data Release Frequency: Varies

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR US Hist Auto Stat: EDR Exclusive Historic Gas Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR US Hist Cleaners: EDR Exclusive Historic Dry Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/10/2014
Number of Days to Update: 193

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

COUNTY RECORDS

CORTLAND COUNTY:

Cortland County Storage Tank Listing
A listing of aboveground storage tank sites located in Cortland County.

Date of Government Version: 06/05/2015
Date Data Arrived at EDR: 06/09/2015
Date Made Active in Reports: 06/19/2015
Number of Days to Update: 10

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 05/04/2015
Next Scheduled EDR Contact: 08/17/2015
Data Release Frequency: Quarterly

Cortland County Storage Tank Listing
A listing of underground storage tank sites located in Cortland County.

Date of Government Version: 06/05/2015
Date Data Arrived at EDR: 06/09/2015
Date Made Active in Reports: 06/19/2015
Number of Days to Update: 10

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 05/04/2015
Next Scheduled EDR Contact: 08/17/2015
Data Release Frequency: Quarterly

NASSAU COUNTY:

Registered Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 11/20/2013
Date Data Arrived at EDR: 11/22/2013
Date Made Active in Reports: 02/11/2014
Number of Days to Update: 81

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 07/01/2015
Next Scheduled EDR Contact: 10/19/2015
Data Release Frequency: No Update Planned

Storage Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 05/04/2015
Next Scheduled EDR Contact: 08/17/2015
Data Release Frequency: Varies

Registered Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 11/20/2013
Date Data Arrived at EDR: 11/22/2013
Date Made Active in Reports: 02/11/2014
Number of Days to Update: 81

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 07/01/2015
Next Scheduled EDR Contact: 10/19/2015
Data Release Frequency: No Update Planned

Storage Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 05/04/2015
Next Scheduled EDR Contact: 08/17/2015
Data Release Frequency: Varies

ROCKLAND COUNTY:

Petroleum Bulk Storage Database
A listing of aboveground storage tank sites located in Rockland County.

Date of Government Version: 06/17/2015
Date Data Arrived at EDR: 06/19/2015
Date Made Active in Reports: 07/23/2015
Number of Days to Update: 34

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 06/08/2015
Next Scheduled EDR Contact: 09/21/2015
Data Release Frequency: Quarterly

Petroleum Bulk Storage Database
A listing of underground storage tank sites located in Rockland County.

Date of Government Version: 06/17/2015
Date Data Arrived at EDR: 06/19/2015
Date Made Active in Reports: 07/23/2015
Number of Days to Update: 34

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 06/08/2015
Next Scheduled EDR Contact: 09/21/2015
Data Release Frequency: Quarterly

SUFFOLK COUNTY:

Storage Tank Database
A listing of aboveground storage tank sites located in Suffolk County.

Date of Government Version: 03/03/2015
Date Data Arrived at EDR: 03/10/2015
Date Made Active in Reports: 03/23/2015
Number of Days to Update: 13

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 05/04/2015
Next Scheduled EDR Contact: 08/17/2015
Data Release Frequency: No Update Planned

Storage Tank Database
A listing of underground storage tank sites located in Suffolk County.

Date of Government Version: 03/03/2015
Date Data Arrived at EDR: 03/10/2015
Date Made Active in Reports: 03/23/2015
Number of Days to Update: 13

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 05/04/2015
Next Scheduled EDR Contact: 08/17/2015
Data Release Frequency: No Update Planned

WESTCHESTER COUNTY:

Listing of Storage Tanks
A listing of aboveground storage tank sites located in Westchester County.

Date of Government Version: 12/11/2014
Date Data Arrived at EDR: 12/12/2014
Date Made Active in Reports: 01/13/2015
Number of Days to Update: 32

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 05/04/2015
Next Scheduled EDR Contact: 08/17/2015
Data Release Frequency: Varies

Listing of Storage Tanks
A listing of underground storage tank sites located in Westchester County.

Date of Government Version: 12/11/2014
Date Data Arrived at EDR: 12/12/2014
Date Made Active in Reports: 01/13/2015
Number of Days to Update: 32

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 05/04/2015
Next Scheduled EDR Contact: 08/17/2015
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data
Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 07/30/2013
Date Data Arrived at EDR: 08/19/2013
Date Made Active in Reports: 10/03/2013
Number of Days to Update: 45

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 05/18/2015
Next Scheduled EDR Contact: 08/31/2015
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2012
Date Data Arrived at EDR: 04/29/2015
Date Made Active in Reports: 05/29/2015
Number of Days to Update: 30

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 07/13/2015
Next Scheduled EDR Contact: 10/28/2015
Data Release Frequency: Annually

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2013
Date Data Arrived at EDR: 07/21/2014
Date Made Active in Reports: 08/25/2014
Number of Days to Update: 35

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 07/20/2015
Next Scheduled EDR Contact: 11/02/2015
Data Release Frequency: Annually

RI MANIFEST: Manifest information
Hazardous waste manifest information

Date of Government Version: 12/31/2013
Date Data Arrived at EDR: 06/19/2015
Date Made Active in Reports: 07/15/2015
Number of Days to Update: 26

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 05/26/2015
Next Scheduled EDR Contact: 09/07/2015
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data
Hazardous waste manifest information.

Date of Government Version: 03/26/2015
Date Data Arrived at EDR: 06/03/2015
Date Made Active in Reports: 07/20/2015
Number of Days to Update: 47

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 07/20/2015
Next Scheduled EDR Contact: 11/02/2015
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 03/19/2015
Date Made Active in Reports: 04/07/2015
Number of Days to Update: 19

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 06/11/2015
Next Scheduled EDR Contact: 09/28/2015
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: PennWell Corporation
Telephone: 281-546-1505
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Electric Power Transmission Line Data
Source: PennWell Corporation
Telephone: 800-823-6277
This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Day Care Providers
Source: Department of Health
Telephone: 212-676-2444

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 2003 & 2011 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

STREET AND ADDRESS INFORMATION

© 2010 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

ROME TURNEY
109 CANAL STREET
ROME, NY 13440

TARGET PROPERTY COORDINATES

Latitude (North):	43.2084 - 43° 12' 30.24''
Longitude (West):	75.4583 - 75° 27' 29.88''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	462770.1
UTM Y (Meters):	4783844.5
Elevation:	439 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	5938529 ROME, NY
Version Date:	2013

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principal investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General South

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Target Property County	FEMA Flood Electronic Data
ONEIDA, NY	YES - refer to the Overview Map and Detail Map

Flood Plain Panel at Target Property:	3605420021B - FEMA Q3 Flood data
Additional Panels in search area:	3605420017B - FEMA Q3 Flood data 3605420023B - FEMA Q3 Flood data 3605420020B - FEMA Q3 Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
NOT AVAILABLE	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Status:	Not found

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

* ©1996 Site−specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT


Era:	Paleozoic
System:	Ordovician
Series:	Middle Ordovician (Mohawkian)
Code:	O2 *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Stratified Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

SSURGO SOIL MAP - 4366780.2s



Target Property
SSURGO Soil
Water

0 1/16 1/8 1/4 Miles

N

SITE NAME:	Rome Turney	CLIENT:	Bergmann Associates
ADDRESS:	109 Canal Street Rome NY 13440	CONTACT:	Megan Borruso
LAT/LONG:	43.2084 / 75.4583	INQUIRY #:	4366780.2s
		DATE:	July 28, 2015 1:37 pm

Copyright © 2015 EDR, Inc. © 2010 Tele Atlas Rel. 07/2009.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. The following information is based on Soil Conservation Service SSURGO data.

Soil Map ID: 1

Soil Component Name: URBAN LAND

Soil Surface Texture:
Hydrologic Group: Not reported

Soil Drainage Class:
Hydric Status: Unknown

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	5 inches		Not reported	Not reported	Max: Min:	Max: Min:

Soil Map ID: 2

Soil Component Name: CANANDAIGUA

Soil Surface Texture: silt loam

Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high water table, or are shallow to an impervious layer.

Soil Drainage Class: Poorly drained

Hydric Status: All hydric

Corrosion Potential - Uncoated Steel: High

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	16 inches	20 inches	silt loam	Not reported	Not reported	Max: 4 Min: 1.4	Max: 7.8 Min: 6.1
2	7 inches	16 inches	very fine sandy loam	Not reported	Not reported	Max: 4 Min: 1.4	Max: 7.8 Min: 6.1
3	33 inches	40 inches	silty clay loam	Not reported	Not reported	Max: 4 Min: 1.4	Max: 8.4 Min: 7.4
4	0 inches	7 inches	silt loam	Not reported	Not reported	Max: 4 Min: 1.4	Max: 7.8 Min: 6.1
5	20 inches	33 inches	silty clay loam	Not reported	Not reported	Max: 4 Min: 1.4	Max: 7.8 Min: 6.1
6	40 inches	72 inches	silt loam	Not reported	Not reported	Max: 4 Min: 1.4	Max: 8.4 Min: 7.4

Soil Map ID: 3

Soil Component Name: ALTON

Soil Surface Texture: very gravelly sandy loam

Hydrologic Group: Class A - High infiltration rates. Soils are deep, well drained to excessively drained sands and gravels.

Soil Drainage Class: Well drained

Hydric Status: Unknown

Corrosion Potential - Uncoated Steel: Low

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	24 inches	40 inches	very gravelly sandy loam	Not reported	Not reported	Max: 42 Min: 14	Max: 7.3 Min: 5.1
2	9 inches	24 inches	very gravelly fine sandy loam	Not reported	Not reported	Max: 42 Min: 14	Max: 7.3 Min: 5.1

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
3	0 inches	9 inches	gravelly loam	Not reported	Not reported	Max: 42 Min: 14	Max: 5.5 Min: 4.5
4	40 inches	57 inches	very gravelly sandy loam	Not reported	Not reported	Max: 42 Min: 14	Max: 7.3 Min: 5.1
5	57 inches	72 inches	very gravelly loamy sand	Not reported	Not reported	Max: 141 Min: 42	Max: 7.8 Min: 6.6

Soil Map ID: 4

Soil Component Name: WATER

Soil Surface Texture: very gravelly sandy loam

Hydrologic Group: Class A - High infiltration rates. Soils are deep, well drained to excessively drained sands and gravels.

Soil Drainage Class:
Hydric Status: Unknown

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

No Layer Information available.

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
A1	USGS40000874819	1/4 - 1/2 Mile WNW
A2	USGS40000874808	1/4 - 1/2 Mile WNW
A3	USGS40000874810	1/4 - 1/2 Mile WNW
A4	USGS40000874809	1/4 - 1/2 Mile WNW
5	USGS40000874807	1/4 - 1/2 Mile ENE
7	USGS40000874854	1/4 - 1/2 Mile ENE
8	USGS40000874639	1/4 - 1/2 Mile SSW
9	USGS40000874924	1/4 - 1/2 Mile NNW
10	USGS40000874627	1/2 - 1 Mile South
11	USGS40000874764	1/2 - 1 Mile East
12	USGS40000874640	1/2 - 1 Mile SW
13	USGS40000874620	1/2 - 1 Mile SE
14	USGS40000874619	1/2 - 1 Mile ESE

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
6	NY0002405	1/4 - 1/2 Mile NNE

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION


MAP ID	WELL ID	LOCATION FROM TP
No Wells Found		

OTHER STATE DATABASE INFORMATION

STATE OIL/GAS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
A1	NYOG70000038785	1/8 - 1/4 Mile East
2	NYOG70000038790	1/8 - 1/4 Mile NE
A3	NYOG70000038787	1/8 - 1/4 Mile East
4	NYOG70000038783	1/2 - 1 Mile ESE
B5	NYOG70000038794	1/2 - 1 Mile NW
6	NYOG70000038793	1/2 - 1 Mile NE
B7	NYOG70000038792	1/2 - 1 Mile NW
8	NYOG70000038795	1/2 - 1 Mile NE
9	NYOG70000038799	1/2 - 1 Mile NNE

PHYSICAL SETTING SOURCE MAP - 4366780.2s



- County Boundary
- Major Roads
- Contour Lines
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons
- Groundwater Flow Direction
- GI Indeterminate Groundwater Flow at Location
- GV Groundwater Flow Varies at Location
- HD Closest Hydrogeological Data
- Oil, gas or related wells

SITE NAME:	Rome Turney	CLIENT:	Bergmann Associates
ADDRESS:	109 Canal Street Rome NY 13440	CONTACT:	Megan Borruso
LAT/LONG:	43.2084 / 75.4583	INQUIRY #:	4366780.2s
		DATE:	July 28, 2015 1:37 pm

Copyright © 2015 EDR, Inc. © 2010 Tele Atlas Rel. 07/2009.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

A1
WNW
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000874819**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-431235075275101		
Monloc name:	OE1449		
Monloc type:	Well: Test hole not completed as a well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	43.2097917
Longitude:	-75.4637863	Sourcemap scale:	24000
Horiz Acc measure:	5	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	432.8
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	19450415	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	89
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1945-04-15	6.8	

A2
WNW
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000874808**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-431234075275401		
Monloc name:	OE 55		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	43.2095139
Longitude:	-75.4646196	Sourcemap scale:	24000
Horiz Acc measure:	10	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	440
Vert measure units:	feet	Vertacc measure val:	20
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Utica Shale		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

A3
WNW **FED USGS** **USGS40000874810**
1/4 - 1/2 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-431234075275403		
Monloc name:	OE 57		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	43.2095139
Longitude:	-75.4646196	Sourcemap scale:	24000
Horiz Acc measure:	10	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	440
Vert measure units:	feet	Vertacc measure val:	20
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Utica Shale		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

A4
WNW **FED USGS** **USGS40000874809**
1/4 - 1/2 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-431234075275402		
Monloc name:	OE 56		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	43.2095139
Longitude:	-75.4646196	Sourcemap scale:	24000
Horiz Acc measure:	10	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	440
Vert measure units:	feet	Vertacc measure val:	20
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Utica Shale		

Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

5
ENE **FED USGS** **USGS40000874807**
1/4 - 1/2 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-431234075270801		
Monloc name:	OE1450		
Monloc type:	Well: Test hole not completed as a well		
Monloc desc:	Not Reported		
Huc code:	02020004	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	43.209514
Longitude:	-75.4518413	Sourcemap scale:	24000
Horiz Acc measure:	5	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	435.5
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	70
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1948-04	18	

6
NNE **FRDS PWS** **NY0002405**
1/4 - 1/2 Mile
Higher

PWS ID:	NY0002405		
Date Initiated:	Not Reported	Date Deactivated:	Not Reported
PWS Name:	ROME CITY CITY HALL ROME, NY 13440		
Addressee / Facility:	System Owner/Responsible Party EILENBERG CARL CITY OF ROME CITY HALL ROME, NY 13440		

Addressee / Facility:	System Owner/Responsible Party GRIFFO JOSEPH CITY OF ROME STOKES-LEE CENTER ROAD LEE CENTER, NY 13363		
Facility Latitude:	43 20 14	Facility Longitude:	075 34 54
Facility Latitude:	43 12 46	Facility Longitude:	075 27 21
City Served:	ROME		
Treatment Class	Not Reported	Population:	Not Reported

Violations information not reported.

7
ENE **FED USGS** **USGS40000874854**
1/4 - 1/2 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-431240075270801		
Monloc name:	OE1336		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02020004	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	43.2111806
Longitude:	-75.4518413	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	431
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	1910	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	34
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

8
SSW **FED USGS** **USGS40000874639**
1/4 - 1/2 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-431206075274301		
Monloc name:	OE1411		
Monloc type:	Well: Test hole not completed as a well		
Monloc desc:	Not Reported		
Huc code:	02020004	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	43.2017362
Longitude:	-75.4615639	Sourcemap scale:	24000

Horiz Acc measure:	5	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	427.5
Vert measure units:	feet	Vertacc measure val:	10
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	22
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

9
NNW **FED USGS** **USGS40000874924**
1/4 - 1/2 Mile
Higher

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-431252075275001		
Monloc name:	OE 145		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	43.2145139
Longitude:	-75.4635085	Sourcemap scale:	24000
Horiz Acc measure:	10	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	460
Vert measure units:	feet	Vertacc measure val:	20
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Utica Shale		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	Not Reported
Wellholedepth units:	Not Reported		

Ground-water levels, Number of Measurements: 0

10
South **FED USGS** **USGS40000874627**
1/2 - 1 Mile
Lower

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-431204075272601		
Monloc name:	OE1410		
Monloc type:	Well: Test hole not completed as a well		
Monloc desc:	Not Reported		
Huc code:	02020004	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	43.2011806
Longitude:	-75.4568415	Sourcemap scale:	24000

Horiz Acc measure:	5	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	430.3
Vert measure units:	feet	Vertacc measure val:	10
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	23
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

11
East
1/2 - 1 Mile
Higher

FED USGS **USGS40000874764**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-431225075265101		
Monloc name:	OE1342		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02020004	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	43.207014
Longitude:	-75.4471189	Sourcemap scale:	24000
Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	445
Vert measure units:	feet	Vertacc measure val:	10
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	18970410	Welldepth:	1632
Welldepth units:	ft	Wellholedepth:	1632
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

12
SW
1/2 - 1 Mile
Lower

FED USGS **USGS40000874640**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-431206075280301		
Monloc name:	OE1335		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	Not Reported	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	43.2017362
Longitude:	-75.4671197	Sourcemap scale:	24000

Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	426.1
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	1910	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	23
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

13
SE
1/2 - 1 Mile
Lower

FED USGS **USGS40000874620**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-431203075264601		
Monloc name:	OE1409		
Monloc type:	Well: Test hole not completed as a well		
Monloc desc:	Not Reported		
Huc code:	02020004	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	43.2009028
Longitude:	-75.4457299	Sourcemap scale:	24000
Horiz Acc measure:	5	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	430.7
Vert measure units:	feet	Vertacc measure val:	10
Vert accmeasure units:	feet		
Vertcollection method:	Interpolated from topographic map		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	Not Reported	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	30
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

14
ESE
1/2 - 1 Mile
Lower

FED USGS **USGS40000874619**

Org. Identifier:	USGS-NY		
Formal name:	USGS New York Water Science Center		
Monloc Identifier:	USGS-431203075263301		
Monloc name:	OE1337		
Monloc type:	Well		
Monloc desc:	Not Reported		
Huc code:	02020004	Drainagearea value:	Not Reported
Drainagearea Units:	Not Reported	Contrib drainagearea:	Not Reported
Contrib drainagearea units:	Not Reported	Latitude:	43.2009029
Longitude:	-75.4421186	Sourcemap scale:	24000

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Horiz Acc measure:	1	Horiz Acc measure units:	seconds
Horiz Collection method:	Interpolated from map		
Horiz coord refsys:	NAD83	Vert measure val:	430.3
Vert measure units:	feet	Vertacc measure val:	0.1
Vert accmeasure units:	feet		
Vertcollection method:	Level or other surveying method		
Vert coord refsys:	NGVD29	Countrycode:	US
Aquifername:	Not Reported		
Formation type:	Not Reported		
Aquifer type:	Not Reported		
Construction date:	1910	Welldepth:	Not Reported
Welldepth units:	Not Reported	Wellholedepth:	30
Wellholedepth units:	ft		

Ground-water levels, Number of Measurements: 0

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance

Database EDR ID Number

A1
East
1/8 - 1/4 Mile

OIL_GAS **NYOG70000038785**

Api wellno:	31065007090000	Cnty:	Oneida
Hole:	00709	Sidetrck:	0
Completion:	0		
Well nm:	Fee		
Coname:	Not Reported		
Opno:	0		
Dt approv:	18-JUN-81	Dt spud:	01-JAN-00
Dt comp:	01-JAN-00	Well typ:	Gas Development
Dtd:	1005		
Wl status:	Unknown	Town:	Rome
Field:	Rome	Prodform:	Trenton
Xloc:	-75.45423		
Yloc:	43.20813		
Confid:	Well does not have confidential information.		
Wellst:	Gas Well		
Quad:	Rome	Quadsec:	E
Deepestfor:	Trenton	Elevation:	425
Dt mod:	24-JAN-03	Site id:	NYOG70000038785

2
NE
1/8 - 1/4 Mile

OIL_GAS **NYOG70000038790**

Api wellno:	31065088800000	Cnty:	Oneida
Hole:	08880	Sidetrck:	0
Completion:	0		
Well nm:	Ft Stanwix 1		
Coname:	Rome Urban Renewal Agency		
Opno:	9038		
Dt approv:	01-OCT-58	Dt spud:	25-OCT-58
Dt comp:	30-DEC-58	Well typ:	Gas Development
Dtd:	0		
Wl status:	Plugged and Abandoned	Town:	Rome
Field:	Rome	Prodform:	Not Applicable
Xloc:	-75.45517		
Yloc:	43.21074		
Confid:	Well does not have confidential information.		
Wellst:	Gas Well Plugged		
Quad:	Rome	Quadsec:	B
Deepestfor:	Not Applicable	Elevation:	445
Dt mod:	15-SEP-95	Site id:	NYOG70000038790

A3
East
1/8 - 1/4 Mile

OIL_GAS **NYOG70000038787**

Api wellno:	31065007070000	Cnty:	Oneida
Hole:	00707	Sidetrck:	0
Completion:	0		
Well nm:	Brass & Copper 1		
Coname:	Not Reported		
Opno:	0		
Dt approv:	18-JUN-81	Dt spud:	01-JAN-00
Dt comp:	01-SEP-36	Well typ:	Gas Development
Dtd:	1598		
Wl status:	Unknown	Town:	Rome
Field:	Rome	Prodform:	Trenton
Xloc:	-75.45366		
Yloc:	43.20882		
Confid:	Well does not have confidential information.		
Wellst:	Gas Well		
Quad:	Rome	Quadsec:	B
Deepestfor:	Pre-Cambrian	Elevation:	0
Dt mod:	24-JAN-03	Site id:	NYOG70000038787

4
ESE **OIL_GAS** **NYOG70000038783**
1/2 - 1 Mile

Api wellno:	31065010270000	Cnty:	Oneida
Hole:	01027	Sidetrck:	0
Completion:	0		
Well nm:	Rome Brass & Copper 2		
Coname:	Rome Brass & Copper		
Opno:	9516		
Dt approv:	18-JUN-81	Dt spud:	01-JAN-00
Dt comp:	22-MAY-36	Well typ:	Gas Development
Dtd:	1632		
Wl status:	Unknown	Town:	Rome
Field:	Rome	Prodform:	Trenton
Xloc:	-75.44745		
Yloc:	43.20679		
Confid:	Well does not have confidential information.		
Wellst:	Gas Well		
Quad:	Rome	Quadsec:	E
Deepestfor:	Pre-Cambrian	Elevation:	420
Dt mod:	24-JAN-03	Site id:	NYOG70000038783

B5
NW **OIL_GAS** **NYOG70000038794**
1/2 - 1 Mile

Api wellno:	31065615480000	Cnty:	Oneida
Hole:	61548	Sidetrck:	0
Completion:	0		
Well nm:	Finley 1		
Coname:	Not Reported		
Opno:	0		
Dt approv:	11-DEC-85	Dt spud:	23-OCT-85
Dt comp:	11-NOV-85	Well typ:	Gas Development
Dtd:	0		
Wl status:	Not Reported on AWR	Town:	Rome
Field:	Rome	Prodform:	Not Applicable

Xloc:	-75.46772		
Yloc:	43.21528		
Confid:	Well does not have confidential information.		
Wellst:	Gas Well		
Quad:	Rome	Quadsec:	A
Deepestfor:	Not Applicable	Elevation:	0
Dt mod:	22-SEP-05	Site id:	NYOG70000038794

6
NE **OIL_GAS** **NYOG70000038793**
1/2 - 1 Mile

Api wellno:	31065007030000	Cnty:	Oneida
Hole:	00703	Sidetrck:	0
Completion:	0		
Well nm:	Humprey, C. M.		
Coname:	Not Reported		
Opno:	0		
Dt approv:	18-JUN-81	Dt spud:	05-NOV-35
Dt comp:	01-JAN-00	Well typ:	Dry Hole
Dtd:	0		
Wl status:	Unknown	Town:	Rome
Field:	Rome	Prodform:	Not Applicable
Xloc:	-75.44822		
Yloc:	43.21514		
Confid:	Well does not have confidential information.		
Wellst:	Dry Hole		
Quad:	Rome	Quadsec:	B
Deepestfor:	Not Applicable	Elevation:	0
Dt mod:	24-JAN-03	Site id:	NYOG70000038793

B7
NW **OIL_GAS** **NYOG70000038792**
1/2 - 1 Mile

Api wellno:	31065006990000	Cnty:	Oneida
Hole:	00699	Sidetrck:	0
Completion:	0		
Well nm:	Fee 1		
Coname:	Not Reported		
Opno:	0		
Dt approv:	18-JUN-81	Dt spud:	01-JAN-35
Dt comp:	01-JAN-00	Well typ:	Gas Development
Dtd:	1125		
Wl status:	Unknown	Town:	Rome
Field:	Rome	Prodform:	Not Applicable
Xloc:	-75.46857		
Yloc:	43.21514		
Confid:	Well does not have confidential information.		
Wellst:	Gas Well		
Quad:	Rome	Quadsec:	A
Deepestfor:	Not Applicable	Elevation:	0
Dt mod:	24-JAN-03	Site id:	NYOG70000038792

Map ID
Direction
Distance

Database EDR ID Number

8
NE
1/2 - 1 Mile

OIL_GAS **NYOG70000038795**

Api wellno:	31065007000000	Cnty:	Oneida
Hole:	00700	Sidetrck:	0
Completion:	0		
Well nm:	Ft Stanwick Mfg Co		
Coname:	Not Reported		
Opno:	0		
Dt approv:	18-JUN-81	Dt spud:	01-JAN-35
Dt comp:	23-NOV-36	Well typ:	Gas Development
Dtd:	820		
Wl status:	Unknown	Town:	Rome
Field:	Rome	Prodform:	Trenton
Xloc:	-75.44606		
Yloc:	43.21583		
Confid:	Well does not have confidential information.		
Wellst:	Gas Well		
Quad:	Rome	Quadsec:	B
Deepestfor:	Trenton	Elevation:	0
Dt mod:	24-JAN-03	Site id:	NYOG70000038795

9
NNE
1/2 - 1 Mile

OIL_GAS **NYOG70000038799**

Api wellno:	31065007050000	Cnty:	Oneida
Hole:	00705	Sidetrck:	0
Completion:	0		
Well nm:	Hazleton		
Coname:	Not Reported		
Opno:	0		
Dt approv:	18-JUN-81	Dt spud:	01-FEB-36
Dt comp:	01-JAN-00	Well typ:	Gas Development
Dtd:	1000		
Wl status:	Unknown	Town:	Rome
Field:	Rome	Prodform:	Not Applicable
Xloc:	-75.45123		
Yloc:	43.22092		
Confid:	Well does not have confidential information.		
Wellst:	Gas Well		
Quad:	Rome	Quadsec:	B
Deepestfor:	Not Applicable	Elevation:	0
Dt mod:	24-JAN-03	Site id:	NYOG70000038799

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

State Database: NY Radon

Radon Test Results

County	Town	Num Tests	Avg Result	Geo Mean	Max Result
ONEIDA	ANNSVILLE	11	5.77	2.34	31.2
ONEIDA	AUGUSTA	19	4.04	2.44	15.2
ONEIDA	AVA	15	9.59	4.19	40.9
ONEIDA	BOONVILLE	26	3.63	1.77	23.3
ONEIDA	BRIDGEWATER	11	7.75	5.55	24.1
ONEIDA	CAMDEN	24	4.97	3.07	15.7
ONEIDA	DEERFIELD	28	10.45	4.31	87.5
ONEIDA	FLOYD	14	13.71	4.54	107.8
ONEIDA	FORESTPORT	3	1.07	0.76	1.7
ONEIDA	KIRKLAND	130	6.42	3.82	49.3
ONEIDA	LEE	49	12.92	6.83	51.4
ONEIDA	MARCY	63	3.92	2.29	19.3
ONEIDA	MARSHALL	15	4.81	3.51	14.4
ONEIDA	NEW HARTFORD	257	4.45	2.71	40.6
ONEIDA	PARIS	61	8.11	5.22	55.8
ONEIDA	REMSEN	33	4.59	2.99	22.4
ONEIDA	ROME	377	8.37	4.1	102.8
ONEIDA	SANGERFIELD	21	4.35	3.79	13.8
ONEIDA	SHERRILL	58	2.39	1.57	13.2
ONEIDA	STEUBEN	3	13.6	7.9	28.3
ONEIDA	TRENTON	58	7.35	3.54	92.2
ONEIDA	UTICA	467	4.37	2.17	57
ONEIDA	VERNON	53	3.44	2.07	20.2
ONEIDA	VERONA	25	3.26	1.78	22.2
ONEIDA	VIENNA	6	1.17	0.98	2.4
ONEIDA	WESTERN	20	11.43	7.1	30.8
ONEIDA	WESTMORELAND	40	4.03	2.4	24.4
ONEIDA	WHITESTOWN	234	3.46	2.32	25.3

Federal EPA Radon Zone for ONEIDA County: 2

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for ONEIDA COUNTY, NY

Number of sites tested: 158

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area	1.380 pCi/L	86%	13%	1%
Basement	2.610 pCi/L	69%	27%	4%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Scanned Digital USGS 7.5' Topographic Map (DRG)
Source: United States Geologic Survey
A digital raster graphic (DRG) is a scanned image of a U.S. Geological Survey topographic map. The map images are made by scanning published paper maps on high-resolution scanners. The raster image is georeferenced and fit to the Universal Transverse Mercator (UTM) projection.

HYDROLOGIC INFORMATION

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 2003 & 2011 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Services
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Services (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Services, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

New York Public Water Wells
Source: New York Department of Health
Telephone: 518-458-6731

OTHER STATE DATABASE INFORMATION

Oil and Gas Well Database
Department of Environmental Conservation
Telephone: 518-402-8072
These files contain records, in the database, of wells that have been drilled.

RADON

State Database: NY Radon
Source: Department of Health
Telephone: 518-402-7556
Radon Test Results

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STREET AND ADDRESS INFORMATION

© 2010 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

APPENDIX C

FOIL REQUESTS/FOIL RESPONSES

July 28, 2015
Regional Freedom of Information Officer
U.S. EPA, Region 2
290 Broadway
New York, NY 10007-1866

Re: Freedom of Information Request

Dear Sir or Madam:

Bergmann Associates has been retained to conduct a Phase I Environmental Site Assessment on the properties below. Bergmann Associates requests copies of environmental files, records, and memoranda concerning the following properties (see attached map):

Former Rome Turney Radiator Co.
109 Canal Street
Rome NY 13440

100 Jasper Street
Rome NY 13440

This information should include: 1) past and present aboveground and/or underground storage tank registration(s); 2) reported spills or releases of hazardous substances; 3) generation, storage, treatment, or disposal of hazardous substances; 4) past and present groundwater, surface water, and soil investigations and/or remediation; 5) environmental permits/violations; and 6) Environmental Liens or Activity Use Limitations (AULs).

We will gladly pay copying costs.

Please let us know if you can accommodate this request in an expedient manner. We would like to schedule an appointment to copy the files/records if this is not possible.

Please email if you have any questions.

Very truly yours,
Bergmann Associates, PC



MEGAN E. BORRUSO
Environmental Specialist
mborruso@bergmannpc.com


RAMP
JAMES ST
RAMP
CANAL ST
RAMP
LAWRENCE ST
AVENUE A
MASSOCK AVE
ERIE BLVD
ERIE BLVD
JASPER ST
BOUCK ST

July 28, 2015
Records Access Officer
New York State Department of Environmental Conservation
625 Broadway
Albany, NY 12233-1500

Re: Freedom of Information Request

Dear Sir or Madam:

Bergmann Associates has been retained to conduct a Phase I Environmental Site Assessment on the properties below. Bergmann Associates requests copies of environmental files, records, and memoranda concerning the following properties (see attached map):

Former Rome Turney Radiator Co.
109 Canal Street
Rome NY 13440
Spill Number 8802056 PBS Number 6-389331

100 Jasper Street
Rome NY 13440


This information should include: 1) past and present aboveground and/or underground storage tank registration(s); 2) reported spills or releases of hazardous substances; 3) generation, storage, treatment, or disposal of hazardous substances; 4) past and present groundwater, surface water, and soil investigations and/or remediation; 5) environmental permits/violations; and 6) Environmental Liens or Activity Use Limitations (AULs).

We will gladly pay copying costs.

Please let us know if you can accommodate this request in an expedient manner. We would like to schedule an appointment to copy the files/records if this is not possible.

Please email if you have any questions.

Very truly yours,
Bergmann Associates, PC



MEGAN E. BORRUSO
Environmental Specialist
mborruso@bergmannpc.com


RAMP
RAMP
RAMP
JAMES ST
CANAL ST
LAWRENCE ST
AVENUE A
MASSOCK AVE
JASPER ST
ERIE BLVD
ERIE BLVD
BUICK ST

July 28, 2015
Freedom of Information Officer
New York State Department of Environmental Conservation, Region 6
317 Washington St.
Watertown, NY 13601

Re: Freedom of Information Request

Dear Sir or Madam:

Bergmann Associates has been retained to conduct a Phase I Environmental Site Assessment on the properties below. Bergmann Associates requests copies of environmental files, records, and memoranda concerning the following properties (see attached map):

Former Rome Turney Radiator Co.
109 Canal Street
Rome NY 13440
Spill Number 8802056 PBS Number 6-389331

100 Jasper Street
Rome NY 13440

This information should include: 1) past and present aboveground and/or underground storage tank registration(s); 2) reported spills or releases of hazardous substances; 3) generation, storage, treatment, or disposal of hazardous substances; 4) past and present groundwater, surface water, and soil investigations and/or remediation; 5) environmental permits/violations; and 6) Environmental Liens or Activity Use Limitations (AULs).

We will gladly pay copying costs.

Please let us know if you can accommodate this request in an expedient manner. We would like to schedule an appointment to copy the files/records if this is not possible.

Please email if you have any questions.

Very truly yours,
Bergmann Associates, PC

Megan E. Borruso

MEGAN E. BORRUSO
Environmental Specialist
mborruso@bergmannpc.com


RAMP
RAMP
RAMP
JAMES ST
CANAL ST
LAWRENCE ST
AVENUE A
MASSOCK AVE
JASPER ST
ERIE BLVD
ERIE BLVD
BUICK ST

July 28, 2015
Records Access Office
New York State Department of Health
Corning Tower Room 2364
Albany, New York 12237-0044

Re: Freedom of Information Request

Dear Sir or Madam:

Bergmann Associates has been retained to conduct a Phase I Environmental Site Assessment on the properties below. Bergmann Associates requests copies of environmental files, records, and memoranda concerning the following properties (see attached map):

Former Rome Turney Radiator Co.
109 Canal Street
Rome NY 13440

100 Jasper Street
Rome NY 13440

This information should include: 1) past and present aboveground and/or underground storage tank registration(s); 2) reported spills or releases of hazardous substances; 3) generation, storage, treatment, or disposal of hazardous substances; 4) past and present groundwater, surface water, and soil investigations and/or remediation; 5) environmental permits/violations; and 6) Environmental Liens or Activity Use Limitations (AULs).

We will gladly pay copying costs.

Please let us know if you can accommodate this request in an expedient manner. We would like to schedule an appointment to copy the files/records if this is not possible.

Please email if you have any questions.

Very truly yours,
Bergmann Associates, PC



MEGAN E. BORRUSO
Environmental Specialist
mborruso@bergmannpc.com


RAMP
RAMP
RAMP
JAMES ST
CANAL ST
LAWRENCE ST
AVENUE A
MASSOCK AVE
JASPER ST
ERIE BLVD
ERIE BLVD
BUICK ST

July 28, 2015
Records Access Office
Oneida County Department of Planning
321 Main Street
Utica, New York 13501

Re: Freedom of Information Request

Dear Sir or Madam:

Bergmann Associates has been retained to conduct a Phase I Environmental Site Assessment on the properties below. Bergmann Associates requests copies of environmental files, records, and memoranda concerning the following properties (see attached map):

Former Rome Turney Radiator Co.
109 Canal Street
Rome NY 13440

100 Jasper Street
Rome NY 13440

This information should include: 1) past and present aboveground and/or underground storage tank registration(s); 2) reported spills or releases of hazardous substances; 3) generation, storage, treatment, or disposal of hazardous substances; 4) past and present groundwater, surface water, and soil investigations and/or remediation; 5) environmental permits/violations; and 6) Environmental Liens or Activity Use Limitations (AULs).

We will gladly pay copying costs.

Please let us know if you can accommodate this request in an expedient manner. We would like to schedule an appointment to copy the files/records if this is not possible.

Please email if you have any questions.

Very truly yours,
Bergmann Associates, PC



MEGAN E. BORRUSO
Environmental Specialist
mborruso@bergmannpc.com


RAMP
RAMP
RAMP
JAMES ST
CANAL ST
LAWRENCE ST
AVENUE A
MASSOCK AVE
JASPER ST
ERIE BLVD
ERIE BLVD
BUICK ST

July 28, 2015
Records Access Office
Rome City Hall
198 N. Washington Street
Rome, NY 13440

Re: Freedom of Information Request

Dear Sir or Madam:

Bergmann Associates has been retained to conduct a Phase I Environmental Site Assessment on the properties below. Bergmann Associates requests copies of environmental files, records, and memoranda concerning the following properties (see attached map):

Former Rome Turney Radiator Co.
109 Canal Street
Rome NY 13440

100 Jasper Street
Rome NY 13440

This information should include: 1) past and present aboveground and/or underground storage tank registration(s); 2) reported spills or releases of hazardous substances; 3) generation, storage, treatment, or disposal of hazardous substances; 4) past and present groundwater, surface water, and soil investigations and/or remediation; 5) environmental permits/violations; and 6) Environmental Liens or Activity Use Limitations (AULs).

We will gladly pay copying costs.

Please let us know if you can accommodate this request in an expedient manner. We would like to schedule an appointment to copy the files/records if this is not possible.

Please email if you have any questions.

Very truly yours,
Bergmann Associates, PC



MEGAN E. BORRUSO
Environmental Specialist
mborruso@bergmannpc.com


RAMP
RAMP
RAMP
JAMES ST
LAWRENCE ST
AVENUE 4
CANAL ST
MASSOCK AVE
JASPER ST
ERIE BLVD
ERIE BLVD
BUICK ST

NYS Department of Environmental Conservation
Office of General Counsel
625 Broadway, Albany, New York 12233-1500
(518) 402-9018 (Fax)

FOIL Request No. 15-3139
8/7/2015

Joe Martens
Commissioner

Ms. Megan Borruso
Bergmann Associates
28 East Main Street 200 First Federal Plaza
Rochester, NY 14614-1909

Dear Ms. Borruso:

This is to acknowledge receipt of your Freedom of Information Law request seeking records regarding: **Former Rome Turney Radiator Co., 109 Canal St., Rome, NY 13440, Spill 8802056, PBS 6-389331; 100 Jasper St., Rome, NY 13440.**

I have referred your request to the following Records Custodian(s) / Freedom of Information Law Coordinator(s) who may possess the records you are requesting:

FOIL COORDINATOR - Region 6
State Office Building 317 Washington Street
Watertown, NY 13601-3787 (315) 785-2513

You may expect a response to your request by **9/4/2015.**

If I can be of further assistance, please contact me at (518) 402-9522 . Refer to request number **15-3139** , if you write or call.

Sincerely,

Ruth L. Earl
Records Access Officer

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION

Region 6 Sub-office
207 Genesee Street, Utica, NY 13501-2885
P: (315) 793-2554 | F: (315) 793-2748
www.dec.ny.gov

via e-mail: mborruso@bergmannpc.com

August 5, 2015

Megan E. Borrusoo, Environmental Specialist
Bergmann Associates
200 First Federal Plaza
28 East Main Street
Rochester, NY 14614-1909

Re: Freedom of Information Request No. U15-99
109 Canal Street, Rome, NY 13440
Formerly: Rome Turney Radiator Company
Current Owner: City of Rome
Tax Map No. 242-066-0001-001
(Include Spill 88-02056/PBS 6-389331)

Dear Ms. Borruso:

This is to acknowledge receipt of the above-referenced request received in New York State's Department of Environmental Conservation, Region 6, Utica sub-office on July 31, 2015. I will consult with the appropriate program personnel and inform you of my findings.

I expect to fulfill your request within 20 days. If there is a problem of some concern that needs to be addressed before then, or for inquiries regarding the status of this request, please contact Kathleen Tripepi at 315-793-2590.

Sincerely,

Nels G. Magnuson
Assistant Regional Attorney

kt

File

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION

Region 6 Sub-office
207 Genesee Street, Utica, NY 13501-2885
P: (315) 793-2554 | F: (315) 793-2748
www.dec.ny.gov

via e-mail: mborruso@bergmannpc.com

August 20, 2015

Megan E. Borruso, Environmental Specialist
Bergmann Associates
200 First Federal Plaza
28 East Main Street
Rochester, NY 14614-1909

Re: Freedom of Information Request No. U15-99
109 Canal Street, Rome, NY 13440
Formerly: Rome Turney Radiator Company
Current Owner: City of Rome
Tax Map No. 242-066-0001-001
(Include Spill 88-02056/PBS 6-389331

Dear Ms. Borruso:

The information you requested that resides in the Utica sub-office is ready to be reviewed or copied. This information can be reviewed in Utica by appointment. Please contact Kathleen Tripepi at (315) 793-2590 to schedule an appointment.

In order for copies to be made of this material, you will need to contact a private copy service. You will be responsible for payment directly to them, and they will send you copies of the material. We estimate approximately 359 copies. Two copying services we are aware of in this area are Avalon Copy Service, (315-724-5555) and Data Flow, (315-735-6131).

There are 32 pages being withheld from your request. These pages are being withheld in accordance with Article VI, §87.2(b, d, and g) of the Public Officers Law as they constitute personal privacy, trade secrets, or intra-agency materials. You may appeal this decision within 30 days by writing to:

FOIL Appeals Officer
Office of General Counsel
New York State Department of Environmental Conservation
25 Broadway
Albany, NY 12233-1500

I refer you to 6 NYCRR §616.28 for further details regarding the appeals process.

If you are no longer interested in this information, please let us know so we can close out the FOIL.

Sincerely,



Nels G. Magnuson
Assistant Regional Attorney

kt

File

NEW YORK
STATE OF
OPPORTUNITY.
Department
of Health

ANDREW M. CUOMO
Governor

HOWARD A. ZUCKER, M.D., J.D.
Commissioner

SALLY DRESLIN, M.S., R.N.
Executive Deputy Commissioner

July 31, 2015

Megan E. Borruso
Bergmann Associates
28 East Main Street
200 First Federal Plaza
Rochester, NY 14614

FOIL # 15-07-574
Canal Street and Jasper Street

Dear Ms. Borruso:

This will acknowledge receipt of your request for records under the Freedom of Information Law, received by this office on July 31, 2015.

Your request has been forwarded to the appropriate Department program area(s) to identify documents that are responsive to your request and which may be made available pursuant to all applicable provisions of the Freedom of Information Law.

A determination as to whether your request is granted or denied will be reached in approximately 20 business days or we will notify you in writing if the responsible program area(s) should require additional time to locate, assemble, and review documents that may be responsive to your request.

Please note that, pursuant to Article 6 of the Public Officers Law, a charge may be applied to your request, including the actual cost of the medium used to respond to your Freedom of Information Law request and/or other related costs. When responsive records have been identified, you will be informed of any cost and how payment should be made.

Sincerely,

Shayla Johnson
Records Access Office

ANTHONY J. PICENTE, JR., *County Executive*
JOHN R. KENT, Jr., *Commissioner*

(315) 798-5710
FAX (315) 798-5852
planning@ocgov.net

Boehlert Center at UNION STATION

Oneida County Department of Planning

Boehlert Center at Union Station, 321 Main Street, Utica, NY 13501

August 3, 2015

Ms. Megan E. Borruso, Environmental Specialist
Bergmann Associates
28 East Main Street
200 First Federal Plaza
Rochester, New York 14614-1909

RE: Freedom of Information Request for the former Rome Turney Radiator Co., 109 Canal Street, Rome, NY & 100 Jasper Street, Rome, NY

Dear Ms. Borruso,

In reference to the above-mentioned request, we have searched our records and we do not have any of the information you requested. We recommend you contact the Utica Office of Region 6 of the New York State Department of Environmental Conservation. The Utica Office is located at 207 Genesee Street, Utica, NY 13501 and their phone number is (315) 793-2554.

Please do not hesitate to contact this office if you have any questions on this matter.

Sincerely,

John R. Kent, Jr.

John R. Kent, Jr.
Commissioner

Cc: Michael C. Clancy, Oneida County Legislator, 4th District

Louise S. Glasso, CMC
City Clerk

Eric R. Seelig
Deputy City Clerk

OFFICE OF THE CITY CLERK
Rome City Hall, 198 N. Washington Street
Rome, New York 13440-5815
Telephone: (315) 339-7659 Fax: (315) 838-1160
www.romenewyork.com

July 30, 2015

Megan E. Borruso
28 E. Main Street
200 First Federal Plaza
Rochester, NY 14614-1909

RE: 7/30/2015 FOIL Request – 109 Canal St. & 100 Jasper St.

Dear Ms. Borruso:

Our office received your request for records pursuant to the Freedom of Information Law on 7/30/2015.

Please be advised that the Codes Enforcement Office and the Department of Public Works have advised that they are not in possession of any records that correspond to your request.

You have thirty (30) days from receipt of a denial of access to records or portions thereof to appeal to the governing body of the City of Rome.

Please feel free to contact our office if we may be of any further assistance.

Sincerely,

Eric R. Seelig
Deputy City Clerk, Records Access Officer

Louise S. Glasso, CMC
City Clerk

Eric R. Seelig
Deputy City Clerk

OFFICE OF THE CITY CLERK
Rome City Hall, 198 N. Washington Street
Rome, New York 13440-5815
Telephone: (315) 339-7659 Fax: (315) 838-1160
www.romenewyork.com

July 30, 2015

Megan E. Borruso
Bergmann Associates
28 E. Main Street
200 First Federal Plaza
Rochester, NY 14614-1909

RE: FOIL Records Request – 109 Canal St. & 100 Jasper St.

Dear Ms. Borruso:

Please be advised that your Freedom of Information Request was received in our office on 7/30/2015. We are currently in the process of seeking the information that you have requested. We will notify you within the next twenty (20) business days when our review is complete. If we should find that more time is required, we will inform you.

Additionally, please be aware that a rate of twenty-five cents **($.25) per page** will be charged for any request requiring photocopying, and/or the actual cost of reproducing the record(s), if necessary.

Please feel free to call the City Clerk's office at (315) 339-7659 should you have any questions or concerns in this regard.

Sincerely,

Eric R. Seelig
Deputy City Clerk, Records Access Officer

APPENDIX D

HISTORIC TOPOGRAPHIC MAPS

Rome Turney
109 Canal Street
Rome, NY 13440

Inquiry Number: 4366780.4
July 28, 2015

EDR Historical Topographic Map Report

6 Armstrong Road, 4th Floor
Shelton, Connecticut 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Historical Topographic Map Report

Environmental Data Resources, Inc.s (EDR) Historical Topographic Map Report is designed to assist professionals in evaluating potential liability on a target property resulting from past activities. EDRs Historical Topographic Map Report includes a search of a collection of public and private color historical topographic maps, dating back to the early 1900s.

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report AS IS. Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2015 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Historical Topographic Map




N	TARGET QUAD NAME: ORISKANY MAP YEAR: 1898 SERIES: 15 SCALE: 1:62500	SITE NAME: Rome Turney ADDRESS: 109 Canal Street Rome, NY 13440 LAT/LONG: 43.2084 / -75.4583	CLIENT: Bergmann Associates CONTACT: Megan Borruso INQUIRY#: 4366780.4 RESEARCH DATE: 07/28/2015

Historical Topographic Map




N	TARGET QUAD NAME: ROME MAP YEAR: 1947 SERIES: 15 SCALE: 1:62500	SITE NAME: Rome Turney ADDRESS: 109 Canal Street Rome, NY 13440 LAT/LONG: 43.2084 / -75.4583	CLIENT: Bergmann Associates CONTACT: Megan Borruso INQUIRY#: 4366780.4 RESEARCH DATE: 07/28/2015

Historical Topographic Map



N	TARGET QUAD NAME: ROME MAP YEAR: 1949 SERIES: 7.5 SCALE: 1:24000	SITE NAME: Rome Turney ADDRESS: 109 Canal Street Rome, NY 13440 LAT/LONG: 43.2084 / -75.4583	CLIENT: Bergmann Associates CONTACT: Megan Borruso INQUIRY#: 4366780.4 RESEARCH DATE: 07/28/2015

Historical Topographic Map



N	TARGET QUAD NAME: ROME MAP YEAR: 1955 SERIES: 7.5 SCALE: 1:24000	SITE NAME: Rome Turney ADDRESS: 109 Canal Street Rome, NY 13440 LAT/LONG: 43.2084 / -75.4583	CLIENT: Bergmann Associates CONTACT: Megan Borruso INQUIRY#: 4366780.4 RESEARCH DATE: 07/28/2015

Historical Topographic Map



N	TARGET QUAD NAME: UTICA MAP YEAR: 1985 SERIES: 30x60 SCALE: 1:100000	SITE NAME: Rome Turney ADDRESS: 109 Canal Street Rome, NY 13440 LAT/LONG: 43.2084 / -75.4583	CLIENT: Bergmann Associates CONTACT: Megan Borruso INQUIRY#: 4366780.4 RESEARCH DATE: 07/28/2015

APPENDIX E

HISTORIC SANBORN® MAP REPORT

Rome Turney
109 Canal Street
Rome, NY 13440

Inquiry Number: 4366780.3
July 28, 2015

Certified Sanborn® Map Report

6 Armstrong Road, 4th Floor
Shelton, Connecticut 06484
Toll Free: 800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

7/28/15

Site Name:
Rome Turney
109 Canal Street
Rome, NY 13440

Client Name:
Bergmann Associates
200 First Federal Plaza
Rochester, NY 14614

EDR Inquiry # 4366780.3

Contact: Megan Borruso

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by Bergmann Associates were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

Certified Sanborn Results:

Site Name: Rome Turney
Address: 109 Canal Street
City, State, Zip: Rome, NY 13440
Cross Street:
P.O. # 010118.00
Project: Former Rome Turney Radiator Co
Certification # 383F-43FF-A1D1

Maps Provided:

1971	1904
1949	1899
1930	1894
1924	1888
1914	1884
1909	

Sanborn® Library search results
Certification # 383F-43FF-A1D1

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ✓ Library of Congress
- ✓ University Publications of America
- ✓ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

Bergmann Associates (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.


Copyright 2015 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Sanborn Sheet Thumbnails


This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1971 Source Sheets


Volume 1, Sheet 3


Volume 1, Sheet 4


Volume 1, Sheet 15



Volume 1, Sheet 38

1949 Source Sheets


Volume 1, Sheet 3


Volume 1, Sheet 4


Volume 1, Sheet 15


Volume 1, Sheet 38

1930 Source Sheets



Volume 1, Sheet 3


Volume 1, Sheet 4


Volume 1, Sheet 15


Volume 1, Sheet 38

1924 Source Sheets


Volume 1, Sheet 3


Volume 1, Sheet 4


Volume 1, Sheet 15


Volume 1, Sheet 38

1914 Source Sheets



Volume 1, Sheet 3



Volume 1, Sheet 4



Volume 1, Sheet 17



Volume 1, Sheet 33

1909 Source Sheets



Volume 1, Sheet 24



Volume 1, Sheet 20



Volume 1, Sheet 21



Volume 1, Sheet 23


1904 Source Sheets



Volume 1, Sheet 18



Volume 1, Sheet 19



Volume 1, Sheet 23




Volume 1, Sheet 24

1899 Source Sheets



Volume 1, Sheet 13



Volume 1, Sheet 14



Volume 1, Sheet 21

1894 Source Sheets



Volume 1, Sheet 11



Volume 1, Sheet 12

1888 Source Sheets



Volume 1, Sheet 2




Volume 1, Sheet 3



Volume 1, Sheet 9



Volume 1, Sheet 10



Volume 1, Sheet 11

1884 Source Sheets




Volume 1, Sheet 5



Volume 1, Sheet 6


1971 Certified Sanborn Map



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600






Volume 1, Sheet 3
Volume 1, Sheet 4
Volume 1, Sheet 15
Volume 1, Sheet 38

N

1949 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600






Volume 1, Sheet 3
Volume 1, Sheet 4
Volume 1, Sheet 15
Volume 1, Sheet 38

N

1930 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600






Volume 1, Sheet 3
Volume 1, Sheet 4
Volume 1, Sheet 15
Volume 1, Sheet 38

N

1924 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 383F-43FF-A1D1


This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 1, Sheet 3
Volume 1, Sheet 4
Volume 1, Sheet 15
Volume 1, Sheet 38

1914 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 383F-43FF-A1D1

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600






Volume 1, Sheet 3
Volume 1, Sheet 4
Volume 1, Sheet 17
Volume 1, Sheet 33

N

1909 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 383F-43FF-A1D1

Site Name:	Rome Turney
Address:	109 Canal Street
City, ST, ZIP:	Rome NY 13440
Client:	Bergmann Associates
EDR Inquiry:	4366780.3
Order Date:	7/28/2015 2:24:02 PM
Certification #	383F-43FF-A1D1
Copyright:	1909

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 24
Volume 1, Sheet 20
Volume 1, Sheet 21
Volume 1, Sheet 23

0 Feet 150 300 600

N

1904 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 383F-43FF-A1D1

Site Name:	Rome Turney
Address:	109 Canal Street
City, ST, ZIP:	Rome NY 13440
Client:	Bergmann Associates
EDR Inquiry:	4366780.3
Order Date:	7/28/2015 2:24:02 PM
Certification #	383F-43FF-A1D1
Copyright:	1904

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 18
Volume 1, Sheet 19
Volume 1, Sheet 23
Volume 1, Sheet 24

0 Feet 150 300 600


N

1899 Certified Sanborn Map



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 13
Volume 1, Sheet 14
Volume 1, Sheet 21

0 Feet 150 300 600

N

1894 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Rome Turney
Address:	109 Canal Street
City, ST, ZIP:	Rome NY 13440
Client:	Bergmann Associates
EDR Inquiry:	4366780.3
Order Date:	7/28/2015 2:24:02 PM
Certification #	383F-43FF-A1D1
Copyright:	1894

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 11
Volume 1, Sheet 12

0 Feet 150 300 600

N

1888 Certified Sanborn Map




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Rome Turney
Address:	109 Canal Street
City, ST, ZIP:	Rome NY 13440
Client:	Bergmann Associates
EDR Inquiry:	4366780.3
Order Date:	7/28/2015 2:24:02 PM
Certification #	383F-43FF-A1D1
Copyright:	1888

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600






Volume 1, Sheet 2
Volume 1, Sheet 3
Volume 1, Sheet 9
Volume 1, Sheet 10
Volume 1, Sheet 11

N

1884 Certified Sanborn Map




The certified Sanborn search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc is authorized to grant rights for commercial reproduction of maps by The Sanborn LLC, the copyright holder for the collection.

Certification # 383F-43FF-A1D1

Site Name:	Rome Turney
Address:	109 Canal Street
City, ST, ZIP:	Rome NY 13440
Client:	Bergmann Associates
EDR Inquiry:	4366780.3
Order Date:	7/28/2015 2:24:02 PM
Certification #	383F-43FF-A1D1
Copyright:	1884

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 1, Sheet 5
Volume 1, Sheet 6

0 Feet 150 300 600

N

APPENDIX F

HISTORIC AERIAL PHOTOGRAPHS

Rome Turney
109 Canal Street
Rome, NY 13440

Inquiry Number: 4366780.9
July 28, 2015

The EDR Aerial Photo Decade Package

6 Armstrong Road, 4th Floor
Shelton, Connecticut 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Aerial Photo Decade Package

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report AS IS. Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2015 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Date EDR Searched Historical Sources:

Aerial Photography July 28, 2015

Target Property:

109 Canal Street

Rome, NY 13440

Year	***Scale***	***Details***	***Source***
1960	Aerial Photograph. Scale: 1"=500'	Flight Date: June 02, 1960	EDR
1985	Aerial Photograph. Scale: 1"=1000'	Flight Date: May 08, 1985	EDR
1989	Aerial Photograph. Scale: 1"=500'	Flight Date: April 01, 1989	EDR
1997	Aerial Photograph. Scale: 1"=500'	DOQQ - acquisition dates: May 02, 1997	USGS/DOQQ
2006	Aerial Photograph. Scale: 1"=500'	Flight Year: 2006	USDA/NAIP
2008	Aerial Photograph. Scale: 1"=500'	Flight Year: 2008	USDA/NAIP
2009	Aerial Photograph. Scale: 1"=500'	Flight Year: 2009	USDA/NAIP
2011	Aerial Photograph. Scale: 1"=500'	Flight Year: 2011	USDA/NAIP


Subject Property
INQUIRY #: 4366780.9
YEAR: 1960
= 500'
N
EDR


Subject Property
INQUIRY #: 4366780.9
YEAR: 1985
= 1000'
N
EDR


Subject Property
INQUIRY #: 4366780.9
YEAR: 1989
= 500'
N
EDR


Subject Property
INQUIRY #: 4366780.9
YEAR: 1997
= 500'
N
EDR


Subject Property
INQUIRY #: 4366780.9
YEAR: 2006
= 500'
N
EDR


Subject Property
INQUIRY #: 4366780.9
YEAR: 2008
= 500'
N
EDR


Subject Property
INQUIRY #: 4366780.9
YEAR: 2009
= 500'
N
EDR


Subject Property
INQUIRY #: 4366780.9
YEAR: 2011
= 500'
N
EDR

APPENDIX G

CITY DIRECTORY IMAGE REPORT

Rome Turney
109 Canal Street
Rome, NY 13440

Inquiry Number: 4366780.5
July 30, 2015

The EDR-City Directory Image Report

Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

Executive Summary

Findings

City Directory Images

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2015 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Report is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Report includes a search of available city directory data at 5 year intervals.

RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. A check mark indicates where information was identified in the source and provided in this report.

Year	Target Street	Cross Street	Source
2013	☑	☑	Cole Information Services
2008	☑	☑	Cole Information Services
2003	☑	☑	Cole Information Services
1999	☑	☑	Cole Information Services
1995	☑	☑	Cole Information Services
1992	☑	☑	Cole Information Services
1987	☑	☑	Polk's City Directory
1981	☑	☑	Polk's City Directory
1976	☑	☑	Polk's City Directory
1971	☑	☑	Polk's City Directory
1966	☑	☑	Polk's City Directory
1961	☑	☑	Polk's City Directory

RECORD SOURCES

EDR is licensed to reproduce certain City Directory works by the copyright holders of those works. The purchaser of this EDR City Directory Report may include it in report(s) delivered to a customer. Reproduction of City Directories without permission of the publisher or licensed vendor may be a violation of copyright.

FINDINGS

TARGET PROPERTY STREET

109 Canal Street
Rome, NY 13440

Year	*CD Image*	*Source*
CANAL ST		
2013	pg A1	Cole Information Services
2008	pg A3	Cole Information Services
2003	pg A5	Cole Information Services
1999	pg A7	Cole Information Services
1995	pg A9	Cole Information Services
1992	pg A11	Cole Information Services
1987	pg A13	Polk's City Directory
1981	pg A15	Polk's City Directory
1981	pg A16	Polk's City Directory
1976	pg A19	Polk's City Directory
1976	pg A20	Polk's City Directory
1971	pg A22	Polk's City Directory
1971	pg A23	Polk's City Directory
1966	pg A26	Polk's City Directory
1961	pg A28	Polk's City Directory
1961	pg A29	Polk's City Directory
1961	pg A30	Polk's City Directory

FINDINGS

CROSS STREETS

Year	*CD Image*	*Source*
JASPER ST		
2013	pg. A2	Cole Information Services
2008	pg. A4	Cole Information Services
2003	pg. A6	Cole Information Services
1999	pg. A8	Cole Information Services
1995	pg. A10	Cole Information Services
1992	pg. A12	Cole Information Services
1987	pg. A14	Polk's City Directory
1981	pg. A17	Polk's City Directory
1981	pg. A18	Polk's City Directory
1976	pg. A21	Polk's City Directory
1971	pg. A24	Polk's City Directory
1971	pg. A25	Polk's City Directory
1966	pg. A27	Polk's City Directory
1961	pg. A31	Polk's City Directory

City Directory Images

Target Street	Cross Street	Source
✓	-	Cole Information Services

CANAL ST 2013

106	PHILIP VESCIO
109	THE MUSIC FACTORY
110	CALVIN VERRO
116	JEFF LEWIS
	SHAWNA MITCHELL
118	RAY CAMPANARO
120	LUCIA CARRIERO
122	CATHY TARDBANIA
124	PATRICIA PRITCHARD
126	CARMEN AMADOR
	HUMBERTO MERY
	KATIE BAYARD
	MICHAEL QUILES
	MICHAEL WILLIAMSON
	MICHELLE STRAFFORD
200	FRANK GRAICHEN
202	THOMAS ARMSTRONG
204	KAYLA WILLIS
208	AMERICANUKRAINIAN VETERANS & MEN
214	ANTHONY BARRETTA
300	JEANNE MONO
	JUSTIN ROACH
	MARIE BALIO
	MICHAEL CAMPANY
310	JIMMY UNDERWOOD
312	DOROTHY COMPO
	ROBERT BABCOCK

Target Street	Cross Street	Source
-	✓	Cole Information Services

JASPER ST 2013

203	AHMED SLAMANI
	E MYRIEE
	MICHAEL GROAT
	WILLIAM RUSSELL
208	LEON RUCH
209	WILLIAM UNDERWOOD
210	ROBERT MARION
211	PETER KERWAWICZ
301	ANDREW JONES
	PHILIP NELSON
307	ROSE TARDABONE
	TAMMY ABLANG
308	PARSONS SHEET METAL
310	OCCUPANT UNKNOWN
313	OCCUPANT UNKNOWN

Target Street	Cross Street	Source
✓	-	Cole Information Services

CANAL ST 2008

106	JOHN HULL
109	ELEGRACE CASKET INC
	ROFIN LLC
	ROME TURNEY RADIATOR CO
110	BONNIE GILLETT
	BYRON WALDRON
	JASON BRADY
	MARY OLMSTEAD
116	VICTORIA GWIN
118	RAY CAMPANARO
120	LUCIA CARRIERO
122	DOMINICK TARDBANIA
124	PATRICIA PRITCHARD
126	CARMEN AMADOR
	JOSE BAEZ
	KARINA PELLOT
	RAYMOND CARLETTA
200	CHARLES GWIN
204	DIANA RUSSITANO
208	AMERICAN UKRAINIAN VETERANS & MEN
214	TINA BARRETTA
300	JUSTIN ROACH
	MARLENE PEZZULA
310	JACK CULLOP
312	ROBERT BABCOCK

Target Street	Cross Street	Source
-	✓	Cole Information Services

JASPER ST 2008

203	AHMED SLAMANI
	E MYRIEE
	JAMES POPE
	VICTORIA PLATO
208	LEON RUCH
209	UNDERWOODS MARKET
	WILLIAM UNDERWOOD
211	PETER KERWAWICZ
301	ANDREW JONES
	PHILIP NELSON
307	ROSE TARDABONE
308	PARSONS & SONS G H
310	TROY TUCKER
313	SIMON KOENIG

Target Street	Cross Street	Source
✓	-	Cole Information Services

CANAL ST 2003

106	OCCUPANT UNKNOWN
109	MUSIC FACTORY
	ROMETURNEYRADI
110	LETCIA MULLIN
116	J SMITH
	KATHY RIGGS
	KELLEY GWIN
	OMAR FRYE
	TERI BATCHELDER
118	RAY CAMPANARO
120	MARY CARRIERO
122	DOMINICK TARDBANIA
124	PATRICIA PRITCHARD
126	MICHELLE CARLETTA
200	CHARLES GWIN
202	OCCUPANT UNKNOWN
204	LISA CURTIS
208	AMERICAN UKRAINIAN VETERANS
214	ANTHONY BARRETTA
300	TIMOTHY PREMO
310	OCCUPANT UNKNOWN
312	DEWEY BECRAFT

Target Street	Cross Street	Source
-	✓	Cole Information Services

JASPER ST 2003

203	J BLANCHARD
208	LLOYD RUCH
209	ROBERT WILKES
301	KIRK SERWAY
	PHILIP NELSON
308	GEORGE PARSONS
	PARSONS GEORGE H & SON
313	SIMON KOENIG

Target Street	Cross Street	Source
✓	-	Cole Information Services

CANAL ST 1999

109	MUSIC FACTORY THE
	ROME TURNEY RADIATOR COMPANY
110	W LINTS
116	OCCUPANT UNKNOWN
117	OCCUPANT UNKNOWN
118	R CAMPANARO
120	LUCIA CARRIERO
122	DOMINIC TARDBANIA
124	OCCUPANT UNKNOWN
126	BETH GOLDEN
	MICHAEL WILLIAMSON
200	RICHARD ZAKALA
204	ROBIN LIGHTHALL
206	ROSE MARABELLA
208	AMERICAN UKRAINIAN VETERANS AND MENS CLUB INCORPORATED
214	ANTHONY BARRETTA
300	LAURENA FRENGER
308	OBEDIAH SWIFT
310	OCCUPANT UNKNOWN
312	CLELAND MCCLAIN

Target Street	Cross Street	Source
-	✓	Cole Information Services

JASPER ST 1999

203	MICHAEL RANDALL
	THELMA SMITH
208	LEON RUCH
209	OCCUPANT UNKNOWN
211	PETER KERWAWICZ
301	PHILIP NELSON
307	MARY TARDABONE
308	PARSONS GEORGE H & SON SHEET METAL WORK
310	OCCUPANT UNKNOWN
313	MARY PALMA

Target Street	Cross Street	Source
✓	-	Cole Information Services

CANAL ST 1995

100	POLK R L & CO
109	LYNCH REALTY
	MUSIC FACTORY THE
	ROME TURNEY RADIATOR CO
	SERWAY BROS INCORPORATED-PLASTIC LAMINATING DIV
110	MARRERO, LOURDES
114	MARULLO, MICHL F
118	RAMSDALE, LAURIE A
120	CARRIERO, L M
122	TARDBANIA, DOMINICK P
124	PRITCHARD, ROBERT M
126	VILLA, GARY
200	BIRD, ROBERT
204	PERFETTI, JOSEPHINE M
206	MARABELLA, RALPH
208	AMERICAN-UKRAINIAN VETERANS AND MEN'S CLUB INC
214	BARRETTA, ANTHONY
	BARRETTA, ANTHONY, JR
300	KIRK, RICHARD TIMMY
306	COLEMAN, J H
312	MC CLAIN, C RAY

Target Street	Cross Street	Source
-	✓	Cole Information Services

JASPER ST 1995

203	SMITH, THELMA I
208	RUCH, L & L
211	KERWAWICZ, PETER
301	NELSON, PHILIP
	PICKARD, B
307	TARDABONE, M & R
308	PARSONS, GEORGE H & SON, SHEET METAL WORK
313	PALMA, M G

Target Street	Cross Street	Source
✓	-	Cole Information Services

CANAL ST 1992

109	LYNCH REALTY
	MUSIC FACTORY THE
	ROME TURNEY RADIATR CO
	SERWAY BROS INCORPORATED-PLASTIC LAMINATING DIV
114	MARULLO, MICHL F
116	GIBBS, DEBRA
	TEAMSTERS LOCAL 182
118	STAPLETON, RICHARD H
120	CARRIERO, MARY
122	TARDBANIA, DOMINICK P
124	FAZIO, KATHERINE M
126	GUGGI, DANIEL M, JR
	SKINNER, WENDY
200	GUGGI, JENNIE
204	PERFETTI, JOSEPHINE M
206	MARABELLA, RALPH
208	AMERICAN-UKRAINIAN VETERANS AND MEN'S CLUB INC
214	BARRETTA, ANTHONY
	BARRETTA, ANTHONY, JR
	JOHNSON, R M
306	COLEMAN, J H
308	BROWN, L
310	CULLOP, P
312	CLARK, ADRIAN
	IRVIN, DENISE
	MC CLAIN, C RAY

Target Street	Cross Street	Source
-	✓	Cole Information Services

JASPER ST 1992

203	DILOSSI, MICHELLE
	GOWETT, JENNIFER
208	RUCH, L & L
211	KERWAWICZ, PETER
301	NELSON, PHILIP
307	TARDABONE, M & R
308	PARSONS, GEORGE H & SON, SHEET METAL WORK
310	WESTCOTT, TINA
313	PALMA, M G

Target Street	Cross Street	Source
✓	-	Polk's City Directory

CANAL ST 1987

N DOXTATER AV
INTERSECTS

230

CANAL ST —FROM 219 S JAMES EAST TO LYNCH ST

ZIP CODE 13440

100 Business Consultants 337-9200
San-Mar Typing Service 337-9200
AVENUE A BEGINS
106 Hull John V ◎
107 Serway Bros Inc (Plastic Div) (stge) 336-1440
109 Rome-Turney Radiator Co heating apparatus 336-2200
110 Cornell Virginia
Schaller Wayne E 336-8332
114 Marullo Michl F ◎ 337-8031
116 Campanaro John R ◎ 336-3762
★Baker Harold
118 Carriero Sharon S
120 Carriero Rosa Mrs ◎ 337-4106
122 Tardbania Nellie Mrs ◎ 336-7271
124 Fazio Kath M Mrs ◎ 336-1114
126 Guggi Danl M Jr 339-1284
★Guggi Albert

254

JASPER ST INTERSECTS
200 Guggi Jennie ◎ 336-4437
202★Mc Donald Wm F ◎ 339-0434
204 Perfetti Josephine Mrs ◎ 336-5506
206 Marabella Rose A ◎ 337-0725
Paniccia Violet M Mrs 336-5585
208 American Ukranian National Home 336-9951
214 Johnson Rose 336-7670
Barretta Louis ◎ 336-9014
★Martin Raymond
DEPEYSTER ST INTERSECTS
300★Norman Bernadette C
306 Coleman John H ◎ 336-6305
Sochia Scharlena L 336-3566
308 Vacant

Target Street	Cross Street	Source
-	✓	Polk's City Directory

JASPER ST 1987

254

JASPER ST —FROM 126 112
CANAL SOUTH TO 107 113
LOUISA

ZIP CODE 13440 115
CONRAIL INTERSECTS 117
CANAL ST INTERSECTS 118
203 Fabrizio Frank A ◎ 337-4402 V
★Novak Scott F 202
MASSOCK AV INTERSECTS 203
208 Ruch Lloyd ◎ 336-9016 204
209 Wilkes Florence Mrs 337-4932 205
Wilkes James 206
210 Jones Marion F Mrs ◎ 337-4643 207
211 Kerwawycz Peter ◎ 337-2101 208
LAWRENCE ST INTERSECTS V
301 Smith Fred W 336-2960 209
305 Vacant 210
307 Tardabone Mary ◎ 336-8975
★Le Claire Phillip 212
308 Parsons Geo H & Son sht mtl contrs 336-6730 214 216
310★Aldrich Robt L 339-2609
313 Palma Mary G ◎ 337-5426 V


300

247

JAY ST N —FROM 422 W 304
DOMINICK NORTH TO 431 305

Target Street	Cross Street	Source
✓	-	Polk's City Directory

CANAL ST 1981



N DOXTATER AV
INTERSECTS

230

CANAL ST —FROM 219 S JAMES EAST TO LYNCH ST

ZIP CODE 13440

100 Romohawk Tobacco Inc
336-6320
Angelicchio & Associates
bkprs 336-1145

AVENUE A BEGINS

106 Hull John V ◎

107 Serway Bros Inc (Plastic Div)
kitchen counter tops
336-1440

109 Rome-Turney Radiator Co
heating apparatus 336-2200

110★Cornell Virginia
★Lighthall Donald G

114 Marullo Michl L ◎ 337-8031

116 Campanaro John R ◎
336-3762

116½ Christman

118 Carriero Sharon 336-0646

120 Carriero Rosa Mrs ◎
337-4106


122 Tardbania Philip ◎ 336-7271

RTS, CRAFTS, & HOBBIES

OFFICE EQUIPMENT

Target Street	Cross Street	Source
✓	-	Polk's City Directory

CANAL ST 1981



CANAL ST—Contd
124 Fazio Kath M Mrs ◎ 336-1114
126★Horeth Bradley 337-0934
★Guggi David J 336-8853

254

JASPER ST INTERSECTS
200 Guggi Albert ◎ 336-4437
202 Boiko Russell ◎
204 Perfetti Josephine Mrs ◎ 336-5506
206 Marabella Rose A ◎ 337-0725
Paniccia Saturno 336-5585
208 American Ukranian National Home 336-9951
214 Libeate Angela
Barretta Louis ◎ 336-9014
Regan Mary Mrs 336-0229

DEPEYSTER ST INTERSECTS
300 Minsaas Harvey 339-3938
306 Coleman John L ◎ 336-6305
★Artryda Fred
308 Vacant
310 Salzaagio Angeline 337-4774

AVENUE B BEGINS
312★Metott Clifford
★Whitaker Gene F
314 Szablewski Stanley ◎ 336-8637
Vacant
316 Hanba Fredrick T ◎ 336-5368
318 Beddia Amedeo ◎
320 Gentile Paul

ANN ST INTERSETTS
400 Reczek Nellie S Mrs ◎ 336-4536
404 Sroka Walter E ◎ 337-5597
Decker Frank A
408 Calandra Guy ◎ 339-2732
410 Kurowski Walter J ◎ 337-8391
Alamo Jonnie

DAY AV BEGINS
416 Rome Iron Mills Inc 337-9000

LYNCH ST BEGINS

231


CANTERBURY HILL RD
—FROM 7931 PENNYSTREET

7154
7155
7225
7255
7272
7288
7315
7438
7460
7487
7490
7560
7580
7588
109
111
113
115
116
117
120
122
123
128

336-8460
301 Mill St. Rome N.Y.
13503


Target Street	Cross Street	Source
-	✓	Polk's City Directory

JASPER ST 1981



Target Street	Cross Street	Source
-	✓	Polk's City Directory

JASPER ST 1981



JASPER ST—Contd

CANAL ST INTERSECTS

203 Tabrizio Frank A ◎

MASSOCK AV INTERSECTS

208 Ruch Helen Mrs ◎ 336-9016

209★Wilkes Florence Mrs
337-4932

★Wilkes James

210 Jones Marion Mrs ◎ 337-4643

211 Kerwawycz Peter ◎ 337-2101

LAWRENCE ST INTERSECTS

305 Vacant

307 Tardabone Mary ◎ 336-8975

308 Parson's Sheet Metal 336-6730

310 Vacant

313 Palma Mary G ◎

247

JAY ST N —FROM 422 W

Target Street	Cross Street	Source
✓	-	Polk's City Directory

CANAL ST 1976

N DOXTATER AV
INTERSECTS

33

CANAL ST —FROM 219 S JAMES EAST TO LYNCH ST

ZIP CODE 13440
100 Martin James P 336-2810
Homadic Inc 339-0007
AVENUE A BEGINS
106 Hull Stella Mrs ◎
107 Serway Bros Inc (Plastic Div)
kitchen counter tops
336-1440

Target Street	Cross Street	Source
✓	-	Polk's City Directory

CANAL ST 1976

109 Rome-Turney Radiator Co
heating apparatus 336-2200
110 Di Bello Cosmo
Anno Tillie Mrs 337-2388
114 Marullo Michl L ◎ 337-8031
116 Campanaro John R ◎
336-3762
116½ Sherman Edw
118 Bandych Thos F 339-2081
120 Carriero Rosa Mrs ◎
337-4106
122 Tardbania Philip 336-7271
124 Fazio Kath M Mrs ◎
336-1114
Vacant
126 Mercurio Vito F 337-5176

22

JASPER ST INTERSECTS
200 Guggi Albert ◎ 336-4437
202 Lovett Joseph R ◎ 336-4704
204 Perfetti Josephine Mrs ◎
336-5506
206 Marabella Ralph ◎ 337-0725
Paniccia Saturno 336-5585
208 American Ukranian National
Home 336-9951
214 Matrassi Mary A Mrs
Barretta Louis ◎ 336-9014
Regan Mary Mrs 336-0229
DEPEYSTER ST INTERSECTS
300 Karces Paul R 337-1461
306 Coleman John L ◎ 336-6305
Coleman Frank L
Coleman Anthony 336-6305
308 Rossi Louis J ◎
310 Salvaggio Frank P ◎
337-4774
AVENUE B BEGINS
312 Sharpe Michl 337-4790
Edwards Albert Jr
314 Novak John J ◎ 337-1634
Bane Thos
316 Hanba Fredrick T 336-5368
318 Beddia Amedio ◎ 336-0256
ANN ST INTERSETTS
400 Reczek Nellie S Mrs ◎
336-4536
404 Sroka Walter E ◎ 337-5597
Decker Frank A
408 Calandra Guy ◎ 339-2732
410 Kurowski Walter J ◎
337-8391
Russell Jack A 339-0435
DAY AV BEGINS
416 Rome Iron Mills Inc 337-9000
LYNCH ST BEGINS

Target Street	Cross Street	Source
-	✓	Polk's City Directory

JASPER ST 1976

204 Gibilaro Joseph P ◎ 336-6173
LOUISA ST INTERSECTS

22

JASPER ST —FROM 126 CANAL SOUTH TO 107 LOUISA

ZIP CODE 13440
100 Kowal Anna Mrs 336-4277
Patane Rose Mrs 337-8373
NYCRR INTERSECTS
CANAL ST INTERSECTS
203 Fabrizio Frank A
MASSOCK AV INTERSECTS
208 Ruch Helen Mrs ◎ 336-9016
209★Blake Timothy 339-1050
210 Joyce Thos ◎ 337-4643
211 Kerwawycz Petro ◎ 337-2101
LAWRENCE ST INTERSECTS
301 No Return
305 Smith Marguerite ◎ 336-8933
307★Palma D
Tardabone Larry 336-8975
308 Parsons Sheet Metal 336-6730
310 Conover Annetta K ◎
313 Palma Mary G ◎ 337-2783


15

JAY ST N —FROM 422 W DOMINICK NORTH TO 431

115
117
118
W
202
203
204
205
206
207
208
W
209
210
212
214
216
W
300
304
305
306

Target Street	Cross Street	Source
✓	-	Polk's City Directory

CANAL ST 1971



INTERSECTS

33

CANAL ST —FROM 219 S JAMES EAST TO LYNCH ST

ZIP CODE 13440

100 H R B-Singer Inc (Br)
electronic research 336-0000
AVENUE A BEGINS
106 Hull Stella Mrs ◎
107 Keltec Inc (Rome Div) coml cln equip mfrs 337-1800
109 Rome-Turney Radiator Co heating apparatus 336-2200
110 Williams Willard K 337-3655
Anno Tillie Mrs 337-2388
114 Marullo Michl F ◎ 337-8031
116 Campanaro John R ◎ 336-3762
118 Mitchell Richd L 336-9329
120 Carriero Rosa Mrs ◎ 337-4106
122 Tardbania Philip 336-7271
124 Fazio Kath M Mrs ◎ 336-1114
Barber John L 336-1666
126 Mercurio Vito F 337-5176

22

JASPER ST INTERSECTS

200 Guggi Albert ◎ 336-0486
202 Lovett Mary M Mrs ◎
204 Perfetti Josephine Mrs ◎ 336-5506
206 Marabella Ralph ◎ 337-0725
Paniccia Saturon 336-5585
208 American Ukranian National Home 336-9951
214 Matrassi Mary A Mrs
Barretta Louis ◎ 336-9014
Regan Mary Mrs
DEPEYSTER ST INTERSECTS
300 Cardiff Donald E 336-9337
306 Coleman John L ◎ 336-6305
Taylor Wilford F
308 Rossi Louis J ◎

Target Street	Cross Street	Source
✓	-	Polk's City Directory

CANAL ST 1971

CANAL ST—Contd

310 Salvaggio Frank P ◎
337-8881

AVENUE B BEGINS

312 Parisi James(337-3007
Parmon Bonnie

314 Novak John J ◎ 337-1634
Szablewski Stanley 336-2583

316 Hanba Fredrick I 336-5368

318 Beddia Anthony ◎

ANN ST INTERSETTS

400 Reczek Nellie S Mrs ◎
336-4536

404 Sroka Walter E ◎ 337-5597
Decker Frank A

408 Vacant

410 Sapp Geo E
Kurowski Walter J ◎
337-8391
Prinze Dorothy Mrs

DORY AV BEGINS

412 Hluska Joseph W 337-7625


416 Rome Iron Mills Inc
337-9000

LYNCH ST BEGINS

CANTERBURY HILL RD

Target Street	Cross Street	Source
-	✓	Polk's City Directory

JASPER ST 1971



[illegible] Joseph P ◎ 112
336-6173 113
LOUISA ST INTERSECTS

---

22 115
JASPER ST —FROM 126 117
CANAL SOUTH TO 107 118
LOUISA W
202
ZIP CODE 13440
100 West End Brewing Co 203
336-1960 204
Kowal Anna Mrs 336-4277 205
Patane Rose Mrs 337-8373
NYCRR INTERSECTS 206
CANAL ST INTERSECTS
203 Cornish Richd V 207
Fabrizio Frank
MASSOCK AV INTERSECTS 208
208 Ruch Lloyd P ◎ 336-9016 W
209 Scaccia Angeline Mrs 209
336-1506

Target Street	Cross Street	Source
-	✓	Polk's City Directory

JASPER ST 1971

210 Joyce Thos pntr ◎ 337-4643
211 Kerwawicz Petro ◎ 337-2101
LAWRENCE ST INTERSECTS
301 Pacheco Maria A Mrs
305 Smith Geo E ◎ 336-8933
307 Kane David
Tardabone Larry ◎ 336-8925
308 Mathis Creamery Inc
337-5480
312 Vacant
313 Palma Mary G ◎ 337-2783

15

JAY ST N —FROM 422 W

Target Street	Cross Street	Source
✓	-	Polk's City Directory

CANAL ST 1966

CAMP ST—Contd

730 POWELL KENNETH G ●
336-5814
734 GILLEN FRANCIS D ●
337-9662
736 FEDUN ANASTASIA MRS ●
336-0757
737 VACANT
738 WOOD LEWIS C ●
337-5712
740 HARLANDER HERMINE
336-5134
741 DEWOLFE MABEL P MRS ●
337-2418
742 JONES GERTRUDE MRS ●
336-1568
744 RICHARDSON LENA ●
336-5123
BRENNAN THOS A
336-3602
746 MODERN DISPLAY SIGN
CO ● 336-9280
MATHER LEO JR ●
336-9280
747 CATELLO ERNEST
751 BURNS HOWARD B
LESZCZYNSKI THOS F
---N DORTATER AV
INTERSECTS

33

CANAL ST -FROM 219 S
JAMES EAST TO DEAD END
BEY JANE

H R B-SINGER INC (PR)
ELECTRONIC RESEARCH
337-2810
---AVENUE A BEGINS
106 HULL VINCENT ●
107 KELTEC INC (ROME DIV)
COML CLN EQUIP MFRS
337-1800
109 ROME-TURNEY RADIATOR
CO HEATING APPARATUS
336-2200
110 SHARROW CHARLES N
337-9314
ANNO TILLIE MRS
337-2388
114 MARULLO MICHL F ●
337-8031
116 CAMPANARO JOHN R ●
336-3762
118 PATANE JOHN ●
337-7807
120 CARRIERO ROSA MRS ●
337-4106
122 TARBANIA PHILLIP
336-7271
124 FAZIO KATH M MRS ●
336-1114
126 ROBINSON WALTER
TUCKER RICHD D
337-2214.

22

---JASPER ST INTERSECTS
200 GUGGI ALBERT ●
336-0486
202 LOVETT GEO E ●
337-3098
204 SCHUCK ROBT G ●
336-0626
206 MARABELLA RALPH ●
337-0725
COSIMERO VIOLET
208 AMERICAN UKRANIAN
NATIONAL HOME
336-9951
214 PODSZEDKA IRENE MRS
337-8177
BARRETTA LOUIS ●
336-9014
---DEPEYSTER ST
INTERSECTS
300 ASHLEY EDITH
306 SABIA PAUL ● 336-2052
TARDBANIA PHILIP M
336-7271
308 ROSSI LOUIS J ●
310 SALVAGGIO FRANK P ●
337-8881
---AVENUE B BEGINS
312 CHILDS JOHN 336-5934
313 BORNLY JOSEPH
314 NOVAK JOHN J ●
336-3933
316 HANBA CAROLINE J MRS
● 336-5637
318 AIELLO JOHN
BEDDIO ANTHONY
---ANN ST INTERSECTS
400 RECZEK NELLIE S MRS ●
336-4536
404 SROKA WALTER E ●
337-5597
DECKER FRANK A
408 RECZEK STANLEY S ●
337-0634
---DORY AV BEGINS
412 AUGUSTINE JENNIE MRS
337-3046
416 ROME IRON MILLS INC ●
337-9000


3

CAREY ST -FROM 1027 E
DOMINICK NORTH TO
REVERE BRASS & COPPER
CO

INDEPENDENT OPTICAL CO

Target Street	Cross Street	Source
-	✓	Polk's City Directory

JASPER ST 1966



---LOUISA ST INTERSECTS

22

JASPER ST -FROM 126 CANAL SOUTH TO 107 LOUISA

100 WEST END BREWING CO
336-1960
KOWAL ANNA MRS
336-4277
PATANE ANTHONY J
337-8373

---NYO&W INTERSECTS

---CANAL ST INTERSECTS

203 ABONE CATH MRS ●
FABRIZIO FRANK

---MASSOCK AV INTERSECTS

208 FITSIK MICHL J ●
337-5107

209 ROMANO MICHL ●
336-1506

210 CURAL ANTOINETTE MRS ●

211 KERWAWICZ PETRO ●

---LAWRENCE ST INTERSECTS


301 LENCI NORMAN

305 SMITH GEO E ●
336-8933

307 FITSIK JOHN M
337-8763

Target Street	Cross Street	Source
✓	-	Polk's City Directory

CANAL ST 1961



N Doxtater av
crosses

7

CANAL—From 219 S James east to a dead end bey Jane, wd 4

Avenue A begins

000 Kent Co Inc The mach mfrs 7-1800
106 Hull Vincent ◎
107 Kent Co Inc The factory
109 Rome Turney Radiator Co 6-2200


Massock av begins

110 Parisi Jos C 6-3404
Paris Anthony J 7-6007

Kitchen Cabinets

Target Street	Cross Street	Source
✓	-	Polk's City Directory

CANAL ST 1961



20

CANAL—Contd

114 Marullo Josephine Mrs ◎ 7-9325
116 Campanaro John R ◎ 6-3762
Campanaro Carmella A Mrs 6-5022
118 Romaniello Leonardo ◎ 7-5106
120 Carriero Salvatore ◎ 7-4160
122 Bochicchio Frank A ◎ 6-0974
124 Fazio Kath M Mrs 6-1114
Fazio Carmen P 7-0681
126 Sammons Marvin O
Welfel Henry D

Jasper crosses

200 Guggi Albert ◎ 6-0486
Guggi Danl M 6-8542
202 Lovett Geo ◎ 6-5373
204 Schuck Robt G ◎ 6-0626
206 Marabella Ralph ◎ 7-0725
Fields Anthony F 7-6598
208 American Ukrainian Natl Home 6-9951
214 Barretta Nicholas A 6-1503
Barretta Louis ◎ 6-9014
Hemmes David

Depeyster crosses

300 Perfetti Albert J 6-5506
306 Sabia Cath Mrs ◎ 6-2052
Tardbania Philip M 6-7271
308 Vacant
310 Salvaggio Frank P ◎ 7-8881

Avenue B begins


312 Porter Marian Mrs 6-2943
314 Novak John J ◎ 6-3933
Sabia Canio D 6-9035
316 Hanba Caroline J Mrs ◎ 6-5637
318 Stachow Susie Mrs ◎
Salvaggio Anthony P 7-5626

Ann crosses

400 Reczek Nellie Mrs ◎ 6-4536
404 Sroka Walter E ◎ 7-5597
Decker Frank A 6-4463

Target Street	Cross Street	Source
✓	-	Polk's City Directory

CANAL ST 1961



20

408 Reczek Stanley S ◎
7-0634
Dory av begins
410 Calandra Saml 6-6367
Marturano Josephine Mrs
◎ 7-6153
Farrar Kenneth L
412 Hluska Mary Mrs
7-5364
Augustine Jennie J Mrs
7-3046
413 Vacant
416 Rome Iron Mills Inc ◎
7-9220
Lynch crosses
Jane begins

3

Target Street	Cross Street	Source
-	✓	Polk's City Directory

JASPER ST 1961

204 Lichko Joseph 7-8165
206 Vacant
Louisa crosses

7

JASPER—From 126 Canal south to 107 Louisa, wd 2


100 West End Brewing Co 6-1960
Patane Anthony 7-8373
Kowal Anna Mrs 6-4277
NYO&WRR crosses
105 Kelley Bros Coal 6-9390
Canal crosses
203 Abone Cath Mrs ◎
Dellork Frank 7-2413
Massock av crosses
208 Fitsik Harry ◎ 7-5107
209 Romano Michl ◎ 6-1506
210 Gural Antoinette Mrs 6-4506
211 Kerwawycz Petro ◎
Lawrence crosses
301 D'Antonio Henry J 7-2183
305 Smith Geo E ◎ 6-8933
307 Tardabone Larry ◎ 6-8975
Fitsik John M 7-8763
308 Mathis Creamery Inc 7-5480
312 Scerra Raffaela Mrs 6-2088
313 Palma Mary G ◎ 7-2783

4

JAY N—From 422 W Dominick north to 431 Turin, wds 4

APPENDIX H

NYSDEC ENVIRONMENTAL RESOURCE MAP




Bergmann associates
architects // engineers // planners

Former Rome-Turney Radiator Co.
109 Canal Street Rome, NY
Phase I ESA

NYSDEC Map

APPENDIX I

FEMA FLOOD INSURANCE RATE MAP



MAP SCALE 1" = 500'

250 0 500 1000 FEET

NFIP

NATIONAL FLOOD INSURANCE PROGRAM

PANEL 0554F

FIRM

FLOOD INSURANCE RATE MAP

for ONEIDA COUNTY, NEW YORK
(ALL JURISDICTIONS)

CONTAINS:

COMMUNITY	NUMBER
ROME, CITY OF	360542

PANEL 554 OF 926
MAP SUFFIX: F

(SEE MAP INDEX FOR FIRM PANEL LAYOUT)

Notice to User: The **Map Number** shown below should be used when placing map orders; the **Community Number** shown above should be used on insurance applications for the subject community.

MAP NUMBER
36065C0554F

EFFECTIVE DATE
SEPTEMBER 27, 2013

Federal Emergency Management Agency

This is an official copy of a portion of the above referenced flood map. It was extracted using F-MIT On-Line. This map does not reflect changes or amendments which may have been made subsequent to the date on the title block. For the latest product information about National Flood Insurance Program flood maps check the FEMA Flood Map Store at www.msc.fema.gov